

INS. CASE OWNER:

CC3 / AIG1800 9018, Kwa3

LKK
IDAC

Surveyor:

1082

DOI:

ASSIGNMENT

12/5/18

Date / Time:

12/5/18

Registered in Merimen:

12/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLV 6735R

Name of Insured:

Lany Xian Lim

Insured Tel No.:

HP:

97996036

Excess Sec II :SS

D.O.A.:

12-05-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHB 9802M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans. Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/5/18
12/5/18SHB 9802M - 12/5/18 15:00:00 / 12/5/18 15:00:00 / 12/5/18 15:00:00
SLV 6735R-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

12/5/18

After call ltr to OI:

12/5/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

S\$ 2621.50

Loss of Rental (LOR):

S\$ 357.28

(

4 days) x 99.32

Loss of Use (LOU):

S\$ 200.00

(

5.50 x 4 days)

Loss of Income (LOI):

S\$ -

(

5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3226.23

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 3226.23

Name 1:

Trans Cab Auto Services Pte Ltd.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

CORRECT
9/11/18

RECEIVED 9 NOV 2018

ASS. REC. BY:

REF: 1161

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S11B 9802m Yr Regn: OF 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 476622 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1ABL15AUC 273335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 12/5/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 15/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/5 Rk pass to Catherine

17/6/18 L1 Log @ 24501 Catherine Jones (2 x 99.32 + 200)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

(12/1) = 31203.63
9371)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG16009018/Kwa3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 17-05-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 6735R	Veh. Inspected	SHB 9802M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Make Year	
Brakes		Modification	
General			

3. Condition of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/05/2018	Report Date	17/05/2018
Survey held at	HUNTS-CAR AUTO SERVICES PTE LTD NO 2 ANG MO KIO ST 63 SINGAPORE 600111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9802M**AAD1805-120***Not Authorized
L1 Sy @ 2450!*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9802M

VF1ABL15AUC273335

RENAULT

LATITUDE

12.5.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>As/As</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>As/As</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>As</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>As</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>As</i> 225.95	X
13	1 BOOT REAR	\$	<i>As</i> 2,872.68	} X
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>As</i> 225.36	
19	1 BOOT BADGE	\$	<i>As</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>As</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>As</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>As</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>As</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1805-120

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9802M

30	1 DOOR PANEL REAR LH	\$	2,844.66	}	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	671.45		
32	1 FENDER PANEL REAR LH	\$	3,299.13		
33	1 WHEELARCH REAR LH	\$	543.47		
34	1 TAILLAMP LH	\$	552.55		
35	1 TAILLAMP PANEL LH	\$	986.70		
36	1 TAILLAMP RH	\$	552.55		
37	1 TAILLAMP PANEL RH	\$	986.70		

TOTAL	\$	21,801.58
10%	\$	2,180.16
	\$	19,621.43

Specical Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	—
11	1SET BOOT FINISHER CLIP	\$	na	24.20	} X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	}
22	1 WINDSCREEN MOULDING	\$	Sm	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	Sm	100.00	

Trans-cab Auto Services Pte Ltd

AAD1805-120

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9802M

TOTAL \$ 1,492.20**TOTAL PARTS \$ 21,113.63****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	22d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	20d
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1805-120

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9802M

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ ~ 380.00 X

TOTAL \$ 12,540.00**Over All Total \$ 33,653.63****(LUMP SUM)****Repair Days**~~20 DAYS~~

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1805-120

Your Ref : SLV6735R

Date : 29.September 2018

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHB9802M AND SLV6735R ON 12/05/18 08:20 PM ALONG PASIR RIS CENTRAL TOWARDS PASIR RIS DRIVE 3

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	2,621.50
2.	Loss of Rental for <u>4</u> days @ \$ <u>99.32</u> per day	\$	397.28
3.	Loss of Income for <u>4</u> days @ \$ <u>50.00</u> per day	\$	200.00
4.	LTA Search Fee	\$	7.45
5.	Survey Fee	\$	0.00
	Total	\$	3,226.23

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18009018/Kwa3

24 May 2018

Kang Xian Bin

Blk 139 Simei Street 1

#04-30

Singapore 520139

Dear Sir/Madam,

ACCIDENT INVOLVING SLV 6735R AND SHB 9802M ON 12/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau

Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHB9802M and SLV6735R along PASIR RIS CENTRAL TOWARDS PASIR RIS DRIVE 3 on 12/05/18 08:20 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 29 (day) of September 2018

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, TRANS-CAB AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 2621.50 (Repair Cost), S\$ 597.28 (Loss of rental/use), S\$ 7.45 (Disbursement), for vehicle no. SHB 9802M that was damaged pursuant to the accident which occurred on 12/5/18 (date) along Pasir Ris Car Park (location) involving vehicle no/s SLV 6735 R. This is pursuant to the inspection conducted on 15/5/18 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner TRANS-CAB SERVICES PTE LTD ("the third party claimant") of vehicle no. SHB 9802M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former, for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHB 9802M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9 (day) of 11 (month) 20 18 (year)

XSC


Signed by appointed surveyor



Signed by "the workshop" (with chop)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AIG ASIA PACIFIC INSURANCE PTE LTD 78 Shenton Way #07-16 CHARTIS Building 079120 Singapore ATTENTION:	INVOICE NO. : INV1806-110 DATE : 30. June 2018 REFERENCE NO : AAD1805-120 TERMS : Net 30 Days DUE DATE : 30. July 2018 PAGE : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHB9802M;DOA 12.05.18(LUMP SUM-18)	1	2,621.50	2,621.50

Total SGD Excl. GST :	2,450.00
7% GST :	171.50
Total SGD Incl. GST :	2,621.50

****** TWO THOUSAND SIX HUNDRED TWENTY ONE AND FIFTY SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

29 September, 2018

To Whom It May Concern

Dear Sir / Madam,

Accident on 12/05/18 08:20 PM at PASIR RIS CENTRAL TOWARDS PASIR RIS DRIVE 3

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHB9802M. The taxi was hired to BEH HUNG SIAH a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$99.32 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan

General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

12-05-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1805-120	Accident Date 12-05-2018
12/5/2018 22:00	16/5/2018 16:40	SHB9802M

Yours Faithfully,

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

[> Back to OneMotoring](#)**Vehicle Insurance Particulars Result**

Vehicle No.	Incident Date/Time	Insurance Company Name
SLV6735R	12 May 2018 / 20:20:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018 Edit Reg		15 May 2018 00:00 Edit Adj Rpt	S\$2,450.00 Edit Estimates	S\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: KANG XIAN BIN , ID: S8512674A									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.: SHB9802M		Date of Loss: 12/05/2018 20:00 - :59 [57 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1714247407SG		Policy/Cover Note No.: 1700094161 (Comprehensive)							
Vehicle Reg. No. (Insured): SLV6735R		Policy No. (Claimant): VPX/P1680520							
		Excess:							
Repairer: Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/05/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (21/05/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB9802M (1714247407SG)
[SLV6735R]
TP
TRANS-CAB SERVICES PTE LTD
May 12 2018 8:00PM
[KANG XIAN BIN]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/05/18 01:18	TP GIA REPORT	Load PDF	
2	15/11/18 10:45	WORKSHOP INVOICE	Load PDF	
3	15/11/18 10:45	AUTHORISATION TO ACT FORM	Load PDF	
4	15/11/18 10:45	Release Voucher	Load PDF	
5	15/11/18 10:45	RENTAL RECEIPT	Load PDF	
6	15/11/18 10:45	RENTAL MILEAGE	Load PDF	
7	15/11/18 10:45	LTA SEARCH	Load PDF	
8	15/11/18 10:45	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/05/18 08:51	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
<div style="border: 1px solid #ccc; width: 100%; height: 100%;"></div> <div style="text-align: right; padding-right: 5px;"> ⬆ ⬇ </div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV6735R (Insd veh)	Model:	RENAULT LATITUDE 2.0 L
	SHB9802M (TP veh)		DCI AUTO D/AB 4DR (A)
Date of Accident:	12/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	36,415.96
Final Repair Cost	:	\$	2,621.50
Loss of Use	:	\$	200.00
Rental (if any)	:	\$	397.28
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,226.23

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	:	\$ 3,226.23
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

15 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18009018/KWA3Q2

Date: 15/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700094161
Claimant Vehicle No : SHB9802M **Insured Vehicle No :** SLV6735R
 Date of Loss: 12/05/2018 Nature of Claim: TP Claim No: 1714247407SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB9802M**
 Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C000341
 Reg. Date: 31/07/2013 (Man. Year: 2013) Chassis No: VF1ABL15AUC273335
 Colour: Metallic White/Red Odometer: 476622 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm
 Front Right Side: Giti 8 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,113.61	2,554.34	18,559.27	87.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	480.00	12,440.00	96.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,033.61	3,034.34	30,999.27	91.08
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	34,033.61	2,450.00	31,583.61	92.80
+ GST 7.00/7.00% (S\$)	2,382.35	171.50	2,210.85	92.80
Nett Amount (S\$)	36,415.96	2,621.50	33,794.46	92.80
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$99.32/day) (S\$)		397.28		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,226.23		

INSPECTION

Date of Assignment: 15/05/2018
 Date Inspected: 15/05/2018 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled / Dented	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
35	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
36	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
39	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
40	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
41	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
42	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
43	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
44	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
45	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
46	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
47	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
48	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
49	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
51	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*-FS
52	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*-FS
53	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
54	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
55	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
56	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
57	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
58	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*-FS
59	1		*REAR WINDSCREEN INNER SPONGE SEAL	Serviceable	100.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	23,293.77	2,819.82
- List Item Discount on L Items 10.00/10.00% (S\$)		2,180.16	265.48

Total Parts (S\$)	21,113.61	2,554.34
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,200.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (\$\$)			12,920.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >