

Trans-cab Auto Services Pte Ltd

AAD1805-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5025K*Not Authorized
L1 Seng & ?*

Vehicle No.:

SHC 5025K

Chassis No.:

VF1ABL15AUC275171

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

10.5.2018

Third Party Insurer :

Alh

PART		LIST	
1	FENDER PANEL FRT RH	\$	<i>B1</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>CNT</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>B1</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>B1</i> 261.28 ✓
1	DOOR HINGE LOWER RH	\$	<i>B1</i> 300.55 ✓
1	DOOR CHECK FRT RH	\$	<i>B1</i> 194.77 ✓
1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75 X
1	DOOR CATCH FRT RH	\$	<i>R</i> 131.23 X
1	DOOR HANDLE OUTER FRT RH	\$	<i>SL</i> 477.76 X
1	DOOR HANDLE COVER FRT RH	\$	<i>SL</i> 13.22 X
1	DOOR HANDLE MODULE FRT RH	\$	<i>SL</i> 133.60 X
1	DOOR REGULATOR FRT RH	\$	<i>B1</i> 505.19 ✓
1	DOOR REGUALTOR MOTOR FRT RH	\$	<i>JL</i> 796.46 ✓
1	DOOR REGULATOR GUIDE FRT RH	\$	120.97 ?
1	DOOR PANEL REAR RH	\$	<i>B1</i> 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>SL</i> 203.06 } X
1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR RH	\$	1,135.10 ?
1	DOOR REGUALTOR MOTOR REAR RH	\$	893.75 ?
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>SL</i> 12.43 X

Trans-cab Auto Services Pte Ltd**AAD1805-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5025K

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	<i>na</i> 6.31	
1	DOOR FINISHER REAR RH	\$	<i>sn</i> 423.10	
1	DOOR MOULDING REAR RH	\$	<i>sn</i> 176.82	
1	DOOR MOULDING CLIP L70Y	\$	<i>na</i> 5.92	
1	DOOR MOULDING SCREW L70Y	\$	<i>na</i> 6.91	
1	DOOR CASING REAR RH	\$	<i>sn</i> 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	<i>sn</i> 30.39	
1	DOOR CASING CLIP	\$	<i>na</i> 12.63	
1	DOOR CASING LIGHT L70Y	\$	<i>sn</i> 48.74	
1	DOOR FINISHER INNER REAR RH	\$	<i>sn</i> 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	<i>sn</i> 210.96	
1	DOOR BLIND REAR RH	\$	<i>sn</i> 741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	<i>sn</i> 410.66	
1	DOOR SEAL REAR RH	\$	<i>sn</i> 162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	<i>sn</i> 229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>sn</i> 334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	<i>sn</i> 115.64	
1	FENDER PANEL REAR RH	\$	<i>n</i> 3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	<i>sn</i> 671.45	
1	WHEELARCH REAR RH	\$	<i>sn</i> 543.47	
1	DOOR MIRROR ASSY RH	\$	<i>sn</i> 1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	<i>sn</i> 466.51	
1	ROCKER PANEL INNER RH	\$	<i>n</i> 1,024.79	
1	ROCKER PANEL CENTER RH	\$	<i>n</i> 990.25	
1	VEHICLE HARNESS PASS ROOM	\$	<i>CNA</i> <i>sn</i> 10,003.86	<i>?</i>
1	DOOR HARNESS WIRE	\$	<i>CNA</i> 2,670.00	
1	CENTRE PILLAR OUTER	\$	<i>n</i> 880.14	<i>x</i>
1	CENTER PILLAR INNER	\$	<i>n</i> 907.76	<i>x</i>
1	CENTER PILLAR REINFORCEMENT LH	\$	<i>n</i> 1,176.15	<i>x</i>

\$	43,937.34
10% \$	4,393.73
\$	39,543.61

Trans-cab Auto Services Pte Ltd

AAD1805-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5025K

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	✓
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	6050
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	1550
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	6050
1	DOOR CHECK BOLT	\$	nn	22.69	}
1	DOOR GUIDE SCREW	\$	nn	10.85	
1	DOOR HINGE BOLT	\$	nn	10.85	
1	DOOR HINGE NUT RH	\$	nn	14.60	
1	DOOR CHECK BOLT	\$	nn	22.69	
1	DOOR CHECK NUT	\$	nn	3.75	
1	DOOR LOCK SCREW L70Y	\$	nn	6.12	
1	DOOR CATCH SCREW L70Y	\$	nn	10.06	

TOTAL	\$	462.13
--------------	-----------	---------------

TOTAL PARTS	\$	40,005.74
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	800
Putty and spray painting of the affected portion.	\$	4,200.00	1100
To rust-proofing of the affected areas.	\$	170.00	120
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	120
To check steering geometry and computer wheel alignment	\$	220.00	600

Trans-cab Auto Services Pte Ltd

AAD1805-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5025K

To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 601
Towing Fees.	\$	120.00 59
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X

TOTAL	\$	11,830.00
--------------	-----------	------------------

Over All Total	\$	51,835.74
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS***8 days*

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature: _____