



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM <i>LKK</i> <i>visit</i> <i>684/1972</i>		S1000020 / TPCLAIM	Mdm Iris Lim Ai Keng 665B Jurong West Street 64 #05-178 Singapore 642665 Mobile: 96646646	
		Document No		
		Document Date		
		0		
		11/05/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	22/05/2017	SLN8750A	0	31071 :5DS/SLN8750A/10051:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W30J007030 2ZR1958822 60 Francis Cher T S --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>FWD LWS -</i> T/P VEH. : SKS6338G ACC DATE : 10.05.18 BY :				50 · 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#) (REAR WITH CASING)				dd ✓ 80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT) (2 SETS)				✓ 200.00
4	B	BP-LAB DRILL HOLE TO INSTALL REVERSE SENSOR.				✓ 169.50
5	B	BP-LAB CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				✓ 169.50
6	B	BP-LAB REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				✓ 339.00
7	B	BP-MECH RESET AND REPROGRAMME ECU.				✓ 508.50
8	B	BP-LAB REMOVE BOOT INTERIOR TO ASSIST REPAIR.				✓ 339.00
9	B	BP-LAB REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				✓ 423.75
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less Amount Due
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE **11/05/2018**
TIME **17:39**

3668110

3668110

VEHICLE NO **SLN8750A**

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mdm Iris Lim Ai Keng 665B Jurong West Street 64 #05-178 Singapore 642665 Mobile: 96646646
	Document No	
	Document Date	
	0	
	11/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	22/05/2017	SLN8750A	0	31071 :5DS/SLN8750A/10051:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W30J007030 2ZR1958822 60 Francis Cher T S --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.				✓ 400.00
11	B	BP-LAB REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-ALMP PANEL, TAIL-GATE AND AFFECTED PORTION OF CAR.	678 / day			2712 3390.00
12	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	556 / panel			2224 2780.00
13	1	T52159-68907 REAR BUMPER COVER,	1.00	574.90		de ✓ 574.90
14	2	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		bt ✓ 1428.40
15	3	T68105-68071 REAR BACK DOOR GLASS,	1.00	1009.20		nel ✓ 1009.20
16	4	T04562-12010 W/SCREEN GLS DAM KIT,	1.00	101.00		nel ✓ 101.00
17	5	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		nel ✓ 173.44
18	6	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		nel ✓ 90.08
19	7	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		nel ✓ 72.20
20	8	T75444-68010 LUGGAGE "VALVE MATIC "	1.00	39.70		nel ✓ 39.70
21	9	T75443-ELGAN ELEGANCE EMBLEM	1.00	40.00		nel ✓ 40.00
22	0	SPZ061-12010 25 202 SENSOR	1.00	151.60		? 151.60
23	1	T89997-30070 ELECTRICAL ANTENNA,	1.00	160.60		? 160.60
24	2	T58307-68031 REAR LOWER FLR PANEL,	1.00	520.00		? 520.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3668111

TO SECURITY GUARD

3668111

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 11/05/2018
TIME 17:39VEHICLE NO
SLN8750A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mdm Iris Lim Ai Keng 665B Jurong West Street 64 #05-178 Singapore 642665 Mobile: 96646646
	Document No	
	Document Date	
	0	
	11/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	22/05/2017	SLN8750A	0	31071 :5DS/SLN8750A/10051:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W30J007030	2ZR1958822	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	3	T52155-58030 R/R SIDE BPR SUPPORT,	1.00	78.00		78.00
26	4	T52156-68030 L/RR BUMPER SUPPORT,	1.00	93.90		93.90
27	5	T52575-68020 R/R SIDE BPR RETAINER,	1.00	44.40		44.40
28	6	T52576-68020 L/R SIDE BPR RETAINER,	1.00	44.40		44.40
29	7	T67935-68020 B0 PLATE BACK DOOR	1.00	288.70		288.70
30	8	T64424-68010 RR LUGGAGE SEPARATOR,	1.00	390.70		390.70
31	9	T52181-68010 REAR BUMPER ARM,	2.00	52.10		104.20
32	0	T81561-68062 LENS,RR COMB LH	1.00	344.00		344.00
33	1	T81551-68062 LENS & BODY, RR	1.00	344.00		344.00
Tanferm 97495749 WP 17/5/18 @ 1715 Revery before paint 8 days sur @ khend.com Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	14,992.67
		Labour	6,093.42
		Materials	8,419.25
		Lubrication/Fluid	480.00
		Others	0.00
		0.00	GST 7.00% 1,049.49
			Less 0.00
			Amount Due 16,042.16

PLEASE TEAR ALONG PERFORATED LINE

3668112

TO SECURITY GUARD

3668112

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 11/05/2018
TIME 17:39

VEHICLE NO
SLN8750A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors