

NAL

ASSIGNMENT

Surveyor:

DOI:

15/5/18

Date / Time:

15/5/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 45760

Name of Insured:

Leo Mui Hong

Insured Tel No.:

HP: 81254927

Excess Sec II :SS

D.O.A: 13/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

181818/1805/1020602

Policy No.:

218VPS016397

Make / Model:

KA FORTE

Place of Accident:

DAILY FARM RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SHC 31040



INSRS:

WSP: 066 10903

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

17/5/18

SHC 31040 - CS/LEC 1700 1637/119602; PBA 25/1/18
SLK 45760 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

17/5

Sent By:

Amv

FINALIZATION

Date/Time:

Confirm with:

Confirm by: NAL

Repair Cost:

SS 1,280

(2 days) Reduction:

50 %

Email

Call

FINAL SETTLEMENT

Date/Time: 30.09.19

Confirm with: 18281

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

SS 1,839.50

01 RBE 2010 TP

Loss of Rental (LOR):

SS 259.56

(2 days) x 111.28

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS 100.00

(\$ 50 x 2 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS 7.44

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Notfinal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: + 450

Total:

SS 1,679.55

Global Sum SS:

FINAL PAYMENT

Date/Time: 30.09.19

Confirm with: 18281

Email

Call

Payee 1:

SS 1,679.55

Name 1:

COMPORTEUR INC, 442246, PLE 110

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

COPY SENT 8/2/19

NA2

REP:

LOMPAC

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S		
		X	X

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / FR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 30 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 3104D Reg: FEB 2014
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: HYUNDAI 140 CC: 1685
 Colour: BLUE Insured: Std / NI / NA
 Sp. Reading: 768,597 Recd: Insured: Std / NI / NA

Eng No: _____
 C No: KMHL841UMEU047560

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205 / 60 R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or WESTLAKE

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 13/5/18 D.O.I: 15/5/18

Survey held at: CDGE LOYANG
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction _____ LOMPAC L/S
21/5/18 FINALIZED LUMP SUM \$1,250.00 / 2 DAYS
(REC: \$1,361.58 55%)

Date/Time File Pass to: Preli. Report
 Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee	
Transportation	

Add Fee: Site Insp \$
 Inter. Insp \$
 Tech Insp \$
 Rep. Insp \$

Report Format: _____
 Lump Sum / L.B: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18009025/Nja3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 18-05-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 4576D	Veh. Inspected	SHC 3104D
Policy No.	Z18VP05016397	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020602	Excess (\$)	0.00
Assign From		Assign Date	18/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/05/2018	Inspection Date	15/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

A member of COMFORTDELGRO

Date/Time: 14.05.2018 17:21 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305160200

CUSTOMER NAME COMFORT TRANSPORTATION PTE LTD CUSTOMER NO 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (D) (P) COUNT CARD NO.	REGN NO SHC3104D	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 14.05.2018 13:30
	YR OF MANU 11.02.2014	TARGET DATE
	CHASSIS CODE KMHLE41UMEU047560	COMPLETION DATE/TIME
	COUNT CARD NO.	

JOB DESCRIPTION

Accident Date: 13.05.2018
 NATURE: 3P 13.05.2018

S/N	LABOR CODE	DESCRIPTION
-----	------------	-------------

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC3104D CHIANG

Vehicle No.: SHC3104D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 3104D

DATE 14/5/2018 16:59

Lonpac

MAKE :

Chans

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket			\$ 49.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 280.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 2,611.58
	<p><i>NAZ LKK</i> <i>15/05/18 1500</i> <i>L/S</i> <i>2 DAYS</i></p> <p>LK& Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

dent
R
R
R
R
R
dent

Nett
Nett
Nett
Nett

200
130
20

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305160200

Date : 15/05/18

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHC3104D

13/05/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: LONPAC SLK4576D
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$1,250.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount.

Signature : 

Signature : 

Name : CHIANG

Name : NAZ

Tel : 62148314

Date : 21/5/18

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 15 May 2018 10:53 AM
To: assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)
Cc: MT_Claim_SG
Subject: New Case Our Ref: 18/18/18/VP05/020602
Attachments: 15052018104848.pdf

11:12am @ 15/5/18
vehicle In
sur @ Naz

Dear Catherine

Please refer to the attached and arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 570701

Mainline +65 6383 8280
Facsimile +65 6280 9755

www.edge.com.sg

Company Registration No: 199300049W

Workshops

Braddell
205 Braddell Road
Singapore 570701

Loyang
58 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 675717

Pandan
45 Pandan Road
Singapore 609288

Ubi
320 Ubi Road 3
Singapore 408648

Senoko
24 Senoko Loop
Singapore 768166

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Dotu
6 Dotu Avenue 1
Singapore 659537

Marymount
800 Sin Ming Avenue
Singapore 675733

Our Ref :

305160200

Date :

150518

Via Fax :

62962706

Time of Fax :

Your Insured :

SLK 4576D

Date of Acc :

130518

Lompac

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO

SNC 3104D

- The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- Enclosed, please find :
 - Our initial estimate of repairs of the damaged vehicle.
 - Accident report made by our client.
- I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148316 or Hp no. 96240811

Jumari Masudin Tel no. 62148315 or Hp no. 96355305

Chiang Liat Choon Tel no. 62148314

Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.

7 Thank you.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery



Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 15 May, 2018 10:53 AM
To: assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)
Cc: MT_Claim_SG
Subject: New Case Our Ref: 18/18/18/VP05/020602
Attachments: 15052018104848.pdf

Dear Catherine

Please refer to the attached and arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Nuz

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6353 8280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 192300048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
58 Loyang Drive
Singapore 508989

Sin Ming
383 Sin Ming Drive
Singapore 675717

Pandan
45 Pandan Road
Singapore 609288

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 768166

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Datu
6 Datu Avenue 1
Singapore 630537

Marymount
800 Sin Ming Avenue
Singapore 675733

Our Ref: 305160200

Date: 150518

Time of Fax: _____

Lompac

Attn: Motor Claims Dept.

Via Fax: 6296 2706

Your Insured: SLK 4576D

Date of Acc: 130518


Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SNC 3104D

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle
- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.
- 7 Thank you.

Lim Kwok Eng Tel no. 62148316 or Hp no. 98240811
 Jumari Masudin Tel no. 62148315 or Hp no. 96355305
 Chiang Lat Choon Tel no. 62148314
 Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

Yours faithfully


 for Vice President
 Crash Repairs & Claims Recovery

Mei Kwan (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 11 June, 2018 12:52 PM
To: Mei Kwan (LKKAuto)
Cc: MT_Claim_SG; GERALD POH WEE BIN; ERIC WOO JUN KIAT; Joy Irene (LKKAuto); Hsiao Tong (LKKAuto); Asher Sng (LKKAuto); Admin A
Subject: RE: New Case Our Ref: 18/18/18/VP05/020602
Attachments: SLK4576D 130518.PDF

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

Attached is our Insured's GIA report that you have requested.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 11 June, 2018 10:56 AM
To: ONG LI LI
Cc: MT_Claim_SG; GERALD POH WEE BIN; ERIC WOO JUN KIAT; Joy Irene (LKKAuto); Hsiao Tong (LKKAuto); Asher Sng (LKKAuto); Admin A
Subject: RE: New Case Our Ref: 18/18/18/VP05/020602

EQI ref: 18/18/18/VP05/020602
LKK REF: CC4/LPC18009025/Nja3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SHC 3104D

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your Insured's GIA report for our necessary action.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

To check availability of the case handler, you may contact the undersigned.

Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18009025/Nea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 06-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 4576D	Veh. Inspected	SHC 3104D
Policy No.	Z18VP05016397	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020602	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU047560	Colour	BLUE
Odometer	768397	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/05/2018	Inspection Date	15/05/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3104D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	NOT NECESSARY	360.00	-
1	REAR BUMPER SIDE BRACKET	NOT NECESSARY	49.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
1	REAR BUMPER UNDER COVER	DENTED	225.00	225.00
	LESS 20% DISCOUNT		-381.47	-170.12
			1,525.88	680.48
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	NECESSARY	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			435.70	435.70
LABOUR				
	PANEL BEATING.		280.00	200.00
	SPRAY PAINTING CHARGE.		200.00	200.00
	WIRING CHARGE.		50.00	30.00
	R/REFIX REVERSE SENSOR.		120.00	20.00
			650.00	450.00
GRAND TOTAL			2,611.58	1,566.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CC4/LPC18009025/Nea3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.