

REPAIR ESTIMATE*

DATE 15/5/2018 9:44

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Grille (RH)			\$ 285.50
	Front Bumper Bracket Top (RH)			\$ 22.40
	Front Bumper Bracket (RH)			\$ 24.60
	SUB TOTAL			\$ 1,563.10
	LESS 20%			\$ 312.62
	DISCOUNTED TOTAL			\$ 1,250.48
	Labour Charge			
	Panel Beating			\$ 280.00
	Spray Painting Charge			\$ 200.00
	TOTAL LABOUR			\$ 480.00
	ESTIMATE TOTAL			\$ 1,730.48
	NAZ LKK			
	15/5/18 1245			
	P/P.			
	2 days			
	KK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 			
	Acknowledged by Repairer Signature: _____			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.