

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3442Y

DATE 15/5/2018 9:31

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Side Bracket			\$ 14.30
	Front Fender (LH)			\$ 619.00
	Front Fender Shield (LH)			\$ 169.80
	Front Fender Retainer			\$ 9.20
	Front Door Mirror (LH)			\$ 980.50
	Frt Wheel Hub Cap, LH			\$ 150.70
	SUB TOTAL			\$ 2,528.20
	LESS 20%			\$ 505.64
	DISCOUNTED TOTAL			\$ 2,022.56
	Frt Fender Advertisement Logo (LH)			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 550.00
	Wiring Charge			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,240.00
	ESTIMATE TOTAL			\$ 3,362.56

NA2 LKK
15/5/18 1245
- PIP -
2 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage 7 parts before resurvey
- Parts prices are subject to confirmation
- Third party is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

for:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.