

ASSIGNMENT

Surveyor:

Wp

DOI:

21/05/2018

Date / Time:

18/1/18

Registered in Merimen:

8/1/18

Pre-assign / CCU / FTE

SfC 3523C



Insured Vehicle No.:

Name of Insured:

CTR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

5/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Duck Since 19

Driver Tel No.:

978 33020

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

M100001

M-2002

P16 > Airport

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Gix



INSRS:

WSP:

Tel:

Liability:

RMKS:

Modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

2/1/18

mva

3523C - 04/11/17 14583 / Tumbaga : DOA: 11/1/2018
 - 05/11/17 14583 / Tumbaga : DOA: 11/1/2018
 - 05/11/17 14583 / Tumbaga : DOA: 11/1/2018

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Handler

Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

4/1/18

Seek liability under via merimen

20/1/18

Receive PIR from TP, O2D was charge by T.P.

21/1/18

Seek liability clear via merimen

24/1/18

File pres to typist type report

28/1/18

Seek mandate via merimen

RECEIVED 21 SEP 2018

RECEIVED 20 NOV 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with MS Chin

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

9630.00

Loss of Rental (LOR):

SS

1800.00

(18 days) x 100.00

Loss of Use (LOU):

SS

500.00 (550 x 10 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

3.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

Total:

SS

11932.00

Global Sum SS: 11900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

11900.00

Name 1:

Modern Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

26/1/18

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SG58776J Yr Regn: 2007, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis cc 1578Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 177695 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M2053ZEC107141789Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/05/18Survey held at: ModernDes. of Damages: Frt / Rear KO/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP III
<u>24/9/18</u>	Conform US \$ 9000.00 with 14 working day
	COE Expiry: 26/03/22
	MV: 21SK
	PV: 19K
	Nett: 8SK

(Ref: #1711-78
66.f)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$ _____)

S + RS \$ _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III18009034/Awa3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 18-05-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3523C	Veh. Inspected	SGS 8776J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/05/2018	Inspection Date	21/05/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4858F
Vehicle Details	
Vehicle No.:	SGS8776J
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4632534
Chassis No.:	MR053ZEC107141779
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	27 Mar 2007
First Registration Date:	27 Mar 2007
Transfer Count:	1
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$19,014.00
Total Rebate Amount:	\$19,014.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	


The information contained herein is correct as at 21 May 2018

OK





DRIVE-AWAY LEASING PROGRAMME
LEARN MORE
WIDE VARIETY OF VEHICLES

6303 6303

SEARCH

Price Range:
Depreciation:

Vehicle Type:

Used Car Comparison

Comparing 3 Vehicles

Toyota Corolla Altis 1.6A (COE till 02/2022)



Toyota Corolla Altis 1.6A (COE till 02/2022)



Toyota Corolla Altis 1.6A (COE till 04/2022)



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

CAR DETAILS

Price	\$26,838	\$26,300	\$28,800	-
Instalment	N.A.	N.A.	N.A.	-
Registration Date	12-Feb-2007	01-Mar-2007	26-Apr-2007	-
Manufactured	2006	2006	2007	-
Mileage	-	-	143,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,598 cc	1,598 cc	1,598 cc	-
Road Tax	\$816 /yr	\$816 /yr	\$816 /yr	-
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	-
Curb Weight	1,115 kg	1,115 kg	1,115 kg	-
Features	Powerful 1.6L 16 Valves VVTi DOHC Engine, 106bhp, Smooth 4 Speed Auto Transmission, Airbags, ABS, Climatic Aircon Controls, Retractable Side Mirrors.	16L VVTi Engine, Airbags, ABS, Climate Control Aircon, Multi Function Steering, \$2500 Drive Away.	Fuel Efficient And Powerful 1.6L 16 Valve DOHC Vvti Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon.	-
Accessories	Sports Rims, Leather Seats, Original Factory Fitted Audio Player, Reverse Sensors, Knockdown Rear Seats, Solar Film.	Leather Seats, Sports Rims, Audio System.	Electric Adjustable Driver Seat LED White Headlight, Pioneer 7" Screen HD Radio With Reverse Camera Front And Rear HD Camera Recorder Leather Boot Mat.	-
Description	2.98% Interest Rates. Loan Up To 54 Months! Well Taken Care By Previous Owner. Original Paint With Beige Interior. 2 Years Free Servicing. Non Smoker Unit. Well Maintained Engine And Transmission In Good Condition. 6 Months Warranty Provided! No Repair Needed! We Deliver Our Promise! High Trade In Most Welcome! 100% In House Loan Available! View To Believe! Don't Miss, Call Now!	Elegant Silver, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available, Very Well Kept, Perfect Condition - \$2500 Drive Away.	Best COE Renewed Condition. View Yourself To See. Well Maintained. Smooth Engine. Just Replaced Front And Rear Brake Pad And Battery On Dec 2017. Car Serviced On Dec 2017. Original Dash Board Radio And Headlights. Insurance Available. Trade In Welcome. Consignment Unit. Call To Make An Appointment.	-
COE	\$25,197	\$25,197	\$25,115	-
OMV	\$15,355	\$15,355	\$15,245	-
ARF	\$16,891	\$16,891	\$16,770	-
Depreciation	\$7,190 /yr	\$6,960 /yr	\$7,330 /yr	-
No. of Owners	5	3	3	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	COE Car	COE Car	COE Car, Consignment Car	-
Availability	Available	Available	Available	-

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

84, Cecil Street # 04 - 05

IOB Building

Singapore 049711

Tel : 6347 - 6100

Fax : 6224 - 4174

Quotation

DATE : 17.05.2018

VEH NO : SGS8776J

MODEL : Toyota Altis

D O A : 05.05.2018

YR REF : SHG3523C

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGS8776J (Toyota Altis)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper <i>Distorted</i>	1	406.70 ✓
2	Front Bumper Clips <i>one</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>one</i>	2	47.80 ✓
4	Front Bumper Reinforcement <i>Best</i>	1	379.10 ✓
5	Front Bumper Fog Lamp - LH & RH <i>one could</i>	2	363.40 181.70
6	Front Bumper Undercover - LH & RH <i>RH torn</i>	2	378.00 189.50
7	Front Bumper Undercover Clips <i>Nil</i>	2 sets	60.00 30
8	Front Grille <i>missing</i>	1	279.10 ✓
9	Front Grille Logo <i>missing</i>	1	45.10 ✓
10	Front Grille Clips <i>one</i>	1 set	10.00 ✓
11	Headlamp - LH & RH <i>cracked</i>	2	716.40 ✓
12	Front Brace Panel <i>one</i>	1	100.90 ✓
13	Front Support Panel <i>Buckled</i>	1	2,108.00 ✓
14	Bonnet <i>Distorted</i>	1	1,429.00 ✓
15	Bonnet Lock <i>one</i>	1	66.30 ✓
16	Bonnet Hinge - LH & RH <i>one</i>	2	102.20 ✓
17	Air Con Condenser <i>Distorted</i>	1	1,319.30 ✓
18	Radiator	1	1,208.20 ✓
19	Radiator Fan Cowling	1	217.60 ✓
20	Radiator Fan Blade	1	48.70 ✓
21	Radiator Fan Motor	1	266.30 ✓
22	Alternator	1	1,027.00 ✓
23	Alternator Belt	1	68.00 ✓
24	ABS Pump <i>cracked</i>	1	2,674.00 ✓
25	Front Fender - LH & RH <i>LH Buckled, RH Distorted</i>	2	603.40 ✓
26	Front Fender Inner Shield - LH & RH <i>RH torn</i>	2	131.80 65.90
27	Front Fender Inner Shield Clips <i>one</i>	2 sets	60.00 30
28	Front Fender Signal Lamp - RH <i>cracked</i>	1	43.70 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SGS6776J (Toyota Altis)

29	Vertical Cross Member <i>Bent</i>	1	328.40 ✓
30	Front Door - RH <i>Distorted</i>	1	1,028.00 ✓
31	Front Door Lock - RH <i>Paint</i>	1	429.70 ✓
32	Front Door Weatherstripe - RH <i>cut</i>	1	187.50 ✓
33	Front Door Protector - RH <i>Distorted</i>	1	132.10 ✓
34	Front Door Hinges - RH <i>gate new</i>	2	77.20 ✗
35	Front Door Check - RH	1	87.30 ✗
36	Front Door Glass Outer Moulding - RH <i>Dented</i>	1	172.40 ✓
37	Front Door Glass Regulator Gear - RH <i>Damaged</i>	1	386.50 ✓
38	Front Door Inner Trim Board - RH <i>gate new</i>	1	544.60 ✗
39	Front Door Inner Trim Board Clips - RH	1 set	30.00 ✗
40	Front Door Wing Mirror - RH <i>cracked</i>	1	340.60 ✓
41	Front Door Outer Handle - RH <i>cut</i>	1	123.20 ✓
42	Rear Door - RH <i>Distorted</i>	1	1,016.70 ✓
43	Rear Door Lock - RH <i>Damaged</i>	1	429.70 ✓
44	Rear Door Weatherstripe - RH <i>cut</i>	1	171.20 ✓
45	Rear Door Protector - RH <i>Distorted</i>	1	118.20 ✓
46	Rear Door Hinges - RH <i>gate new</i>	2	77.20 ✗
47	Rear Door Check - RH	1	87.30 ✗
48	Rear Door Glass Outer Moulding - RH <i>missing</i>	1	174.20 ✓
49	Rear Door Glass Regulator Gear - RH <i>Damaged</i>	1	386.50 ✓
50	Rear Door Inner Trim Board - RH <i>gate new</i>	1	444.60 ✗
51	Rear Door Inner Trim Board Clips - RH	1 set	30.00 ✗
52	Rear Fender - RH <i>Distorted</i>	1	757.70 ✓
53	Rear Bumper <i>torn</i>	1	418.30 ✓
54	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
55	Rear Bumper Side Holder - RH <i>New</i>	1	24.50 ✓
56	Rear Windscreen Moulding <i>New</i>	1	75.20 ✓
57	Front Lower Arm - RH <i>?</i>	1	289.90 ✗
58	Front Shock Absorber - RH <i>gate new</i>	1	282.80 ✗
59	Front Knuckle Arm - RH	1	334.20 ✗
60	Front Wheel Hub c/w Bearing - RH <i>new</i>	1	287.70 ✗
61	Engine Mounting - RH <i>torn</i>	1	201.30 ✓

17790
13342.50
Less 25%

	23,695.70
	(5,923.93)
\$	17,771.78

S/NET ITEMS

1	Front Number Plate <i>gate new</i>	1	30.00 ✗
2	Front Number Plate Holder	1	30.00 ✗
3	Front Door Black Tape - RH <i>cut</i>	1	50.00 ✓
4	Front Door Visor - RH <i>new</i>	1	60.00 ✓
5	Rear Door Black Tape - RH <i>cut</i>	1	50.00 ✓
6	Rear Door Visor - RH <i>new</i>	1	60.00 ✓
7	Rear Windscreen Sealant <i>new</i>	1	60.00 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SGS8776J (Toyota Altis)

8	Rear Wheel Rim - RH <i>see NW</i>	1	580.00 X
9	Front Wheel Rim - RH <i>at</i>	1	580.00 400
Total Parts			\$ 19,271.78

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 2,400.00 1800
2	To putty & spray up paint works	\$ 2,200.00 1800
3	To check wing	\$ 150.00 30
4	To underseal	\$ 200.00 120
5	To remove condenser, radiator & to re-gas	\$ 180.00 120
6	To remove engine and gearbox	\$ 450.00 380
7	To remove front undercarriage - RH	\$ 380.00 X
8	To perform wheel alignment	\$ 150.00 80
9	To straighten chassis members	\$ 300.00 280
10	To transfer front & rear door fittings	\$ 300.00 160
11	To remove rear windscreen	\$ 180.00 120
12	To remove fuel tank	\$ 150.00 80
Total Labour		\$ 7,040.00
Grand Total		\$ 26,311.78

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 18992.50
L/S. 9K (Nett Value)
14 Days.

View Received Message

This mail is associated with :

***SGS8776J (MCT18050106)
[SHC3523C]**

TP

SYED ABDUL KADER BIN SYED ALI@SYED ABDUL KADER ALH
May 5 2018 11:00PM

Modern Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **04/06/2018 11:01 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SGS8776J - Claim Handler: Sundari Nagarajan

Approved:0.00:As on date we have not received the Video. We will forward it to you once we receive it.

DOCUMENTS SUMMARY

There are no documents.



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/26759/2018
Date : 28 May, 2018

SYED HUSSEIN BIN SYED ALWI MADIHI
APT BLK 629 BEDOK RESERVOIR ROAD
#06-1638
SINGAPORE 470629

Dear Sir/Madam

**ACCIDENT INVOLVING SGS8776J/SHC3523C ON 05.05.2018 AT 2355 HRS, ALONG PIE (AP)
7.5 KM**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SHC3523C has committed an offence of Inconsiderate driving (accident) under Section 65(b) Of The Road Traffic Act Chapter 276. Action has been initiated against the driver for the said offence.

3. If you have any queries, please contact the Investigation Officer, Shahrul Nizam at telephone number 6547 6904.

Yours faithfully

SHAHUL HAMEED
FOR HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

View Received Message

This mail is associated with :

***SGS8776J (MCT18050106)
[SHC3523C]**

TP

SYED ABDUL KADER BIN SYED ALI@SYED ABDUL KADER ALH
May 5 2018 11:00PM

Modern Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **21/09/2018 11:46 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SGS8776J - Claim Handler: Sundari Nagarajan

Approved:0.00:Agreed to do direct settlement. Please revert with your quantum advice

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SGS8776J (MCT18050106)**
[SHC3523C]

TP

SYED ABDUL KADER BIN SYED ALI@SYED ABDUL KADER ALH
May 5 2018 11:00PM

[-]

Modern Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 20/11/2018 11:08 AM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11932.00) - SGS8776J - Claim Handler: Sundari Nagarajan

Approved:11932.00:

DOCUMENTS SUMMARY

There are no documents.

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 58/ 61
SINGAPORE 408717
GST REG. NO : 200501102H
TEL : 6748 4422 / 6745 4422 FAX : 6747 6720
Email: chin@modernautomotive.com.sg

YOUR REF : SHC3523C
OUR REF : SGS8776J

Date : 22.06.2018

The Claims Manager
India International Insurance Pte Ltd
64 Cecil Street #04-05
IOB Building
Singapore 049711
Tel : 6347 6100
Fax : 6224 4174

RE : ACCIDENT INVOLVING SGS8776J & SHC3523C ON 05.05.2018
ALONG PIE TOWARDS CHANGI AIRPORT

We refer to the above matter.

We have been authorized by our client Mr Syed Abdul Kader Bin Syed Ali to make claim against your insured vehicle No. SHC3523C in respect of the above accident for the following :

Repair Cost	\$	9,630.00	(Incl GST)
LOU for PRI (\$100 x 10 days)	\$	1,000.00	(06.05.2018 - 15.05.2018)
LOR for PRI (\$120 x 5 days)	\$	600.00	(16.05.2018 - 20.05.2018)
Loss of Rental (\$120 x 16 days)	\$	1,920.00	(21.05.2018 - 06.06.2018)
Search Fee	\$	7.49	

Total : \$ 13,157.49

Remark: Vehicle is at traffic police compound from 06.05.2018 to 15.05.2018

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap.

Yours faithfully



Modern Automotive Pte Ltd

LETTER OF AUTHORIZATION

Date: 16/5/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SGS 8776 J & SHC 3523 C

ON 5/5/18 ALONG PIE towards Changi

Airport

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

SYED ABUL KADER BIN SYED ALI

Name / NRIC 50094858F



INDIA
INTERNATIONAL
INSURANCE
PTE LTD
SINGAPORE
Incorporated in Singapore

INDIA INTERNATIONAL INSURANCE PTE LTD
11, Regent Street, #01-01, Regent Singapore, Singapore 170031
4111, Hill Street, #01-01, Hill Street, Singapore 170031
Office: (65) 63376100 Email: info@indiaintl.com
Tel: (65) 63376173 Website: www.indiaintl.com

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18050106
Claimant Ref: SGS 8776J

We/I, Modern Automotive Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 11,900.00 (GLOBAL SUM) (repair cost), S\$ 0.00 (loss of use/rental), S\$ 0.00 (search fee), vehicle no. SGS 8776J that was damaged pursuant to the accident which occurred on 05/05/2018 (date) at PIE TWDS AIRPORT (location) involving vehicle no. SHC 3523C (insured vehicle). This is pursuant to the inspection conducted on 21/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SYED ABDUL KADER BIN SYED ALI@SYED ABDUL KADER ALH ("the third party claimant") of vehicle no. SGS 8776J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGS 8776J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 11,900.00 to Modern Automotive Pte Ltd

Dated this 21 day of NOV 20 18

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC: MODERN AUTOMOTIVE PTE LTD

Address: BLK 3023A UBI ROAD 1
#01-61, SINGAPORE 408717
TEL: 6747 4422 FAX: 6747 6720

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

Nationality:

Occupation:



MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04-05 IOB Building
Singapore 049711

Attention : Motor Claim Department
Contact : 6347 - 6100 Fax No. : 6224 - 4174

Tax Invoice : TP001222

Date : 22/06/2018
Vehicle Num. : SGS 8776J
Make/Model : TOYOTA ALTIS-2007
Chassis/Eng# : MR053ZEC107141779/3ZZ4632534
Accident Date : 05/05/2018
Claim No. :
Reference :
Policy No. : 5089259320-01

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		9,000.00
		Labour Total S\$:		9,000.00

Total S\$:	9,000.00
GST @ 7% S\$:	630.00
Amount Due S\$:	9,630.00


MODERN AUTOMOTIVE PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1

SINGAPORE 798125

TEL: 6383 2661 FAX: 6484 2836

REG. NO: 430058/000

No. 19376

6/6/18

OFFICIAL RECEIPT

Received from

Syed Abd. Kader B. Syed AU

the sum of Dollars

Two thousand five hundred twenty only

being Payment Of

S\$ 1651.00 (16/5/18 - 6/6/18)

DAWN ENTERPRISES

\$

2520/2

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Nº 35527

RENTAL AGREEMENT

DATE

16/5/18

HIRER'S PARTICULARS

Name Syed Abd. Kader B. Syed Ali

Address _____

IC or Passport No. 00948588 Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (HP) 91178741 (Residence) _____

DRIVER'S PARTICULARS

Name Syed Hussam B. Syed Ali MAJIDI

Address _____

IC or Passport No. 8004886 Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (Office) 91178741 (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving license
2. This vehicle is licensed to carry 2000 passengers only
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only
10. No Service on Public Holiday and Sunday

CHARGES

21 Day at \$ <u>120.00</u> per days	\$ <u>2520.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	

TOTAL AMOUNT

\$ 2520.00

AMOUNT PAID

\$ 2520.00

BALANCE DUE

Days Extension From _____ To _____

Amount Deposit (refundable) \$ _____

SCHEDULE

SLD 16510

MODEL

ALU'm

Date

Time

Mileage

16/5/18

6.00pm

6/6/18

FROM

16/5/18

TO

6/6/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES



Thank you

Minder Kaur has successfully logged out.

Your last login date and time was 16 May 2018, 14:46:37.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

SGS8776J

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SHC3523C	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	16 May 2018 / 14:49:52

Enquire Vehicle & Owner Information (Vehicle No. SHC3523C As At 05 May 2018 / 23:55:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MODERN AUTOMOTIVE

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 3B3
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHC3523C
Make Description/Model: MERCEDES BENZ / E 220 CDI BLUEEFFICIENCY
Insurance Company Name: INDIA INT'L INS PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018 Edit Reg		21 May 2018 00:00 Edit Adj Rpt	\$59,000.00 Edit Estimates	\$59,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	SYED ABDUL KADER BIN SYED ALI@SYED ABDUL KADER ALH. ID: S0094858F								
Vehicle Reg. No.:	SGS8776J	Date of Loss:	05/05/2018 23:00 - :59 [133 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050106	Policy/Cover Note No.:	MCDM0015						
Vehicle Reg. No. (Insured):	SHC3523C	Policy No. (Claimant):	5089259320-01						
		Excess:							
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (20/11/2018): Alert - Adj Mandate Approved (\$11932.00) - SGS8776J - Claim Handler: Sundari Na... - III_SG (02/11/2018): Alert - Adj Mandate Approved (\$11432.00) - SGS8776J - Claim Handler: Sundari Na... - III_SG (21/09/2018): Alert - Adj Mandate Approved (\$0.00) - SGS8776J - Claim Handler: Sundari Nagara... - III_SG (08/08/2018): Alert - Adj Mandate Approved (\$0.00) - SGS8776J - Claim Handler: Sundari Nagara... - III_SG (02/08/2018): Alert - Adj Mandate Approved (\$0.00) - SGS8776J - Claim Handler: Sundari Nagara... - III_SG (04/06/2018): Alert - Adj Mandate Approved (\$0.00) - SGS8776J - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGS8776J (MCT18050106)

[SHC3523C]

TP

SYED ABDUL KADER BIN SYED ALI@SYED ABDUL KADER ALH

May 5 2018 11:00PM

[COMFORT TRANSPORTATION PTE LTD]

Modern Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 18:05	General View	 Load JPG	☒
2	11/06/18 18:05	General View	 Load JPG	☒
3	11/06/18 18:05	General View	 Load JPG	☒
4	11/06/18 18:05	General View	 Load JPG	☒
5	11/06/18 18:05	General View	 Load JPG	☒
6	11/06/18 18:05	General View	 Load JPG	☒
7	11/06/18 18:05	General View	 Load JPG	☒
8	11/06/18 18:05	General View	 Load JPG	☒
9	11/06/18 18:05	General View	 Load JPG	☒
10	11/06/18 18:05	General View	 Load JPG	☒
11	11/06/18 18:05	General View	 Load JPG	☒
12	11/06/18 18:05	General View	 Load JPG	☒
13	11/06/18 18:05	General View	 Load JPG	☒
14	11/06/18 18:05	General View	 Load JPG	☒
15	11/06/18 18:05	General View	 Load JPG	☒
16	11/06/18 18:05	General View	 Load JPG	☒
17	11/06/18 18:05	General View	 Load JPG	☒
18	11/06/18 18:05	General View	 Load JPG	☒
19	11/06/18 18:05	General View	 Load JPG	☒
20	11/06/18 18:05	General View	 Load JPG	☒
21	11/06/18 18:05	General View	 Load JPG	☒
22	11/06/18 18:05	General View	 Load JPG	☒
23	11/06/18 18:05	General View	 Load JPG	☒
24	11/06/18 18:05	General View	 Load JPG	☒
25	11/06/18 18:05	General View	 Load JPG	☒
26	11/06/18 18:05	General View	 Load JPG	☒
27	11/06/18 18:05	General View	 Load JPG	☒
28	11/06/18 18:05	General View	 Load JPG	☒
29	11/06/18 18:05	General View	 Load JPG	☒
30	11/06/18 18:05	General View	 Load JPG	☒
31	11/06/18 18:05	General View	 Load JPG	☒
32	11/06/18 18:05	General View	 Load JPG	☒
33	11/06/18 18:05	General View	 Load JPG	☒
34	11/06/18 18:05	General View	 Load JPG	☒
35	11/06/18 18:05	General View	 Load JPG	☒
36	11/06/18 18:05	General View	 Load JPG	☒
37	11/06/18 18:05	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/06/18 18:05	General View	 Load JPG	☒
39	11/06/18 18:05	General View	 Load JPG	☒
40	11/06/18 18:05	General View	 Load JPG	☒
41	11/06/18 18:05	General View	 Load JPG	☒
42	11/06/18 18:05	General View	 Load JPG	☒
43	11/06/18 18:05	General View	 Load JPG	☒
44	11/06/18 18:05	General View	 Load JPG	☒
45	11/06/18 18:05	General View	 Load JPG	☒
46	11/06/18 18:05	General View	 Load JPG	☒
47	11/06/18 18:05	General View	 Load JPG	☒
48	11/06/18 18:05	General View	 Load JPG	☒
49	11/06/18 18:05	General View	 Load JPG	☒
50	11/06/18 18:05	General View	 Load JPG	☒
51	11/06/18 18:05	General View	 Load JPG	☒
52	11/06/18 18:05	General View	 Load JPG	☒
53	11/06/18 18:05	General View	 Load JPG	☒
54	11/06/18 18:05	General View	 Load JPG	☒
55	11/06/18 18:05	General View	 Load JPG	☒
56	11/06/18 18:05	General View	 Load JPG	☒
57	11/06/18 18:05	General View	 Load JPG	☒
58	11/06/18 18:05	General View	 Load JPG	☒
59	11/06/18 18:05	General View	 Load JPG	☒
60	11/06/18 18:05	General View	 Load JPG	☒
61	11/06/18 18:05	General View	 Load JPG	☒
62	11/06/18 18:05	General View	 Load JPG	☒
63	11/06/18 18:05	General View	 Load JPG	☒
64	11/06/18 18:05	General View	 Load JPG	☒
65	11/06/18 18:05	General View	 Load JPG	☒
66	11/06/18 18:05	General View	 Load JPG	☒
67	11/06/18 18:05	General View	 Load JPG	☒
68	11/06/18 18:05	General View	 Load JPG	☒
69	11/06/18 18:05	General View	 Load JPG	☒
70	11/06/18 18:05	General View	 Load JPG	☒
71	11/06/18 18:05	General View	 Load JPG	☒
72	11/06/18 18:05	General View	 Load JPG	☒
73	11/06/18 18:05	General View	 Load JPG	☒
74	11/06/18 18:05	General View	 Load JPG	☒
75	11/06/18 18:05	General View	 Load JPG	☒
76	11/06/18 18:05	General View	 Load JPG	☒
77	11/06/18 18:05	General View	 Load JPG	☒
78	11/06/18 18:05	General View	 Load JPG	☒
79	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
80	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
81	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
82	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
83	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
84	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
85	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
86	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
87	11/06/18 18:05	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
89	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
90	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
91	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
92	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
93	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
94	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
95	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
96	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
97	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
98	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
99	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
100	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
101	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
102	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
103	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
104	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
105	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
106	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
107	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
108	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
109	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
110	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
111	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
112	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
113	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
114	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
115	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
116	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
117	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
118	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
119	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
120	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
121	11/06/18 18:05	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 11:30	TP GIA REPORT	 Load PDF	
2	20/09/18 14:51	SGS8776J (Police Investigation Result	 Load PDF	
3	30/10/18 10:24	WORKSHOP INVOICE	 Load PDF	
4	30/10/18 10:24	RENTAL RECEIPT	 Load PDF	
5	30/10/18 10:24	LTA SEARCH	 Load PDF	
6	30/10/18 10:24	LOD	 Load PDF	
7	19/11/18 15:30	recepit of vehicle on TP compound	 Load PDF	
8	28/11/18 12:36	AUTHORISATION TO ACT FORM	 Load PDF	
9	28/11/18 12:36	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 09:42	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18009034/AWA3Q2

Date: 28/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MC0M0015
 Claimant Vehicle No: SGS8776J Insured Vehicle No: SHC3523C
 Date of Loss: 05/05/2018 Nature of Claim: TP Claim No: MCT18050106

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS8776J
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4632534
 Reg. Date: 27/03/2007 (Man. Year: 2006) Chassis No: MR053ZEC107141779
 Colour: Grey Odometer: 177695 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,271.77	14,022.50	5,249.27	27.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,040.00	4,970.00	2,070.00	29.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,311.77	18,992.50	7,319.27	27.82
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	26,311.77	9,000.00	17,311.77	65.79
+ GST 7.00/7.00% (S\$)	1,841.82	630.00	1,211.82	65.79
Nett Amount (S\$)	28,153.59	9,630.00	18,523.59	65.79
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Car Rental (18.0 x S\$100.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,932.00		
Global Sum Settlement (S\$)		11,900.00		

INSPECTION

Date of Assignment: 21/05/2018

Date Inspected: 21/05/2018 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGS8776J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	406.70 FL	*406.70 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*FRONT BUMPER SIDE HOLDER -LH & RH	Necessary	47.80 FL	*47.80 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	379.10 FL	*379.10 FL
5	1		*FRONT BUMPER FOG LAMP -LH & RH	O/S Cracked	363.40 FL	*181.70 FL
6	1		*FRONT BUMPER UNDERCOVER -LH & RH	O/S Torn	379.00 FL	*189.50 FL
7	2		*SETS FRONT BUMPER UNDERCOVER CLIPS	Necessary	60.00 FL	*30.00 FL
8	1		*FRONT GRILLE	Missing	279.10 FL	*279.10 FL
9	1		*FRONT GRILLE LOGO	Missing	45.10 FL	*45.10 FL
10	1		*SET FRONT GRILLE CLIPS	Necessary	10.00 FL	*10.00 FL
11	2		*HEADLAMP -LH & RH	Cracked	716.40 FL	*716.40 FL
12	1		*FRONT BRACE PANEL	Bent	100.90 FL	*100.90 FL
13	1		*FRONT SUPPORT PANEL	Buckled	2,108.00 FL	*2,108.00 FL
14	1		*BONNET	Distorted	1,429.00 FL	*1,429.00 FL
15	1		*BONNET LOCK	Damaged	66.30 FL	*66.30 FL
16	2		*BONNET HINGE -LH & RH	Bent	102.20 FL	*102.20 FL
17	1		*AIR CON CONDENSER	Dented	1,319.30 FL	*1,319.30 FL
18	1		*RADIATOR	Not Necessary	1,208.20 FL	*- FL
19	1		*RADIATOR FAN COWLING	Not Necessary	217.60 FL	*- FL
20	1		*RADIATOR FAN BLADE	Not Necessary	48.70 FL	*- FL
21	1		*RADIATOR FAN MOTOR	Not Necessary	266.30 FL	*- FL
22	1		*ALTERNATOR	Not Necessary	1,027.00 FL	*- FL
23	1		*ALTERNATOR BELT	Not Necessary	68.00 FL	*- FL
24	1		*ABS PUMP	Cracked	2,674.00 FL	*2,674.00 FL
25	2		*FRONT FENDER -LH & RH	N/S Buckled / O/S Distorted	603.40 FL	*603.40 FL
26	1		*FRONT FENDER INNER SHIELD -LH & RH	O/S Torn	131.80 FL	*65.90 FL
27	2		*SETS FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*30.00 FL
28	1		*FRONT FENDER SIGNAL LAMP -RH	Cracked	43.70 FL	*43.70 FL
29	1		*VERTICAL CROSS MEMBER	Bent	328.40 FL	*328.40 FL
30	1		*FRONT DOOR -RH	Distorted	1,028.00 FL	*1,028.00 FL
31	1		*FRONT DOOR LOCK -RH	Damaged	429.70 FL	*429.70 FL
32	1		*FRONT DOOR WEATHERSTRIPE -RH	Cut	187.50 FL	*187.50 FL
33	1		*FRONT DOOR PROTECTOR -RH	Deformed	132.10 FL	*132.10 FL
34	2		*FRONT DOOR HINGE -RH	Not Necessary	77.20 FL	*- FL
35	1		*FRONT DOOR CHECK -RH	Not Necessary	87.30 FL	*- FL
36	1		*FRONT DOOR GLASS OUTER MOULDING -RH	Dented	172.40 FL	*172.40 FL
37	1		*FRONT DOOR GLASS REGULATOR GEAR -RH	Damaged	386.50 FL	*386.50 FL
38	1		*FRONT DOOR INNER TRIM BOARD -RH	Not Necessary	544.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS-RH	Not Necessary	30.00 FL	*- FL
40	1		*FRONT DOOR WING MIRROR -RH	Cracked	340.60 FL	*340.60 FL
41	1		*FRONT DOOR OUTER HANDLE -RH	Cut	123.20 FL	*123.20 FL
42	1		*REAR DOOR -RH	Distorted	1,016.70 FL	*1,016.70 FL
43	1		*REAR DOOR LOCK -RH	Damaged	429.70 FL	*429.70 FL
44	1		*REAR DOOR WEATHERSTRIPE-RH	Cut	171.20 FL	*171.20 FL
45	1		*REAR DOOR PROTECTOR -RH	Deformed	118.20 FL	*118.20 FL
46	2		*REAR DOOR HINGE -RH	Not Necessary	77.20 FL	*- FL
47	1		*REAR DOOR CHECK-RH	Not Necessary	87.30 FL	*- FL
48	1		*REAR DOOR GLASS OUTER MOULDING -RH	Missing	174.20 FL	*174.20 FL
49	1		*REAR DOOR GLASS REGULATOR GEAR -RH	Damaged	386.50 FL	*386.50 FL
50	1		*REAR DOOR INNER TRIM BOARD -RH	Not Necessary	444.60 FL	*- FL
51	1		*SET REAR DOOR INNER TRIM BOARD CLIPS-RH	Not Necessary	30.00 FL	*- FL
52	1		*REAR FENDER -RH	Distorted	757.70 FL	*757.70 FL
53	1		*REAR BUMPER	Torn	418.30 FL	*418.30 FL
54	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
55	1		*REAR BUMPER SIDE HOLDER-RH	Necessary	24.50 FL	*24.50 FL
56	1		*REAR WINDSCREEN MOULDING	Necessary	75.20 FL	*75.20 FL
57	1		*FRONT LOWER ARM -RH	Not Necessary	289.90 FL	*- FL
58	1		*FRONT SHOCK ABSORBER -RH	Not Necessary	282.80 FL	*- FL
59	1		*FRONT KNUCKLE ARM -RH	Not Necessary	334.20 FL	*- FL
60	1		*FRONT WHEEL HUB C/W BEARING -RH	Not Necessary	287.70 FL	*- FL
61	1		*ENGINE MOUNTING -RH	Torn	201.30 FL	*201.30 FL
62	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
63	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
64	1		*FRONT DOOR BLACK TAPE-RH	Cut	50.00 FS	*50.00 FS
65	1		*FRONT DOOR VISOR -RH	Necessary	60.00 FS	*60.00 FS
66	1		*REAR DOOR BLACK TAPE-RH	Cut	50.00 FS	*50.00 FS
67	1		*REAR DOOR VISOR -RH	Necessary	60.00 FS	*60.00 FS
68	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
69	1		*REAR WHEEL RIM -RH	Not Necessary	580.00 FS	*- FS
70	1		*FRONT WHEEL RIM -RH	Cut	580.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 25,195.70 18,470.00
 - List Item Discount on L Items 25.00/25.00% (\$\$) 5,923.93 4,447.50

Total Parts (\$\$) 19,271.77 14,022.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	2,400.00	1,800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	2,200.00	1,800.00
3	TO CHECK WIRING	New	150.00	30.00
4	TO UNDERSEAL	New	200.00	120.00
5	TO REMOVE CONDENSER ,RADIATOR & TO RE-GAS	New	180.00	120.00
6	TO REMOVE ENGINE AND GEARBOX	New	450.00	380.00
7	TO REMOVE FRONT UNDERCARRIAGE -RH	New	380.00	0.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
9	TO STRAIGHTEN CHASSIS MEMBERS	New	300.00	280.00
10	TO TRANSFER FRONT & REAR DOOR FITTINGS	New	300.00	160.00
11	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
12	TO REMOVE FUEL TANK	New	150.00	80.00
Gross Labour Cost (S\$)			7,040.00	4,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >