

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

data

14/5/18



PT8871Z

Brake lever	@ 85	/	Cat.
mirror	@ 70	/	cat.
Inner Fork tube L&R	@ 660	/	BT (photo)
Fork oil seal L&R	@ 98	/	After repair.
Fork oil X2	@ 56	/	
steering stem	@ 390	/	
steering cone	@ 120	/	
Exhaust header	@ 1350	/	BT (photo After repair)
Exhaust header gasket x4	@ 40	/	
muffler	@ 1150	/	Cat (photo After repair)
frame slider	@ 160	/	
Brake pedal	@ 90	/	
front footrest "R"	@ 95	/	
Rear pillion footrest "R"	@ 75	/	
footrest bracket "R"	@ 195	/	
Clutch lever	/	\$48	/
Tow	@ 45	40	
labour	@ 450	250.	
	@ 5129		

3 Days.

Gino Riap - 82880282

4503.8

After repair photos.

17/5/18.