

ASS. REC. BY:

REF: CS/FWD 18009055/GrbSV

Special Instruction:

Surveyor  
Meimien

GA

ASSIGNMENT (Office)

From (Person): Josey Loh of FWD Date/Time: 18052018 11:53am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDW 30376 Insured:

at Workshop m/s Ah Lim Motor Tel: 6483 1244

of BK 10 Amk Ind Park 2A #01-09

Policy No: PNPV2018 - 00004998 Claim No: 1201800006065

Sum Insured: Excess: \$ 600.00

Make of Veh: D.O.A. 17052018  
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 18052018 1:35pm Person Contacted: Ah Lim Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDW 30376 - X
21/5/18	Report from meimien
22/5/18	Authorise repair ; Inform Eileen to proceed repair.
10/9/18	Confirm \$ 2204.00 @ 5 days Red: 81941.00, 47%.

Signature

Xho

REF:

ASSIGNMENT

(-2021)

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Ah Lim Motor

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \$600

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$19k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA /  RE / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SDW30376 Yr Regn: 28 Apr 2006

Type:  M.Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy c.c. 1997

Colour: Red A/C:  Insured /  Std /  NI /  NA

Sp. Reading: 194106 T/Radio:  Insured /  Std /  NI /  NA

Eng/No: \_\_\_\_\_

C/No: JN1BA611Z0200090

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  In order /  Jammed /  Leaked /  Burnt or

Brake:  In order /  Jammed /  Leaked /  Burnt or

Modi:  Nil /  S/Rim /  STD /  R/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS /  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /

TOYO /  YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 18-05-18

Survey held at W/S 5:30pm

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  U/C /  Rooftop or

Rt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

limit \$4000.

RECEIVED 10 SEP 2018

Date/Time, File Pass to?  : Preli. Report

1) typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:	<input type="checkbox"/> Site Insp (\$)	) S+RS, \$	200	
<input type="checkbox"/> Interview (\$)	) Photos			50
<input type="checkbox"/> Tech. Invs (\$)	) Others			10
<input type="checkbox"/> Weekend (\$)	)			
TOTAL			310	

Report Format: 00

Lump Sum / I.B.I.: (\$ 2204.00)

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 May 2018 Sendback Est	18 May 2018 11:14 S\$4,145.00	18 May 2018 11:53 Assign				<b>New Assignment</b> Cancel Case

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS**

Insured:	NAZREEN BIN OSMAN, ID: S8038109C		
Vehicle Reg. No.:	SDW3037G	Date of Loss:	17/05/2018 00:00 - :59 [144 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800006065	Policy/Cover Note No.:	PNPV2018-00004998 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2018]		
Driver/Custodian:	NAZREEN BIN OSMAN (), NRIC: S8038109C		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 21 May 2018

## Preliminary Advice

Vehicle No	: SDW3037G	Accident Date	: 17/05/2018
Make	: NISSAN SYLPHY	Policy No.	: PNPV2018-00004998
Assignment Date	: 18/05/2018	Excess	: S\$600.00
Date of Inspection	: 18/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,145.00
Revised Amount	:S\$	2,164.00
Check Items (Estimated)	:S\$	477.00
Total	:S\$	2,641.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	19,000.00
COE / PARF Rebate	:S\$	14,622.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,378.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Print Received Message

This mail is associated with :

**SDW3037G (1201800006065)**

OD

May 17 2018 12:00AM  
[NAZREEN BIN OSMAN]  
Ah Lim Motor Company

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 22/05/2018 09:28 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$2641.00) - SDW3037G - Claim Handler: Josey Loh

Approved:2641.00.

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Tuesday, May 22, 2018 9:53 AM  
**To:** 'ahlimmc@singnet.com.sg'  
**Cc:** SUR  
**Subject:** SDW 3037G FWD DOA: 17.05.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SDW 3037G (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/05/2018 09:27
Date Of Accident	17/05/2018 08:00
Exact Location Of Accident	KPE JLN BAHAR FILTER LANE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW3037G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NAZREEN BIN OSMAN
NRIC No	S8038109C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91016541
Alternative Phone No	HOME-91016541

### Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 2.0 CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------


### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00004998
Cover Note Number	

### Driver

Name of Driver	NAZREEN BIN OSMAN
NRIC No	S8038109C
Date Of Birth	06/12/1980
Occupation	INDOOR
Date Of Driving Pass	19/05/2006
Driving Experience	11 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91016541
Fax Number	
Contact Number	HOME-91016541
EEmail Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving into Jalan Bahar after exiting KPE (Teras). When approach Jalan Bahar the Volvo moved forward but hesitated and made sudden brake. I was looking toward my right side to move forward when I collided his rear.

**Important:**

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE** WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- |                                     |  |
|-------------------------------------|--|
| <input type="checkbox"/>            | - Reporting Only                         |
| <input type="checkbox"/>            | - Claim OD                               |
| <input type="checkbox"/>            | - Claim TP                               |
| <input checked="" type="checkbox"/> | - Claim <u>OD</u> / TP at other workshop |

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

*[Signature]*  
17 May 18 9.30am

Policyholder's signature  
Date & Time

*[Signature]*  
17 May 18 9.50am

Driver's Signature  
(if driver not the policyholder)  
Date & Time

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
Nric/Fin No.



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8109C

### Vehicle Details

Vehicle No.: SDW3037G  
Vehicle to be Exported: No  
Intended De-registration Date: 17 May 2018  
Vehicle Make: NISSAN  
Vehicle Model: SYLPHY 2.0 CVT  
Primary Colour: Red  
Manufacturing Year: 2006  
Engine No.: MR20146202A  
Chassis No.: JN1BBAG11Z0200090  
Maximum Power Output: 98.0 kW (131 bhp)  
Open Market Value: \$21,407.00  
Original Registration Date: 28 Apr 2006  
First Registration Date: 28 Apr 2006  
Transfer Count: 2  
Actual ARF Paid: \$23,548.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Mar 2021  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$25,466.00  
COE Rebate Amount: \$14,622.00  
**Total Rebate Amount: \$14,622.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 May 2018

OK

*MV - \$19,200*

## ▶ Sylphy Used Vehicle List (7 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Nissan Sylphy 1.5A (COE till 06/2021)</b>	<b>\$19,700</b>	<b>\$6,330 /yr</b>	21-Jul-2006	1,498 cc	136,000 km	AMG Automobile Express Pte Ltd	Availat
Low Monthly Under \$500/Month. Car In Good Condition. No Crack On The Dashboard! Teacher Owner Who Drives To School. Call Us To For More Details Trade In Welcome. Office No. - 63488178 Wee - 92240044   Regina - 98334578   Leong - 96825725							
<b>Nissan Sylphy 1.5A (COE till 10/2021)</b>	<b>\$26,800</b>	<b>\$7,800 /yr</b>	27-Oct-2006	1,498 cc	135,357 km	United Motoring Pte Ltd	Availat
- Office No. - 64635355 Alan - 93483386   Zac - 84821223   Calvin - 96371831							
<b>Nissan Sylphy 1.5A (COE till 01/2027)</b>	<b>\$49,955</b>	<b>\$5,740 /yr</b>	31-Jan-2007	1,498 cc	-	KelvinCarz Automobile	Availat
Consignment Unit. COE Paid \$50645 Till Jan 2027. New SLV Nice Number 2787. Viewing And Test Drive Is Available. Price Negotiable. Office No. - - KL - 97933333							
<b>Nissan Sylphy 1.5A (COE till 06/2022)</b>	<b>\$25,800</b>	<b>\$6,390 /yr</b>	04-Jun-2007	1,498 cc	106,892 km	Clarity Cars Pte Ltd	Availat
10% Down Payment \$2500 Drive Away Possible! 1 Owner Consigned Vehicle! Beautiful Black On Black Leather Interior. Low Fuel Consumption And Very Reliable Vehicle! Well Maintained. Call For Viewing Appo... Office No. - - Trevor Ng - 91058969							
<b>Nissan Sylphy 1.5A (COE till 08/2022)</b>	<b>\$26,888</b>	<b>\$6,340 /yr</b>	16-Aug-2007	1,498 cc	78,857 km	Quan Feng Motors (Singapore) Pte Ltd	Availat
No Repairs Needed. High Loan With \$3000 Down Payment Drive Away! 100% Approval Buy With Trust And Confidence Only. Office No. - - Marcus - 88337722							
<b>Nissan Sylphy 1.5A (COE till 09/2022)</b>	<b>\$32,000</b>	<b>\$7,340 /yr</b>	29-Sep-2007	1,498 cc	192,000 km		Availat
Recently Change Tyres, Shockpusars, Fully Covered New Mates, New Cd Player, Radio, And Reverse Camera. Office No. - - Sekar Meena - 81813668							
<b>Nissan Sylphy 1.5A (COE till 11/2022)</b>	<b>\$30,000</b>	<b>\$6,620 /yr</b>	17-Dec-2007	1,498 cc	168,000 km		Availat
1 Owner Teacher. Renewed COE, Fully Maintained By Tan Chong Motors Singapore From Day One. Original Pearl White Colour. Number Plate To Be Kept. Owner. New Owner Will Get New Number Plate. Nissan GP... Office No. - - Kuldip Singh - 93261183							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C results.

© 2004-2018 sgCarMart. All rights reserved.

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

License Number: **S8038109C**  
 Name: **NAZREEN BIN OSMAN**

Birth Date: **06 Dec 1980**  
 Issue Date: **04 Apr 2013**

002167755A




REPUBLIC OF SINGAPORE  
 IDENTITY CARD NO. **S8038109C**



Name: **NAZREEN BIN OSMAN**

نزرين بن اوسمن

Race: **MALAY**

Date of birth: **06-12-1980** Sex: **M**

Country/Place of birth: **SINGAPORE**




Hp: 9101 6241

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class	Vehicle Description	EFFECTIVE DATE
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	19 May 2006

Licence No: S8038109C



NP 428A

5236075



NRIC No: **S8038109C**



Date of issue: **14-10-2013**

**18A CANBERRA DRIVE #02-42**  
**SINGAPORE 768099**

NRIC No: **S8038109C** Date: **10/07/2015**



**CERTIFICATE OF INSURANCE**

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.  
All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

**POLICY NUMBER: PNPV2018-00004998 (Comprehensive - Classic Plan)**

Car plate number: SOW3037G

Your name (As the policyholder): Nazreen Bin Osman

Coverage start date: 27/04/2018

Coverage end date: 26/04/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

- (a) You; and
- (b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: s9 Capital pte ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 12/04/2018

Abhishek Bhatia  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please immediately inform us at +65-6920-8888  
or email us at [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details  
in this Certificate of Insurance need to be changed.

# AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A  
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST Reg No: M9-0009639-E

INSURER: FWD Singapore Pte. Ltd. (HQ)

SURVEYOR COPY

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00004998	Date of Loss:	17/05/2018
Vehicle Reg. No.:	SDW3037G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NAZREEN BIN OSMAN		
Driver:	NAZREEN BIN OSMAN		
Make/Model:	NISSAN SYLPHY, 2.0 CVT (A)	Vehicle Reg. Date:	28/04/2006
Vehicle Colour:	RED		
Engine No:	MR20146202A	Chassis No:	JN1BBAG11Z0200090
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Remarks:	CAR IS IN THE WORKSHOP AT AMK. PLS ARRANGE SURVEY SOONEST		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS	Amount
Parts	2,085.00
Miscellaneous Items	0.00
Labour	2,060.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,145.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>290.15</b>
<b>Nett Amount (S\$)</b>	<b>4,435.15</b>

This claim is handled by: KEE MUI HONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

### REPAIR DETAILS

#### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 May 2018)  
 Parts: 143 NISSAN SYLPHY 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Ah Lim Motor Company/SDW3037G/18/05/2018 11:14  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>X repairs</i>	0.00	0.00	*350.00F
2	1		*FRONT BONNET HINGE LH <i>X</i>	0.00	0.00	*35.00F
3	8		*FRONT BONNET INSULATOR CLIPS <i>X</i>	0.00	0.00	*16.00F
4	2		*FRONT BONNET SIDE RUBBER <i>X</i>	0.00	0.00	*40.00F
5	1		*FRONT BONNET OUTER CHROME MOULDING <i>X</i>	0.00	0.00	*70.00F
6	1		*HEADLAMP LH <i>- CRA</i>	0.00	0.00	*280.00F
7	1		*HEADLAMP BULB LH	0.00	0.00	*22.00F
8	1		*HEADLAMP HIGHBEAM BULB LH	0.00	0.00	*17.00F
9	1		*HEADLAMP LOWER BEAM LH	0.00	0.00	*18.00F
10	2		*HEADLAMP CLIPS - CHK PRICE <i>X REC.</i>	0.00	0.00	*-F
11	1		*FRONT BUMPER <i>- RL</i>	0.00	0.00	*270.00F
12	1		*FRONT BUMPER SIDE RETAINER LH <i>- RL</i>	0.00	0.00	*15.00F
13	12		*FRONT BUMPER CLIPS <i>- NBL</i>	0.00	0.00	*18.00F
14	1		*FRONT BUMPER REINFORCEMENT <i>X NN</i>	0.00	0.00	*135.00F
15	1		*FRONT BUMPER SPONGE <i>- CRA</i>	0.00	0.00	*75.00F
16	1		*FRONT BUMPER LOWER GRILLE - CHK PRICE <i>X NN</i>	0.00	0.00	*-F
17	2		*FRONT BUMPER LOWER SIDE CHROME MOULDING <i>- REC.</i>	0.00	0.00	*36.00F
18	1		*FOGLAMP LH <i>X NN</i>	0.00	0.00	*225.00F
19	1		*FOGLAMP OUTER COVER LH <i>X NN</i>	0.00	0.00	*35.00F
20	1		*FRONT FENDER LH <i>- BUC</i>	0.00	0.00	*165.00F
21	1		*FRONT FENDER COWLING LH <i>- RL</i>	0.00	0.00	*55.00F
22	10		*FRONT FENDER COWLING CLIPS <i>- REC.</i>	0.00	0.00	*20.00F
23	2		*FRONT FENDER TOP INNER BRACKET <i>X BT</i>	0.00	0.00	*70.00F
24	1		*FRONT FENDER SIDE SIGNAL LAMP LH <i>X NN</i>	0.00	0.00	*28.00F
25	1		*RADIATOR SUPPORT TOP GARNISH <i>X REC.</i>	0.00	0.00	*75.00F
26	10		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS <i>X REC.</i>	0.00	0.00	*15.00F

F=Franchise part.

Total Parts (S\$) **2,085.00**

Ah Lim Motor Company/SDW3037G/18/05/2018 11:14. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

#### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

#### Estimates on Labour

No	Particulars	Lab.Type	Amount
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	<i>30</i> 40.00

Ah Lim Motor Company/SDW3037G/18/05/2018 11:14. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New <i>MX</i>	120.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT WITH BRACKET; FRONT FENDER TOPMINNER BRACKER. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL; FRONT WHEEL HOUSEPANEL LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New <i>500</i>	900.00
4	TO SPRAY BONNET; BUMPER; BUMPER REINFORCEMENT; BARCKET RH; RADIATOR SUPPORT PANEL; WHEELHOUSE PANEL; FRONT DOOR LH; FRONT FENDER TOP INNER BRACKET LH	New <i>700</i>	1,000.00
Gross Labour Cost (\$\$)			<b>2,060.00</b>

Ah Lim Motor Company/SDW3037G/18/05/2018 11:14. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5 Days.

part by part.

before paint photos.

*[Signature]*  
23/5/18

Emo Qiong - 82880282

18/5/18.

Not Authorized

Excess \$600

Auto Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Prices are subject to confirmation
- 1 party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimco@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**DRAFT FINALISATION**

M/S : FWD SINGAPORE PTE LTD  
6 TEMASEK BOULEVARD  
#18-01 SUNTEC TOWER 4  
SINGAPORE 038986

TEL: 67275700

FAX: 67275799

ATTN: Motor Claim Department

Claim No: MC0913103  
Ref No: MF0911181  
Date: 30 Jul 2018  
Policy No: PNPV2018-00004998  
Veh Reg No: SDW3037G  
Make/Model: NISSAN SYLPHY 2.0

Your Ref No: -  
Claim Type: Own Damage  
Accident Date: 17/05/2018

**DRAFT FINALISATION**<sup>GVT</sup>

## Repair Cost to Vehicle No (For Finalization):SDW3037G

Description	U/Price	Quantity	Cost S\$	Amount S\$
<b>SPARE PARTS</b>				
1 HEADLAMP LH		1 PC	280.00	
2 FRONT BUMPER		1 PC	270.00	
3 FRONT BUMPER SIDE RETAINER LH		1 PC	15.00	
4 FRONT BUMPER CLIPS		12 PC	18.00	
5 FRONT BUMPER SPONGE		1 PC	75.00	
6 FRONT BUMPER LOWER SIDE CHROME MOULDING		2 PC	36.00	
7 FRONT FENDER LH		1 PC	165.00	
8 FRONT FENDER COWLING LH		1 PC	55.00	
9 FRONT FENDER COWLING CLIPS		10 PC	15.00	
10 FRONT FENDER TOP INNER BRACKET LH		1 PC	30.00	
11 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS		10 PC	15.00	
				974.00
<b>LABOUR</b>				
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	30.00	
13 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT WITH BRACKET, FRONT FENDER TOPINNER BRACKET. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL, FRONT WHEEL HOUSEPANEL LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	500.00	
14 TO SPRAY BONNET, BUMPER, BUMPER REINFORCEMENT, BARCKET RH, RADIATOR SUPPORT PANEL, WHEELHOUSE PANEL, FRONT DOOR LH, FRONT FENDER TOP INNER BRACKET LH		1 PC	700.00	
				1,230.00

**AH LIM MOTOR COMPANY**  
No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint Singapore  
Tel: 6483 1244 Fax: 6483 6170



# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : FWD SINGAPORE PTE LTD  
6 TEMASEK BOULEVARD  
#18-01 SUNTEC TOWER 4  
SINGAPORE 038986

TEL: 67275700 FAX: 67275799  
ATTN: Motor Claim Department

Claim No: MC0913103  
Ref No: MF0911181  
Date: 30 Jul 2018  
Policy No: PNPV2018-00004998  
Veh Reg No: SDW3037G  
Make/Model: NISSAN SYLPHY 2.0  
CVT

DRAFT FINALISATION

Your Ref No: -  
Claim Type: Own Damage  
Accident Date: 17/05/2018

### Repair Cost to Vehicle No (For Finalization):SDW3037G

Amount Before Excess	SS 2,204.00
Less Excess	SS 600.00
Amount Before GST	SS 1,604.00
Add GST @ 7%	112.28
Total Amount payable	SS 1,716.28

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED SIXTEEN AND CENTS TWENTY EIGHT ONLY

The above vehicle was surveyed by Guo Qiang - LKK on 18/05/2018

For AH LIM MOTOR COMPANY  
**AH LIM MOTOR COMPANY**  
No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint Singapore  
Tel: 6483 1244 Fax: 6483 6170  
AUTHORISED SIGNATURE

# AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A  
 #01-09 AMK AUTOPOINT Singapore 568047  
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlmmc@singnet.com.sg  
 GST Reg No: M9-0009639-E

**SURVEYOR COPY**

INSURER: FWD Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00004998	Date of Loss:	17/05/2018
Vehicle Reg. No.:	SDW3037G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NAZREEN BIN OSMAN		
Driver:	NAZREEN BIN OSMAN		
Make/Model:	NISSAN SYLPHY, 2.0 CVT (A)	Vehicle Reg. Date:	28/04/2006
Vehicle Colour:	RED	Chassis No:	JN1BBAG11Z0200090
Engine No:	MR20146202A		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Remarks:	CAR IS IN THE WORKSHOP AT AMK. PLS ARRANGE SURVEY SOONEST		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

**COST OF CLAIMS**

Parts	2,085.00
Miscellaneous Items	0.00
Labour	2,060.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,145.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>290.15</b>
<b>Nett Amount (S\$)</b>	<b>4,435.15</b>

*Also taken by Simon 23/5/18  
 E mail photo back*

This claim is handled by: KEE MUI HONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

### REPAIR DETAILS

#### Reference

Part Source: MRM-SG      Version: 1.0 (Last Synchronised: 18 May 2018)  
 Parts: 143      NISSAN SYLPHY 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's      (Price-denominated Standard List)  
 Print Code: Ah Lim Motor Company/SDW3037G/18/05/2018 11:14  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>X Repair</i>	0.00	0.00	*350.00F
2	1		*FRONT BONNET-HINGE LH <i>X</i>	0.00	0.00	*35.00F
3	8		*FRONT BONNET INSULATOR CLIPS <i>X</i>	0.00	0.00	*16.00F
4	2		*FRONT BONNET-SIDE-RUBBER <i>X</i>	0.00	0.00	*40.00F
5	1		*FRONT BONNET-OUTER CHROME MOULDING <i>X</i>	0.00	0.00	*70.00F
6	1		*HEADLAMP LH <i>CPA</i>	0.00	0.00	*280.00F
7	1		*HEADLAMP BULB LH <i>?</i>	0.00	0.00	*22.00F
8	1		*HEADLAMP-HIGHBEAM BULB LH <i>?</i>	0.00	0.00	*17.00F
9	1		*HEADLAMP-LOWER-BEAM LH <i>?</i>	0.00	0.00	*18.00F
10	2		*HEADLAMP-GLIPS-GHK-PRICE <i>acc.</i>	0.00	0.00	*F
11	1		*FRONT BUMPER <i>re</i>	0.00	0.00	*270.00F
12	1		*FRONT BUMPER SIDE RETAINER LH <i>/</i>	0.00	0.00	*15.00F
13	12		*FRONT BUMPER CLIPS <i>/</i>	0.00	0.00	*18.00F
14	1		*FRONT BUMPER-REINFORCEMENT <i>X</i>	0.00	0.00	*135.00F
15	1		*FRONT BUMPER SPONGE <i>CPA</i>	0.00	0.00	*75.00F
16	1		*FRONT BUMPER-LOWER GRILLE <i>CHK PRICE X</i>	0.00	0.00	*E
17	2		*FRONT BUMPER LOWER SIDE CHROME MOULDING <i>acc.</i>	0.00	0.00	*36.00F
18	1		*FOGLAMP LH <i>?</i>	0.00	0.00	*225.00F
19	1		*FOGLAMP OUTER COVER LH <i>?</i>	0.00	0.00	*35.00F
20	1		*FRONT FENDER LH <i>Blue</i>	0.00	0.00	*165.00F
21	1		*FRONT FENDER COWLING LH <i>re</i>	0.00	0.00	*55.00F
22	10		*FRONT FENDER COWLING CLIPS <i>acc.</i>	0.00	0.00	*20.00F
23	27		*FRONT FENDER TOP INNER BRACKET <i>? LH</i>	0.00	0.00	*70.00F <i>Mojo</i>
24	1		*FRONT FENDER-SIDE-SIGNAL-LAMP LH <i>X</i>	0.00	0.00	*28.00F
25	1		*RADIATOR-SUPPORT-TOP-GARNISH <i>?</i>	0.00	0.00	*75.00F
26	10		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS <i>?</i>	0.00	0.00	*15.00F <i>Mojo</i>
Total Parts (S\$)						2,085.00

F=Franchise part.

Ah Lim Motor Company/SDW3037G/18/05/2018 11:14. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

#### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

#### Estimates on Labour

No	Particulars	Lab.Type	Amount
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30 40.00

Ah Lim Motor Company/SDW3037G/18/05/2018 11:14. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
<del>2</del>	<del>TO REMOVE AND REPLAGE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.</del>	New	<del>X 120.00</del>
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT WITH BRACKET; FRONT FENDER TOPMINNER BRACKER. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL; FRONT WHEEL HOUSEPANEL LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	500 900.00
4	TO SPRAY BONNET; BUMPER; BUMPER REINFORCEMENT; BARCKET RH; RADIATOR SUPPORT PANEL; WHEELHOUSE PANEL; FRONT DOOR LH; FRONT FENDER TOP INNER BRACKET LH	New	700 1,000.00
Gross Labour Cost (S\$)			2,060.00

Ah Lim Motor Company/SDW3037G/18/05/2018 11:14. Not valid without Reference section.  
 Generated using Merlimen e-Claims IEAS  
 < END OF ESTIMATES >

5 Days.  
 part by part.  
 before paint photos.  
 Gino Qiong - 82880282  
 18/5/18.



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 GO. REG. NO.: 199307741M

AMERICAN CLASS  
Dept Direct: 6417 8791 / 6745 9039

Dept Direct: 6306 0610

Dept Direct: 6417 8794

managed by MCC

TOYOTA CHANGI PARTS  
Dept Direct: 6305 9011

Dept Direct: 6417 8795

LEXUS DAIHATSU  
Dept Direct: 6417 8192

NISSAN  
Dept Direct: 6417 8793

Wiper blade: NWB (Nippon Wiper blades), Sliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Dense, NGK (Made in Japan)

AH LIM MOTOR COMPANY  
10 ANG MO KIO PARKS 2A  
#01-09 AMK AUTO POINT

SINGAPORE 568047  
TEL : 64831244 FAX : 64836170  
ATTN : SIMON 96205405

TAX INVOICE : AR201805-12006  
DATE : 23/05/2018  
CUSTOMER ID : AHL008  
VEH REG. NO. : SDW3037G  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	N62072-EW000YL	FRONT BUMPER MOULDING L@R	PA	2	18.00	36.00
	G11		PL3-A1-12A			
2	N01553-09321-24YL	CLIP FENDER SHIELD CLIP	PA	22	1.50	33.00
	B16N16M11A33J31		PL3-A1-14A			
3	N01553-09611YL	CLIP BUMPER TOP 01553-10501	PA	10	1.50	15.00
	B15N16J31C11G11		PL3-A1-12A			
4	N63161-EW00A	FENDER BRACKET LH	PA	1	30.00	30.00
	G11		PL3-D1-08B			

00923

SUB-TOTAL : 114.00 ✓  
ADD GST 7.00 % 7.98

E. & O.E TOTAL AMOUNT SGD : 121.98

[P] 23/05/2018 10:25:47AM

[E] 23/05/2018 10:22:27AM

Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.  
Sales Executive: GUAN



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

*[Handwritten Signature]*



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg  
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper Blade), Silper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY  
10 ANG MO KIO PARKS 2A  
#01-09 AMK AUTO POINT

SINGAPORE 568047  
TEL : 64831244 FAX : 64836170  
ATTN : SIMON 96205405

TAX INVOICE : AR201805-11271  
DATE : 22/05/2018  
CUSTOMER ID : AHL008  
VEH REG. NO. : SDW3037G  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	N26065-EW00A G11	H/LAMP UNIT LH	PA PL3-B1-090	1	280.00	280.00
2.	N62022-EW025 G11	FRT BUMPER //SLYPHY\	PA PL4-D1-17	1	270.00	270.00
3.	N62223-EW900YL/EW000 G11	F/BUMPER SIDE/BRKT LH	PA PL3-A1-14A	1	15.00	15.00
4.	N62090-EW000/900YL G11	FRT BUMPER SPONGE	PA PL3-D1-03S	1	75.00	75.00
5.	N63101-EW030/000/91JYL G11	FRT FENDER LH	PA PL3-A1-09B	1	165.00	165.00
6.	N63843-EW000/900YL G11	F/FENDER IN/SHIELD LH	PA PL3-B1-05S	1	55.00	55.00

SUB-TOTAL : 860.00 ✓  
ADD GST 7.00 % 60.20

E. & O.E TOTAL AMOUNT SGD : 920.20

[P] 22/05/2018 10:56:24AM

[E] 22/05/2018 10:49:00AM

Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.  
Sales Executive: GUAN



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

*[Handwritten Signature]*

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 May 2018 <a href="#">Sendback Est</a>	18 May 2018 11:14 <b>S\$4,145.00</b>	18 May 2018 11:53 <a href="#">Edit Adj Rpt</a>	<b>S\$2,204.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,204.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:	<b>NAZREEN BIN OSMAN</b> , ID: S8038109C		
Vehicle Reg. No.:	<b>SDW3037G</b>	Date of Loss:	17/05/2018 00:00 - :59 [144 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / 1201800006065</b>	Policy/Cover Note No.:	PNPV2018-00004998 (Comprehensive)
		Excess:	S\$600.00
Repairer:	<b>Ah Lim Motor Company (AMK)</b> 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Josey Loh</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 30/05/2018]		
Driver/Custodian:	NAZREEN BIN OSMAN (), NRIC: S8038109C		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- FWD\_SG (22/05/2018): **Alert - Adj Mandate Approved (S\$2641.00) - SDW3037G - Claim Handler: Josey Loh**

**ALL ASSOCIATED TASKS**  [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**SDW3037G (1201800006065)**

OD

**May 17 2018 12:00AM**  
**[NAZREEN BIN OSMAN]**  
**Ah Lim Motor Company**

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	18/05/18 11:14	<b>Repairer Estimates</b>	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 11:46	<b>Adjuster Immediate Advice</b>	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
2	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
3	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
4	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
5	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
6	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
7	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
8	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
9	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
10	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
11	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
12	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
13	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
14	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
15	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
16	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
17	18/05/18 11:11	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	21/05/18 11:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail Print
15	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
16	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
17	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
18	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
19	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
20	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
21	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
22	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
23	21/05/18 11:58	General View		Load JPG <input checked="" type="checkbox"/>
24	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
25	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
28	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
29	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
30	06/09/18 10:44	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail Print
1	18/05/18 11:14	Certificate of Insurance		Load PDF <input type="checkbox"/>
2	18/05/18 11:14	Copy of Claimant's Identity Card		Load PDF <input type="checkbox"/>
3	18/05/18 11:14	Log card (if available)		Load PDF <input type="checkbox"/>
4	18/05/18 11:14	E-filed GIA report		Load PDF <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	21/05/18 11:57	SDW 3037G ESTIMATE		Load PDF <input type="checkbox"/>
2	27/09/18 10:40	PARTS INVOICE		Load PDF <input type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Repairer  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD18009055/GRBS2

Date: 27/09/2018

### REFERENCE

Insured/Claimant: NAZREEN BIN OSMAN Policy No: PNPV2018-00004998  
Date of Loss: 17/05/2018 Nature of Claim: OD Claim No: 1201800006065

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDW3037G**  
Make & Model: NISSAN SYLPHY, 2.0 CVT (A) Engine No: MR20146202A  
Reg. Date: 28/04/2006 (Man. Year: 2006) Chassis No: JN1BBAG11Z0200090  
Colour: Red Odometer: 194106 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: S\$19,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,085.00	974.00	1,111.00	53.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,230.00	830.00	40.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,145.00</b>	<b>2,204.00</b>	<b>1,941.00</b>	<b>46.83</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>600.00</b>	<b>-600.00</b>	
<b>(S\$)</b>	<b>4,145.00</b>	<b>1,604.00</b>	<b>2,541.00</b>	<b>61.30</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>290.15</b>	<b>112.28</b>	<b>177.87</b>	<b>61.30</b>
<b>Nett Amount (S\$)</b>	<b>4,435.15</b>	<b>1,716.28</b>	<b>2,718.87</b>	<b>61.30</b>

### INSPECTION

Date of Assignment: 18/05/2018 Present Location: Ah Lim Motor Company (AMK)  
Ah Lim Motor Company (AMK)  
Date Inspected: 18/05/2018 Inspected At: 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK  
Autopoint  
Singapore 568047  
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

*any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2018)
<b>Parts:</b> 143	NISSAN SYLPHY 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SDW3037G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	350.00 F	*- F
2	1		*FRONT BONNET HINGE LH	Not Necessary	35.00 F	*- F
3	8		*FRONT BONNET INSULATOR CLIPS	Not Necessary	16.00 F	*- F
4	2		*FRONT BONNET SIDE RUBBER	Not Necessary	40.00 F	*- F
5	1		*FRONT BONNET OUTER CHROME MOULDING	Not Necessary	70.00 F	*- F
6	1		*HEADLAMP LH	Cracked	280.00 F	*280.00 F
7	1		*HEADLAMP BULB LH	Not Necessary	22.00 F	*- F
8	1		*HEADLAMP HIGHBEAM BULB LH	Not Necessary	17.00 F	*- F
9	1		*HEADLAMP LOWER BEAM LH	Not Necessary	18.00 F	*- F
10	2		*HEADLAMP CLIPS - CHK PRICE (NPA)	Not Necessary	0.00 F	*- F
11	1		*FRONT BUMPER	Deformed	270.00 F	*270.00 F
12	1		*FRONT BUMPER SIDE RETAINER LH	Deformed	15.00 F	*15.00 F
13	12		*FRONT BUMPER CLIPS	Necessary	18.00 F	*18.00 F
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	135.00 F	*- F
15	1		*FRONT BUMPER SPONGE	Cracked	75.00 F	*75.00 F
16	1		*FRONT BUMPER LOWER GRILLE - CHK PRICE (NPA)	Not Necessary	0.00 F	*- F
17	2		*FRONT BUMPER LOWER SIDE CHROME MOULDING	Necessary	36.00 F	*36.00 F
18	1		*FOGLAMP LH	Not Necessary	225.00 F	*- F
19	1		*FOGLAMP OUTER COVER LH	Not Necessary	35.00 F	*- F
20	1		*FRONT FENDER LH	Buckled	165.00 F	*165.00 F
21	1		*FRONT FENDER COWLING LH	Deformed	55.00 F	*55.00 F
22	10		*FRONT FENDER COWLING CLIPS	Necessary	20.00 F	*15.00 F
23	2		*FRONT FENDER TOP INNER BRACKET	Bent	70.00 F	*30.00 F
24	1		*FRONT FENDER SIDE SIGNAL LAMP LH	Not Necessary	28.00 F	*- F
25	1		*RADIATOR SUPPORT TOP GARNISH	Not Necessary	75.00 F	*- F
26	10		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	Necessary	15.00 F	*15.00 F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>2,085.00</b>	<b>974.00</b>
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	30.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	120.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT BUMPER REINFORCEMENT WITH BRACKET; FRONT FENDER TOPMINNER BRACKER. TO KNOCK & REPAIR RADIATOR SUPPORT PANEL; FRONT WHEEL HOUSEPANEL LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	900.00	500.00
4	TO SPRAY BONNET; BUMPER; BUMPER REINFORCEMENT; BARCKET RH; RADIATOR SUPPORT PANEL; WHEELHOUSE PANEL; FRONT DOOR LH; FRONT FENDER TOP INNER BRACKET LH	New	1,000.00	700.00
<b>Gross Labour Cost (S\$)</b>			<b>2,060.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >