

Survey by LKK

FAX : 6542 6039

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet is			\$ 1,526.00
	Bonnet Lock is			\$ 50.90
	Radiator Grille & crack			\$ 294.35
	Radiator Grille H Emblem Nec			\$ 113.65
	Front Bumper Cover distorted			\$ 562.30
	Front Bumper Sponge & torn			\$ 142.20
	Front Bumper Reinforcement & Dent			\$ 526.10
	Front Bumper Grille (LH/RH) NN		\$ 40.30	\$ 80.60
	Front Bumper Centre Grille deformed			\$ 178.60
	Front Bumper Centre Grille Top Garnish N/S CNT	O/S NN	\$ 80.00	\$ 160.00
	Front Bumper Bracket Top (LH/RH) NN		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) NN		\$ 24.60	\$ 49.20
	Front Bumper Retainer Mounting NN		\$ 9.20	\$ 18.40
	Headlamp Support Top Cover NN			\$ 398.00
	Headlamp Support Panel Assy & set			\$ 1,067.50
	Headlamp (LH/RH) & mounting crack		\$ 1,388.00	\$ 2,776.00
	Radiator & set			\$ 850.20
	Radiator Fan Blade,Cowling,Motor Assy NN			\$ 792.95
	Radiator Bracket (RH/LH) NN		\$ 6.50	\$ 13.00
	Radiator Hose Upper NN			\$ 47.40
	Radiator Hose Lower NN			\$ 47.40
	Radiator Expansion Tank NN			\$ 48.00
	Radiator Guard & s/c		\$ 35.00	\$ 70.00
	Horn Unit (LH/RH) & broken		\$ 86.75	\$ 173.50
	Horn Wire broken NN			\$ 156.50
	Aircon Condenser & set			\$ 1,137.35
	Inter Cooler & punctured			\$ 921.90
	Inter Cooler Mounting (2 PCS) NN			\$ 25.90
	SUB TOTAL			\$ 12,272.70
	LESS 20%			\$ 2,454.54
	DISCOUNTED TOTAL			\$ 9,818.16
	Front Number Plate crack			\$ 25.00
	Front No Plate Trim Cover broken			\$ 15/-30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 100.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,800.00

SHC 3969A

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker Hec			\$ 30.00	Nett ✓
	Rear No. Plate S/L			\$ 25.00	Nett X
	Rear Bumper Reverse Sensor Dem			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo Hec HF			\$ 50.00	Nett X
	Rear Bumper Rubber Mat disturbed			\$ 30.00 - 50.00	Nett ✓
	Rear Windscreen Sealant Hec			\$ 46.00	Nett ✓
				\$ 336.70	
	Labour Charge				
	Panel Beating			\$ 2,500.00	1000/-
	Spray Painting Charge			\$ 1,600.00	1000/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 100.00	60/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 360.00	80/-
	TOTAL LABOUR			\$ 5,050.00	
	ESTIMATE TOTAL			\$ 35,459.22	
18/05/2018 @ 1130am Hot Autumn L/Sun 9/12 days. R nyn LKK Auto g					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					