

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

17-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6695 U

1 pc	Rear bumper <i>X repair</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>X repair</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$ 58.00
		<hr/>
		\$ 960.00
		Less 10%
		<hr/>
		\$ 864.00

S/NETT

1 set	Rear bumper clips <i>X</i>	\$ 48.00
1 set	Reverse sensor <i>X</i>	\$ 280.00
1 pc	Rear bumper top protector <i>X</i>	\$ 80.00
Sundry		<hr/>
		\$ 50.00 <i>X</i>
To dismantle / replace/test reverse sensor to new bumper and reset to the same		\$ 120.00 <i>X</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$ 100.00 <i>X</i>
To putty and spray painting on rear bumper		\$ 200.00 <i>280</i>
To apply rustproofing on the repaired and replaced panels.		\$ 120.00 <i>X</i>
		<hr/>
		\$ 2,392.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kohm 10/10/18
21/5/18 1345hrs
2 hrs.
45
After Repair pld.

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____