

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-May-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1195 Z

1 pc	Rear windscreen moulding	X 11	\$	64.10
1 pc	Tailgate	X 1 kg. 2	\$	2,292.30
1 pc	Tailgate lower garnish	— one	\$	362.61
1 pc	Tailgate trim	X one	\$	431.12
1 pc	Tailgate weatherstrip	X one	\$	276.98
1 pc	Emblem I30	— one	\$	27.80
1 pc	Emblem CRDI	— one	\$	29.40
1 pc	Emblem Hyundai	— one	\$	29.40
1 pc	Rear bumper	— one	\$	811.11
1 pc	Rear bumper sponge	X one	\$	79.20
1 pc	Rear bumper reinforcement	X one	\$	815.64
1 pc	Rear bumper reinforcement centre	X one	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	n/s one o/s one	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50	n/s one o/s one	\$	215.00
			\$	5,618.26
		Less 20%	\$	1,123.65
			\$	4,494.61

S/NETT

1 set	Rear bumper clips	— one	\$	48.00
1 set	Reverse sensor	— shake	\$	280.00 20.
1 set	Tailgate sticker	— one	\$	100.00
1 set	Tailgate garnish clips	— one	\$	38.00
1 pc	Sealant	X one	\$	50.00

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1195 Z

Sundry	\$	50.00 20
To dismantle and replace reverse sensor and test system	\$	80.00 20
To replace the rear windscreen into new shell tailgate	\$	120.00 X 21
To dismantle and refit the inner component into new tailgate, test wiper motor and water etc	\$	120.00 X 21
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc.	\$	650.00 400
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel.	\$	1,000.00 540
To apply rustproofing on the repaired and replaced panels	\$	150.00 X 21
Total	\$	7,180.61

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kellick

17/5/18 0920 L

3 Pys

P/P

Before Paint photo

24/5/18

chud 45,2500/36

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: