

Trans-cab Auto Services Pte Ltd

AAD1805-126

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7808K

Vehicle No.:	SHB 7808K
Chassis No.:	KL1LA69RJBB109867
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	13.5.2018
Third Party Insurer :	EQ

PART**LIST**

1	1	Front Fender RH ✓	\$	837.60
2	1	Front Fender Liner RH ✗	\$	47.00
3	1	Fender Insulation RH ✗	\$	39.00
4	1	Front Fender Inner Wheel House Panel RH ✗	\$	1,437.00
5	1	Front Door RH ✓	\$	1,133.00
6	1	Front Door Glass Guide RH Chrome Moulding ✗	\$	60.00
7	1	Front Door Outer Moulding ✗	\$	220.00
8	1	Front Door Outer Handle ✗	\$	125.00
9	1	Front Door Handle Support ✗	\$	3.00
10	1	Front Door outer handle inner seal ✗	\$	89.15
11	1	Front Door outer key lock ✗	\$	25.00
12	1	Front Door Hinge Upper ✗	\$	65.00
13	1	Front Door Hinge Lower ✗	\$	65.00
14	1	Front Door inner lock ✗	\$	586.00
15	1	Front Door Inner Lock Latch RH ✗	\$	206.00
16	1	Front Door Check / Arrestor ✗	\$	67.50
17	1	Front Door Weatherstrip RH ✗	\$	138.79
18	1	Front Door glass channel weatherstrip ✗	\$	160.00
19	1	Front Door inner trim board ✗	\$	455.69
20	1	Front Door window glass ✗	\$	456.12
21	1	Front Door Power Window Motor (Master) RH ✗	\$	284.97
22	1	Front Door power window motor switch ✗	\$	145.00
23	1	Front Door Window Regulator Gear RH ✗	\$	84.58
24	1	Front Door Outer Pillar Panel RH ✗	\$	715.00
25	1	Front Door Pillar Inner Panel RH ✗	\$	850.00
26	1	Front Door Center Pillar Panel RH ✗	\$	698.15
27	1	Front Side View Mirror Assy RH ✗	\$	1,191.00

Trans-cab Auto Services Pte Ltd

AAD1805-126

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7808K

28	1	Rear Door RH (Panel A-RR DR LH)	X	\$	1,133.00
29	1	Front Side Rocker Panel Garnish RH	X repair	\$	236.40
30	1	Front Side Rocker Panel Outer RH	X	\$	600.00
31	1	Front Side Rocker Panel Inner RH	X	\$	519.30

Front Bumper X repair

TOTAL	\$	12,673.25
10%	\$	1,267.33
	\$	11,405.93

Special Nett

1 Set	Front Bumper Fastener Clip	X	\$	24.00
1 Set	Front licence plate with holder	X	\$	192.00
1 Set	Radiator Grille clip	X	\$	35.00
1 Set	Front Fender Liner clip	X	\$	30.00
1	Front Fender RR Bracket RH	X	\$	7.10
1	Rear Wheel Rim Hub Cap RH	X	\$	166.30
1	Rear Tyre RH	X	\$	180.00
1	Rear Tyre Rim RH	X	\$	126.00
1Set	Rear Fender Inner Trim Clip RH	X	\$	30.00

TOTAL	\$	783.30
--------------	-----------	---------------

TOTAL PARTS	\$	16,917.10
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 600
Putty and spray painting of the affected portion.	\$	4,000.00 800
Towing Fees.	\$	120.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-126

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7808K

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To rust-proofing of the affected areas.	\$	170.00 50
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00 50
TOTAL		\$ 10,460.00
Over All Total		\$ 25,577.10

Repair Days (Lump Sum)

15 days

Kahn / CLKK
17/5/18 15 hrs
4 days
L/S
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: