

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8800U

MAKE :

MODEL : HYUNDAI i40

DATE 16/5/2018 16:57

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>X SK</i>			\$ 1,681.40
	Boot Lid Rubber <i>X SK</i>			\$ 115.80
	Boot Lid Lock Upper <i>X SK</i>			\$ 137.90
	Boot Lid Lock Lower <i>X SK</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>X AN</i>			\$ 27.20
	Boot Lid CRDI Plate <i>+ in</i>			\$ 41.00
	Rear Bumper <i>— sk</i>			\$ 603.60
	Rear Bumper Reinforcement <i>X SK</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X SK</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X SK</i>		\$ 49.00	\$ 98.00
	Rear Bumper Clips <i>— SK</i>			\$ 22.00
	Rear Bumper Sponge <i>X SK</i>			\$ 143.40
	Rear Bumper Under Cover <i>— SK</i>			\$ 225.00
	Rear Panel <i>X SK</i>			\$ 592.30
	Rear Panel Garnish <i>X SK</i>			\$ 57.70
	Rear Panel Lower Panel <i>X SK</i>			\$ 495.50
	<i>Rear Bootlid lower garnish X SK</i>			
	SUB TOTAL			\$ 5,136.85
	LESS 20%			\$ 1,027.37
	DISCOUNTED TOTAL			\$ 4,109.48
	Boot Lid Comfort Logo & Tel No. Sticker <i>X SK</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>X SK</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>— SK</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>— SK</i>		\$ 100.00	\$ 200.00
	<i>Rear Bumper Rubber Mat — SK \$50</i>			
				\$ 415.70
	Labour Charge			200
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,940.00
	ESTIMATE TOTAL			\$ 6,465.18

LKK Auto Consultancy Service Pte Ltd
 the Repairer of the following:
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from insurance company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK/Kalvin

pbyr

AIG

Like

1 Calvin LKK
 17/5/18 11:30 hrs.
 2 hrs.
 PIP

Before Paint ptt.

400
 X 11
 X 11
 X 11
 X 20