11/5/2019

(00/11/12)		
ameur: Kalvin REF:		*
	ASSIGNMENT	
From: Date: .	VEN NO: SHC	14855 Yr Regn: 25m , 217
Estimated Cost:	Type: M.Car / M.Cycle / B	lus / Van / Lorry / Tao / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or	, 0
To Insped Vehicle No:	- Make:	July 240 00 1685
at Workshop m/s	Colour	AC: Insuffed / Std / NI / NA
of		6960 T/Radio: Insuged / Std / NI / NA
Insured:	Eng/No:	
Policy No.	[DISCUSSED	MHLB414MH4098558
Claims No.	Gen. Cond: Good / For / I	
Sum In swed: Excess:	Steering: Inorgan I Jamme	
(Client's Record)	Brake: Inogfer / Jamme	CONTRACTOR OF THE CONTRACTOR O
Make of Veh;	Modl: Nil / S/Rim / ST	
(Policy Condition)	Tyle data, R:	201/60R16
Remark: The veh had commenced Its		/FS/LIZA/MIC/OHTSU/PIR/SUMI/
repair at the time of Inspection.	TOYO/YOKO or	Hallak
Bal. or Market Value:	Front	Rear
IDAC Accident Rport: Consistent? : Yes or	-No. 1	mm R/Bal. 1 mm
GIA / PR Seen: Consistent? : Yes or	No. I mel 1	mm L/Bal. 7 mm
Est Repairs: z days Res.: Yes o		D.O.I. 12/5/18
Lum Sum: - % 3 Val.: Yes or	r No Survey held at	1060 11
CA / PEV / PER / Address	10 DESCRIPTION OF THE PARTY NAMED IN COLUMN TWO IS NOT THE PARTY NAMED IN COLUMN TWO	ear I QIS I N/S I U/C I Rooftop or
CA / REV / REP. / 24 HRS	ehicle: 'IN / OUT	als Front
Date: Person Contacted:		me / Body Structure affected due to collision.
Date / Time Action / Instruction		
245/18 Whil PIP\$ 3896.	16/2/2	(72
		PIP
(RED: \$ 1,850.64	337/.)	
	1.	
Date/Time, File Pass to? People Papart		-
Frem. Report	Days Of Repair:	
1) : Final Report Data/Time, File Return to?	Resurvey No. of Trip: _	
2)	Add Fee: : Site Insp (\$	Transportation:
7	: Interview (\$)s+Rssi
Report Format:	: Tech, Invs (\$) Photos
Lump Sum / I.B.I: (S	—) Others
)	:Weekend (\$	
		TOTAL

(08/11/13)

COMFORTDELGRO ENGINEERING PTE LTD

.REPAIR ESTIMATE*

VEHICLE NO : SHC 1485S :

MAKE

MODEL : HYUNDAI i40 Children (ai ping CPIP)

Qty	Parts Description/ Labour	Type	Unit Price	1 2	Amount
	Radiator Grille _ G			8	1,480.00
	Front Bumper Cover			S	1,052.20
	Front Rumper Sponge XIX			S	142.20
	Front Bumper Reinforcement			S	526.10
	Front Bumper Grille (RH) × ***			S	285.50
	Front Bumpar Crilla Airdust (PH)			S	155.00
	Front Bumper Bracket Top (LH/RH)		\$ 22.40	5	44.80
	Front Bumper Bracket (LH/RH)		\$ 24.60	S	49.20
	Headlamp (RH) / hratel		3 24.00	S	1,388.00
	Front Fender (RH) × M			5	619.00
	Front Fender Shield (RH)			\$	169.80
	Front Fonder Batainer as 114			5	
	Front Fender Retainer × 3			2	9.20
	SUB TOTAL			s	5,921.00
	LESS 20%			S	1,184.20
	DISCOUNTED TOTAL			S	4,736.80
	Labour Charge Panel Beating Spray Painting Charge			\$ \$	\$60.00 \$60.00
	Tuff Kote			\$	59.00
	TOTAL LABOUR			S	1,010.00
	ESTIMATE TOTAL			s	5,746.80
	Kahi (UM) 17/5/18 1510hs. 2hs PIP Before P.21 phh Before P.21 phh	To re To de To de Parts Third No site Supples Supples	Auto Consultants hence repairer of the following: survey before after spray pair apply damaged partist during prices are subject to confirmate and a survey survey on a "Without France of the survey	ting tesury tion trejudi	ey ce" basis

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305161453 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date 21/05/18 **FINALIZATION FORM** LKK Fax: To KALVIN ANG Attn : Vehicle Reg No. : SHC1485S Date of Accident : 16-May-18 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-The repair job shall bill to: CHINA TAIPING ---SDP9818S 2. The finalized amount shall be: Spare Parts after List discount \$3,136.16 (a) \$760.00 Labour Charges (b) \$3,896.16 Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost Estimated normal period for repairs: 2 working days. 3. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature Name LIMTS Name KALVIN Tel 62148398 Date Fax 65468156 For Official Use Only Document Confirm By Item: Amount Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES Loss of Income Paid Survey Fees 4. LTA Search Fee Medical Fees (on behalf of driver, if applicable) Overrun Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inter	nationale Des Experts En Autor	nobile		
CHINA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI18009	092/K1ea3		
3 ANSON ROAD #16- SPRINGLEAF TOWER	00 RSINGAPORE 079909	Date: 18-05-2018 Code: CTI			
1. Kennelli selle	Policy Particul	ars :- THIRD PARTY CLA	IM		
Insured Veh.	SDP 9818S	Veh. Inspected	SHC 1485S		
Policy No.	DMPCSN1524151702	Coverage (\$)	0.00		
Claim No.	SNM18D02505C02/8	Excess (\$)	0.00		
Assign From		Assign Date	18/05/2018		
2.	Vehicle P	articulars & Condition			
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer	28	Steering			
Brakes		Modification			
General					
3.	Cor	nditions of Tyres			
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4.	Descr	iption of Damages	Bertal Interest ber		
5.	Gen	eral Information			
Accident Date	16/05/2018	Inspection Date	17/05/2018		
Survey held at	COMFORTDELGRO ENGIN	EERING PTE LTD			
	59 LOYANG DRIVE SINGAPORE 508969				
5a.	S. S. S. S. Williams	Remarks			
	ON WAS CONDUCTED ON A'CE TO YOUR INSTRUCTIONS				

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

REGN NO. SHC1485S

MILEAGE

FUEL

Date/Time: 17:05.2018 14:11

Page : 1

am:

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305161453

MER

COMFORT TRANSPORTATION PTE LTD

7010045 OMER NO

83 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(P)

YR OF MANU 25.01.2017 CODE UHLB41UMHU098558

HYUNDAI

COMPLETION DATE/TIME:

TARGET DATE

UNT CARD NO.

Service Advisor

urned to Service Reception upon collection

JOB DESCRIPTION

cident Date: 16.05.2018

TURE: 3P 16.05.18/C

NO

LABOR CODE

DESCRIPTION



Date

KED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE Exit Pass edgement Slip Vehicle No.: SHC1485S SHC1485S LIMTS

Name of Service Advisor

To be kept by Security Guard


Signature/Date

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 1485S

MAKE



DATE 17/5/2018

LKK-KALVIN

	T	Unit Dates	-	Alvin
1	Type	Unit Price	+	Amount
TO THE SECOND CONTRACTOR OF THE PARTY OF THE			REPLA	1,480.00
			100	1,052.20
1				142.20
[[] 전 10 10 10 10 10 10 10 10 10 10 10 10 10			35.00	526.10
# 3 Walter 1				285.50
7			19000	155.00
. [[[[[[[[[[[[[[[[[[[[15] L.	0.27	44.80
8 8		\$ 24.60	5	49.20
			\$	1,388.00
		11	S	619.00
Front Fender Shield (RH) ×			S	169.80
Front Fender Retainer ×			S	9.20
SUB TOTAL			s	5,921.00
LESS 20%			S	1,184.20
DISCOUNTED TOTAL			S	4,736.80
Tuff Kote TOTAL LABOUR			s	59:00 1,010.00
ESTIMATE TOTAL			\$	5,746.80
the third	o resurvey belo to display dama and prices and third party sur	relation spray parameter good parts.) during resurvey subject to confirmation my is on a "Nimous Prayudice"	pasis and pripar	
	Radiator Grille Front Bumper Cover Front Bumper Sponge .' Front Bumper Reinforcement .' Front Bumper Grille (RH) Front Bumper Grille (RH) Front Bumper Bracket Top (LH/RH) .' Front Bumper Bracket (LH/RH) .' Headlamp (RH) Front Fender (RH) Front Fender Retainer SUB TOTAL LESS 20% DISCOUNTED TOTAL Labour Charge Panel Beating Spray Painting Charge Tuff Kote TOTAL LABOUR ESTIMATE TOTAL Kake CMA LABOUR LABOUR	Radiator Grille Front Bumper Cover Front Bumper Sponge . Front Bumper Reinforcement . Front Bumper Grille (RH) × Front Bumper Grille (RH) 2 Front Bumper Bracket Top (LH/RH) . Front Bumper Bracket (LH/RH) . Front Fender (RH) 2 Headlamp (RH) Front Fender Shield (RH) × Front Fender Retainer > SUB TOTAL LESS 20% DISCOUNTED TOTAL Labour Charge Panel Beating Spray Painting Charge Tuff Kote TOTAL LABOUR ESTIMATE TOTAL Kake CMA 1 7/5/8 15/6 15/6 A. LKK Auto Constitute Total	Radiator Grille Front Bumper Cover Front Bumper Sponge ? Front Bumper Reinforcement ? Front Bumper Grille (RH) × Front Bumper Grille (RH) × Front Bumper Bracket Top (LH/RH) ? Front Bumper Bracket (LH/RH) ? Front Fender (RH) × / / / / Front Fender (RH) × / / / Front Fender Retainer × SUB TOTAL LESS 20% DISCOUNTED TOTAL LESS 20% DISCOUNTED TOTAL LESS 20% TOTAL LABOUR ESTIMATE TOTAL Kake CUlly A 1 f / s / 8 15 (s / s) LEX Auto Consultants hence notify the Repairer of the tollowing: the R	Radiator Grille Front Bumper Cover Front Bumper Reinforcement Front Bumper Grille (RH) × Front Bumper Grille (RH) ? Front Bumper Bracket Top (LH/RH)? Front Bumper Bracket (LH/RH)? Front Fender (RH) × Y A S Front Fender Retainer × SUB TOTAL LESS 20% DISCOUNTED TOTAL LESS 20% DISCOUNTED TOTAL LESS 20% TOTAL LABOUR ESTIMATE TOTAL Kaki CUlly LK Auto Consultants hence notify the Regaler of the following: the Regaler of th

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.05.2018 Time: 17:55:14

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: 305161453 : SHC1485S : 0000000000 : HYUNDAI

MAKE MODEL : I-40

DATE OF REGN : 25.01.2017 DATE/TIME IN : 17.05.2018 : 17.05.2018 10:10

ACCIDENT DATE : 16.05.2018

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A FRT BUMPER I 1,052.20 20.00 841.76

0002 04-01-0103-2164-G RADIATOR GRILLE 1 1.480.00 20.00 1.184.00

0003 04-01-0103-0782-A HEADLAMP RH 1 1,388.00 20.00 1,110.40

SUB-TOTAL : 3,136.16

JOB NATURE

0000 L PANEL BEATING

400.00

DATE:

0001 23-502 SPRAYPAINT ON AFFECTED AREA

360.00

SUB-TOTAL : 760.00

TOTAL : 3,896.16

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE DATE:

Mei Kwan (LKKAuto)

From:

Lucas Lee < lucas.lee@sg.cntaiping.com>

Sent:

Thursday, 31 May, 2018 3:10 PM

To:

Mei Kwan (LKKAuto)

Subject:

RE: Direct Settlement - Accident Involving SDP9818S (OI: CTI - SNM18D02505C02)

and SHC1485S (TP: LKK REF - CC3/CT18009092/K1ea3) on 16/05/2018

Attachments:

leeSZ_SNM18D02505C01-SDP9818S-

LKKDirectSettlementAccidentLtr_CLCR95.551.pdf; MCC418064984-02-SDP9818S.pdf

Follow Up Flag:

Follow up

Flag Status:

Completed

Categories:

HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181 Fax (65) 6222 7175

Email: <u>lucas.lee@sq.cntaiping.com</u> Website: <u>www.sq.cntaiping.com</u>



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, 30 May, 2018 2:39 PM

To: Claims Dept of CTI

Cc: Elaine Cheong; Lucas Lee; Joy Irene (LKKAuto); Hsiao Tong (LKKAuto); Asher Sng (LKKAuto); Admin A Subject: Direct Settlement - Accident Involving SDP9818S (OI: CTI - TBA) and SHC1485S (TP: LKK REF -

CC3/CTI18009092/K1ea3) on 16/05/2018

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHC 1485S at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com



中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #15-00 Springleaf Tower Singapore 079900 Tel: 6389 6111 Fax: 6222 1033 Website: www.sg.cntaiping.com Co. Reg. No. 200208384E

Our Reference: SNM18D02505/C01/8

Date: 31 MAY 2018

via Ordinary & Registered Mail

BANK OF COMMMUNICATIONS CO. LTD. 50 RAFFLES PLACE #18-01, SINGAPORE LAND TOWER SINGAPORE 048623

Dear Sir / Madam

ACCIDENT INVOLVING SDP9818S AND SHC1485S ON 16 MAY 2018 ALONG BATTERY ROAD

We refer to the abovementioned accident.

Please be advised that the third party vehicle, SHC1485S, is filling a third party property claim against your vehicle.

We have appointed LKK Auto Consultants Pte Ltd, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn

ASHER

CC3/CTI18009092/K1EA3

Contact No: 68416051

via Email : ASHER@LKKAUTO.COM

CC : Agent - (DR0378A) - BANK OF COMMUNICATIONS CO., LTD

F01/LKKDS-2013

COMFORTDELGRO ENGINEERING

Our Re	T 0518 / SHC1485S /WT(st)			III	
Your	Ref:	ent	Com	fortDelGro En	gineering Pte Ltd Singapore 579701
Date	: 05-Jun-18 CDGE Taxi Claims De 59 Loyang Drive 4th F		2051		ine +65 6383 6280
CLUMA	INSURANCE CO LTD Singapore 508969			Facsim	llin +65 6280 9755
	ON ROAD				www.cdge.com.5g
J ANS	0 SPRINGLEAF TOWER			Company Fley	Workshops
	APORE 079909				Braddell
	: Motor Claims Department WITHOUT PREJUDICE				205 Braddelf Road Singapore 579701
Deer	Cir	ED S	npo	98185	59 Loyang Drive Singapore 508969
ANID	DENT INVOLVING OUR TAXI SHC1485S YOUR INSURIOTHER				Sin Ming 383 Sin Ming Drive Singapore 575717
AND	to Comfort Transportation Pte L	td, the	own	er of motor	Pandan
Vehic	tle No : SHC1485S which was involved in the objection	and a	utho	rized us to	45 Pandan Road Singapore 609286 Ubl
assis	t them in presenting their claims against the party response	all appli	cable	e matters	320 Ubi Road 3 Singapore 408649
arisin	ig from the damage to the venicle.	SDP9	818		Senoko 24 Senoko Loop Singapore 758158
we a	re submitting these claims for your consideration on seven	laiman	ts.		Sungei Kadul 7 Sungei Kadul Way Singapore 728791
TAX	I OWNER'S CLAIM		\$	4,168.89	Defi
1	Cost of Repair 2 days Loss of Rental @ \$ 117.00 per day		\$	234.00	6 Defu Avenue Singapore 53953
2	Survey Report Fees (Surveyed by M/s LKK)	-	\$ \$	7.49	Yishu
4	LTA Search Fees	-	\$	- 501 YH	thun Industrial Park Singapore 76873
5	GIA / Police Report Fees	3.4	\$		
6	- Land Jack / Transporation Fees	Total:	-	4,410.38	= =
шр	ER'S CLAIM		\$	160.00	
7	days Loss of Income @ \$ 80.00 per days		_	4,570.38	
	Total Cl		Ф	4,570.50	-
	enclose herewith the following documents to support the claims: - Original repair bill and photocopies of photographs:			6	pcs.
a) b)	LTA search slin/s of SDP98183				
c)	GIA / Police report/s of : SHC14855				
d)	the fram owner / hirer / operator	record tors	COMPANIE OF THE PARIE OF THE PA	00	
1000	() Traffic Compound () Towing/Medical bill/receipts () Certification () Photograph/s of Accident Scen (x) Downtime/Mileage record		1.00		letter
soc	dly look into the matter and let us hear from you on the settlement on as possible.	of the s			
300	ase note that it is a condition of any settlement reached that it shall	ll be wit	hou	t prejudice	
Ple to a	any personal injury claim (if any) of the taxi driver.				
Yo	urs faithfully				
De	puty Manager				
CD	GE Claims Department				

A member of







Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg
This is a computer generated letter. No signature is required.



51 UBLANE 1, #61-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Our Ref: CC3/CTI18009092/K1ea3

07 JUNE 2018

BANK OF COMMUNICATIONS CO., LTD 50 RAFFLES PLACE #18-01 SINGAPORE LAND TOWER SINGAPORE 048623

Dear Sir/Madam,

ACCIDENT INVOLVING SDP 9818S AND SHC 1485S ON 16/05/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 day, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: ashersng@lkkauto.com

c.c. China Taiping Insurance (Singapore) Pte Ltd (Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

i 40 SHC1485S , SDP9818S

ON 16-May-18 16:50

ALONG

ALONG BATTERY ROAD, OUTSIDE 9 BATTERY ROAD

I/We

TAN YONG MONG ALAN

(Hirer) NRIC No.:

S1313218F

and/or

(Relief) NRIC No .:

Taxi Number

SHC1485S

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

17-May-2018

Name of Hirer

TAN YONG MONG ALAN

Hirer NRIC

S1313218F

Signature:

200

Address

74 BEDOK NORTH ROAD #09-100

460074

Contact No.

96681101

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN1524151702

Claim No : SNM18D02505C02/8

Claimant : COMFORT TRANSPORTATION PTE LTD

Amount

: \$\$2,258.94

DOLLARS TWO THOUSAND TWO HUNDRED FIFTY EIGHT AND CENTS

NINETY FOUR ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHC 1485S/ Insured Vehicle No. : SDP 9818S

Date of Loss

: 16/05/2018 /

Place of Accident

: BATTERY ROAD OUTSIDE 9 BATTERY ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE, LTD, and/or

Insured Name

: BANK OF COMMUNICATIONS CO, LTD

Driver Name

: TOH HENG SYE

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

A Charles Stormer Stormer (Annalysis (Annalysis (Annalysis Annalysis	g ĝ	
(1) General Damages	ss 2,084.45	
2) Cost of Repair/Excess	55 2,004,45 /	
 Loss of Use/Rental/Earning 	s\$ 167.00	
4) GIA/Police Reports/	S 728 321 V	
Investigation Results/Search Fees	ss 7.49	
5) Medical Reports/Expenses	S\$ 7.49 S\$ S\$	
	SS	
6) Survey Fees/P.T. Fees	88	
7) Cost including Disbursement	54	
	2 2 25 24	
TOTAL	S\$ 2,258.94	

Claimant Name: COMFORT TRANSPORTATION FIE LTD

NRIC No :

Signature

DOMESTICATION SHOW THE PRESTA 59 COYANG DHUSE

SINGAPORE SORRER

the contents or this document exply to vehicle damages only All personal injuries and damages arising therefrom are excluded from the ambit and application of this document

Please forward your cheque made payable to. COMFORTDELGRO ENGINEERING PTE ITO



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3 TA

ComfortDelGro Engineering Pte Ltd 205 Britanii Roan Singapore 579701 Munime + 65 6383 6280 Finctionis - 05 6200 0755

Morkuhopa

Workuhopa

58 Layang Drive Bingalpote 578788

58 Layang Drive Bingalpote 578787

78 Sangal Kadul Way Singalpote 7887

79 Sangal Kadul Way Singalpote 7887

70 Sangal Kadul Way Singalpote

X INVOICE	COMPANY	REG.	NU. :	1995060 Pade

S010012 CHINA TAIPING INSURAN. EPRINGLEAF TOWER 3 ANSON HOAD #16-00 INGAPONE SO 079908	CE CO(S) PPE L	VEHCLE SHC148: MAKE EYUNDAI	S	INV. NO 91375046 JOB NO. 30516145	/DATE 30.05.2018
CONTACT NO: 62222366		MODEL I-40		GDOMETRI	READING
Description : 3P 15.05	5.18	CHASSI	F REG 2017 S CODR UMHUU9855S		E IN DIS 10:10
Sillo Part No.		Qty	Unit Price	Albase	Net
PART ENQUISITION					
0001 04-01-0103-2322 0002 04-01-0103-2164	140V3 BUMPER W LIP & FOG 140V3 GRILLE ASSY-RADIATO 140V2 LAMP ASSY-HEAD RH#	1	1,052.20 1,480.00 1,388.00	20.00 20.00	1,410,40
JOB NATURE					

ODDI	I.	PANEL BEATING	400.00	400.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	360.00	360.00

SUB-TOTAL 760.00

mfortDelGro Engineering Pte Ltd tember of COMFORTDUIGNO

id Office: Braddell Road gapore 579701

3ly note that no receipt shall be issued unless requested.

STOMER'S COPY

INVOICE No.	AMOUNT	BANK/CHQ No.
91375046	4,168.89	
		of the same
		91375046 4.168.89



A member of ComfortDelgro

GST REG. NO. M2-8921817-3

AMSUN ROAD #16-00 INCAPORE 38 079909

CONTACT NUMBER 52222366

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singspore 578701 Maintine = 85 6383 6280 Facalitie = 65 6290 3780

SP Loyang Orize Singapore 509059 383 Shi Ming Orize Singapore 579717 45 Pander Road Singapore 908098 300 Ulfr Plant & Singapore 408048

COMPANY REG. No.: 199506048W

Page: 2

VEHCLE NO

INV. NO/DATE 91375046 30.05.2018

SHC14858

HYUNDAI

JOB NO. 305161453

MODEL I-40

COMMETER READING

DATE OF REG 25.01.2017

DATE/TIME IN 17.05.2016 10:10

CHASSIS CODE NUMBLE 41UMHU098558

Items total

3,896,16

Add GST 8

7.000 %

272.73

Invoice ascunt

4,168.89

CHEWBEELENG 30.05.2018 09:48:39 CLSO/57/57

Issued by : CHEWBEELENG 30. Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

CHINA TAIPING INSURANCE CO(S) PTE L

mfortDelGro Engineering Pte Ltd lember of COMFORTDELGILO

id Office: Braddelf Road gapore 579701

tly note that no receipt shall be issued unless requested.

STOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91375046	4.168.89	
Dec - 1995			

Our Ref: CT18050443

Date: 23 May 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

16/05/2018 @ 16:50 hrs

ALONG

ALONG BATTERY ROAD OUTSIDE 9 BATTERY ROAD

INVOLVING

SDP9818S

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC1485S (the "Taxi"). The Taxi was hired to TAN YONG MONG ALAN IC NO S1313218F a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$117.00 per day (inclusive of GST).

Please be advised that the Taxi was insured with India International Insurance Pte Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

O. TSEW CHASEN HOURS OPERATED (TIME) 2300 0890 0101 0650 FROM MILEAGE TRAVELLED (KM) 137 032113 234850 repair Kradem NAME OF DRIVER 3 16/5/18 DATE 1800 Sas HOURS OPERATED (TIME) 0362 FIES 0840 (887 0630 19m 1900 0750 000 000 8,00 1800 ras/ FROM 150 Jan MILEAGE TRAVELLED (KM) 24 335 83 540

100

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SDP98185 16 May 2018 / 16:50:00 Successful

C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHI	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI18009	092/K1ea3q2
	NSON ROAD #16-I RINGLEAF TOWER	00 RSINGAPORE 079909	Date : 23-08-2018 Code : CTI	
1.		Policy Particula	ars :- THIRD PARTY CLA	IM .
	Insured Veh.	SDP 9818S	Veh. Inspected	SHC 1485S
	Policy No.	DMPCSN1524151702	Coverage (\$)	0.00
	Claim No.	SNM18D02505C02/8	Excess (\$)	0.00
	Assign From		Assign Date	17/05/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	HYUNDAI 140	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KMHLB41UMHU098558	Colour	BLUE
	Odometer	234980	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	HANKOOK	7 mm
	L/H Front Tyre	205/60 R16	HANKOOK	7 mm /
	R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
	L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
k.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S FRONT PORTION.	
	DAMAGES SEE D	ETAILS.	<u> </u>	
5.		Gene	eral Information	
	Accident Date	16/05/2018	Inspection Date	17/05/2018
	Survey held at	COMFORTDELGRO ENGINE	EERING PTE LTD	
		59 LOYANG DRIVE SINGAPORE 508969		
ia.	SIN REVIEW		Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"	WE HAVE NOT AUTHORIS	SED REPAIRS
5b.	TE THE SERVICE STATES		ate Days of Repair	A PART HIND
100	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Day	16



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1485S.

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			- 338
1	RADIATOR GRILLE	CRACKED	1,480.00	1,480.00
1	FRONT BUMPER COVER	CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	SERVICEABLE	142.20	
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	526.10	
1	FRONT BUMPER GRILLE (RH)	SERVICEABLE	285.50	
1	FRONT BUMPER GRILLE AIRDUCT (RH)	SERVICEABLE	155.00	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	SERVICEABLE	44.80	
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	SERVICEABLE	49.20	
1	HEADLAMP (RH)	GRAZED	1,388.00	1,388.00
1	FRONT FENDER (RH)	TO REPAIR SEE LABOUR	619.00	
1	FRONT FENDER SHIELD (RH)	SERVICEABLE	169.80	
1	FRONT FENDER RETAINER	SERVICEABLE	9.20	
	LESS 20% DISCOUNT		-1,184.20	-784.04
			4,736,80	3,136.16
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER (RH).		560.00	400.00
	SPRAY PAINTING CHARGE.		400.00	360.00
	TUFF KOTE:	NOT NECESSARY	50.00	
			1,010.00	760.00
	GRAND TOTAL		5,746.80	3,896,16

RECOMMENDED COST OF REPAIRS	3.896.10
-----------------------------	----------

Report Ref No. CC3/CTI18009092/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tert, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.