

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping (P/P) TS
 DATE 17/5/2018

VEHICLE NO : SHC 1485S

MAKE :

MODEL : HYUNDAI i40

LKK-Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille — <i>one</i>			\$ 1,480.00
	Front Bumper Cover — <i>one</i>			\$ 1,052.20
	Front Bumper Sponge <i>X 500</i>			\$ 142.20
	Front Bumper Reinforcement <i>X 500</i>			\$ 526.10
	Front Bumper Grille (RH) <i>X 500</i>			\$ 285.50
	Front Bumper Grille Airduct (RH) <i>X 500</i>			\$ 155.00
	Front Bumper Bracket Top (LH/RH) <i>X 500</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>X 500</i>		\$ 24.60	\$ 49.20
	Headlamp (RH) — <i>bracket</i>			\$ 1,388.00
	Front Fender (RH) <i>X repair</i>			\$ 619.00
	Front Fender Shield (RH) <i>X 500</i>			\$ 169.80
	Front Fender Retainer <i>X 500</i>			\$ 9.20
	SUB TOTAL			\$ 5,921.00
	LESS 20%			\$ 1,184.20
	DISCOUNTED TOTAL			\$ 4,736.80
	Labour Charge			
	Panel Beating			\$ 560.00 <i>400</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	TOTAL LABOUR			\$ 1,010.00
	ESTIMATE TOTAL			\$ 5,746.80
<i>Kalvin 16/11/14</i> <i>17/5/18 1510 hrs.</i> <i>2 R/s</i> <i>P/P</i> <i>Before part photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				