

Surveyor

Sebastian

ASSIGNMENT (Office)

CWS

From (Person)

May Chua

of

FCI

Date/Time: 18/05/18 @ 4:26pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 9188P

Insured:

SHC 2970B

at Workshop m/s

World Auto

Tel:

63 62 1776

of

47 Jalan Pemimpin #01-02/03

Policy No:

Claim No:

D18003945MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/05/2018

CA / REV / REP. / REV 24 HRS

(wp)

Insp: No. 1 Kranji Twp @ 21/5/18

H.O.D. Endorsement:

Date/Time:

5:11pm @ 18/5/18

Person Contacted:

Ainee

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 9188P-X
	SHC 2970B- NS/INC17006538/H1/bs4
	DOA: 24/3/17
23/5/18	Email preli revised to FCI
27/5/18	Final fig \$ 5922 confirmed by email (Real 5114, 4610)

REF: FEL

INSURANCE

Form Date 21/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLK 9188P
World Auto

at Workshop no:

1 Kranji Loop

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Vehicle No SLK 9188P

Yr Regn 5/8/2016

Type Motor / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Honda Shuttle

cc 1496

Colour Black

A/C Insured / Std / NI / NA

Sp Reading 133088

T/Radio Insured / Std / NI / NA

Eng/No:

C/No: GK8 / 602710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 185/60 R15

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/5/18

D.O.A. 2/5/18

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 2 JUL 2018

Date/Time File Passed to:



Preli. Report

if:



Final Report

Date/Time File Returned to:

2/7 - typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

J. S. P. S. S.

J. S. P. S. S.

J. S. P. S. S.

J. S. P. S. S.

J. S. P. S. S.

Report Format:

CWS

Lump Sum / L.B.P.:

59221/2

Add Fee:



Site Insp. 15



Interview 15



Tech. Insp. 15



Photocopy 15

170+15

50

50

46

331



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009096/Svd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2970B	Veh. Inspected	SLE 9188P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003945MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/05/2018	Inspection Date		
Survey held at	NO.1 KRANI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18003945MFSH
Our ref: CS/FCI18009096/Svd3

Date: 23/5/2018

The Motor Claims Department
M/s First Capital Insurance Limited

Without Prejudice

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 9188P


We thank for your instruction on 18/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 21/5/2018 at the premises of M/s WORLD AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,036.00
Revised Estimate Amount	: S\$5,922.00
"Check" Items Amount	: S\$2,792.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

YEANG WAI KEEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-05-2018	Our Ref No. D18003945MFSH
Accident Date	14-05-2018	Claim Type. Third Party
Insured Vehicle	SHC2970B	Third Party Vehicle. SLE9188P
Survey Location	47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG	
Contact Person.	AINEE	
Contact No.	64513933/ 63621776	Fax No. 64557576
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240451)



PRI Documents



Close



PRI Header Details

Claim No	D18003945MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WORLD A
Workshop Name	WORLD AUTO PTE LTD (Contact Person : AINEE)	Survey Location & Contact Details	47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG Mobile: 63621776 , Phone: 64513933 , Fax: 64557571 EmailId: AINEE31@WORLD AUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2970B	TP Vehicle No	SLE9188P
PRI Recieved Date	17-05-2018 03:14:48 PM	Surveyor Appointed Date	18-05-2018 04:25:19 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-05-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 May 2018 9:26 AM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003945MFSH/1, SLE 9188P
Attachments: SLE 9188P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLE 9188P
Date of survey: 21/5/2018
Number of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 18 May 2018 5:15 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003945MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 18 May 2018 4:25 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003945MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 2 July 2018 2:40 PM
To: 'tggtan@worldauto.com.sg'
Cc: SUR
Subject: RE: SLE9188P Our ref: TP/2022/18

Dear Sophia,

Noted with thanks.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg [mailto:tggtan@worldauto.com.sg]
Sent: Monday, 2 July 2018 2:37 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SLE9188P Our ref: TP/2022/18

Hi Veron

Finalised COR @ \$5922 and 6 working days.

Rdgs

Sophia Tan

World Auto Pte Ltd (Kranji)

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 29 June 2018 3:19 PM
To: tggtan@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLE9188P Our ref: TP/2022/18

Dear Sophia,

WITHOUT PREJUDICE

Finalize amount \$5922/- before GST @ 6 working days

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg [mailto:tggtan@worldauto.com.sg]

Sent: Monday, 25 June 2018 6:08 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: SLE9188P Our ref: TP/2022/18

Hi Veron

Attach b/f paint photos for your attention.

Kindly revert with your finalisation.

Rdgs

Sophia Tan

World Auto Pte Ltd (Kranji)

From: Ainee31 <ainee31@worldauto.com.sg>

Sent: Monday, 25 June 2018 5:54 PM

To: SOPHIA <tggtan@worldauto.com.sg>

Subject: SLE9188P

Ainee

Thanks and Rgds,

World Auto Pte Ltd

Kranji: 63621776

Fax: 64557576

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSURANCE LIMITED
 80 ROBINSON RD #09-02/03
 068898

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000128

Date : 16/05/2018
 Vehicle Num. : SLE 9188P (LCR)
 Make/Model : HONDA SHUTTLE
 Chassis/Eng# :
 Accident Date : 14/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID ✓DT		1,150.00 ✓DT
2.	1	REAR WINDSCREEN GLASS MOULDING ✓NEC		250.00 ✓NEC
3.	1	REAR BOOT LOCK ASSY ✓JM		260.00 ✓JM
4.	1	REAR BOOT HAND GRIP COVER ?		100.00 X }
5.	1	REAR BOOT NUMBER PLATE MOULDING ✓Deform X		250.00 X } NN
6.	1	REAR BOOT INNER TRIM BOARD ?		250.00 X }
7.	1	REAR BOOT WEATHER STRIP ✓Deform		180.00 ✓Deform
8.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) ✓NEC		100.00 ✓NEC
9.	1	REAR BOOT 'H' LOGO ✓Q NEC		150.00 ✓NEC
10.	2 (LH&RH)	REAR BOOT REFLECTOR LAMP ?	720.00	1,440.00 X }
11.	2 (LH&RH)	REAR TAIL LAMP ?	850.00	1,700.00 X }
12.	1	REAR BUMPER ✓Deform		1,100.00 ✓Deform
13.	1	REAR BUMPER TOW COVER ✓MS		120.00 ✓MS
14.	2 (LH&RH)	REAR BUMPER REFLECTOR GARNISH X	150.00	300.00 X }
15.	2 (LH&RH)	REAR BUMPER REFLECTOR LENS X	120.00	240.00 X }
16.	1	REAR END PANEL ✓Deform		950.00 ✓Deform
17.	1	REAR END PANEL TOP GARNISH ✓Deform		260.00 ✓Deform
18.	1	REAR COMPARTMENT BOX ✓Deform		420.00 ✓Deform
19.	1	REAR COMPARTMENT BOX BACK COVER X		160.00 X NN
20.	1	REAR WIPER CAP ✓MS		25.00 ✓MS
21.	1 LH	REAR BOOT ABSORBER X		190.00 X NN
List Total S\$:				9,595.00
20.00% Discount S\$:				1,919.00
				7,676.00

SPECIAL NETT ITEMS :

1. 1 REAR BOOT INNER TRIM BOARD CLIP ✓NEC 30 50.00 ✓NEC

CONTINUE / ...

Sebastian.
 21/5/18.
 - Part by part repair.
 - Question Mark Item
 Photo
 - Photo Before Paint
 23/5/18

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000128

Date : 16/05/2018

Vehicle Num. : SLE 9188P (LCR)

Make/Model : HONDA SHUTTLE

Chassis/Eng# :

Accident Date : 14/05/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR BUMPER CLIP ✓ NEC	30	50.00 ✓ } NEC
3.	1	REAR END PANEL TOP GARNISH CLIPS ✓ NEC	30	50.00 ✓ } NEC
4.	1	REVERSE SENSOR ✓ DMG	200	280.00 ✓ DMG
5.	1	REAR NUMBER PLATE X		50.00 XNN
6.	1	REAR WINDSCREEN SEALANT ✓ NEC	60	120.00 ✓ NEC
Special Nett Total S\$:				600.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				120 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				80 180.00
LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.				800 1,400.00
PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)				600 1,000.00
Labour Total S\$:				2,760.00

E. & O.E.

Total S\$:

11,036.00

=====

for WORLD AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009096/Vvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2970B	Veh. Inspected	SLE 9188P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18003945MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GK81002710	Colour	BLACK	
Odometer	133088	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	PIRELLI	6 mm	
L/H Front Tyre	185/60 R15	PIRELLI	6 mm	
R/H Rear Tyre	185/60 R15	PIRELLI	6 mm	
L/H Rear Tyre	185/60 R15	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/05/2018	Inspection Date	21/05/2018	
Survey held at	NO.1 KRANI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 9188P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	1,150.00	1,150.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	250.00	250.00
1	REAR BOOT LOCK ASSY	JAMMED	260.00	260.00
1	REAR BOOT HAND GRIP COVER	NOT NECESSARY	100.00	-
1	REAR BOOT NUMBER PLATE MOULDING	NOT NECESSARY	250.00	-
1	REAR BOOT INNER TRIM BOARD	NOT NECESSARY	250.00	-
1	REAR BOOT WEATHER STRIP	DEFORMED	180.00	180.00
1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	NECESSARY	100.00	100.00
1	REAR BOOT "H" LOGO	NECESSARY	150.00	150.00
2	REAR BOOT REFLECTOR LAMP LH & RH @\$720.00	NOT NECESSARY	1,440.00	-
2	REAR TAIL LAMP LH & RH @\$850.00	NOT NECESSARY	1,700.00	-
1	REAR BUMPER	DEFORMED	1,100.00	1,100.00
1	REAR BUMPER TOW COVER	MISSING	120.00	120.00
2	REAR BUMPER REFLECTOR GARNISH LH & RH @\$150.00	NOT NECESSARY	300.00	-
2	REAR BUMPER REFLECTOR LENS LH & RH @\$120.00	NOT NECESSARY	240.00	-
1	REAR END PANEL	DEFORMED	950.00	950.00
1	REAR END PANEL TOP GARNISH	DEFORMED	260.00	260.00
1	REAR COMPARTMENT BOX	DEFORMED	420.00	420.00
1	REAR COMPARTMENT BOX BACK COVER	NOT NECESSARY	160.00	-
1	REAR WIPER CAP	MISSING	25.00	25.00
1	REAR BOOT ABSORBER LH	NOT NECESSARY	190.00	-
	LESS 20% DISCOUNT		-1,919.00	-993.00
			7,676.00	3,972.00
SPECIAL NETT ITEMS				
1	REAR BOOT INNER TRIM BOARD CLIP (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/FCI18009096/Vvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
			600.00	350.00
	LABOUR			
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	80.00
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,400.00	800.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		1,000.00	600.00
			2,760.00	1,600.00
GRAND TOTAL			11,036.00	5,922.00
RECOMMENDED COST OF REPAIRS				5,922.00

Report Ref No. CS/FCI18009096/Vvd3n2

SATHYA SAI KATHIRRASEN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.