

15/07/2018

/NS CASE OWNER:

CC 4 / III1800

9122

Miha39

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: \$14

SS \$1,721.84 (5 days) Reduction: 59 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: \$1,721.84

SS \$1,721.84

COW FROM WIMOR ROAD

Loss of Rental (LOR):

SS \$600.00 (6 days) X \$100

Loss of Use (LOU):

SS \$ (5 x days)

Loss of Income (LOI):

SS \$ (5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/TA Search

SS \$36.45

Medical:

SS \$-

Disbursement:

SS \$-

Legal Cost

SS \$-

(e.g. Tow/ independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$500.00

Total:

SS \$6,750.81

Global Sum SS:

\$6,750.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS \$6,750.00

Name 1:

BH AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS \$-

Name 2:

-

Payee 3: (Strike if N.A.)

SS \$-

Name 3:

-

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / CO RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

ID&C Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

5

days

Res: _____

Yes or No

Lum Sum: _____

-

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SLX6631C Yr Regr: April 2018
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI

130

Colour: Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 2441

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: TUAAH3534308822Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: Nil / STD A/Rim or

Tyre Size: F: _____

R: _____

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXISFront: 8Rear: 8

R/Bal: _____

mm

R/Bal: _____

mm

L/Bal: _____

mm

L/Bal: _____

mm

D.O.A: _____

D.O.I: 15PM

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

OS BODY

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

P/P 25.7.21.86

CRPD: \$ 8,883.54 (69%)

WV: \$ 97,000.00 (net).

LTH: \$ 47,196.00 (net)

Nett: \$ 49,804.00 (net)

Date/Time, File Pass to?

☐

: Preli. Report

11

☐

: Final Report

Date/Time, File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Disruption:

Y. 2021 9

[2000]

Y. 2021

[1000]

Total:

Report Format :

Lump Sum / I.B. is:

Add Fee:

☐

Site Insp: 15

☐

Interview: 15

☐

Tech. Insp: 15

☐

Weekend: 15



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199807198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18009122/M1ha3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-05-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2202K	Veh. Inspected	SLX 6031C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/05/2018	Inspection Date	17/05/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLX6031C

MODEL : HYUNDAI I30

POLICY NO : CN885543

CHASSIS NO : TMAH3513VJJ063822

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD

THIRD PARTY VEHICLE NO : SHC2202K

Date: 17/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Rear Fender RH X <i>tl</i>	1	1830.10		1,830.10
2 Rear Fender Shield RH X <i>tl</i>	1	311.95		311.95
3 Rocker Panel X <i>tl</i>	1	2281.57		2,281.57
4 Rear Door RH <i>dentado</i>	1	1819.70		1,819.70
5 Rear Door Upper Hinge RH <i>nec</i>	1	46.00		46.00
6 Rear Door Lower Hinge RH <i>nec</i>	1	36.10		36.10
7 Rear Door Window Glass RH X <i>3 un</i>	1	381.70		381.70
8 Rear Door Quarter Glass RH X <i>3 un</i>	1	365.90		365.90
9 Rear Door Quarter Glass Moulding RH <i>nec</i>	1			217.50
10 Rear Door Weatherstrip RH <i>nec</i>	1	266.90		266.90
11 Rear Door Frame Sticker/Garnish RH <i>nec</i>	2	12.00		24.00
12 Rear Door Window Glass Outer Moulding Chrome RH <i>nec</i>	1	89.10		89.10
13 Front Door RH <i>dentado</i>	1	1723.60		1,723.60
14 Front Door Upper Hinge RH X <i>3 un</i>	1	41.10		41.10
15 Front Door Lower Hinge RH X <i>3 un</i>	1	36.70		36.70
16 Front Door Window Glass RH X <i>3 un</i>	1	421.90		421.90
17 Front Door Frame Sticker/Garnish RH <i>nec</i>	1	12.00		12.00
18 Front Door Weatherstrip RH <i>nec</i>	1	266.90		266.90
19 Front Door Glass Window Outer Moulding Chrome RH <i>nec</i>	1	108.00		108.00
20 Front Door Lock Assy X <i>un</i>	1	201.20		201.20
21 Front Door Inner Trim X <i>un</i>	1	1794.80		1,794.80
22 Rear Windscreen Moulding X <i>un</i>	1			

Sub-Total: 12,059.22

Less Discount 20% 2,411.84

Total Parts: 9,647.38

4609.80

20%

3687.24

Special Nett Items

1 Anti-rust coating	4	80.00	80	320.00	<i>nec</i>
2 Front Door Inner Trim Clips	10	4.00		40.00	<i>nec</i>
3 Rear Fender Shield Clips <i>un</i>	10				
4 Rear Windscreen Sealant	1	100.00	\$120	X 100.00	<i>un</i>

Total Parts: 460.00

Labour Charges For Front and Side Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Remove and refit rear windscreen
- 5 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs
- 6 Remove and refit/replace window glass
- 7 Dismantle and transfer door fittings and mechanism to new door/facilitate repairs

Total Labour:

\$1810

Total Parts & Labour:

GST 7%

Grand Total:

~~2,000.00~~ 800

~~1,000.00~~ 800

30.00

180.00 X

~~150.00~~ 60

X ~~180.00~~ 120

180.00 120

3,720.00

13,827.38

967.92

14,795.29

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SLX6031C

Page : 2 of 2

14,105.34

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

Contact No: _____

Email : _____

Not Anthony
PIP Repair
Before PIP Photo
17/5/2018
SW days
Ck Auto MA

Part : \$3687.84 + \$104 (Sup)

S/N : \$120.00

Labour : \$1810

Total : \$5721.84

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

SUPPLEMENTARY

ACCIDENT REPAIR ON : SLX6031C

MODEL : HYUNDAI I30

POLICY NO : CN885543

CHASSIS NO : TMAH3513VJJ063822

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD

THIRD PARTY VEHICLE NO : SHC2202K

Date: 05/07/2018

Page : 1 of 1

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N		Quantity	Unit Price S\$	Condition	Amount S\$	
1	Front door upper moulding chrome RH	1	75.00	Necessary	75.00	✓
2	Rear door upper moulding chrome RH	1	55.00	Necessary	55.00	✓
Sub-Total:					130.00	
Less Discount 20%					26.00	
Total Parts:					104.00	

130 - 20%
= 104

Special Nett Items

1	-
2	-
	-
	-
Total Parts:	-

Labour Charges For Front and Side Portion

Total Labour:

Total Parts & Labour:	104.00
GST 7%	7.28
Grand Total:	111.28



BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLX6031C
MODEL : HYUNDAI I30
POLICY NO : CN885543
CHASSIS NO : TMAH3513VJJ063822
MANUFACTURING YEAR : 2018
DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD
THIRD PARTY VEHICLE NO : SHC2202K

Date: 17/05/2018
Page: 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
1	1	1830.10		1,830.10
2	1	311.95		311.95
3	1	2281.57		2,281.57
4	1	1819.70		1,819.70
5	1	46.00		46.00
6	1	36.10		36.10
7	1	381.70		381.70
8	1	365.90		365.90
9	1	266.90		266.90
10	1	12.00		24.00
11	2	12.00		24.00
12	1	89.10		89.10
13	1	1723.60		1,723.60
14	1	41.10		41.10
15	1	36.70		36.70
16	1	421.90		421.90
17	1	12.00		12.00
18	1	266.90		266.90
19	1	108.00		108.00
20	1	201.20		201.20
21	1	1794.80		1,794.80
22	1			
Sub-Total:				12,059.22
Less Discount 20%				2,411.84
Total Parts:				9,647.38

Special Nett Items

1	Anti-rust coating	4	80.00	80	320.00
2	Front Door Inner Trim Clips	10	4.00		40.00
3	Rear Fender Shield Clips	10			
4	Rear Windscreen Sealant	1	100.00	\$120	X 100.00

4609.80
- 20%
3687.84

Total Parts: 460.00

Labour Charges For Front and Side Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Remove and refit rear windscreen
- 5 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs
- 6 Remove and refit/replace window glass
- 7 Dismantle and transfer door fittings and mechanism to new door/facilitate repairs

2,000.00 800

1,000.00 800

30.00

180.00 X

150.00 60

X 180.00 120

180.00 120

Total Labour:

\$1810

Total Parts & Labour:

3,720.00

GST 7%

13,827.38

Grand Total:

967.92

14,795.29

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SLX6031C

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

Contact No: _____

Email : _____

Not Anthony
PIP Repair
Before PIP Photo
17/5/2018
5w days
LKK Auto (MA)

Part: \$3687.84 + \$104 (Supp)

S/N: \$120.00

Labour: \$1810

Total: \$5721.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

SUPPLEMENTARY

ACCIDENT REPAIR ON : SLX6031C

MODEL : HYUNDAI I30

POLICY NO : CN885543

CHASSIS NO : TMAH3513VJJ063822

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD

THIRD PARTY VEHICLE NO : SHC2202K

Date: 05/07/2018

Page : 1 of 1

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front door upper moulding chrome RH	1	75.00	Necessary	75.00
2 Rear door upper moulding chrome RH	1	55.00	Necessary	55.00
			Sub-Total:	130.00
			Less Discount 20%	26.00
			Total Parts:	104.00

130 - 20%
= 104

Special Nett Items

1

2

Total Parts: -

Labour Charges For Front and Side Portion

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

104.00

7.28

111.28

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLX6031C

MODEL : HYUNDAI I30

POLICY NO : CN885543

CHASSIS NO : TMAH3513VJJ063822

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD

THIRD PARTY VEHICLE NO : SHC2202K

Date: 17/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Rear Fender RH X	1	1830.10		1,830.10
2 Rear Fender Shield RH X	1	311.95		311.95
3 Rocker Panel X	1	2281.57		2,281.57
4 Rear Door RH ✓	1	1819.70		1,819.70
5 Rear Door Upper Hinge RH ✓	1	46.00		46.00
6 Rear Door Lower Hinge RH ✓	1	36.10		36.10
7 Rear Door Window Glass RH X	1	381.70		381.70
8 Rear Door Quarter Glass RH X	1	365.90		365.90
9 Rear Door Quarter Glass Moulding RH ✓	1			-
10 Rear Door Weatherstrip RH ✓	1	266.90		266.90
11 Rear Door Frame Sticker/Garnish RH ✓	2	12.00		24.00
12 Rear Door Window Glass Outer Moulding ✓				-
Chrome RH	1	89.10		89.10
13 Front Door RH ✓	1	1723.60		1,723.60
14 Front Door Upper Hinge RH X	1	41.10		41.10
15 Front Door Lower Hinge RH X	1	36.70		36.70
16 Front Door Window Glass RH X	1	421.90		421.90
17 Front Door Frame Sticker/Garnish RH ✓	1	12.00		12.00
18 Front Door Weatherstrip RH ✓	1	266.90		266.90
19 Front Door Glass Window Outer Moulding ✓				-
Chrome RH	1	108.00		108.00
20 Front Door Lock Assy 7	1	201.20		201.20
21 Front Door Inner Trim X	1	1794.80		1,794.80
22 Rear Windscreen Moulding X	1			-
Sub-Total:				12,059.22
Less Discount 20%				2,411.84
Total Parts:				9,647.38

Special Nett Items

1 Anti-rust coating	4	80.00	80	320.00
2 Front Door Inner Trim Clips	10	4.00		40.00
3 Rear Fender Shield Clips	10			-
4 Rear Windscreen Sealant	1	100.00	X	100.00

Total Parts: 460.00

Labour Charges For Front and Side Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Remove and refit rear windscreen
- 5 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs
- 6 Remove and refit/replace window glass
- 7 Dismantle and transfer door fittings and mechanism to new door/facilitate repairs

2,000.00 800
1,000.00 800
30.00
180.00 X
150.00 60
X 180.00 120
180.00 120

Total Labour:

3,720.00

Total Parts & Labour:

13,827.38

GST 7%

967.92

Grand Total:

14,795.29

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SLX6031C

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : _____

Company : _____

Date : _____

Time : _____

Contact No: _____

Email : _____

Not Anthony
PIP Repair
Before Paint/Plat
17/5/2018
5w days
UK Auto (M)

Print Received Message

This mail is associated with :

***SLX6031C (MCT18050249)**

[SHC2202K]

TP

TAN SOK FERN

May 10 2018 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

BH Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/01/2019 09:57 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6758.82) - SLX6031C - Claim Handler: Sherini Pillai

Approved:6758.82.

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SHC2202K

Our Reference: SLX6031C

Date: 23/01/2019

M/s India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

BY POST & EMAIL

Attention: Claims Department

CLAIMANT: TAN SOK FERN

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 10/05/2018 ALONG TANGLIN ROAD INVOLVING VEHICLE NO SLX6031C & SHC2202K

We act for **TAN SOK FERN** who was the owner of motor vehicle no. **SLX6031C**

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 10/05/2018 involving our client's vehicle registration number SLX6031C and vehicle registration number SHC2202K, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 6122.36
2	Loss of Rental (06days x \$120.00)	\$ 720.00
3	LTA Search Fee	\$ 36.45
	Total :	\$ 6878.81

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,



Yun Shi

(O): 6559 8944 (F): 6269 2404

Email: yunshi.chan@bhauto.com.sg

AUTHORISATION

Name of owner of m/vehicle: Tan Sok Fern (Chen Shufen)
Address: BK 820 Vishnu St #1 A07-850 S (760820)
NRIC No: S7108069B
RE ACCIDENT ON 10/05/18 ALONG Tanglin Road
INVOLVING SLX 6031C Y8 SHC2202K

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no SLX6031C at my/our request, I/We the abovenamed owner of motor vehicle no. SLX6031C hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop

Date this 10 (day) of 05 (month) 18 (year)

Signed: 

Owner of m/vehicle: Tan Sok Fern SLX 6031C

HP: 96396317

Witnessed: 

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18050249
Claimant Ref: SLX6031C

We, BH AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 6,750.00 (Global Sum - all in) (loss of incremental) S\$ --- (search fee), vehicle no SLX6031C that was damaged pursuant to the accident which occurred on 10/05/2018 (date) at TANGLIN ROAD (location) involving vehicle no SHC2202K insured vehicles. This is pursuant to the inspection conducted on 17/05/2018 (date) at the workshop.

We confirm that we/ we/ian authorized by the owner TAN SOK FERN (CHEN SHUFEN) ("the third party claimant") of vehicle no SLX6031C make the claim as set out in the above paragraph and we/ we/ian have full authority to settle the matter on his/her behalf in a manner that we/ we/ian deem fit. We/ we/ian enclose herein the letter of authority given by "the third party claimant".

We/ we/ian further confirm that we/ we/ian will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLX6031C vehicle no. 1 as a result of the accident.

We/ we/ian confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/ we/ian authorize you to pay the total amount of S\$ 6,750.00 to BH AUTO SERVICES PTE LTD

Dated this 13 day of March 2019

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by "the workshop" (MCT)
GUAN YUN SHU
97674078Q
BH Auto Services Pte Ltd
Blk 1 Sin Ming Industrial Estate
Sector C #01-111/113/115/117
Singapore 575636
Admin

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Uct
Signed by appointed Surveyor
LKK AUTO CONSULTANTS PTE LTD
199607198R
51 UBI AVENUE 1 #01-25
PAYA UBI INDUSTRIAL PARK (S) 408933

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: SLX6031C

Date: 23/01/2019

M/s India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

BY POST & EMAIL

Vehicle No : **SLX6031C**
Make/ Model : **HYUNDAI I30**
Year of Manufacture : **2018**
Chassis No. : **TMAH3513VJJ063822**
Colour : **BLUE**
D.O.A : **10/05/2018**


QTY	ITEM/PARTICULARS	AMOUNT (\$S)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. **SLX6031C**
Type of repair: Part By Part :SS 5721.84

GST @ 7% : SS 400.52

GRAND TOTAL:SS 6122.36

Total : Singapore Dollars Six Thousand One Hundred Twenty Dollars and Thirty-Six Cents Only.


Company's Stamp & Signature

B & O VEHICLE RENTAL

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)

Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000

Reg. No: 53060835M

TOWING SERVICE: 6858 4067 (After 10.30 pm)

HYUNDAI 130.

车辆出租合同 VEHICLE RENTAL AGREEMENT

SLX6031C

Date: 25/6/18
Owner: B & O VEHICLE RENTAL ("the owner")
Hirer: chin chao Ming Lawrence
NRIC / Co. Reg. No: S8712356A
Tel: Fax: H/P: 9776 5131
Address: 8, soo chow way Singapore 575309.

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SGB PONT D		Agreement No.: 18294	
Driver's Particulars		Odometer:	
Name: Chin Chao Ming, Lawrence		Date & Time Out: 25/6/18	
Address: 8 Soo chow way Singapore 575309		Date & Time In: 6/7/18	
I/C No: S8712356 A	Dr/Licence No: S8712356 A	Hour @\$	
Date of Issue: 21/04/2006	Occupation: indoor	11 Days @\$ 20k	
Date of Birth: 14/05/1987	Tools: Spare Tyre: 060 one set	Wks @\$	
		Mths @\$	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 3000/- comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$ 3000/- excess for collision/damage to first party, (i.e.) B & O VEHICLE RENTAL (including windscreen) plus loss of earnings while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable):

Sub-Total:

Balance To Pay: 1320

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

B & O VEHICLE RENTAL

Authorised Signature

Hirer's Signature

Unit 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000
Reg. No: 53060835M
TOWING SERVICE: 6858 4067 (After 10.30 pm)

新華及華通
河車修運
保造附性
代運保險
買貨車
理車將
中心

Date 6/7/18

E. & O. E.

for B & O VEHICLE RENTAL

L

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-072846

Date of Request: 14/05/2018

Your Ref No:

Online Purchase

BH Auto Services Pte Ltd
Blk 1 Sin Ming Industrial Estate Sector C
#01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Date of Accident: 10/05/2018
Vehicle No: SLX6031C
Place of Accident: TANGLIN ROAD
Involving Vehicle No: SHC2202K

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHC2202K	TANGLIN ROAD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-072843
Date of Request: 14/05/2018

Your Ref No: Online Purchase

BH Auto Services Pte Ltd
Blk 1 Sin Ming Industrial Estate Sector C
#01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 10/05/2018
Place of Accident: TANGLIN ROAD
Client Vehicle No: SLX6031C

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHC2202K	TANGLIN ROAD TWDS ORCHARD RD	10/05/2018 14:50

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

[> Back to OneMotoring](#)

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 14 May 2018 / 13:13:29

Receipt Date/Time : 14 May 2018 / 13:13:29

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180514-001124

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHC2202K				
As at 10 May 2018/14:50:59				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHC2202K Enquiry Fee 20180514131220948013	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx0664	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

DIRECT CREDIT AUTHORISATION FORM

This form is to be completed by the Supplier of India International Insurance. Payment will be credited directly
(Name of Paying Organisation)
into the Supplier's bank account stated below through Interbank Giro. The Supplier has to complete Part I of the form,
obtain his banker's certification in Part II and return the duly completed form to
India International Insurance,
(Name of Paying Organisation)

Part I (To Be Completed By Supplier)

(A) To: India International Insurance
(Name of Paying Organisation)

Supplier's Particulars:

Name : BH AUTO SERVICES PTE LTD
Address : 81K1 Sin Ming Industrial Estate Sector C #01-111/13/15/17/18/19/20/21/22/23/24/25/26/27/28/29/30/31/32/33/34/35/36/37/38/39/40/41/42/43/44/45/46/47/48/49/50/51/52/53/54/55/56/57/58/59/60/61/62/63/64/65/66/67/68/69/70/71/72/73/74/75/76/77/78/79/80/81/82/83/84/85/86/87/88/89/90/91/92/93/94/95/96/97/98/99/100
Telephone Number: 6559 8942 Fax Number: 6269 2404
Name of Bank : Maybank Name of Branch: Maybank
Account Number To Be Credited : 042 110 20567


I/We hereby authorise India International Insurance to credit payments due to me/us to the above account.
(Name of Paying Organisation)

This authorisation shall continue to be in force until I/we have expressly revoked it by notice in writing delivered to you. You may in your absolute discretion terminate this arrangement by written notice delivered to my/our address last known to you.

In the event of a change of bank account, I/we shall inform you in writing 2 weeks in advance before the change.

(B) To: India International Insurance
(Name of Supplier's Bank)

I/We hereby consent to the Bank's disclosure of customer information relating to me/us as requested for in this document.


Signature and Company's stamp As In Bank Account



13/03/2019
Date

Part II (To Be Completed By Supplier's Bank)

To: _____
(Name of Paying Organisation)

Without responsibility on the part of the Bank or the signing officer, we confirm that the signature/other particulars agree with that in our files. The account number to be presented in the Interbank Giro format is as follows:

Bank	Branch	Account Number
<input type="text"/>	<input type="text"/>	<input type="text"/>

Name & Signature of Authorised Bank Officer

Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018 Edit Reg		16 May 2018 00:00 Edit Adj Rpt	\$45,721.84 Edit Estimates	\$45,721.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	TAN SOK FERN, ID: S7108069B		
Vehicle Reg. No.:	SLX6031C	Date of Loss:	10/05/2018 14:00 - :59 [1 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18050249	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC2202K	Policy No. (Claimant):	CN885543
		Excess:	
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 31/05/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- III_SG (29/01/2019): Alert - Adj Mandate Approved (\$6758.82) - SLX6031C - Claim Handler: Sherini Pillai
- III_SG (30/05/2018): Alert - Adj Mandate Approved (\$0.00) - SLX6031C - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLX6031C (MCT18050249)**
[SHC2202K]
TP
TAN SOK FERN
May 10 2018 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
BH Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 17:37	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	03/10/18 17:37	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
4	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
5	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
6	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
7	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
8	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
9	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
10	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
11	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
12	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
13	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
14	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
15	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
16	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
17	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
18	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
19	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
20	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
21	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
22	03/10/18 17:39	General View	Load JPG	<input checked="" type="checkbox"/>
23	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	03/10/18 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 13:36	TP ESTIMATE - MARKED	Load PDF	
2	21/05/18 13:36	EMAIL FROM III DD 16.05.2018	Load PDF	
3	28/01/19 10:19	RENTAL RECEIPT	Load PDF	
4	28/01/19 10:19	LTA SEARCH	Load PDF	
5	20/03/19 11:59	WORKSHOP INVOICE	Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
6	20/03/19 11:59	AUTHORISATION TO ACT FORM		Load PDF
7	20/03/19 11:59	DISCHARGE VOUCHER		Load PDF
8	20/03/19 11:59	GIA SEARCH		Load PDF
9	20/03/19 11:59	GIROFORM		Load PDF
10	20/03/19 11:59	LOD		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	22/05/18 08:33	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009122/M1HA3Q2

Date: 20/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle
No : SLX8031C

Insured Vehicle No : SHC2202K

Date of Loss: 10/05/2018

Nature of Claim: TP

Claim No: MCT18050249

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX6031C

Make & Model: HYUNDAI I30 PDE, 1.4 T-GDI DCT (A)

Engine No: G4LDHD127939

Reg. Date: 02/04/2018 (Man. Year: 2018)

Chassis No: TMAH3513VJJ063822

Colour: Blue

Odometer: 2441 km

Engine Capacity: 1353 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Hankook 8 mm

Rear Left Side: Hankook 8 mm

Front Right Side: Hankook 8 mm

Rear Right Side: Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,065.38	3,831.84	6,233.54	61.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,890.00	2,150.00	53.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,105.38	5,721.84	8,383.54	59.44
+ GST 7.00/7.00% (S\$)	987.38	400.53	586.85	59.44
Nett Amount (S\$)	15,092.76	6,122.37	8,970.39	59.44
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,758.82		
Global Sum Settlement (S\$)		6,750.00		

INSPECTION

Date of Assignment: 16/05/2018

Date Inspected: 17/05/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts:	144	HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6031C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	1,830.10 FL	*- FL
2	1		*REAR FENDER SHIELD RH	Repair	311.95 FL	*- FL
3	1		*ROCKER PANEL	Repair	2,281.57 FL	*- FL
4	1		*REAR DOOR RH	Dented	1,819.70 FL	*1,819.70 FL
5	1		*REAR DOOR UPPER HINGE RH	Necessary	46.00 FL	*46.00 FL
6	1		*REAR DOOR LOWER HINGE RH	Necessary	36.10 FL	*36.10 FL
7	1		*REAR DOOR WINDOW GLASS RH	Not Necessary	381.70 FL	*- FL
8	1		*REAR DOOR QUARTER GLASS RH	Not Necessary	365.90 FL	*- FL
9	1		*REAR DOOR QUARTER GLASS MOULDING RH	Necessary	217.50 FL	*217.50 FL
10	1		*REAR DOOR WEATHERSTRIP RH	Necessary	266.90 FL	*266.90 FL
11	2		*REAR DOOR FRAME STICKER /GARNISH RH	Necessary	24.00 FL	*24.00 FL
12	1		*REAR DOOR WINDOW GLASS OUTER MOULDING CHROME RH	Necessary	89.10 FL	*89.10 FL
13	1		*FRONT DOOR RH	Dented	1,723.60 FL	*1,723.60 FL
14	1		*FRONT DOOR UPPER HINGE RH	Not Necessary	41.10 FL	*- FL
15	1		*FRONT DOOR LOWER HINGE RH	Not Necessary	36.70 FL	*- FL
16	1		*FRONT DOOR WINDOW GLASS RH	Not Necessary	421.90 FL	*- FL
17	1		*FRONT DOOR FRAME STICKER /GARNISH RH	Necessary	12.00 FL	*12.00 FL
18	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	266.90 FL	*266.90 FL
19	1		*FRONT DOOR GLASS WINDOW OUTER MOULDING CHROME RH	Necessary	108.00 FL	*108.00 FL
20	1		*FRONT DOOR LOCK ASSY	Not Necessary	201.20 FL	*- FL
21	1		*FRONT DOOR INNER TRIM	Not Necessary	1,794.80 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
23	10		*FRONT DOOR INNER TRIM CLIPS	Necessary	40.00 FS	*40.00 FS
24	10		*REAR FENDER SHIELD CLIPS (NPA)	Not Necessary	0.00 FS	*- FS
25	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*FRONT DOOR UPPER MOULDING CHROME RH	Necessary	75.00 FL	*75.00 FL
27	1		*REAR DOOR UPPER MOULDING CHROME RH	Necessary	55.00 FL	*55.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,546.72	4,779.80
				- List Item Discount on L Items 20.00/20.00% (S\$)	2,481.34	947.96
				Total Parts (S\$)	10,065.38	3,831.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	320.00	80.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	2,000.00	800.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,000.00	800.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	30.00	30.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	180.00	0.00
6	REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM ,GARNISH ,ROOF LINING AND /OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	60.00
7	REMOVE AND REFIT/REPLACE WINDOW GLASS	New	180.00	0.00
8	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE REPAIRS	New	180.00	120.00
Gross Labour Cost (S\$)			4,040.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >