

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

**India International Insurance Pte Ltd**  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

**ACCIDENT REPAIR ON : SLX6031C**

**MODEL : HYUNDAI I30**

**POLICY NO : CN885543**

**CHASSIS NO : TMAH3513VJJ063822**

**MANUFACTURING YEAR : 2018**

**DATE / TIME OF ACCIDENT : 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD**

**THIRD PARTY VEHICLE NO : SHC2202K**

Date: 17/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

**Replacement Of Parts**

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Rear Fender RH ✕	1	1830.10		1,830.10
2 Rear Fender Shield RH ✕	1	311.95		311.95
3 Rocker Panel ✕	1	2281.57		2,281.57
4 Rear Door RH ✓	1	1819.70		1,819.70
5 Rear Door Upper Hinge RH ✓	1	46.00		46.00
6 Rear Door Lower Hinge RH ✓	1	36.10		36.10
7 Rear Door Window Glass RH ✕	1	381.70		381.70
8 Rear Door Quarter Glass RH ✕	1	365.90		365.90
9 Rear Door Quarter Glass Moulding RH ✓	1			
10 Rear Door Weatherstrip RH ✓	1	266.90		266.90
11 Rear Door Frame Sticker/Garnish RH ✓	2	12.00		24.00
12 Rear Door Window Glass Outer Moulding ✓				
Chrome RH	1	89.10		89.10
13 Front Door RH ✓	1	1723.60		1,723.60
14 Front Door Upper Hinge RH ✕	1	41.10		41.10
15 Front Door Lower Hinge RH ✕	1	36.70		36.70
16 Front Door Window Glass RH ✕	1	421.90		421.90
17 Front Door Frame Sticker/Garnish RH ✓	1	12.00		12.00
18 Front Door Weatherstrip RH ✓	1	266.90		266.90
19 Front Door Glass Window Outer Moulding ✓				
Chrome RH	1	108.00		108.00
20 Front Door Lock Assy ✓	1	201.20		201.20
21 Front Door Inner Trim ✕	1	1794.80		1,794.80
22 Rear Windscreen Moulding ✕	1			

4609.80  
- 20%  
-----  
3687.84

Sub-Total: 12,059.22  
Less Discount 20% 2,411.84  
**Total Parts: 9,647.38**

**Special Nett Items**

1 Anti-rust coating	4	80.00		320.00
2 Front Door Inner Trim Clips	10	4.00		40.00
3 Rear Fender Shield Clips	10			
4 Rear Windscreen Sealant	1	100.00		100.00

80  
\$120  
X

Total Parts: 460.00

**Labour Charges For Front and Side Portion**

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	<del>2,000.00</del> 800
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,000.00 800
3	Provide skill labour to disconnect and check electrical wiring	30.00
4	Remove and refit rear windscreen	180.00 X
5	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs	<del>450.00</del> 60
6	Remove and refit/replace window glass	X 180.00 <del>150</del>
7	Dismantle and transfer door fittings and mechanism to new door/facilitate repairs	180.00 120
<b>Total Labour:</b>		<b>3,720.00</b>

\$1810

**Total Parts & Labour:** 13,827.38  
**GST 7%:** 967.92  
**Grand Total:** 14,795.29

**Estimate Repair Duration** 10 days

ACCIDENT VEHICLE OF : SLX6031C

Page : 2 of 2

**Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.**

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : \_\_\_\_\_  
Company : \_\_\_\_\_  
Date : \_\_\_\_\_  
Time : \_\_\_\_\_  
Contact No: \_\_\_\_\_  
Email : \_\_\_\_\_

*Not Anthony*  
*PIP Repair*  
*Before Panel Photo*  
*17/5/2018*  
*SW days*  
*LKK Auto*

Part: \$3687.84 + \$104 (Supp)  
S/N: \$120.00  
Labour: \$1810  


---

Total: \$5721.84

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
 Tel: 6559 8944 / Fax: 6269 2404

**India International Insurance Pte Ltd**

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

**SUPPLEMENTARY**

ACCIDENT REPAIR ON : SLX6031C

MODEL : HYUNDAI I30

POLICY NO : CN885543

CHASSIS NO : TMAH3513VJJ063822

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD

THIRD PARTY VEHICLE NO : SHC2202K

Date: 05/07/2018

Page : 1 of 1

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

**Replacement Of Parts**

S/N	Quantity	Unit Price	Condition	Amount
		SS		SS
1 Front door upper moulding chrome RH	1	75.00	Necessary	75.00 ✓
2 Rear door upper moulding chrome RH	1	55.00	Necessary	55.00 ✓
			Sub-Total:	130.00
			Less Discount 20%	26.00
			<b>Total Parts:</b>	<b>104.00</b>

130 - 20%  
= 104

**Special Nett Items**

- 1
- 2

Total Parts: -

**Labour Charges For Front and Side Portion**

Total Labour:

Total Parts & Labour:	104.00
GST 7%	7.28
<b>Grand Total:</b>	<b>111.28</b>