

BH AUTO SERVICES PTE LTD

Blk 1, Sector C , Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLX6031C

MODEL : HYUNDAI I30

POLICY NO : CN885543

CHASSIS NO : TMAH3513VJJ063822

MANUFACTURING YEAR : 2018

DATE / TIME OF ACCIDENT: 10/05/2018 Time: 1450Hrs ALONG TANGLIN ROAD

THIRD PARTY VEHICLE NO : SHC2202K

Date: 17/05/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Rear Fender RH ✕	1	1830.10		1,830.10
2 Rear Fender Shield RH ✕	1	311.95		311.95
3 Rocker Panel ✕	1	2281.57		2,281.57
4 Rear Door RH ✓	1	1819.70		1,819.70
5 Rear Door Upper Hinge RH ✓	1	46.00		46.00
6 Rear Door Lower Hinge RH ✓	1	36.10		36.10
7 Rear Door Window Glass RH ✕	1	381.70		381.70
8 Rear Door Quarter Glass RH ✕	1	365.90		365.90
9 Rear Door Quarter Glass Moulding RH ✓	1			-
10 Rear Door Weatherstrip RH ✓	1	266.90		266.90
11 Rear Door Frame Sticker/Garnish RH ✓	2	12.00		24.00
12 Rear Door Window Glass Outer Moulding ✓				-
Chrome RH	1	89.10		89.10
13 Front Door RH ✓	1	1723.60		1,723.60
14 Front Door Upper Hinge RH ✕	1	41.10		41.10
15 Front Door Lower Hinge RH ✕	1	36.70		36.70
16 Front Door Window Glass RH ✕	1	421.90		421.90
17 Front Door Frame Sticker/Garnish RH ✓	1	12.00		12.00
18 Front Door Weatherstrip RH ✓	1	266.90		266.90
19 Front Door Glass Window Outer Moulding ✓				-
Chrome RH	1	108.00		108.00
20 Front Door Lock Assy ✓	1	201.20		201.20
21 Front Door Inner Trim ✕	1	1794.80		1,794.80
22 Rear Windscreen Moulding ✕	1			-
Sub-Total:				12,059.22
Less Discount 20%				2,411.84
Total Parts:				9,647.38

Special Nett Items

1 Anti-rust coating	4	80.00	80	320.00
2 Front Door Inner Trim Clips	10	4.00		40.00
3 Rear Fender Shield Clips	10			-
4 Rear Windscreen Sealant	1	100.00		100.00

Total Parts: 460.00

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	2,000.00 800
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,000.00 800
3	Provide skill labour to disconnect and check electrical wiring	30.00
4	Remove and refit rear windscreen	180.00 X
5	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and/or upholstery to facilitate repairs	150.00 60
6	Remove and refit/replace window glass	X 180.00 120
7	Dismantle and transfer door fittings and mechanism to new door/faciliate repairs	180.00 120

Total Labour:

Total Parts & Labour:	3,720.00
GST 7%	13,827.38
Grand Total:	967.92
	14,795.29

Estimate Repair Duration 10 days

ACCIDENT VEHICLE OF : SLX6031C

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name :
Company :
Date :
Time :
Contact Nc :
Email :

Not Anthony
PIP Repair
Before PIP Repair
17/5/2018
5w days
C&C Auto