

INS. CASE OWNER:

Surveyor:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner? (YES / NO)

If NO, Driver Name / Age :

Driver Tel No. :

CCP/QBE1800 9127, T2 w6752

LKK:

IDAC:

ASSIGNMENT

DOI:

Date / Time :

Registered in Merimen:

SJP 1063 J

Pung POON YUEN

HP: 98765663

D.O.A: 15/5/18

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

V6011501

8-001718-AVA

TOMOTA

Upp Thomson Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SJP 4650A



INSRS:

WSP:

Tel :

Liability :

RMKS:

bing
auto

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 12/5/18

Sent By: BIC

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 14/9/18

Confirm with Michelle

Email ☐ Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia :

0% involved in 3:1

0% is the motorist.

Repair Cost:

SS

6206.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

1400.00 x 14 days

Loss of Income (LOI):

SS

(S x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

745

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

7613.45

Global Sum SS: 7610.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

7610.00

Name 1:

Ding Auto Pte Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

RECEIVED 10 SEP 2018

COPY SENT

Taufik

REF:

ASE

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

960K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF 4150 H Yr Regn: 2016 Aug
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Mitsubishi 4th gen C.C. 1193
 Colour: Grey Insured / Std / NI / NA

Sp. Reading: 120530 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMBSTA13AF4019675

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ Rim / STD A/Rim or

Tyre Size F: 185/55 R15
 R: 9 9

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / ☒ YOKO or

Front: R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 18/5/18

Survey held at Ding Auk

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/8/18 Confirm CLS # 5800.00 with 9 working days

(Red) = \$9593.20
 63%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + PS. \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC4/QBE18009127/T1wb3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 21-05-2018	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJP 1063J	Veh. Inspected	SLF 4150A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/05/2018	Inspection Date	18/05/2018	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTO PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20
 Singapore 575645
 Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

18/05/2018 9:42

JOB-NO: 85008322

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD

CONTACT:

Page 1 of 2

ADDRESS: 60 ANSON ROAD
 MAPLETREE ANSON
 LEVEL 11 SINGAPORE
 079914

NOEMAIL@GMAIL.COM

VEHICLE DETAILS

LICENSE NO: SLF4150A

TRANS: AUTO

CHASSIS: MMBSTA13AFH019675

MAKE / MODEL: MITSUBISHI Others

ENGINE: 3A92UCY7008

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV. PRIC.
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	3,000.00	0.00	3,000.00	Y		1400 1500
2 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL, BOOTLID, REAR FENDER LHS, REAR FENDER RHS	1.00	1,800.00	0.00	1,800.00	Y		1200
3 RUST PROOFING	1.00	180.00	0.00	180.00	Y		90
4 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	120.00	0.00	120.00	Y		30
5 REMOVE & REFIT REVERSE SENSOR AND SPRAY	1.00	120.00	0.00	120.00	Y		30
6 REMOVE REAR WINDSCREEN	1.00	120.00	0.00	120.00	Y		✓
7 MOUNT WORKBENCH	1.00	350.00	0.00	350.00	Y		1750 plus
8 REMOVE & REFIT EXHAUST PIPE	1.00	120.00	0.00	120.00	Y		X n n
9 REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER TRIM LHS & RHS, REAR SPARE TYRE BOARD, CUSHION, AND ETC	1.00	180.00	0.00	180.00	Y		60
10 REMOVE & REFIT FUEL TANK & REAR AXLE	1.00	120.00	0.00	120.00	Y		X n n
11 ALIGNMENT REAR CHASSIS	1.00	350.00	0.00	350.00	Y		X n n
12 R & R BOOTLID COMPONENTS	1.00	120.00	0.00	120.00	Y		60
13 REMOVE REAR SEAT & REAR SPEAKER PANEL TRIM	1.00	250.00	0.00	250.00	photo Y		100Xmm
14 ALIGNMENT REAR DOOR LHS	1.00	120.00	0.00	120.00	Y		60
TOTAL:		6,950.00	0.00	6,950.00			
MATERIALS							
1 REAR BUMPER	1.00	708.00	70.80	637.20	L	Y	48
2 REAR BUMPER REFLECTOR LHS	1.00	25.00	2.50	22.50	L	Y	ant
3 REAR BUMPER REFLECTOR RHS	1.00	25.00	2.50	22.50	L	Y	X n n
4 BOOTLID	1.00	928.00	92.80	835.20	L	Y	56
5 BOOTLID "ATTRAGE" EMBLEM	1.00	38.00	3.80	34.20	L	Y	net
6 BOOTLID "LOGO" BADGE	1.00	41.00	4.10	36.90	L	Y	net
7 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L	Y	Rx
8 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L	Y	Rx
9 BOOTLID LOCK	1.00	206.00	20.60	185.40	L	Y	? n n
10 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L	Y	X n n

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
11 BOOTLID LICENSE PLATE LAMP LHS	1.00	48.00	4.80	43.20	L	Y	X nn
12 BOOTLID LICENSE PLATE LAMP RHS	1.00	48.00	4.80	43.20	L	Y	X nn
13 BOOTLID LOCK CATCH	1.00	19.00	1.90	17.10	L	Y	X nn
14 TAIL LAMP PANEL LHS	1.00	112.00	11.20	100.80	L	Y	bt
15 EXHAUST PIPE	1.00	571.00	57.10	513.90	L	Y	X nn
16 EXHAUST PIPE TOP MOUNTING	2.00	48.00	4.80	43.20	L	Y	X nn
17 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	bt
18 REAR END PANEL TOP GARNISH	1.00	62.00	6.20	55.80	L	Y	bt
19 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	Rx
20 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	185.00	18.50	166.50	L	Y	ant
21 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	ant
22 REAR FENDER LHS	1.00	723.00	72.30	650.70	L	Y	bt
23 REAR FENDER RHS	1.00	723.00	72.30	650.70	L	Y	X nn
24 REAR FENDER INNER SHIELD LHS	1.00	38.00	3.80	34.20	L	Y	? nn
25 REAR FENDER INNER SHIELD RHS	1.00	38.00	3.80	34.20	L	Y	X nn
26 REAR FENDER INNER PANEL TRIM LHS	1.00	158.00	15.80	142.20	L	Y	dec
27 REAR FENDER INNER PANEL TRIM RHS	1.00	158.00	15.80	142.20	L	Y	X nn
28 REAR BUMPER SIDE RETAINER LHS	1.00	35.00	3.50	31.50	L	Y	net
29 REAR BUMPER SIDE RETAINER RHS	1.00	35.00	3.50	31.50	L	Y	X nn
30 AIR DUCT LHS	1.00	36.00	3.60	32.40	L	Y	? nn
31 REAR CHASSIS LHS	1.00	718.00	71.80	646.20	L	Y	Rx
32 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	ant
33 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	? X nn
34 TAIL LAMP PANEL RHS	1.00	112.00	11.20	100.80	L	Y	Rx
35 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	na
36 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200? nu
37 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	45 bt
38 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	net
39 REAR FENDER INNER SHIELD CLIP	1.00	35.00	0.00	35.00	S	Y	X nn
40 REAR FENDER INNER PANEL TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	net 20
41 REAR SPARE TYRE PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	X nn
42 REAR END PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	net
43 REAR WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	S	Y	net 40
44 REAR WINDSCREEN DAMPER	1.00	50.00	0.00	50.00	S	Y	na
TOTAL:		9,298.00	854.80	8,443.20			

TOTAL PARTS & LABOUR :

16,248.00

854.80

15,393.20

EXCESS/LOADING: S\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 16, 5, 17

SURVEYED BY: Tanjun A

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DING AUTO PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20
 Singapore 575645
 Tel: 6452 1208 Fax: 6452 0614

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

18/05/2018 9:42

JOB-NO: 85008322

Page 1 of 2

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD
 ADDRESS: 60 ANSON ROAD
 MAPLETREE ANSON
 LEVEL 11 SINGAPORE
 079914

CONTACT:

NOEMAIL@GMAIL.COM

VEHICLE DETAILS

LICENSE NO: SLF4150A

TRANS: AUTO

CHASSIS: MMBSTA13AFH019675

ENGINE: 3A92UCY7008

MAKE / MODEL: MITSUBISHI Others

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	3,000.00	0.00	3,000.00			Y 1400 1500
2 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,REAR BUMPER,REAR END PANEL,REAR SPARE TYRE PANEL,BOOTLID,REAR FENDER LHS,REAR FENDER RHS	1.00	1,800.00	0.00	1,800.00			Y 1200
3 RUST PROOFING	1.00	180.00	0.00	180.00			Y 90
4 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	120.00	0.00	120.00			Y 30
5 REMOVE & REFIT REVERSE SENSOR AND SPRAY	1.00	120.00	0.00	120.00			Y 60
6 REMOVE REAR WINDSCREEN	1.00	120.00	0.00	120.00			Y 120
7 MOUNT WORKBENCH	1.00	350.00	0.00	350.00			Y 150
8 REMOVE & REFIT EXHAUST PIPE	1.00	120.00	0.00	120.00			Y X
9 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	180.00	0.00	180.00			Y 60
10 REMOVE & REFIT FUEL TANK & REAR AXLE	1.00	120.00	0.00	120.00			Y X
11 ALIGNMENT REAR CHASSIS	1.00	350.00	0.00	350.00			Y X
12 R & R BOOTLID COMPONENTS	1.00	120.00	0.00	120.00			Y 60
13 REMOVE REAR SEAT & REAR SPEAKER PANEL TRIM	1.00	250.00	0.00	250.00			Y 100
14 ALIGNMENT REAR DOOR LHS	1.00	120.00	0.00	120.00			Y 60
TOTAL:		6,950.00	0.00	6,950.00			
MATERIALS							
1 REAR BUMPER	1.00	708.00	70.80	637.20	L		Y de
2 REAR BUMPER REFLECTOR LHS	1.00	25.00	2.50	22.50	L		Y at
3 REAR BUMPER REFLECTOR RHS	1.00	25.00	2.50	22.50	L		Y X
4 BOOTLID	1.00	928.00	92.80	835.20	L		Y 66
5 BOOTLID "ATTRAGE" EMBLEM	1.00	38.00	3.80	34.20	L		Y nel
6 BOOTLID "LOGO" BADGE	1.00	41.00	4.10	36.90	L		Y ne
7 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L		Y Rv
8 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L		Y Rv
9 BOOTLID LOCK	1.00	206.00	20.60	185.40	L		Y ?
10 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L		Y X

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
11 BOOTLID LICENSE PLATE LAMP LHS	1.00	48.00	4.80	43.20	L	Y	X
12 BOOTLID LICENSE PLATE LAMP RHS	1.00	48.00	4.80	43.20	L	Y	X
13 BOOTLID LOCK CATCH	1.00	19.00	1.90	17.10	L	Y	Ry
14 TAIL LAMP PANEL LHS	1.00	112.00	11.20	100.80	L	Y	bt
15 EXHAUST PIPE	1.00	571.00	57.10	513.90	L	Y	X
16 EXHAUST PIPE TOP MOUNTING	2.00	48.00	4.80	43.20	L	Y	X
17 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	bt
18 REAR END PANEL TOP GARNISH	1.00	62.00	6.20	55.80	L	Y	de
19 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	Rp
20 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	185.00	18.50	166.50	L	Y	car
21 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	art
22 REAR FENDER LHS	1.00	723.00	72.30	650.70	L	Y	bt
23 REAR FENDER RHS	1.00	723.00	72.30	650.70	L	Y	X
24 REAR FENDER INNER SHIELD LHS	1.00	38.00	3.80	34.20	L	Y	?
25 REAR FENDER INNER SHIELD RHS	1.00	38.00	3.80	34.20	L	Y	X
26 REAR FENDER INNER PANEL TRIM LHS	1.00	158.00	15.80	142.20	L	Y	dec
27 REAR FENDER INNER PANEL TRIM RHS	1.00	158.00	15.80	142.20	L	Y	X
28 REAR BUMPER SIDE RETAINER LHS	1.00	35.00	3.50	31.50	L	Y	rel
29 REAR BUMPER SIDE RETAINER RHS	1.00	35.00	3.50	31.50	L	Y	X
30 AIR DUCT LHS	1.00	36.00	3.60	32.40	L	Y	?
31 REAR CHASSIS LHS	1.00	718.00	71.80	646.20	L	Y	Rp
32 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	car
33 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	?
34 TAIL LAMP PANEL RHS	1.00	112.00	11.20	100.80	L	Y	Rp
35 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	na
36 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200 mm
37 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	45 bt
38 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	rel
39 REAR FENDER INNER SHIELD CLIP	1.00	35.00	0.00	35.00	S	Y	X
40 REAR FENDER INNER PANEL TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	rel 20
41 REAR SPARE TYRE PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	X
42 REAR END PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	rel
43 REAR WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	S	Y	rel 40
44 REAR WINDSCREEN DAMPER	1.00	50.00	0.00	50.00	S	Y	na
TOTAL:		9,298.00	854.80	8,443.20			

TOTAL PARTS & LABOUR: 16,248.00 854.80 15,393.20

EXCESS/LOADING: \$\$ 0.00

No. Of Day: 9 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 16, 5, 17

SURVEYED BY: Tanylin A

CONTACT NO: 92495779

FAX NO: 62563561

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR:

STA AUTOCENTRE

TEL:

FAX:

Labour = \$3300
 Part = \$3456.90
 Special = \$505.00
 TOTAL = \$7261.90
 TOTAL - 20% = \$5809.52

Catherine Chong (LKK Auto)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Wednesday, 16 May, 2018 3:37 PM
To: 'assignments'
Cc: Jenny Toh
Subject: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Our ref: V0117218

Dear Sir/Madam

Kindly survey the TP vehicle :-

Insured : SJP1063J
TP Vehicle : SLF4150A
Date of accident :15/05/2018
Contact : as below

Kindly acknowledge receipt.

9.15am @ 17/5/18
person @ Michelle
vehicle in
sur @ fault

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Dd hashim [mailto:dd.hashim@dingauto.sg]
Sent: Wednesday, 16 May, 2018 2:42 PM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>; Duan Hongbo <duan.hongbo@dingauto.sg>
Subject: Re: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Dear Jenny,

We would like to request surveyor from LKK Auto Consultant Pte Ltd to survey our clients vehicle.

Please arrange survey as soon as possible.

Thank you
BEST REGARDS
DD HASHIM

DING AUTO PTE LTD
TEL Office : 92394128
FAX :62652690
ADDRESS:249 JALAN BOON LAY SINGAPORE 619523

On Wed, May 16, 2018 at 2:15 PM, Jenny Toh <jenny.toh@qbe.com> wrote:

Our ref : V0117218

Dear Hashim

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Priority Services
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225

Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Dd hashim [mailto:dd.hashim@dingauto.sg]

Sent: Wednesday, 16 May, 2018 1:06 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>; Duan Hongbo <duan.hongbo@dingauto.sg>

Subject: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Dear Motor Claims Dept,

Vehicle lying at 249 Jalan Boon Lay.

Please arrange survey for the above vehicle.

Case is in Chain collision.

Here I attached together GIA report for your reference.

Thank you

BEST REGARDS

DD HASHIM

DING AUTO PTE LTD

TEL Office : 92394128

FAX :62652690

ADDRESS:249 JALAN BOON LAY SINGAPORE 619523

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of

this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shu Pei (LKKAUTO)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Wednesday, 4 July 2018 2:55 PM
To: Shu Pei (LKKAUTO)
Cc: Jenny Toh
Subject: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY
****LKK REF:CC4/QBE18009127/T1wb3
Attachments: SJP1063J.pdf

Our ref: VC011501


Hi Shu Pei

Please find attached as per requested.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 3 July, 2018 10:32 AM
To: Jenny Toh <jenny.toh@qbe.com>
Subject: RE: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY ****LKK
REF:CC4/QBE18009127/T1wb3

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 22 May 2018 9:09 AM

To: 'Jenny Toh' <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY ****LKK
REF:CC4/QBE18009127/T1wb3

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLF 4150A at M/s Ding Auto Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 17 May 2018 2:29 PM

To: 'Jenny Toh' <jenny.toh@qbe.com>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh [<mailto:jenny.toh@qbe.com>]

Sent: Wednesday, 16 May 2018 3:37 PM

To: 'assignments' <assignments@lkkauto.com>

Cc: Jenny Toh <jenny.toh@qbe.com>

Subject: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Our ref: V0117218

Dear Sir/Madam

Kindly survey the TP vehicle :-

Insured : SJP1063J

TP Vehicle : SLF4150A


Date of accident :15/05/2018

Contact : as below

Kindly acknowledge receipt.

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Dd hashim [<mailto:dd.hashim@dingauto.sg>]

Sent: Wednesday, 16 May, 2018 2:42 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>; Duan Hongbo <duan.hongbo@dingauto.sg>

Subject: Re: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Dear Jenny,

We would like to request surveyor from LKK Auto Consultant Pte Ltd to survey our clients vehicle.

Please arrange survey as soon as possible.

Thank you
BEST REGARDS
DD HASHIM
DING AUTO PTE LTD
TEL Office : 92394128
FAX :62652690
ADDRESS:249 JALAN BOON LAY SINGAPORE 619523

On Wed, May 16, 2018 at 2:15 PM, Jenny Toh <jenny.toh@qbe.com> wrote:

Our ref : V0117218

Dear Hashim

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Priority Services
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225

Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Dd hashim [mailto:dd.hashim@dingauto.sg]

Sent: Wednesday, 16 May, 2018 1:06 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; You jingfeng <jingfeng@dingauto.sg>; Duan Hongbo <duan.hongbo@dingauto.sg>

Subject: ACCIDENT INVOLVING SLF4150A&SJP1063J ON 15/05/2018-ARRANGE SURVEY

Dear Motor Claims Dept,

Vehicle lying at 249 Jalan Boon Lay.

Please arrange survey for the above vehicle.

Case is in Chain collision.

Here I attached together GIA report for your reference.

Thank you

BEST REGARDS

DD HASHIM

DING AUTO PTE LTD

TEL Office : 92394128

FAX :62652690

ADDRESS:249 JALAN BOON LAY SINGAPORE 619523

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-074493

Date of Request: 16/05/2018

Your Ref No: Online Purchase

Ding Auto Pte Ltd
Blk 10, #01-20
Sin Ming Industrial Estate Sector C
Singapore 575645

Dear Sir/Madam,

Enquiry Date 16/05/2018

Enquiry By You Jing Feng

Vehicle No. SJP1063J

Accident Date 15/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJP1063J	QBE Insurance (Singapore) Pte Ltd	11/03/2018-10/03/2019	62246633

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-074493

Date of Request: 16/05/2018

Your Ref No: Online Purchase

Ding Auto Pte Ltd
Blk 10, #01-20
Sin Ming Industrial Estate Sector C
Singapore 575645

Dear Sir/Madam,

Enquiry Date 16/05/2018
Enquiry By You Jing Feng
Vehicle No. SJP1063J
Accident Date 15/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18009127/T1wb3s2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 18-09-2018	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJP 1063J	Veh. Inspected	SLF 4150A
Policy No.	8-V0017218-MVA	Coverage (\$)	0.00
Claim No.	VC011501	Excess (\$)	0.00
Assign From	JENNY TOH	Assign Date	16/05/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMBSTA13AFH019675	Colour	GREY
Odometer	120530	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55R15	YOKOHAMA	6 mm
L/H Front Tyre	185/55R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/55R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/55R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/05/2018	Inspection Date	18/05/2018
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 4150A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	708.00	708.00
1	REAR BUMPER REFLECTOR LHS	CUT	25.00	25.00
1	REAR BUMPER REFLECTOR RHS	NOT NECESSARY	25.00	-
1	BOOTLID	BENT	928.00	928.00
1	BOOTLID "ATTRAGE" EMBLEM	NECESSARY	38.00	38.00
1	BOOTLID "LOGO" BADGE	NECESSARY	41.00	41.00
1	BOOTLID HINGE LHS	TO REPAIR SEE LABOUR	192.00	-
1	BOOTLID HINGE RHS	TO REPAIR SEE LABOUR	192.00	-
1	BOOTLID LOCK	NOT NECESSARY	206.00	-
1	BOOTLID OUTER CHROME GARNISH	NOT NECESSARY	318.00	-
1	BOOTLID LICENCE PLATE LAMP LHS	NOT NECESSARY	48.00	-
1	BOOTLID LICENCE PLATE LAMP RHS	NOT NECESSARY	48.00	-
1	BOOTLID LOCK CATCH	TO REPAIR SEE LABOUR	19.00	-
1	TAIL LAMP PANEL LHS	BENT	112.00	112.00
1	EXHAUST PIPE	NOT NECESSARY	571.00	-
2	EXHAUST PIPE TOP MOUNTING	NOT NECESSARY	48.00	-
1	REAR END PANEL	BENT	402.00	402.00
1	REAR END PANEL TOP GARNISH	DEFORMED	62.00	62.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	906.00	-
1	REAR SPARE TYRE PANEL FLOOR BOARD	CRACKED	185.00	185.00
1	REAR END PANEL WEATHERSTRIP	CUT	148.00	148.00
1	REAR FENDER LHS	BENT	723.00	723.00
1	REAR FENDER RHS	NOT NECESSARY	723.00	-
1	REAR FENDER INNER SHIELD LHS	NOT NECESSARY	38.00	-
1	REAR FENDER INNER SHIELD RHS	NOT NECESSARY	38.00	-
1	REAR FENDER INNER PANEL TRIM LHS	DEFORMED	158.00	158.00
1	REAR FENDER INNER PANEL TRIM RHS	NOT NECESSARY	158.00	-
1	REAR BUMPER SIDE RETAINER LHS	NECESSARY	35.00	35.00

Report Ref No. CC4/QBE18009127/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SIDE RETAINER RHS	NOT NECESSARY	35.00	-
1	AIR DUCT LHS	NOT NECESSARY	36.00	-
1	REAR CHASSIS LHS	TO REPAIR SEE LABOUR	718.00	-
1	TAIL LAMP LHS	CRACKED	276.00	276.00
1	TAIL LAMP RHS	NOT NECESSARY	276.00	-
1	TAIL LAMP PANEL RHS	TO REPAIR SEE LABOUR	112.00	-
	LESS 10% DISCOUNT		-	-384.10
			8,548.00	3,456.90
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	260.00	200.00
1	REAR NUMBER PLATE & CASING (SN)	BENT	60.00	45.00
1	REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	35.00	35.00
1	REAR FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR FENDER INNER PANEL TRIM CLIP (SN)	NECESSARY	35.00	20.00
1	REAR SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	80.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
	REAR WINDSCREEN DAMPER (SN)	NECESSARY	50.00	50.00
			750.00	505.00
	LABOUR			
	TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF BOOTLID HINGE LHS, BOOTLID HINGE RHS, BOOTLID LOCK CATCH, REAR SPARE TYRE PANEL, REAR CHASSIS LHS AND TAIL LAMP PANEL RHS.		3,000.00	1,500.00
	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS, REAR BUMPER, REAR END PANEL, REAR SPARE TYRE PANEL, BOOTLID, REAR FENDER LHS, REAR FENDER RHS.		1,800.00	1,200.00
	RUST PROOFING.		180.00	90.00
	TO ADJUST TAIL LAMP & CHECK WIRING.		120.00	30.00
	REMOVE & REFIT REVERSE SENSOR AND SPRAY.		120.00	30.00

Report Ref No. CC4/QBE18009127/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE REAR WINDSCREEN.		120.00	120.00
	MOUNT WORKBENCH.		350.00	150.00
	REMOVE & REFIT EXHAUST PIPE.	NOT NECESSARY	120.00	-
	REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER TRIM LHS & RHS, REAR SPARE TYRE BOARD, CUSHION, AND ETC.		180.00	60.00
	REMOVE & REFIT FUEL TANK & REAR AXLE.	NOT NECESSARY	120.00	-
	ALIGNMENT REAR CHASSIS.	NOT NECESSARY	350.00	-
	R&R BOOTLID COMPONENTS.		120.00	60.00
	REMOVE REAR SEAT & REAR SPEAKER PANEL TRIM.	NOT NECESSARY	250.00	-
	ALIGNMENT REAR DOOR LHS.		120.00	60.00
			6,950.00	3,300.00
GRAND TOTAL			16,248.00	7,261.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,800.00
--	--	--	----------

Report Ref No. CC4/QBE18009127/T1wb3s2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.