

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

18/05/2018 9:42

JOB-NO: 85008322

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD CONTACT:

Page 1 of 2

ADDRESS: 60 ANSON ROAD
MAPLETREE ANSON
LEVEL 11 SINGAPORE
079914

NOEMAIL@GMAIL.COM

VEHICLE DETAILS

LICENSE NO: SLF4150A

TRANS: AUTO

CHASSIS: MMBSTA13AFH019675

MAKE / MODEL: MITSUBISHI/ Others

ENGINE: 3A92UCY7008

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	3,000.00	0.00	3,000.00	Y		1400 1500
2 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,REAR BUMPER,REAR END PANEL,REAR SPARE TYRE PANEL,BOOTLID,REAR FENDER LHS,REAR FENDER RHS	1.00	1,800.00	0.00	1,800.00	Y		1200
3 RUST PROOFING	1.00	180.00	0.00	180.00	Y		90
4 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	120.00	0.00	120.00	Y		30
5 REMOVE & REFIT REVERSE SENSOR AND SPRAY	1.00	120.00	0.00	120.00	Y		30
6 REMOVE REAR WINDSCREEN	1.00	120.00	0.00	120.00	Y		✓
7 MOUNT WORKBENCH	1.00	350.00	0.00	350.00	Y		1750 plus
8 REMOVE & REFIT EXHAUST PIPE	1.00	120.00	0.00	120.00	Y		X
9 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	180.00	0.00	180.00	Y		60
10 REMOVE & REFIT FUEL TANK & REAR AXLE	1.00	120.00	0.00	120.00	Y		X
11 ALIGNMENT REAR CHASSIS	1.00	350.00	0.00	350.00	Y		X
12 R & R BOOTLID COMPONENTS	1.00	120.00	0.00	120.00	Y		60
13 REMOVE REAR SEAT & REAR SPEAKER PANEL TRIM	1.00	250.00	0.00	250.00	Y	photo	100
14 ALIGNMENT REAR DOOR LHS	1.00	120.00	0.00	120.00	Y		60
TOTAL:		6,950.00	0.00	6,950.00			
MATERIALS							
1 REAR BUMPER	1.00	708.00	70.80	637.20	L	Y	de
2 REAR BUMPER REFLECTOR LHS	1.00	25.00	2.50	22.50	L	Y	ant
3 REAR BUMPER REFLECTOR RHS	1.00	25.00	2.50	22.50	L	Y	X
4 BOOTLID	1.00	928.00	92.80	835.20	L	Y	bt
5 BOOTLID "ATTRAAGE" EMBLEM	1.00	38.00	3.80	34.20	L	Y	net
6 BOOTLID "LOGO" BADGE	1.00	41.00	4.10	36.90	L	Y	ne
7 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L	Y	Ry
8 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L	Y	Ry
9 BOOTLID LOCK	1.00	206.00	20.60	185.40	L	Y	?
10 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L	Y	X

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
11 BOOTLID LICENSE PLATE LAMP LHS	1.00	48.00	4.80	43.20	L	Y	X
12 BOOTLID LICENSE PLATE LAMP RHS	1.00	48.00	4.80	43.20	L	Y	X
13 BOOTLID LOCK CATCH	1.00	19.00	1.90	17.10	L	Y	Ry
14 TAIL LAMP PANEL LHS	1.00	112.00	11.20	100.80	L	Y	bt
15 EXHAUST PIPE	1.00	571.00	57.10	513.90	L	Y	X
16 EXHAUST PIPE TOP MOUNTING	2.00	48.00	4.80	43.20	L	Y	X
17 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	bt
18 REAR END PANEL TOP GARNISH	1.00	62.00	6.20	55.80	L	Y	de
19 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	Rp
20 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	185.00	18.50	166.50	L	Y	ant
21 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	ant
22 REAR FENDER LHS	1.00	723.00	72.30	650.70	L	Y	bt
23 REAR FENDER RHS	1.00	723.00	72.30	650.70	L	Y	X
24 REAR FENDER INNER SHIELD LHS	1.00	38.00	3.80	34.20	L	Y	?
25 REAR FENDER INNER SHIELD RHS	1.00	38.00	3.80	34.20	L	Y	X
26 REAR FENDER INNER PANEL TRIM LHS	1.00	158.00	15.80	142.20	L	Y	ded
27 REAR FENDER INNER PANEL TRIM RHS	1.00	158.00	15.80	142.20	L	Y	X
28 REAR BUMPER SIDE RETAINER LHS	1.00	35.00	3.50	31.50	L	Y	new
29 REAR BUMPER SIDE RETAINER RHS	1.00	35.00	3.50	31.50	L	Y	X
30 AIR DUCT LHS	1.00	36.00	3.60	32.40	L	Y	?
31 REAR CHASSIS LHS	1.00	718.00	71.80	646.20	L	Y	Rp
32 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	ant
33 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	?
34 TAIL LAMP PANEL RHS	1.00	112.00	11.20	100.80	L	Y	Rp
35 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	new
36 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200 new
37 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	45 bt
38 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	new
39 REAR FENDER INNER SHIELD CLIP	1.00	35.00	0.00	35.00	S	Y	X
40 REAR FENDER INNER PANEL TRIM CLIP	1.00	35.00	0.00	35.00	S	Y	new 20
41 REAR SPARE TYRE PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	X
42 REAR END PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	new
43 REAR WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	S	Y	new 40
44 REAR WINDSCREEN DAMPER	1.00	50.00	0.00	50.00	S	Y	new
TOTAL:		9,298.00	854.80	8,443.20			

TOTAL PARTS & LABOUR :

16,248.00

854.80

15,393.20

EXCESS/LOADING:\$\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY:

SURVEYED BY:

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: