

22/03/2018

ASS. REC. BY:

REF:

CA/FCL/8009128/Usbn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): CWS Wurene Jaw of FCL Date/Time: 21.5.2018 12.11pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 5165D Insured: SHB 3237Jat Workshop m/s Fastech Tel: 6746 5415of Blk 1 Kaki Bukit Ave 6 #01-46Policy No: _____ Claim No: D18004042MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19052018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' H.O.D. Endorsement: _____

Date/Time: 22052018 Person Contacted: Nancy Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 5165D - X
	SHB 3237J - CA/QW 11006688/Rgn. DCA 07042011
<u>23/05/18</u>	<u>@ 14:34 p.m. revised Pending Estimate to Wurene v's email.</u>

(08/11/13) wef

REF:

ASS. REC. BY: Morais

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV5165Dat Workshop m/s PP.

of _____

Insured: SR/B3237J

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 70k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV5165D Yr Regn: 9.15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda City C.C. 1497Colour: Grey A/C: Insured / Std / NI / NASp. Reading: Ex Hay Flep T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRT HGM 66606P000236

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 19/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 yrs month LTA \$2045 Net 17 35528/9/18 4/5 \$16900 confirmed with Alar.01/10/18 Confirmed LTA \$16,900/- @ 14 days with morais.
(\$20,387.30 Red - 55%)

RECEIVED 1 OCT 2018

Date/Time, File Pass to?

1) 01/10/18
typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 14Resurvey No. of Trip: 4Add Fee: ☐ : Site Insp (\$ 1)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 170+375Transportation: 50

S + RS \$ _____

Photos: 580

Others: _____

TOTAL

25 x 15 = 375170+3755050+50+50+2681063

Report Format :

Lump Sum / I.B.I. (\$ 16,900/- Hs)

MOTOR SURVEY ASSIGNMENT

Date	21-05-2018	Our Ref No. D18004042MFSH
Accident Date	19-05-2018	Claim Type. Third Party
Insured Vehicle	SHB3237J	Third Party Vehicle. SKV5165D
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

- Hyundai Kona
- Beware of 2nd Hand Car Dealers(Part 2) - Blacklist Her...
- Mercedes Owners Thread

Honda City Price Range Depreciation 2015 Vehicle Type [Advanced Search](#)

[Home](#) » [Used Cars](#) » [Inchcape Pre-Owned](#) » [Honda City 1.5A SV](#)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle



Trim your debts and enjoy
interest rate
from as low
as 4.70% p.a.
(EIR: 8.48% p.a.)
Maybank Debt Consolidation Plan

FIND OUT MORE

Terms and Conditions apply.



Maybank

Compare

Honda City 1.5A SV

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#) [PREMIUM AD](#)



[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price	\$67,800	?
Depreciation	\$8,490 /yr View models with similar depreciation	?
Reg Date	14-Aug-2015 (7yrs 2mths 23days COE left)	?
Manufactured	2015	?
Mileage	55,861 km (20.2k /yr)	?
Transmission	Auto	?
Engine Cap	1,497 cc	?
Road Tax	\$684 /yr	?
Power	88.0 kW (118 bhp) View specs of the Honda City (2014-2017)	?
Curb Weight	1,096 kg	?
Features	4 Cylinder Inline SOHC I-I-VTEC. Engine Producing 118Bhp. Auto Transmission CVT Gearbox.	?
Accessories	Leather Seats. Sports Rims. Touchscreen Display DVD. Reverse Camera. Bluetooth. Paddle Shifter. Eco Mode.	?
Description	Kah Motor Unit With Full Serviced History. Kah Motor Warranty Till Aug 2020. 160 Points Vehicle Inspection. Extremely Well Maintained By One Owner. Smooth Running Engine And Gearbox. Please Call/SMS Our Sales Consultant For Viewing Appointment.	?
COE	\$55,889	?
OMV	\$17,797	?
ARF	\$12,797	?
Dereg Value	\$50,037 as of today (change)	?
No. of Owners	1	?
Type of Veh	Mid-Sized Sedan	?
Category	PARF Car, Premium Ad Car	?
Availability	Available	?

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#)

Posted on: 21-May-2018 | Last Updated on: 21-May-2018



Location Map



Price Analysis

Seller Information

Company	Inchcape Pre-Owned • dealer's pricelist • 55 vehs sold 39 vehs available	
Address	2 Pandan Crescent Level 1 Search cars nearby this location	
Location	Inchcape Centre	
Office No	63036303	
Contact Person(s)	Colin Tan Kelvin Kee	96860038 98719789

Honda City Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company
Honda City 1.5A SV	\$67,800	\$8,490 /yr	14-Aug-2015	1,497 cc	55,861 km	Inchcape Pre-Owned
Kah Motor Unit With Full Serviced History. Kah Motor Warranty Till Aug 2020. 160 Points Vehicle Inspection. Extremely Well Maintained By One Smooth Running Engine And Gearbox. Please Call/SMS O... Office No. - 63036303 Colin Tan - 96860038 Kelvin Kee - 98719789						
Honda City 1.5A SV	\$70,800	\$8,650 /yr	22-Oct-2015	1,497 cc	45,000 km	AC Carlink Pte Ltd
Price Reduce! Down Payment \$7,280, One Owner Only, 2015 Newest Honda City 1.5A SV.5 Years Warranty From Agent, Kah Motor Till Oct 20: Service And Maintained Since Day 1.Beautiful Red Colo... Office No. - 64669792 Mr Teo - 97433225 Mr Ng Julian - 96791611 Vicky - 82469627						
Honda City 1.5A SV	\$68,800	\$8,310 /yr	16-Nov-2015	1,497 cc	59,000 km	Just Paper Motoring
1 Owner Only, 2015 Newest Honda City 1.5A SV. 5 Years Warranty And Maintained Kah Motor Till Nov 2020. 4 New And New Battery. Beautiful With Dark Grey Leather Seats. Smooth Running Transmi... Office No. - 64574192 Fendy - 94655569						
Honda City 1.5A SV	\$68,800	\$8,500 /yr	15-Sep-2015	1,497 cc	48,000 km	AC Carlink Pte Ltd
Price Reduce! Down Payment \$7,080, One Owner Only, 2015 Newest Honda City 1.5A SV.5 Years Warranty From Agent, Kah Motor Till Sep 20: Service & Maintained. Beautiful Grey Colour With Dark... Office No. - 64669792 Mr Teo - 97433225 Mr Ng Julian - 96791611 Vicky - 82469627						
Honda City 1.5A SV	\$69,666	\$8,820 /yr	31-Jul-2015	1,497 cc	68,000 km	Creative Auto
1 Owner Only. 5 Years Agent Warranty, Full Agent Service Records, No Accident, Stock Condition, Bank And In House Loan Available, Viewing By Appointment, Call Or SMS Our Friendly Sales... Office No. - - Cedric Yeak - 97294443 Vix Teo - 97997602 Terence Leow - 90290899						
Honda City 1.5A SV	\$66,800	\$8,340 /yr	17-Aug-2015	1,497 cc	-	Motorhead Singapore Pte Ltd
5 Years Agent Warranty Till Aug 2020, Full Agent Service Records Roadtax Till Aug18. Trade In And High Loan Available. Call For Viewing Now. Office No. - - Alex - 96840608 Lip - 96968660 Jo - 98181109						

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. For price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner si openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle I results.

© 2004-2018 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8071D
Vehicle Details	
Vehicle No.:	SKV5165D
Vehicle to be Exported:	No
Intended De-registration Date:	21 May 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	L15Z12712420
Chassis No.:	MRHGM6660GP000236
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,174.00
Original Registration Date:	22 Sep 2015
First Registration Date:	22 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$13,174.00 6587
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2025
PARF Rebate Amount:	\$9,880.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$42,165.00
Total Rebate Amount:	\$52,045.00

The information contained herein is correct as at 21 May 2018

OK

FASTECH AUTO PTE LTD
1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

not allocated
21/5/18
2/5/18 6900/2
14dy.

VEHICLE NO: SKV 5165D

QTY	PARTICULAR		
1 PCS	BONNET	Bul	\$406.10 ✓
2 PCS	BONNET HINGES @\$45.50	Set	\$91.00 ✓
2 PCS	BONNET RUBBER SEAL @\$10.50	Set	\$21.00 ✓
1 PCS	BONNET INSULATOR	Dis	\$99.20 ✓
1 SET	BONNET INSULATOR CLIPS	Set	\$30.00 ✓
1 PCS	BONNET STAND	11	\$66.50 X
1 PCS	BONNET LOCK	11	\$91.10 ✓
1 PCS	FRONT BUMPER	Dis	\$459.80 ✓
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$33.60	Set	\$67.20 ✓
2 PCS	FRONT BUMPER FOG LAMPS @ \$277.90	Set/Car	\$555.80 ✓
1 PCS	FRONT BUMPER BEAM	Dis	\$236.00 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$27.50	Dis	\$55.00 ✓
1 PCS	FRONT BUMPER CENTRE GRILLE	To. n	\$62.60 ✓
1 PCS	FRONT BUMPER LOWER GARNISH	Dis	\$68.50 ✓
1 PCS	FRONT BUMPER LICENCE GARNISH	NF	\$28.50 X
1 PCS	FRONT BUMPER TOW COVER	To. n	\$20.00 ✓
1 SET	FRONT BUMPER CLIPS	Set	\$30.00 ✓
1 PCS	FRONT GRILLE	Set	\$86.90 ✓
1 PCS	FRONT GRILLE 'H' LOGO	Set	\$28.80 ✓
1 PCS	FRONT SUPPORT PANEL	Dis	\$337.80 ✓
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	Dis	\$92.30 ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	Set	\$30.00 ✓
1 PCS	FRONT GRILLE CHROME MOULDING	Set	\$180.60 ✓
2 PCS	HEADLAMPS @\$324.10	Car	\$648.20 ✓
2 PCS	FRONT FENDERS @\$270.60	Bul	\$541.20 ✓
2 PCS	FRONT FENDER INNER SHIELDS @\$78.50	To. n	\$157.00 ✓
1 SET	FRONT FENDER INNER SHIELD CLIPS	Set	\$30.00 ✓
2 PCS	FRONT FENDER INNER PANELS @\$425.10	Set	\$850.20 X
2 PCS	FRONT WHEEL HOUSING PANELS @\$666.20	Set	\$1,332.40 X
1 PCS	FRONT ENGINE UNDER COVER	Dis	\$98.90 ✓
1 SET	FRONT ENGINE UNDER COVER CLIPS	Set	\$30.00 ✓
1 PCS	WIPER GARNISH	11	\$148.20 X
2 PCS	WIPER ARMS @\$180.00	11	\$360.00 X
1 PCS	WIPER WASHER TANK	Set	\$105.00 ✓
1 PCS	WIPER WASHER TANK MOTOR	Dis	\$188.20 ✓
1 PCS	AIR CON CONDENSER	Dis	\$788.20 ✓
2 PCS	CONDENSER UPPER BRACKETS \$10.50	Set	\$21.00 ✓

(202)

1 PCS	AIR CON DISCHARGE HOSE	SM	\$102.30	✓
1 PCS	AIR CON SUCTION HOSE	Bel	\$105.80	✓
1 PCS	AIR CON FAN MOTOR	Jm	\$205.30	✓
1 PCS	AIR CON FAN COWLING	SM	\$86.20	✓
1 PCS	RADIATOR	Dis	\$1,100.50	✓
2 PCS	RADIATOR TOP BRACKETS @\$12.50	twi	\$25.00	✓
1 PCS	RADIATOR FAN COWLING	SM	\$88.20	✓
1 PCS	RADIATOR FAN MOTOR	Jm	\$250.20	✓
1 PCS	RADIATOR FAN BLADE	Bel	\$54.10	✓
1 PCS	RADIATOR TOP HOSE	twi	\$36.80	✓
1 PCS	RADIATOR SPARE TANK	Re	\$45.50	✓
1 PCS	ENGINE MOUNTING N/S	11	\$108.20	X
1 PCS	ENGINE MOUNTING O/S	Page	\$105.50	✓
1 PCS	ENGINE MOUNTING BRACKET O/S	cm	\$91.50	✓
1 PCS	STARTER MOTOR	Page/club	\$1,450.00	✓
1 PCS	AIR CON COMPRESSOR	DD/Jm	\$1,650.00	✓
1 PCS	ALTERNATOR	SM	\$1,108.20	X
1 PCS	AIR DUCT	Dis	\$78.80	✓
1 PCS	AIR CLEANER BOX ASSY	cm	\$233.20	✓
1 PCS	BATTERY BRACKET	11	\$85.80	X
1 PCS	FRONT WINDSCREEN	SM	\$1,076.10	✓
1 PCS	FRONT WINDSCREEN MOULDING	rec	\$46.50	✓
1 PCS	AIR INTAKE MANIFOLD	SM	\$1,422.30	✓
1 PCS	AIR BAG DRIVER	Acuf	\$1,780.50	✓
1 PCS	AIR BAG DRIVER CLOCK SENSOR	Acuf	\$61.50	✓
1 PCS	PASSENGER AIR BAG	Acuf	\$2,236.80	✓
1 PCS	DASHBOARD	11	\$866.20	✓
2 PCS	SEAT BELT FRONT @\$404.60	Acuf	\$809.20	✓
1 PCS	AIR BAG SRS UNIT	Acuf	\$806.70	✓
1 PCS	OIL COOLER PUMP	DD	\$165.30	✓
1 PCS	OIL COOLER HOSE	11	\$22.50	X
2 PCS	FRONT SHOCK ABSORBERS @\$291.00	11	\$582.00	X
2 PCS	FRONT LOWER ARMS @\$265.00	11	\$530.00	X
2 PCS	FRONT KNUCKLE ARMS @\$366.20	11	\$732.40	X
2 PCS	FRONT KNUCKLE ARM BEARINGS @\$150.00	11	\$300.00	X
1 PCS	BATTERY TERMINAL BRACKET	cm	\$92.50	✓
2 PCS	FRONT CHASSIS MEMBERS @\$545.00	11	\$1,090.00	X
			\$28,074.80	
		(202)		
		20729.9		
		1658342		
1 PCS	S.NETT	SM	\$20.00	✓
1 PCS	FRONT LICENCE PLATE	rec	\$200.00	180
1 PCS	FRONT WINDSCREEN SOLAR FILM	rec	\$50.00	40
1 PCS	FRONT WINDSCREEN SEALANT	DD	\$20.00	15
1 PCS	ENGINE OIL FILTER	DD	\$200.00	80
1 PCS	BATTERY			

490

LABOUR CHARGES:

TOWING CHARGE	\$120.00	100
TO CHECK WIRING	\$80.00	30
TO SPRAY RUST PROOFING	\$180.00	120
TO REFILL AIR CON GAS	\$150.00	100
TO DISMENTLE & REFIX ENGINE & GEARBOX	\$500.00	350
TO DISMENTLE & REFIX FRONT UNDERCARRIAGE	\$500.00	300
TO MOUNTING VEHICLE ON CAR O-LINER	\$380.00	X
TO DISMENTLE & REPLACING FRONT DASHBORAD	\$380.00	260
TO DISMENTLE & REPLACING FRONT AIRBAG ,SEATBELT	\$300.00	200
TO DISMENTLE & REPLACING FRONT WINDSCREEN	\$150.00	120
LABOUR FOR PANEL BEATING,CUT,WELD STRAIGHTEN & REPLACING PARTS	\$2,500.00	1500
TO PUTTY & SPRAY PAINTING	\$2,000.00	1500

TOTAL

~~\$37,287.30~~ 7240

35804.80

4615

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009128/Usbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3237J	Veh. Inspected	SKV 5165D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004042MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	21/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MRHGM6660GP000236	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	7 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/05/2018	Inspection Date	21/05/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 5165D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BUCKLED	406.10	406.10
2	BONNET HINGES @\$45.50	BENT	91.00	91.00
2	BONNET RUBBER SEAL @\$10.50	NECESSARY	21.00	21.00
1	BONNET INSULATOR	DISTORTED	99.20	99.20
1	SET BONNET INSULATOR CLIPS	NECESSARY	30.00	30.00
1	BONNET STAND	NOT NECESSARY	66.50	-
1	BONNET LOCK	TWISTED	91.10	91.10
1	FRONT BUMPER	DISTORTED	459.80	459.80
2	FRONT BUMPER FOG LAMP COVERS @\$33.60	BROKEN	67.20	67.20
2	FRONT BUMPER FOG LAMPS @\$277.90	BROKEN / CRACKED	555.80	555.80
1	FRONT BUMPER BEAM	DISTORTED	236.00	236.00
2	FRONT BUMPER SIDE RETAINERS @\$27.50	DISTORTED	55.00	55.00
1	FRONT BUMPER CENTRE GRILLE	TORN	62.60	62.60
1	FRONT BUMPER LOWER GARNISH	DISTORTED	68.50	68.50
1	FRONT BUMPER LICENCE GARNISH	NOT FITTED	28.50	-
1	FRONT BUMPER TOW COVER	TORN	20.00	20.00
1	SET FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
1	FRONT GRILLE	BROKEN	86.90	86.90
1	FRONT GRILLE "H" LOGO	NECESSARY	28.80	28.80
1	FRONT SUPPORT PANEL	DISTORTED	337.80	337.80
1	FRONT SUPPORT PANEL TOP GARNISH	DISTORTED	92.30	92.30
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	30.00	30.00
1	FRONT GRILLE CHROME MOULDING	BROKEN	180.60	180.60
2	HEADLAMPS @\$324.10	CRACKED	648.20	648.20
2	FRONT FENDERS @\$270.60	BUCKLED	541.20	541.20
2	FRONT FENDER INNER SHIELDS @\$78.50	TORN	157.00	157.00
1	SET FRONT FENDER INNER SHIELD CLIPS	NECESSARY	30.00	30.00
2	FRONT FENDER INNER PANELS @\$425.10	TO REPAIR SEE LABOUR	850.20	-
2	FRONT WHEEL HOUSING PANELS @\$666.20	TO REPAIR SEE LABOUR	1,332.40	-

Report Ref No. CS/FCI18009128/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT ENGINE UNDER COVER	DISTORTED	98.90	98.90
1	SET FRONT ENGINE UNDER COVER CLIPS	NECESSARY	30.00	30.00
1	WIPER GARNISH	NOT NECESSARY	148.20	-
2	WIPER ARMS @\$180.00	NOT NECESSARY	360.00	-
1	WIPER WASHER TANK	DEFORMED	105.00	105.00
1	WIPER WASHER TANK MOTOR	DAMAGED	188.20	188.20
1	AIR CON CONDENSER	DISTORTED	788.20	788.20
2	CONDENSER UPPER BRACKETS @\$10.50	TWISTED	21.00	21.00
1	AIR CON DISCHARGE HOSE	BENT	102.30	102.30
1	AIR CON SUCTION HOSE	BENT	105.80	105.80
1	AIR CON FAN MOTOR	JAMMED	205.30	205.30
1	AIR CON FAN COWLING	BROKEN	86.20	86.20
1	RADIATOR	DISTORTED	1,100.50	1,100.50
2	RADIATOR TOP BRACKETS @\$12.50	TWISTED	25.00	25.00
1	RADIATOR FAN COWLING	BROKEN	88.20	88.20
1	RADIATOR FAN MOTOR	JAMMED	250.20	250.20
1	RADIATOR FAN BLADE	BENT	54.10	54.10
1	RADIATOR TOP HOSE	TWISTED	36.80	36.80
1	RADIATOR SPARE TANK	DEFORMED	45.50	45.50
1	ENGINE MOUNTING N/S	NOT NECESSARY	108.20	-
1	ENGINE MOUNTING O/S	DAMAGED	105.50	105.50
1	ENGINE MOUNTING BRACKET O/S	CRACKED	91.50	91.50
1	STARTER MOTOR	DAMAGED / SHORTED	1,450.00	1,450.00
1	AIR CON COMPRESSOR	DENTED / JAMMED	1,650.00	1,650.00
1	ALTERNATOR	SERVICEABLE	1,108.20	-
1	AIR DUCT	DISTORTED	78.80	78.80
1	AIR CLEANER BOX ASSY	CRACKED	233.20	233.20
1	BATTERY BRACKET	NOT NECESSARY	85.80	-
1	FRONT WINDSCREEN	BROKEN	1,076.10	1,076.10
1	FRONT WINDSCREEN MOULDING	BROKEN	46.50	46.50
1	AIR INTAKE MANIFOLD	BROKEN	1,422.30	1,422.30
1	AIR BAG DRIVER	ACTIVATED	1,780.50	1,780.50

Report Ref No. CS/FCI18009128/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR BAG DRIVER CLOCK SENSOR	ACTIVATED	61.50	61.50
1	PASSENGER AIR BAG	ACTIVATED	2,236.80	2,236.80
1	DASHBOARD	TORN	866.20	866.20
2	SET BELT FRONT @\$404.60	ACTIVATED	809.20	809.20
1	AIR BAG SRS UNIT	ACTIVATED	806.70	806.70
1	OIL COOLER PUMP	DENTED	165.30	165.30
1	OIL COOLER HOSE	NOT NECESSARY	22.50	-
2	FRONT SHOCK ABSORBERS @\$291.00	NOT NECESSARY	582.00	-
2	FRONT LOWER ARMS @\$265.00	NOT NECESSARY	530.00	-
2	FRONT KNUCKLE ARMS @\$366.20	NOT NECESSARY	732.40	-
2	FRONT KNUCKLE ARM BEARINGS @\$150.00	NOT NECESSARY	300.00	-
1	BATTERY TERMINAL BRACKET	CRACKED	92.50	92.50
2	FRONT CHASSIS MEMBERS @\$545.00	TO REPAIR SEE LABOUR	1,090.00	-
	LESS 20% DISCOUNT		-	-4,145.98
			28,074.80	16,583.92
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENCE PLATE (SN)	BENT	20.00	20.00
1	FRONT WINDSCREEN SOLAR FILM (SN)	NECESSARY	200.00	180.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	ENGINE OIL FILTER (SN)	DENTED	20.00	15.00
1	BATTERY (SN)	DENTED	200.00	80.00
			490.00	335.00
	<u>LABOUR</u>			
	TOWING CHARGE.		120.00	100.00
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.		180.00	120.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO DISMENTLE & REFIX ENGINE & GEARBOX.		500.00	350.00
	TO DISMENTLE & REFIX FRONT UNDERCARRIAGE.		500.00	300.00
	TO MOUNTING VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMENTLE & REPLACING FRONT DASHBOARD.		380.00	260.00

Report Ref No. CS/FCI18009128/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMENTLE & REPLACING FRONT AIRBAG, SEATBELT.		300.00	200.00
	TO DISMENTLE & REPLACING FRONT WINDSCREEN.		150.00	120.00
	LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER PANELS, FRONT WHEEL HOUSING PANELS AND FRONT CHASSIS MEMBERS.		2,500.00	1,500.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,500.00
			7,240.00	4,580.00
GRAND TOTAL			35,804.80	21,498.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				16,900.00

Report Ref No. CS/FCI18009128/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.