



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT18001840	Page	1
	5 MAXWELL ROAD	Date	: 4. May 2018		
	#17-00 TOWER BLK MND BUILDING	Customer No.	: WZE011		
	SINGAPORE 069110	Svc Advisor	: NG SIN HAI		
Registration No	: SKW398B	Engine No	: L15Z12101985		
Chassis No	: MRHDD4870FP000381	Date Time	: 4. May 2018 9:04:54 PM		
Model	: MOBILIO YM 2015	Surveyor Name	:		
Owner's Name	: TING SHANG KEE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 3/5/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:TING SHANG KEE						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:03/05/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:EQ INSURANCE COMPANY LTD						
	TP VEH:GBE1929P						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	150.00		150.00	10.50	160.50
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00	280	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	2500.00	1120	2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00	900	2800.00	196.00	2996.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	280.00		280.00	19.60	299.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	350.00	X	350.00	24.50	374.50
	Sum Labor				8300.00	581.00	8,881.00
RS-2P	BUMPER SENSOR 2PCS	1	150.00	X	150.00	10.50	160.50
33501-TE7-T01	LAMP UNIT,R.	1	205.70	X	154.27	10.80	165.07
33551-TE7-T01	LAMP UNITL.	1	205.70	X	154.27	10.80	165.07



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110
Registration No : SKW398B
Chassis No : MRHDD4870FP000381
Model : MOBILIO YM 2015
Owner's Name : TING SHANG KEE
Ins Policy No. :
Date of Accident : 3/5/2018

Document No. : SQT18001840
Date : 4. May 2018
Customer No. : WZE011
Svc Advisor : NG SIN HAI
Engine No : L15Z12101985
Date | Time : 4. May 2018 9:04:54 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
34150-TE7-T01	LIGHT ASSYR.LID	1	67.50	X 25	50.62	3.54	54.16
34155-TE7-T01	LIGHT ASSY,L.LID	1	67.50	X 25	50.62	3.54	54.16
74890-TE7-K11ZC	GARNISH ASSY,RR.LICENSE	1	152.20	X 25	114.15	7.99	122.14
75701-TE7-K00	EMBLEM H	1	17.90	X 25	13.42	0.94	14.36
90301-ST0-003	NUTPUSH 3MM	2	1.90	X 25	2.85	0.20	3.05
68100-TRD-K10ZZ	TAILGATE COMP	1	1092.30	PH 25	819.22	57.35	876.57
74440-TE7-K01	WEATHERSTRIPTAILGATE	1	62.80	X 25	47.10	3.30	50.40
74801-TF0-902	LOCK ASSYTAILGATE	1	174.70	X 25	131.02	9.17	140.19
75722-TE8-K00	EMBLEM SETRR.MOBILIO	1	18.30	an 25	13.72	0.96	14.68
75725-TRD-T00	EMBLEMRR.I VTEC	1	11.90	an 25	8.92	0.62	9.54
75723-TE7-K90	EMBLEMRR.RS	1	17.30	an 25	12.97	0.91	13.88
73225-TE7-K00	RUBBER A WINDSHIELD DAMPER	1	18.10	an 25	13.57	0.95	14.52
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.50	an 25	14.25	1.00	15.25
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	an 25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00	25	120.00	8.40	128.40
33505-TE7-T01	REFLECTOR ASSY (LEFT REAR)	1	7.00	X 25	5.25	0.37	5.62
33555-TE7-T01	REFLECTOR ASSY (RIGHT REAR)	1	7.00	an 25	5.25	0.37	5.62
71501-TE7-K90ZZ	FACERR.BUMPER	1	463.70	an 25	347.77	24.34	372.11
71502-TE7-K90	MOLDINGRR.BUMPER	1	109.10	an 25	81.82	5.73	87.55
71570-TE7-K90	ABSORBERR.RR.BUMPER	1	60.20	X 25	45.15	3.16	48.31
71575-TE7-K90	ABSORBERL.RR.BUMPER	1	60.20	X 25	45.15	3.16	48.31
71593-TE7-K01	SPACERR.RR.BUMPER SIDE	1	27.60	X 25	20.70	1.45	22.15
71598-TE7-K01	SPACERL.RR.BUMPER SIDE	1	27.60	X 25	20.70	1.45	22.15
91505-TG1-T01	CLIP ABUMPER	2	6.10	an 25	9.15	0.64	9.79
66100-TE7-K10ZZ	PANEL COMP,RR.	1	314.70	X 25	236.02	16.52	252.54
65510-TE7-K00ZZ	PANEL COMPRR.FLOOR	1	1310.10	X 25	982.57	68.78	1051.35
84640-TE7-K01ZB	LINING ASSYRR.PANEL	1	60.80	X 25	45.60	3.19	48.79
83785-TRD-P01ZB	LINING COMPL.RR.SIDE	1	117.20	X 25	87.90	6.15	94.05

Printed on 4/5/2018 9:13:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT18001840	Page	3
	: 5 MAXWELL ROAD	Date	: 4. May 2018		
	: #17-00 TOWER BLK MND BUILDING	Customer No.	: WZE011		
	: SINGAPORE 069110	Svc Advisor	: NG SIN HAI		
Registration No	: SKW398B	Engine No	: L15Z12101985		
Chassis No	: MRHDD4870FP000381	Date Time	: 4. May 2018 9:04:54 PM		
Model	: MOBILIO YM 2015	Surveyor Name	:		
Owner's Name	: TING SHANG KEE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 3/5/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
83735-TRD-P01ZB	LINING COMPR.RR.SIDE	1	117.20	25	87.90	6.15	94.05
84440-TE7-K00ZB	LINING ASSYTAILGATE LOWER	1	39.20	25	29.40	2.06	31.46
72841-SH3-315	OILSHEET	3	39.90	25	89.77	6.28	96.05
Sum Item					4033.27	282.32	4,315.59

Survey By	<u>Ram - Hp 90010068</u>	Total Amount	12,333.27	863.32	13,196.59
Date & Time	<u>18/06/18 @ 1145</u>	Total (Inclusive of GST)			<u>13,196.59</u>
Excess	<u>5 days</u>				
Status					
Signature	<u>Ram</u>				
	<u>Ram 54 print</u>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 4/5/2018 9:13:17 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)