


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : TIB1169Z
 Ref. No : BUS/05/18/1014
 Reg. Date : 15/05/2018
 Vehicle Type : BUS -17M
 Make : MB0405G 17M (MERCEDES)
 Model : MERCEDES 0405G
 Name of Driver : Che Wanliang
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 12/05/2018 06:30:00 AM
 Accident Reported Date / Time : 14/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : China Tai Ping
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 TIB1169Z - LEFT CENTRE PORTION
 YN3424X (TP) - INSURED WITH CHINA
 Prepared Date : 15/05/2018 10:26:39 AM



Sebastian
 16/5/18

- Lump Sum Repair
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	3,180.00	0.00
Total Spray Painting Charges :	1,466.00	0.00
Total Material Charges :	3,787.44	3,787.44
Other Charges :	0.00	0.00
TOTAL :	8,433.44	0.00
Lum Sum Total :	8,450.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :	Sunny Tan Ah Leong	<i>Sunny</i>
Arc / Surveyor Sign Off Date :	16/05/2018 10:15:23 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/05/2018 09:08:16 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	3,180.00	0.00 <i>2650</i>
Total Labour	3,180.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,466.00	0.00 <i>1200</i>
Total Spray Painting & Panel Beating	1,466.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
4515724002	COMMON	6008141	SIDE GLASS#2 1295X1480X5	1	1,975.80	10.00	1,778.22	Replace	Replace ✓	No <i>CHK</i>
	COMMON	6008143	SIDE WINDOW GLASS	1	1,140.26	10.00	1,026.23	Replace	Replace ✓	No
	COMMON	4006314	SEALANT SIKAFLEX	16	37.00	0.00	592.00	Replace	Replace ✓	No <i>N/E</i>
		4006315	ACTIVATOR	2	80.00	0.00	160.00	Replace	Replace ✓	No
	COMMON	4006313	PRIMER	2	80.00	0.00	160.00	Replace	Replace ✓	No
4879739696	VE	6004577	SIGNAL LIGHT	1	62.21	10.00	55.99	Replace	Replace ✓	No <i>CHK</i>
		4	60KM/H STICKER	1	15.00	0.00	15.00	Replace	Replace ✓	No <i>N/E</i>
TOTAL MATERIALS							3,787.44	3,787.44		
TOTAL MATERIALS(Discounted)							3,787.44	3,787.44		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									