

AXA

FZ p1

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ✗			\$ 142.20
	Front Bumper Reinforcement ✗			\$ 526.10
	Front Bumper Bracket Top (LH) ✗			\$ 22.40
	Front Bumper Side Bracket ✗			\$ 14.30
	Headlamp (LH) ✗			\$ 1,388.00
	SUB TOTAL			\$ 4,625.20
	LESS 20%			\$ 925.04
	DISCOUNTED TOTAL			\$ 3,700.16
	Labour Charge			
	Panel Beating			\$ 280.00 ²⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 50.00 ^x
	TOTAL LABOUR			\$ 580.00
	ESTIMATE TOTAL			\$ 4,280.16
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9536L

DATE 18/5/2018 16:06

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,681.40
	Boot Lid Rubber ✕			\$ 115.80
	Boot Lid Lock Upper ✕			\$ 137.90
	Boot Lid Lock Lower ✕			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 27.20
	Boot Lid CRDI Plate ✓			\$ 41.00
	Bootlid Moulding ✕			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 41.00
	Bootlid Lower Garnish ✕ <i>14 per</i>			\$ 398.00
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ✓			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>24 ✓ 14 x</i>	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket ✕	\$	49.00	\$ 98.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (LH) ✕			\$ 32.00
	<i>Ren End Panel ✕ repair</i>			
	SUB TOTAL			\$ 4,547.35
	LESS 20%			\$ 909.47
	DISCOUNTED TOTAL			\$ 3,637.88
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor ✕			\$ 135.70
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓	\$	100.00	\$ 200.00
				\$ 415.70
	Labour Charge			
	Panel Beating			\$ 400 850.00
	Spray Painting Charge			\$ 750.00 600
	Wiring Charge			\$ 50.00 ✕
	Tuff Kote			\$ 50.00 ✕
	Remove/Refix Reverse Sensor			\$ 120.00 20 ✕
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 5,873.58
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR

Signature:

ESTIMATE TOTAL

Kalan LKK

21/5/18 11:15 hrs

4 Days

PIP

Before Paint photo