

CONNECT 3

7 Old Toh Tuck Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/PC4477B/TPC-228

AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower
Singapore 068811

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC4477B

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)	
1.	Rear RH bumper	1	1,350.00	1,350.00	Repair
2.	RH side panel lower	1	2,400.00	2,400.00	PA✓
3.	Rear RH wheel rubber guard	1	250.00	250.00	SC✓
4.	Excursion bus sticker	1	15.00	15.00	X
5.	Apply anti rust	1	80.00	80.00	60
6.	Labour charges	1	1,200.00	1,200.00	600
7.	Spray painting	1	1,600.00	1,600.00	600
SUB-TOTAL				SS\$6,895.00	

Thank you.

Yours faithfully,


Winnie Chai
HP: 9850-9666



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasuk
Hp 90010068

5 days

Hs

21/05/18 @ 1050

Reg after repair