



# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Adrian Ling / Marcia Clua*  
**QUOTATION**  
11-00am  
GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

*Lkt auto 67418434 michella*

Customer : AXA INSURANCE S'PORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

Registration No : SLP4006G

Chassis No : MRHFC5650GT001488

Model : CIVIC 1.6 VTI YM2016

Owner's Name : LEE KOK KEONG

Ins Policy No. : 10759066

Date of Accident : 15/5/2018

Document No. : SQT18001989 Page 1

Date : 15. May 2018

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : R16B21601800

Date | Time : 15. May 2018 11:56:34 AM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 8100 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70493) OWNER: LEE KOK KEONG OWNER INSURER: AVIVA INSURANCE LTD ACC DATE: 15/05/2018@08.00AM SURVEYED BY: 8~12 WORKING DAYS REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SLR3914G (HONDA/SHUTTLE/SILVER)						
75722-TBA-A00	EMBLEM SETRR.	1 <i>new</i>	11.50	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR.	1 <i>new</i>	10.60	25	7.95	0.56	8.51
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1 <i>del</i>	97.70	25	73.27	5.13	78.40
91505-TM8-003	CLIPBUMPER	14 <i>new</i>	2.00	25	21.00	1.47	22.47
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1 <i>del</i>	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISHRR.BUMPER LOWER	1 <i>del</i>	35.30	25	26.47	1.85	28.32
71506-TEX-Y00	COVERRR.TOWING HOOK	1 <i>del</i>	3.00	25	2.25	0.16	2.41
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1 ?	7.60	25	5.70	0.40	6.10
33555-TEA-T01	REFLECTOR ASSYL.RR.	1 ?	7.00	25	5.25	0.37	5.62
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1 <i>new</i>	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1 <i>new</i>	11.50	25	8.62	0.60	9.22
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1 <i>new</i>	2.20	25	1.65	0.12	1.77
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1 <i>new</i>	2.20	25	1.65	0.12	1.77
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>photo.</i>	1 ?	160.00	25	120.00	8.40	128.40
66100-TEC-307ZZ	PANEL SETRR.	1 ?	236.00	25	177.00	12.39	189.39
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1 ?	26.00	25	19.50	1.37	20.87
63722-TEA-T00ZZ	ADAPTERL.RR.COMBINATION LIGHT	1 ?	58.90	25	44.17	3.09	47.26
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1 ?	210.40	25	157.80	11.05	168.85
68500-TEA-N00ZZ	LID COMP TRUNK	1 <i>bt</i>	472.10	25	354.07	24.78	378.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1 ?	70.00	25	52.50	3.68	56.18
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1 ?	43.50	25	32.62	2.28	34.90



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

Registration No : SLP4006G

Chassis No : MRHFC5650GT001488

Model : CIVIC 1.6 VTI YM2016

Owner's Name : LEE KOK KEONG

Ins Policy No. : 10759066

Date of Accident : 15/5/2018

Document No. : SQT18001989 Page 2

Date : 15. May 2018

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : R16B21601800

Date | Time : 15. May 2018 11:56:34 AM

Surveyor Name : DID : +65 6846 5673

Survey Date : HP : +65 6100 6306

Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1 ?	43.50	25	32.62	2.28	34.90
74851-TEA-003	LOCK ASSYTRUNK	1 ?	72.20	25	54.15	3.79	57.94
34150-TEX-Y01	LIGHT ASSYR.LID	1 X	118.70	25	89.02	6.23	95.25
34155-TEX-Y01	LIGHT ASSYL.LID	1 X	118.70	25	89.02	6.23	95.25
33500-TEA-T01	TAILLIGHT ASSYR.	1 X	253.80	25	190.35	13.32	203.67
33550-TEA-T01	TAILLIGHT ASSYL.	1 <i>100%</i>	273.10	25	204.82	14.34	219.16
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1 ?	27.20	25	20.40	1.43	21.83
39680-TEX-Y41ZT	SENSOR ASSYPARKING	4 ?	79.80	25	239.40	16.76	256.16
72841-SH3-315	OILSHEET	1 ?	39.90	25	29.92	2.09	32.01
<b>Sum Item</b>					<b>2541.31</b>	<b>177.89</b>	<b>2,719.20</b>
BOSUN	SUNDRIES	1 <i>20</i>	50.00		50.00	3.50	53.50
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 <i>140</i>	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 <i>140</i>	240.00		240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BOMISC1	REMOVE,INSTALL & CALIBRATE REVERSE CAMERA	1 <i>300</i>	350.00		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM DOORS	1 <i>300</i>	350.00		350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1 <i>300</i>	450.00		450.00	31.50	481.50
BKTRR	REMOVE & RENEW TRUNK LID.	1 <i>400</i>	450.00		450.00	31.50	481.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1 <i>1350</i>	2800.00		2800.00	196.00	2996.00
BKRP22B	CUT OFF & RENEW RR FLOOR PANEL & RR PANEL	1 <i>1680</i>	4800.00		4800.00	336.00	5136.00
<b>Sum Labor</b>					<b>10120.00</b>	<b>708.40</b>	<b>10,828.40</b>

Survey By

*Tan Jiah 97495749*

*sur@kauto.com*

Date & Time

*24/5/18 11:50*

*Resurvey before paint*

Excess

*WP*

*5-6 days.*

Total Amount to 12,661.31  
Total (Inclusive of GST) 13,547.60

- 13,547.60**
- the Repairer of the following:
- To resurvey before after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modifications is allowed
  - Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 15/5/2018 12:58:32 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)