



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE CAI FONG CLAUDIA
BLK 822 JURONG WEST ST 81 #10-396
SINGAPORE 640822

Attention : THE OWNER
Contact : 96541077

Estimate : ES006354

Date : 16/05/2018
Vehicle Num. : SJS7927L
Make/Model : KIA CERATO FORTE-2009
Chassis/Eng# : KNAFW411MA5112285/G4FC9H2845
Accident Date : 16/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	REAR FENDER R/H / BUC ?		885.30 ?
2.	1	REAR FENDER INNER TRIM R/H		285.00
3.	6	REAR FENDER INNER TRIM CLIP R/H / MCL	5.00	30.00 ?
4.	1	TAIL LAMP R/H / CHA		352.00 ?
5.	1	REAR DOOR R/H / BUC		866.80 ?
6.	1	REAR DOOR OUTER HANDLE R/H / Cut		95.00
7.	1	FRONT DOOR OUTER HANDLE R/H / Cut		95.00
8.	1	REAR FENDER INNER SHIELD R/H / ee.		133.00
9.	4	REAR INNER SHIELD CLIP R/H / MCL	5.00	20.00
10.	1	REAR W/SCREEN MOULDING / MCL		185.00
11.	1	REAR BUMPER / ee		685.00 ?
12.	6	REAR BUMPER CLIP / MCL	6.80	40.80
13.	1	REAR BUMPER SIDE RETAINER R/H / ee		69.00
14.	1	REAR MUDFLAP R/H X		61.00
15.	1	REAR WHEEL BEARING R/H /		391.00
16.	1	REAR KNUCKLE ARM R/H X		633.00 X
17.	1	REAR AXLE ASSY X		1,592.00 X
18.	1	REAR SPORT RIM R/H X		790.00 150
19.	1	FRONT DOOR R/H X { Repairs. 150 (SN) (local repair)		840.00 X
Nett Total S\$:				8,048.90
10.00% Discount S\$:				804.89
				7,244.01
SPECIAL NETT ITEMS :				
1.	1	REAR W/SCREEN SEALANT / MCL.		65.00
Special Nett Total S\$:				65.00

CONTINUE / ...



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

LEE CAI FONG CLAUDIA
 BLK 822 JURONG WEST ST 81 #10-396
 SINGAPORE 640822

Attention : THE OWNER
 Contact : 96541077

Estimate : ES006354

Date : 16/05/2018
 Vehicle Num. : SJS7927L
 Make/Model : KIA CERATO FORTE-2009
 Chassis/Eng# : KNAFW411MA5112285/G4FC9H2845;
 Accident Date : 16/05/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
		REMOVE & REINSTALL REAR W/SCREEN GLASS	100	180.00
		REMOVE & REINSTALL REAR UPHOLSTERY, SEATS AND BELTS	80	260.00
		TRANSFER R/H REAR DOOR COMPONENTS TO NEW DOOR	60	150.00
		TRANSFER R/H FRONT DOOR COMPONENTS TO NEW DOOR	150	150.00
		REMOVE & RE-INSTALL REAR AXLE ASSY	150	250.00
		TO PRESS OUT AND IN REAR WHEEL BEARING	30	60.00
		CHANGE TAIL LAMP AND CHECK LIGHTING		45.00
		TO CUT OFF REAR R/H FENDER, KNOCK AND STRAIGHTEN R/H		
		CENTER DOOR PILLAR, R/H ROCKER PANEL, AND CHANGE ALL		
		NECESSARY PARTS	700	1,600.00
		RUST PROOFING TREATMENT	60	100.00
		SPRAY PAINT DAMAGED AREA AFFECTED	800	1,100.00
		TOW VEHICLE	100	120.00
Labour Total S\$:				4,015.00

Gua Qian. - 82880282

18/5/18.

Lump Sum Repair.

After repair photos.

SingDollars : Eleven Thousand Three Hundred Twenty-Four & Cents One Only

8 Days.

Total S\$: 11,324.01
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: