

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel: +65 6679 1146

email:ben@allswellmotor.com.sg

2 Days

part by part.

before part photos.

Eno Qiao 22/5/18

(3rd party claim against Ergo Insured GEGTTTTK)

Estimate repair

Vehicle No.

: SKZ 3464 H

Submitted by

Ben

Make & Model

: Toyota Auris

COE expiry

: 18-01-2026

Chassis No.

Engine No.

Date of survey

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper - CFA	01	\$1,019.00	531.75	
			25%	398.81	
	Labour Description				
01	Dismantle / Assembly of rear bumper including sensor elements.	01	\$160	40	
02	Spray painting of rear bumper	01	\$360	200	
03	Make sensor's holes (2x) on rear bumper	01	\$120	X	NN
	Special Mett				
01	Change bumper @ \$11.00 each	02	\$22.00	/ MC	
	LKK Auto Consultants hence notify the Repairer of the following:				
	• To resurvey before/after spray painting				
	• To display damaged part(s) during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
			1681.00		
				660.81	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Acknowledged by Repairer

Signature:

Date: