



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

AXA/FC(SHB2345L)

DOA: 14/05/2018@1410

MS FIRST CAPITAL INSURANCE LTD

17/5/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJJ 194 C - AUDI A6 2.0T FSI MU CVT ABS D/AIRBAG GAS/D

CHASSIS NO: WAUZZZ4F78N154975 (2008)

Supplementary

20 pcs	Front bonnet sponge clips @ \$3.50	\$ 70.00	new ✓
1 pc	Front fender inner shield LH	\$ 395.40	?
1 pc	Front fender inner shield round cover LH	\$ 25.50	miss ✓
1 pc	Front headlamp xenon bulb	\$ 412.50	?
1 pc	Front headlamp balast LH	\$ 641.50	?
1 pc	Front headlamp support bracket	\$ 55.60	new ✓
1 pc	Front bumper nozzle LH	\$ 250.70	?
1 pc	Front bumper sensor LH	\$ 245.70	ant ✓
1 pc	Front grille top garnish	\$ 102.10	ant ✓
1 pc	Front support panel	\$ 958.30	? plus to.
1 pc	Inter-cooler	\$ 855.40	?
		\$ 4,012.70	
	LESS 5%	\$ 200.64	
		\$ 3,812.06	
	Radiator coolant	\$ 40.00	?
	To remove, reinstall a/c assy and refill gas	\$ 100.00	?
	Remove and replace front support panel	\$ 300.00	200.
		\$ 4,252.06	
	ADD 7% GST	\$ 297.64	
		\$ 4,549.70	

CHARN'S CUSTOMCRAFT

.....