

ASS. REC. BY:

REF:

CS/FCL18009163/Usbn2

Special Instruction:

Surveyor: MarwaASSIGNMENT (Office)From (Person): WS Eileen Lee of FCL Date/Time: 21/05/2018 3:18pm

Estimated Cost: _____ Bill to: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLK 7115 G Insured: SHD 3748Rat Workshop m/s Pegasus Tel: 6858 1846of 51 Delta Lane 10Policy No: _____ Claim No: D13003968MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16052018
(Client's Record)CA / REV / REP. / REV 24 HRS wp 24052018 H.O.D. Endorsement: _____Date/Time: 21/05/2018 3:02pm Person Contacted: Alvin Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	SLK 7115 G - X
	SHD 3748R - CA / ALU711002046 / 62 D.O.A. 01/02/11
<u>28/05/18</u>	<u>@ 17:07 p.m. revised to Eileen (PA) via email.</u>
<u>08/06/18</u>	<u>(\$5,937.84 - \$3,500/-) & - Reduction = 41%</u>

REF: FCI

ASSIGNMENT

From:

Date:

24/5/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLK 7115G

at Workshop m/s

Pegasus
51 Refu Lane 10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

30

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLK 7115G

Yr Regn:

1/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

mercedes

C.C.

1496

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

10/111

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM 63N 22A 8H 0135880

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/5/18

D.O.I.

24/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/6/18 confirmed 4/5 @ 3500 with willian.

RECEIVED 8 JUN 2018

Date/Time: File Pass to?

08/06/18

1)

T.p.s.t

Date/Time: File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

3,500 - 45

TOTAL

140

50

50

40

280



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003968MFSH

Date: 28 May 2018

Our Ref: CS/FCI18009163/Usb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 7115G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/05/2018 at the premises of M/s Pegasus Engineering & Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,937.84</u> .
Revised Estimate Amount	: S\$ <u>4,048.48</u> .
"Check" Items Amount	: S\$ <u>328.56</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-05-2018	Our Ref No. D18003968MFSH
Accident Date	16-05-2018	Claim Type. Third Party
Insured Vehicle	SHD3748R	Third Party Vehicle. SLK7115G
Survey Location	51 DEFU LANE 10	
Contact Person.	WEE	
Contact No.	68581846/ 68581846	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

21/05/18 @ 3:02 PM
Alvin Wee

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	7200G

Vehicle Details

Vehicle No.:	SLK7115G
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 May 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520421222
Chassis No.:	JM6BN22A8H0135850
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,777.00
Original Registration Date:	24 Jan 2017
First Registration Date:	24 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$9,777.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2027
PARF Rebate Amount:	\$7,332.00

Intended COE Rebate Details

COE Expiry Date:	23 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$38,400.00
Total Rebate Amount:	\$45,732.00

The information contained herein is correct as at 16 May 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 7200G

Vehicle Details

Vehicle No.: SLK7115G

Vehicle to be Exported: No

Intended De-registration Date: 24 May 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: P520421222

Chassis No.: JM6BN22A8H0135850

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$14,777.00

Original Registration Date: 24 Jan 2017

First Registration Date: 24 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$9,777.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Jan 2027

PARF Rebate Amount: \$7,332.00

Intended COE Rebate Details

COE Expiry Date: 23 Jan 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$48,000.00

COE Rebate Amount: \$41,587.00

Total Rebate Amount: \$48,919.00

The information contained herein is correct as at 24 May 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 28 May 2018 5:07 PM
To: 'Claim Workflow System'; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Cc: sur@lkkauto.com; 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18003968MFSH/1
Attachments: SLK 7115G - Preli Advise.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLK 7115G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 21 May 2018 3:03 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18003968MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 21 May, 2018 2:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003968MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

24/5/18
not placed
3500/2
d/s
5 day
Reg: 446 - American
Chaple Office
24/05/18 c 1050h

Quotation No : QO18/05-1181	Quotation Date : 16/05/2018	Terms : 30 DAYS
Vehicle No : SLK7115G	Chassis No : JM6BN22A8H0135850	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHD3748R, DATE OF ACCIDENT: 16.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR DOOR RH <i>50/600</i>	1	999.4000	999.40 ✓
2	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11</i>	1	116.8000	116.80 ✓
3	REAR DOOR OUTER WEATHERSTRIP MOULDING <i>11</i>	1	141.0000	141.00 ✓
4	REAR DOOR INNER LOCK <i>11</i>	1	179.7000	179.70 ✓
5	REAR DOOR INNER LOCK STRIKER <i>11</i>	1	28.0000	28.00 ✓
6	REAR DOOR WEATHERSTRIP <i>nee</i>	1	120.7000	120.70 ✓
7	REAR DOOR WINDOW FRAME GARNISH FRONT <i>11</i>	1	108.0000	108.00 ✓
8	REAR DOOR WINDOW FRAME GARNISH TOP <i>11</i>	1	49.0000	49.00 ✓
9	REAR DOOR POWER WINDOW MOTOR <i>3m/s wheel</i>	1	290.0000	290.00 ✓
10	REAR DOOR REGULATOR <i>11</i>	1	120.7000	120.70 ✓
11	REAR FENDER RH <i>30/1500</i>	1	334.0000	334.00 ✓
12	REAR FENDER INNER LINER RH <i>11</i>	1	146.0000	146.00 ✓
13	REAR FENDER INNER LINER CLIPS <i>11</i>	4	5.0000	20.00 ✓
14	REAR WINDSHIELD GLASS WEATHERSTRIP <i>nee</i>	1	117.0000	117.00 ✓
15	REAR BUMPER <i>deep cut</i>	1	1,075.0000	1,075.00 ✓
16	REAR BUMPER SIDE RETAINER RH <i> Bent</i>	1	37.0000	37.00 ✓
17	REAR BUMPER CLIPS <i>nee</i>	8	5.0000	40.00 ✓
18	REAR WHEEL HUB CAP RH <i>cut</i>	1	75.0000	75.00 ✓
19	LESS 20% (ITEM 1 - 18)	1	-799.4600	-799.46
20	REAR WINDSHIELD GLASS SEALANT <i>nee</i>	1	200.0000	200.00 <i>40</i> ✓ <i>S.N</i>
21	REAR WINDSHIELD GLASS SPONGE <i>nee</i>	1	120.0000	120.00 <i>30</i> ✓ <i>S.N</i>
22	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	900.0000	900.00 <i>680</i> ✓ <i>680</i>

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/05-1181	Quotation Date : 16/05/2018	Terms : 30 DAYS
Vehicle No : SLK7115G	Chassis No : JM6BN22A8H0135850	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHD3748R, DATE OF ACCIDENT: 16.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	850.0000	850.00
24	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	120.00
25	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GANISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00
26	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	40.0000	40.00
27	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	180.00
28	TO TRANSFER OF RH REAR DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	150.0000	150.00

Let Auto Insurance Service notify the Repairer of the following:

- To get job before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Sub Total	5,937.84
GST(7.00%)	415.65
Total (SGD)	6,353.49

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation *(confirmed)*

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216
Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer : *28/05/18*
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn : *1. Han*
Tel :
Fax : *28/05/18*
24/05/18 10:50h

Quotation No : QO18/05-1181	Quotation Date : 16/05/2018	Terms : 30 DAYS
Vehicle No : SLK7115G	Chassis No : JM6BN22A8H0135850	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHD3748R, DATE OF ACCIDENT: 16.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR DOOR RH <i>Scld</i>	1	999.4000	999.40
2	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11</i>	1	116.8000	116.80
3	REAR DOOR OUTER WEATHERSTRIP MOULDING <i>11</i>	1	141.0000	141.00
4	REAR DOOR INNER LOCK <i>11</i>	1	179.7000	179.70
5	REAR DOOR INNER LOCK STRIKER <i>11</i>	1	28.0000	28.00
6	REAR DOOR WEATHERSTRIP <i>rec</i>	1	120.7000	120.70
7	REAR DOOR WINDOW FRAME GARNISH FRONT <i>11</i>	1	108.0000	108.00
8	REAR DOOR WINDOW FRAME GARNISH TOP <i>11</i>	1	49.0000	49.00
9	REAR DOOR POWER WINDOW MOTOR <i>gm/shld</i>	1	290.0000	290.00
10	REAR DOOR REGULATOR <i>11</i>	1	120.7000	120.70
11	REAR FENDER RH <i>Bo/bod</i>	1	334.0000	334.00
	REAR FENDER INNER LINER RH <i>11</i>	1	146.0000	146.00
13	REAR FENDER INNER LINER CLIPS <i>11</i>	4	5.0000	20.00
14	REAR WINDSHIELD GLASS WEATHERSTRIP <i>rec</i>	1	117.0000	117.00
15	REAR BUMPER <i>deep cut</i>	1	1,075.0000	1,075.00
16	REAR BUMPER SIDE RETAINER RH <i> Bent</i>	1	37.0000	37.00
17	REAR BUMPER CLIPS <i>rec</i>	8	5.0000	40.00
18	REAR WHEEL HUB CAP RH <i>cut</i>	1	75.0000	75.00
19	LESS 20% (ITEM 1 - 18)	1	-799.4600	-799.46
20	REAR WINDSHIELD GLASS SEALANT <i>rec</i>	1	200.0000	200.00
21	REAR WINDSHIELD GLASS SPONGE <i>rec</i>	1	120.0000	120.00
22	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	900.0000	900.00

C/F 0.00
Page 1 of 2

3088-1
2470.48

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO18/05-1181

Quotation Date : 16/05/2018

Terms : 30 DAYS

Vehicle No : SLK7115G

Chassis No : JM6BN22A8H0135850

Third Party Insurer :

Model : MAZDA 3

Date of Accident :

ks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHD3748R, DATE OF ACCIDENT: 16.05.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
23	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	850.0000	850.00
24	TO RUST-PROOFING OF THE AFFECTED AREAS	1	120.0000	120.00
25	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GANISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00
26	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	40.0000	40.00
27	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1	180.0000	180.00
28	TO TRANSFER OF RH REAR DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	150.0000	150.00

Parts: 2,238.48

Labour: 1,890.00

4,128.48

Less 70%, 3,302.78

1/sum @ 3,300/-

4380.48

Sub Total	5,937.84
GST(7.00%)	415.65
Total (SGD)	6,353.49

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC118009163/Usbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3748R	Veh. Inspected	SLK 7115G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003968MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	21/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0135850	Colour	GREY	
Odometer	101111	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/05/2018	Inspection Date	24/05/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7115G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR RH	BADLY DENTED	999.40	999.40
1	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	116.80	-
1	REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	141.00	-
1	REAR DOOR INNER LOCK	NOT NECESSARY	179.70	-
1	REAR DOOR INNER LOCK STRIKER	NOT NECESSARY	28.00	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	120.70	120.70
1	REAR DOOR WINDOW FRAME GARNISH FRONT	NOT NECESSARY	108.00	-
1	REAR DOOR WINDOW FRAME GARNISH TOP	NOT NECESSARY	49.00	-
1	REAR DOOR POWER WINDOW MOTOR	JAMMED / SHORTED	290.00	290.00
1	REAR DOOR REGULATOR	NOT NECESSARY	120.70	-
1	REAR FENDER RH	BADLY DENTED	334.00	334.00
1	REAR FENDER INNER LINER RH	NOT NECESSARY	146.00	-
4	REAR FENDER INNER LINER CLIPS @\$5.00	NOT NECESSARY	20.00	-
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NECESSARY	117.00	117.00
1	REAR BUMPER	DEEP CUT	1,075.00	1,075.00
1	REAR BUMPER SIDE RETAINER RH	BENT	37.00	37.00
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
1	REAR WHEEL HUB CAP RH	CUT	75.00	75.00
	LESS 20% DISCOUNT		-799.46	-617.62
			3,197.84	2,470.48
SPECIAL NETT ITEMS				
1	REAR WINDSHIELD GLASS SEALANT (SN)	NECESSARY	200.00	40.00
1	REAR WINDSHIELD GLASS SPONGE (SN)	NECESSARY	120.00	30.00
			320.00	70.00
LABOUR				
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		900.00	680.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		850.00	800.00

Report Ref No. CS/FCI18009163/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	80.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		180.00	80.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		40.00	20.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO TRANSFER OF RH REAR DOOR FITTING, FICTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST.		150.00	60.00
			2,420.00	1,840.00
GRAND TOTAL			5,937.84	4,380.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/FCI18009163/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.