

SS. REC. BY:

REF:

CS/CT18009164 / Ksb

Special Instruction:

Surveyor

Munnen

ASSIGNMENT (Office)

From (Person): Sharon Him

of CTL

Date/Time: 21052018 1009am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 7405J

Insured:

SLC 3399Y

at Workshop m/s

Accord Auto

Tel:

64819517

of

Blk 10 AMK Ind Park 2A #03-11

Policy No:

DMPCSN3081831700

Claim No:

SNM18D02408602

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12052018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

03052018 @ after 12pm

H.O.D. Endorsement:

Date/Time:

21052018 1055am

Person Contacted:

Jessey

Vehicle IN LOT

Date/Time	Action/Instruction (✓) Estimate	
	SJH 7405J - NS/INC17011586 / Kibbe1	DIA: 130617
	SLC 3399Y - PS/CT18005405 / Uvd3	DIA: 180318
24/7	11pm 8510d enal & cgr firm	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 May 2018		21 May 2018 10:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KATHERINA SIM PEI MING, ID: S8269946E								
Main Claimant:	ALEXLOH138, Co. Reg. No.: 53353658L								
Vehicle Reg. No.:	SJH7405J	Date of Loss:	12/05/2018 14:00 - :59						
Claim Type:	TP / SNM18D02408C02	Policy/Cover Note No.:	DMPCSN3082631700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLC3399Y	Policy No. (Claimant):	5087382111						
		Excess:	S\$0.00						
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/05/2018]								
Driver/Custodian (Insured):	KATHERINA SIM PEI MING (35 / Female), NRIC: S8269946E								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

21052018 @ 1055am
 Jessy with red in

> Back to OneMotoring

Enquire Transfer Fee

Vehicle No. :	SJH7405J
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	VIOSE AUTO
Chassis No. :	MRD53HY9305050925
Propellant :	Petrol
Engine No. :	1NZX697518
Engine Capacity :	1497 cc
Maximum Power Output :	80.0 kW (107 bhp)
Maximum Laden Weight :	1505 kg
Unladen Weight :	1095 kg
Year Of Manufacture :	2008
Original Registration Date :	22 Aug 2008
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
PQP Paid :	\$19,107.00
COE Expiry Date :	30 Jun 2023
Road Tax Expiry Date :	21 Aug 2018
PARF Eligibility Expiry Date :	21 Aug 2018
Inspection Due Date :	21 Aug 2019
Intended Transfer Date :	29 Jun 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
The current road tax expiry is 21 Aug 2018. You may renew the road tax from 22 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	377.00	-	377.00
Total Amount Payable :			402.00

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	753.00	-	753.00
Total Amount Payable :			778.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2018 14:20
Date Of Accident	12/05/2018 14:00
Exact Location Of Accident	YUAN CHING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH7405J
Insured/Policyholder	
Name Of Registered Owner	ALEXLOH138
Co Reg No	53353658L
Email Address	ALEXLOH138@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-85136488

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087382111
Cover Note Number	

Driver

Name of Driver	LOH CHEN OO
NRIC No	S2583386D
Date Of Birth	27/06/1967
Occupation	OUTDOOR
Date Of Driving Pass	09/05/2013
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91067947
Fax Number	
Contact Number	
Email Address	ALEXLOH138@YAHOO.COM.SG

Address	BLK 435 JURONG WEST STREET 42 #04-554
Postcode	640435
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : LOH SOOK CHOON GENDER: : FEMALE
Passenger 2	NAME: : LOH MEI XUAN GENDER: : FEMALE
Passenger 3	NAME: : LOH CHEE YONG GENDER: : MALE
Passenger 4	NAME: : LOH JUN MING GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC3399Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LOH CHEN OO
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJH7405J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 435 JURONG WEST STREET 42 #04-554
Postcode	640435

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ALEXLOH138

Co-Reg No. 53353658L

Policyholder's Signature

Date & Time:

14/5/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

14/5/2018

Reporting Centre Personnel's Signature

Name:

Jodelle Tan


NRIC/FIN No.:

AMK AUTOPPOINT PTE LTD

15-05-2018

Sketch Plan #2

SKETCH PLAN Vehicle A: JH 7405J Vehicle B: SLC 3399Y.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Accident: _____ Time of Accident: _____

While I driving along Yuan Ching Road, suddenly vehicle C turning out from Ho Chi Ching Road and I make the emergency brake to complete stop. However vehicle B behind me could not stop in time and hit onto my rear vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

ALEXLOH138
CA Reg No: 53353658L

Policyholder's Signature
Date & Time: 12/5/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/15/2023

Reporting Centre Personnel's Signature

Name: JOELLE TAN
NRIC/PPN NO.: ARNK AUTOPPOINT PTE LTD
15.05.2018

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#15-00 Springleft Tower

Singapore 079909

Attn: Accident Claims Department

Date: 18/05/2018
Vehicle No: SJH7405J
Veh Make/Model: Toyota Vios E Auto
YOM: 2008
Chassis No: MR053HY9305050925
Date of Accident: 12/05/2018

Not Authorized
1/18/2018 @ \$1000
Reserve After Repair
8 days

No	Qty	Description	Amount S
		<u>List Items:-</u>	
1	1	Bootlid	\$ 642.00
2	2	Bootlid hinge	\$ 114.20
3	1	Bootlid lock	\$ 109.10
4	1	Bootlid lock striker	\$ 42.10
5	1	Bootlid rubber	\$ 188.20
6	4	Bootlid stopper	\$ 87.80
7	1	Bootlid logo	\$ 49.20
8	1	Bootlid "Vios" emblem	\$ 47.50
9	1	Bootlid "Sport" emblem	\$ 47.50
10	1	Bootlid center garnish	\$ 132.00
11	2	Bootlid number plate lamp	\$ 74.00
12	1	Rear windscreen glass moulding	\$ 105.00
13	1	Rear LH fender	\$ 979.70
14	1	Rear LH fender splash shield	\$ 49.50
15	10	Rear LH fender splash shield clip	\$ 30.00
16	1	Rear RH fender	\$ 979.70
17	1	Rear RH fender splash shield	\$ 49.50
18	10	Rear RH fender splash shield clip	\$ 30.00
19	1	LH taillamp	\$ 289.00
20	1	LH taillamp panel	\$ 195.20
21	1	LH taillamp gasket	\$ 6.00
22	1	RH taillamp	\$ 289.00
23	1	RH taillamp panel	\$ 195.20
24	1	RH taillamp gasket	\$ 6.00
25	1	Rear bumper	\$ 670.10
26	2	Rear bumper side retainer	\$ 246.20
27	10	Rear bumper clip	\$ 30.00
28	1	Rear bumper reflector - LH	\$ 134.60
29	1	Rear bumper reflector - RH	\$ 134.60
30	1	End panel	\$ 608.10
Balance b/f			\$ 6,561.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleft Tower
Singapore 079909
Attn: Accident Claims Department

Date : 18/05/2018
Vehicle No : SJH7405J
Veh Make/Model : Toyota Vios E Auto
YOM : 2008
Chassis No : MR053HY9305050925
Date of Accident : 12/05/2018

No	Qty	Description	Amount S
		Balance c/f	\$ 6,561.00
31	1	End panel top garnish	\$ 383.90
32	6	End panel top garnish clip	\$ 9.00
33	1	LH airduct	\$ 155.40
34	1	RH airduct	\$ 155.40
35	1	Floor panel	\$ 867.80
36	1	Floor panel board	\$ 301.70
37	1	Floor panel side board - LH	\$ 261.46
38	1	Floor panel side board - RH	\$ 261.46
39	1	Floor panel carpet	\$ 307.10
40	1	Rear LH fender inner trim board	\$ 230.30
41	1	Rear RH fender inner trim board	\$ 230.30
42	1	Spare tyre trunk	\$ 151.70
43	1	Spare tyre mounting bolt	\$ 56.30
44	1	Spare tyre tools tray	\$ 285.30
45	1	Car jack	\$ 161.80
46	1	Car jack bracket	\$ 96.10
47	1	Exhaust silencer	\$ 781.90
48	3	Exhaust silencer mounting	\$ 122.20
49	1	Exhaust silencer chorme pipe	\$ 120.00
50	1	Exhaust silencer gasket	\$ 53.90
51	1	Exhaust silencer heat shield	\$ 171.20
		Total - List Item	\$ 11,725.22
		Less 25%	\$ 2,931.31
		Total	\$ 8,793.92
		Balance b/f	\$ 8,793.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleft Tower
Singapore 079909
Attn: Accident Claims Department

Date : 18/05/2018
Vehicle No : SJH7405J
Veh Make/Model : Toyota Vios E Auto
YOM : 2008
Chassis No : MR053HY9305050925
Date of Accident : 12/05/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 8,793.92
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ <i>CMA</i> 55.00
2	1 set	Rear reverse sensor	\$ <i>Short</i> 280.00
3	1	Bootlid compartment waterproof sealant	\$ <i>nn</i> 150.00
4	1	Spare tyre	\$ <i>nn</i> 280.00
5	1	Spare tyre wheel rim	\$ <i>nn</i> 340.00
6	1	Rear windscreen glass sealant and gum	\$ <i>nn</i> 80.00
		Total - SN Item	\$ 1,185.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 2,100.00
2		Labour Remove/Refix Accident Damages parts to knock, jack, cut weld and realign accident affected area.	\$ 2,100.00
3		To apply anti rust treatment.	\$ 200.00
4		To check wiring system and light.	\$ 120.00
5		To remove and replace/reinstall bootlid attachment.	\$ 200.00
6		To remove and replace reverse sensor.	\$ 120.00
7		To remove and reinstall rear inner compartment/interior upholstery & rear seat to facilities repair.	\$ 200.00
8		To remove and reinstall rear windscreen glass to replace rear LH & RH fender.	\$ <i>nn</i> 150.00
9		To check and text bootlid water leaking.	\$ 80.00
10		To remove and replace exhaust silencer, pipe, mounitng & etc..	\$ 180.00
		Total - L/C	\$ 5,450.00
		Sub-Total	\$ 15,428.92
		7% GST	\$ 1,080.02
		Total	\$ 16,508.94

6500
2000
X
X
X
X

11000
12000
600
200
500
500
1000
X
200
600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 May 2018		21 May 2018 10:09 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	KATHERINA SIM PEI MING , ID: S8269946E								
Main Claimant:	ALEXLOH138 , Co. Reg. No.: 53353658L								
Vehicle Reg. No.:	SJH7405J	Date of Loss:	12/05/2018 14:00 - :59 [116 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02408C02	Policy/Cover Note No.:	DMPCSN3082831700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLC3399Y	Policy No. (Claimant):	5087382111						
		Excess:	S\$0.00						
Repairer:	Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point, 568047 Ang Mo Kio - Tel: 64819517/85715140								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/05/2018]								
Driver/Custodian (Insured):	KATHERINA SIM PEI MING (35 / Female), NRIC: S8269946E								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents
























*SJH7405J (SNM18D02408C02)
[SLC3399Y]
TP
ALEXLOH138
May 12 2018 2:00PM
[KATHERINA SIM PEI MING]
Accord Auto Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print			
1	15/05/18 14:33	Accident Statement		Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print			
1	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
2	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
3	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
4	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
5	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
6	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
7	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
8	15/05/18 14:27	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
9	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
10	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
11	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
12	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
13	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
14	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
15	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
16	15/05/18 14:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
17	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
18	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
19	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
20	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
21	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
22	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
23	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
24	15/05/18 14:29	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	25/07/18 09:36	General View		Load JPG				

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
2	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
4	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
13	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
14	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
15	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
16	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
17	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
18	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
19	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
20	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
21	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
22	25/07/18 09:36	General View	Load JPG	<input checked="" type="checkbox"/>
23	25/07/18 09:36	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
24	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	25/07/18 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/05/18 10:08	PRS	Load PDF	
2	21/05/18 10:08	OI GIA REPORT	Load PDF	
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print
1	15/05/18 14:31	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	15/05/18 14:31	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print	
1	15/05/18 14:33	Accident Statement	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print	
1	15/05/18 14:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
2	15/05/18 14:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
3	15/05/18 14:27	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print
4	15/05/18 14:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/05/18 14:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/05/18 14:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/05/18 14:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	15/05/18 14:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	15/05/18 14:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
24	15/05/18 14:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print
1	15/05/18 14:31	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	15/05/18 14:31	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118009164/KSBQ2

Date: 30/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3082831700

Claimant Vehicle
No : SJH7405JInsured Vehicle
No : SLC3399Y

Date of Loss: 12/05/2018

Nature of Claim: TP

Claim
No: SNM18D02408C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH7405J**

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX697518

Reg. Date: 22/08/2008 (Man. Year: 2008)

Chassis No: MR053HY9305050925

Colour: Metallic Gold

Odometer: 306639 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 1 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 1 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,978.91	3,723.97	6,254.94	62.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	2,660.00	2,790.00	51.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,428.91	6,383.97	9,044.94	58.62
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	15,428.91	5,100.00	10,328.91	66.95
+ GST 7.00/7.00% (S\$)	1,080.02	357.00	723.02	66.95
Nett Amount (S\$)	16,508.93	5,457.00	11,051.93	66.95

INSPECTION

Date of Assignment: 21/05/2018

Date Inspected: 03/07/2018 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK
Auto Point
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2018)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH7405J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	642.00 FL	*642.00 FL
2	2		*BOOTLID HINGE	Repair	114.20 FL	*- FL
3	1		*BOOTLID LOCK	Dented	109.10 FL	*109.10 FL
4	1		*BOOTLID LOCK STRIKER	Necessary	42.10 FL	*42.10 FL
5	1		*BOOTLID RUBBER (50%)	Cut	141.15 FS	*94.10 FS
6	4		*BOOTLID STOPPER	Serviceable	87.80 FL	*- FL
7	1		*BOOTLID LOGO	Necessary	49.20 FL	*49.20 FL
8	1		*BOOTLID VIOS EMBLEM	Necessary	47.50 FL	*47.50 FL
9	1		*BOOTLID SPORT EMBLEM	Necessary	47.50 FL	*47.50 FL
10	1		*BOOTLID CENTER GARNISH	Warped	132.00 FL	*132.00 FL
11	2		*BOOTLID NUMBER PLATE LAMP	Serviceable	74.00 FL	*- FL
12	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	105.00 FL	*- FL
13	1		*REAR LH FENDER	Repair	979.70 FL	*- FL
14	1		*REAR LH FENDER SPLASH SHIELD	Serviceable	49.50 FL	*- FL
15	10		*REAR LH FENDER SPLASH SHIELD CLIP	Not Necessary	30.00 FL	*- FL
16	1		*REAR RH FENDER	Repair	979.70 FL	*- FL
17	1		*REAR RH FENDER SPLASH SHIELD	Serviceable	49.50 FL	*- FL
18	10		*REAR RH FENDER SPLASH SHIELD CLIP	Not Necessary	30.00 FL	*- FL
19	1		*LH TAILLAMP	Broken	289.00 FL	*289.00 FL
20	1		*LH TAILLAMP PANEL	Bent	195.20 FL	*195.20 FL
21	1		*LH TAILLAMP GASKET	Necessary	6.00 FL	*6.00 FL
22	1		*RH TAILLAMP	Cracked	289.00 FL	*289.00 FL
23	1		*RH TAILLAMP PANEL	Bent	195.20 FL	*195.20 FL
24	1		*RH TAILLAMP GASKET	Necessary	6.00 FL	*6.00 FL
25	1		*REAR BUMPER	Bent	670.10 FL	*670.10 FL
26	2		*REAR BUMPER SIDE RETAINER	Distorted	246.20 FL	*246.20 FL
27	10		*REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
28	1		*REAR BUMPER REFLECTOR -LH	Cracked	134.60 FL	*134.60 FL
29	1		*REAR BUMPER REFLECTOR -RH	Serviceable	134.60 FL	*- FL
30	1		*END PANEL	Bent	608.10 FL	*608.10 FL
31	1		*END PANEL TOP GARNISH	Dented	383.90 FL	*383.90 FL
32	6		*END PANEL TOP GARNISH CLIP	Necessary	9.00 FL	*9.00 FL
33	1		*LH AIRDUCT	Serviceable	155.40 FL	*- FL
34	1		*RH AIRDUCT	Serviceable	155.40 FL	*- FL
35	1		*FLOOR PANEL	Repair	867.80 FL	*- FL
36	1		*FLOOR PANEL BOARD	Serviceable	301.70 FL	*- FL
37	1		*FLOOR PANEL SIDE BOARD -LH	Serviceable	261.46 FL	*- FL
38	1		*FLOOR PANEL SIDE BOARD -RH	Deformed	261.46 FL	*261.46 FL
39	1		*FLOOR PANEL CARPET	Serviceable	307.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR LH FENDER INNER TRIM BOARD	Serviceable	230.30 FL	*- FL
41	1		*REAR RH FENDER INNER TRIM BOARD	Serviceable	230.30 FL	*- FL
42	1		*SPARE TYRE TANK	Serviceable	151.70 FL	*- FL
43	1		*SPARE TYRE MOUNTING BOLT	Serviceable	56.30 FL	*- FL
44	1		*SPARE TYRE TOOLS TRAY	Serviceable	285.30 FL	*- FL
45	1		*CAR JACK	Repair	161.80 FL	*- FL
46	1		*CAR JACK BRACKET	Repair	96.10 FL	*- FL
47	1		*EXHAUST SILENCER	Repair	781.90 FL	*- FL
48	3		*EXHAUST SILENCER MOUNTING	Serviceable	122.20 FL	*- FL
49	1		*EXHAUST SILENCER CHROME PIPE	Missing	120.00 FL	*120.00 FL
50	1		*EXHAUST SILENCER GASKET	Serviceable	53.90 FL	*- FL
51	1		*EXHAUST SILENCER HEAT SHIELD	Serviceable	171.20 FL	*- FL
52	1		*REAR NUMBER PLATE WITH HOLDER	Cracked	55.00 FS	*45.00 FS
53	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
54	1		*BOOTLID COMPARTMENT WATERPROOF SEALANT	Not Necessary	150.00 FS	*- FS
55	1		*SPARE TYRE	Serviceable	280.00 FS	*- FS
56	1		*SPARE TYRE WHEEL RIM	Serviceable	340.00 FS	*- FS
57	1		*REAR WINDSCREEN GLASS SEALANT AND GUM	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,863.17	4,852.26
- List Item Discount on L Items 25.00/25.00% (S\$)	2,884.26	1,128.29
Total Parts (S\$)	9,978.91	3,723.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	2,100.00	1,100.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT ,WELD AND REALIGN ACCIDENT AFFECTED AREA	New	2,100.00	1,200.00
3	TO APPLY ANTI RUST TREATMENT	New	200.00	60.00
4	TO CHECK WIRING SYSTEM AND LIGHT	New	120.00	20.00
5	TO REMOVE AND REPLACE /REINSTALL BOOTLID ATTACHMENT	New	200.00	50.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
7	TO REMOVE AND REINSTALL REAR INNER COMPARTMENT /INTERIOR UPHOLSTERY & REAR SEAT TO FACILITATE REPAIR	New	200.00	100.00
8	TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO REPLACE REAR LH & RH FENDER	New	150.00	0.00
9	TO CHECK AND TEST BOOTLID WATER LEAKING	New	80.00	20.00
10	TO REMOVE AND REPLACE EXHAUST SILENCER ,PIPE ,MOUNTING & ETC	New	180.00	60.00
Gross Labour Cost (\$\$)			5,450.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >