

ASS. REC. BY:

REF:

CS/FCL18009165/Avbn2

Special Instruction:

Survivor

Adrian

ASSIGNMENT (Office)

From (Person):

LWS Lunene Jua

of

FCL

Date/Time:

19/05/2018 3pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 9688L

Insured:

SHA 9188H

at Workshop m/s

Reliable Carz

Tel:

8166 9797.

of

8 Kaki Sukit Ave 4 #03-00

Policy No:

Claim No:

D18003826MESH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

wpi

22/05/2018 @ after 10am

H.O.D. Endorsement:

Date/Time:

21/05/2018 11:17am

Person Contacted:

Jason

Vehicle IN / OUT

Date/Time

Action/Instruction (

✓)

Estimate

LS 1900

SLJ 9688L - X

SHA 9188H - CS / FCL17004506 / Khb3

DUA: 03/03/2017

23/5/18

Informed FCI pending workshop est by email

28/6/18

Adrian Confirmed LS \$ 1900 Cred 4711.95, 7115

29/6/18

Email preli revised to FCI

REF: FCI

ASSIGNMENT

From:

Date: 22/5/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLJ 9688L

at Workshop m/s

Reliable Carz

of

8 kaki Bkt Ave 4 #05-50

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10am
jason

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ9688L

Yr Regn:

2012 Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520i

C.C.

1997

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

90717

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NBAXG120700X50921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/30 R20

R:

275/30 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

22/05/18

Survey held at

Reliable

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 29 JUN 2018

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

29/6 - typist

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format:

CWS

Lump Sum / I.B.I. (\$

1900/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

145

50

50 + 50

26

321



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18003826MFSH
Our ref: CS/FCI18009165/Avb

Date : 29/6/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 9688L


We thank you for your instruction on 19/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/5/2018 at the premises of M/s RELIABLE CARZ PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,611.95
Revised Estimate Amount	: S\$1,900.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	14-05-2018	Our Ref No. D18003826MFSH
Accident Date	11-05-2018	Claim Type. Third Party
Insured Vehicle	SHA9188H	Third Party Vehicle. SLJ9688L
Survey Location	8 KAKI BUKIT AVENUE 4#05-50	
Contact Person.	JASON LEE	
Contact No.	81669797/ 81669797	Fax No. 00
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

21/05/2018 @ 11:17am
Jason veh not in
22/05/2018 @ after 10am

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RELIABLE CARZ PTE LTD	Attention. NIL
Cc : TP Solicitor	CROSSBORDERS LLC	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 23 May 2018 9:04 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003826MFSH/1, SLJ 9688L

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLJ 9688L on 22/5/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Saturday, 19 May 2018 3:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003826MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7034673G



LIM PIN WAN
林炳源
CHINESE
Date of Birth 07-10-1970
Country of Birth SINGAPORE



0620638



NIC NO. S7034673G



Valid Group A4 Date of Issue 18-11-1992

APT BLK 51 KENT ROAD #08-31
SINGAPORE 210051
NRIC No. S7034673G Date 19-02-1999 No. 2590194



10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref 1611170203N057010423

16 Nov 2017

HYPE MEDIA PTE LTD
362 UPPER PAYA LEBAR ROAD
#07-07A
DA JIN FACTORY BUILDING
SINGAPORE 534963



Dear Sir/Madam

NOTIFICATION ON SUCCESSFUL REPLACEMENT OF VEHICLE REGISTRATION NO. SLS9934D WITH VEHICLE REGISTRATION NO. SLJ9688L

You may be pleased to know that your application of 16 Nov 2017 for replacement of registration number is approved.

2. The details of the vehicle after the transaction are as follows:

Vehicle Registration No.	: SLJ9688L (Previously SLS9934D)
Vehicle Make	: B.M.W.
Vehicle Model	: 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Chassis No.	: WBAXG12070DX50921
Engine No./ Motor No.	: A7040294N20B20B / -

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875
Contact No.: +65 8166 9797 Fax No.: +65 6385 1751

TP 1st Cap
Vern

Vehicle No.: SLJ 9688L

Model: BMW 520i

WBAXG12070DXS0921

QTY DESCRIPTION

AMOUNT (S\$)

List Items:

1	Rear bumper <i>Deformed</i>	1980.00 <i>1430</i>
1	Rear bumper towing cover <i>new</i>	25.00 <i>x</i>
1	Rear bumper under cover <i>new</i>	137.50 <i>x</i>
1	Rear bumper guide centre <i>new</i>	135.00 <i>x</i>
2	Rear bumper retainer @ S\$298.00 <i>new</i>	596.00 <i>x</i>
1	Rear bumper reinforcement <i>new</i>	946.00 <i>x</i>
1	Rear bumper reinforcement adaptor <i>cauled</i>	96.00 <i>✓</i>
4	Reverse sensor @ S\$380.00 <i>2 pieces damaged</i>	1520.00 <i>500</i>
		5435.50
		Less 20 % (1087.10)
		Subtotal 4348.40

Special Nett Items:

1	Rear bumper clip (set) <i>new</i>	60.00 <i>30</i>
		Subtotal 60.00

Labour Charges:

To apply under coating		150.00	x
To remove and refix reverse sensor		180.00	60.
To check wiring system	540	80.00	30.
To remove and replace above parts		650.00	200
To spray painting on affected area		600.00	250
		<u>Subtotal</u>	1660.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

6068.40 *6611.95*

Total: 2393.40

K/S: 1.9K

02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RELIABLE CARZ PTE LTD

8 Kaki Bukit Ave 4 #05-50. Premier @ Kaki Bukit
Singapore 415875 Tel: 65919999
ACRA No: 201612430M

INVOICE

Date: 24-May-18

Bill To:

Name: HYPE MEDIA PTE LTD
Address: c/o 362 Upper Paya Lebar Road #07-07A Singapore 534963

Description	Rate	Day	Amount
Car Plate: SLJ9688L (BMW520I)			
Final repair bill for vehicle no. SLJ9688L			
To supply and replace parts, labour charges for repairing, knocking, welding and to respray painting			\$1,900.00
Remarks: Repair cost as per agreed with SJE - LKK AUTO Total No of Days: 02 working days			
TOTAL			\$1,900.00

Authorised Signature



PROPRIETARY INFORMATION: This document and the contents hereof are considered proprietary and confidential information of Reliable Carz Pte Ltd. Disclosure to unauthorized individuals or dissemination, publication or copying is prohibited without the prior written consent of Reliable Carz Pte Ltd Management.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009165/Avbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9188H	Veh. Inspected	SLJ 9688L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003826MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	19/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W 520i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAXG12070DX50921	Colour	BLACK	
Odometer	90717	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R20	DUNLOP	6 mm	
L/H Front Tyre	275/30 R20	DUNLOP	6 mm	
R/H Rear Tyre	275/30 R20	DUNLOP	6 mm	
L/H Rear Tyre	275/30 R20	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/05/2018	Inspection Date	22/05/2018	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9688L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,980.00	1,430.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	25.00	-
1	REAR BUMPER UNDER COVER	NOT NECESSARY	137.50	-
1	REAR BUMPER GUIDE CENTRE	NOT NECESSARY	135.00	-
2	REAR BUMPER RETAINER @\$298.00	NOT NECESSARY	596.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	946.00	-
1	REAR BUMPER REINFORCEMENT ADAPTOR	CRACKED	96.00	96.00
4	REVERSE SENSOR @\$380.00	DAMAGED (2 PCS ONLY)	1,520.00	500.00
	LESS 10% DISCOUNT		-543.55	-202.60
			4,891.95	1,823.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
			60.00	30.00
LABOUR				
	TO APPLY UNDER COATING.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIX REVERSE SENSOR.		180.00	60.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TO REMOVE AND REPLACE ABOVE PARTS.		650.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREA.		600.00	250.00
			1,660.00	540.00
GRAND TOTAL			6,611.95	2,393.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/FCI18009165/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.