

ASS. REC. BY:

REF: CS/FCI 8009168/Klr b72 | Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person): WJ Lurene Jaw of FCI Date/Time: 19052018 3:12pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1707Y Insured: SHA 8140B

at Workshop m/s Premier Automotive Tel: 6544 6689

of 23 Changi South Ave 2 #03-02

Policy No: Claim No: D18003970MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 17052018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp.

H.O.D. Endorsement:

Date/Time: 21052018 11:21am Person Contacted: Gary Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SHD 1707Y - X

SHA 8140B - CS/FCI 8007615 / Tlb

D.O.A. 200418

Revert thru email

(08/11/13)

Q. Insurer: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ITP / WS / ITP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 1707Y Yr Regn: 26 Sep 1812

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 2.3 c.c. 1582Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 8498 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TMAP2814VHJIK1709

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195 65 145

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 17/5/18 D.O.I. 24/5/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/5/18	Subst 4/5 at 1700 / 3 hrs
	Red: 42804.71, 62%

RECEIVED 25 MAY 2018

Date/Time, File Pass to?

☐ : Prell. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.t. (\$) 1700

Survey Fee:

Transportation:

Photos

Others

TOTAL

135
50
50
26
261

MOTOR SURVEY ASSIGNMENT

Date	17-05-2018	Our Ref No. D18003970MFSH
Accident Date	17-05-2018	Claim Type. Third Party
Insured Vehicle	SHA8140B	Third Party Vehicle. SHD1707Y
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GARY SHI	
Contact No.	65446676/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: PENDING ID'S VF TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

21052018 @ 11:21am
Gans veh not in



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003970MFSH

Our Ref: CS/FCII8009168/K1rb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1707Y .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.05.2018 at the premises of M/s PREMIER AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 4,504.71 .
Revised Estimate Amount	: S\$ 2,138.88 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at o/s body.



Yours faithfully
KALVIN
Automotive Assessor

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1707Y
 Previous Vehicle No.: -
 Effective Date of Ownership: 26 Sep 2017
 Original Regn Date: 26 Sep 2017
 Registration Date: 26 Sep 2017
 Year of Manufacture: 2017
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ141709
 Engine No.: D4FBHZ171693
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,151.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 25 Sep 2025
 Minimum PARF Benefit: \$7,627.00
 No. of Transfers: 0
 IU Label No.: 1050709759
 COE No.: 2017092601003849D
 COE Expiry Date: 25 Sep 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$44,081.00
 PQP Paid: \$35,265.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-May-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1707 Y

1 pc	Front o/s door	\$	1,723.60
2 pcs	Front o/s door hinges @ \$36.10	\$	72.20
1 pc	O/s rocker panel	\$	1,935.09
		\$	3,730.89
	Less 20%	\$	746.18
		\$	2,984.71

S/NETT

1 set	o/s door sticker	\$	100.00
	Sundry	\$	50.00
	To dismantle and refit the inner component of the front o/s door into new shell door	\$	150.00
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the o/s rocker panel. Including knock-out, straighten, repair, reshape and adjust of same, etc.	\$	600.00
	To putty and spray painting on front o/s door, o/s rocker panel.	\$	500.00
	To apply rustproofing on the repaired and replaced panels.	\$	120.00
		\$	4,504.71

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalish (UCC)
22/5/18 11:00 hrs.
3 Days.
PIP
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009168/K1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8140B	Veh. Inspected	SHD 1707Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003970MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	19/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ141709	Colour	SILVER	
Odometer	84918	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/05/2018	Inspection Date	22/05/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1707Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT O/S DOOR	DENTED	1,723.60	1,723.60
2	FRONT O/S DOOR HINGES @\$36.10	SERVICEABLE	72.20	-
1	O/S ROCKER PANEL	TO REPAIR SEE LABOUR	1,935.09	-
	LESS 20% DISCOUNT		-746.18	-344.72
			2,984.71	1,378.88
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
			150.00	100.00
<u>LABOUR</u>				
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF THE FRONT O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE O/S ROCKER PANEL INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF SAME. ETC.		600.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S DOOR, O/S ROCKER PANEL.		500.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
			1,370.00	660.00
GRAND TOTAL			4,504.71	2,138.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS/FCI18009168/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING**B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.