



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 NISSAN QASHQAI 1.2 (SKW3013S)

Date of Loss

11 May 2018

Time of Loss

13.50

Loss Description

SKW3013S (INSD) HIT IN REAR GBB4172B

Comment

Workshop Details

Total Rebate Amount

51623

Nett Loss Amount

\$42,377.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

05/08/2018



Days of work completion *

79



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKW3013S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

26/10/2015



Mileage

49563

Age of Vehicle

2

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

CATEGORY

Driver Name

ASSESSMENT INFO... 2015

FNOL INFORMATI... LEE SIOK HENG GEORGETTE

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... QASHQAI 1.2

ASSESSMENT INFO... QASHQAI 1.2 DIG-T CVT ABS 2WD 5D

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... SJNFEAJ11U1477253

CATEGORY Date of Birth

FNOL INFORMATI... 26 August 1954

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 63

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... HRA2185890A

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 42

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... NO.18, JALAN SEAVIEW, 438332,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Female

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S0108838F

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

27/05/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/60R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

215/60R17

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			EMBLEM (DISC 20%)			Necessary	69.6		5		66.12	Approve
		2	1			EMBLEM REAR (DISC 20%)			Necessary	47.76		5		45.37	Reviewing
		3	1			A LOCK LIFT			Serviceable	0	0	5	0	0	Deny
		4	1			RUBBER-DUM (DISC 20%)			Necessary	48.16		5		45.75	Reviewing
		5	1			GLASS-TAIL GATE (DISC 20%)			Necessary	724.48		5		688.26	Reviewing
		6	1			DOOR BACK (DISC 20%)			Bent	2349.44		5		2231.97	Reviewing
		7	1			REINF-BUMPER RR (DISC 20%)			Bent	495.36		5		470.59	Reviewing
		8	1			STAY ASSY-REAR RH (DISC 20%)			Deformed	100.8		5		95.76	Reviewing
		9	1			STAY ASSY-REAR LH (DISC 20%)			Deformed	100.8		5		95.76	Reviewing
		10	4			GROMMET BUMPER (DISC 20%)			Necessary	2		5		7.6	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		11	3			CLIP BUMPER (DISC 20%)			Necessary	5.92		5		16.87	Reviewing
☐		12	1			RETAINER-BUMPER RH (DISC 20%)			Necessary	19.04		5		18.09	Reviewing
☐		13	1			RETAINER-BUMPER LH (DISC 20%)			Necessary	19.04		5		18.09	Reviewing
☐		14	1			BRACKET-BUMPER RH (DISC 20%)			Deformed	28.72		5		27.28	Reviewing
☐		15	1			BRACKET-BUMPER LH (DISC 20%)			Deformed	28.72		5		27.28	Reviewing
☐		16	1			ENERGY ABSORBER			Serviceable	0	0	5	0	0	Deny
☐		17	1			FINISHER-REAR BUMPER TOW COVER (DISC 20%)			Cut	13.44		5		12.77	Reviewing
☐		18	1			FASCIA-RR BUMP (DISC 20%)			Deformed	573.6		5		544.92	Reviewing
☐		19	2			CLIP LUGGAUGE			Serviceable	0	0	5	0	0	Deny
☐		20	4			CLIP LUGGAUGE			Serviceable	0	0	5	0	0	Deny
☐		21	1			PLATE-LUGGAGE			Serviceable	0	0	5	0	0	Deny

Labour

Add

Approve

Deny

Submit All

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOV
		1		REMOVE / INSTALL & TEST REAR REVERSE CAMERA (DISC 5%)	114	0	0	Reviewing		
		2		SUPPLY & INSTALL REVERSE SENSOR (DISC 5%)	104.5	0	0	Reviewing		
		3		INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN (DISC 5%)	142.5	0	0	Reviewing		
		4		RENEW REAR WINDSCREEN GLASS ASSY (DISC 5%)	228	0	0	Reviewing		
		5		REPAIR END PANEL, LH REAR FENDER AND RENEW TAILGATE REAR BUMPER (DISC 5%)	712.5	0	0	Reviewing		
		6		S/PAINT REAR PORTION (DISC 5%)	665	0	0	Reviewing		
		7		R/I REAR DVR TO ASSIST REPAIR (DISC 5%)	114	0	0	Reviewing		
		8		CHECK LIGHTING (DISC 5%)	45.6	0	0	Reviewing		
		9		TRANSFER DOOR MECHNCIAL PARTS TO NEW DOOR (DISC 5%)	76	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 8 DAYS	Reviewing			
☐		2	REVERSE SENSOR (J11 & T32)	Deny	0	NOT NECESSARY	
☐		3	SUNDRIES	Reviewing	20	NECESSARY	
☐		4	REAR W/SCREEN SEALANT	Reviewing	80	NECESSARY	
☐		5	MOTOR-WIPER	Deny	0	NOT NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--	--------------------------	--	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$6,714.58

Claim Amount

\$6,714.58

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,202.10	\$2,202.10
Miscellaneous	\$100.00	\$100.00
Spare Parts	\$4,412.48	\$4,412.48