

Speed Auto Works
(Co Reg. No. 5321801E)
Blk 90 Bedok North Street 4
#13-1537 Singapore 460090
Tel: 6789 5155 Fax : 6783 5155

TO	: INDIA	DATE	: 10-May-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: YN4419E
ADDRESS	:	MODEL	: MITSUBISHI FEB21
TEL. NO.	:	CHASSIS NO	:
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP <i>lt</i>	1	\$ 322.00	\$ 322.00
2	TAIL LAMP BRACKET <i>new</i>	1	\$ 110.50	\$ 110.50
3	REAR NUMBER PLATE LAMP <i>2 new</i>	1	\$ 98.00	\$ 98.00
4	REAR CHASSIS COSSMEMBER	1	\$ 2,245.00	\$ 2,245.00

322
241.50

TOTAL PRICE \$ 2,775.50
LESS 10% 25% \$ 277.55
SUB TOTAL PRICE \$ 2,497.95

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL DOOR (SPECIAL TYPE) RH <i>new</i>	1	\$ 2,000.00	\$ 2,000.00
2	TAIL DOOR HINGE RH <i>Bent</i>	1	\$ 250.00	\$ 250.00
3	TAIL DOOR PILLAR RH <i>Dented</i>	1	\$ 1,500.00	\$ 1,500.00
4	TAIL DOOR PILLAR ALUMINIUM PLATE RH <i>lt</i>	1	\$ 800.00	\$ 800.00
5	TAIL GATE '70KM' STICKER <i>new</i>	1	\$ 50.00	\$ 50.00
6	REAR BOX SIDE PANEL ALUMINIUM RH <i>Repair</i>	1	\$ 3,000.00	\$ 3,000.00
7	REAR END PANEL <i>2</i>	1	\$ 1,600.00	\$ 1,600.00
8	REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 200.00	\$ 200.00
9	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
10	REAR END BEAM (WOODEN)	1	\$ 1,000.00	\$ 1,000.00

TOTAL \$ 10,450.00

1320

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 1,200.00	500-	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 500.00	350	
3	TUFF COAT	\$ 150.00	x	
4	BULB CHECKING, WIRING	\$ 50.00	30	
5	TRANSFER TAILGATE	\$ 80.00	x	
6	REMOVE AND REFIX REAR REAR CARGO BED CHASSIS (WOODEN)	\$ 1,500.00	x	
TOTAL		\$ 3,480.00	880	

ESTIMATE REPORT

: \$ 12,947.95
 TOTAL PARTS COST : \$ 3,480.00
 TOTAL LABOUR COST : \$ 16,427.95
 TOTAL REPAIR COST

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

Adrian Ling
 1/5 14/05/18

total: 2441.50

1/5: 1.9K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: