

ASS. REC. BY:

REF: CS/FC118009176/Grbn2

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): CWS Karen Tan of FCL Date/Time: 18/05/2018 5:32pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 647T Insured: SHA 1116H

at Workshop m/s Trans - 600 Auto Tel:

of No 2 AMK ST 63

Policy No: Claim No: D1800 3849MTSH

Sum Insured: Excess:

Make of Veh: D.O.A. 11/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'PS' H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHD 647T - CS/FC116000807 / kvbr2	DA: 070414
	SHA 1116H - CS/AT1617007434 / Hhg342	DA: 130417
	Confirm \$11,668.52 @ 6 days	
	Red: \$61,939.12, 84%.	

Signature

abd.

REF:

ASSIGNMENT

*From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Trans cab

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD647T

Yr Regn:

30 Nov 2017

Type: M / C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault latitude 1995

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

36677

T/Radio: Insured / Std / NI / NA

Eng/No:

VF/ABL15AUG283211

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21-05-18

Survey held at

w/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 05 SEP 2018

Date/Time, File Pass to?

1)

Emp 1st

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I: (\$ *11,668.52*)

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

65x15: 97

1704 925

50

50

47

580

OSP 10/9/18

1292

MOTOR SURVEY ASSIGNMENT

Date	14-05-2018	Our Ref No. D18003849MFSH
Accident Date	11-05-2018	Claim Type. Third Party
Insured Vehicle	SHA4416H	Third Party Vehicle. SHD647T
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	GHIEEN YEE LOONG	
Contact No.	62876666/ 62876666	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

5/14/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

3878K

Vehicle Details

Vehicle No.:

SHD647T

Vehicle to be Exported:

Yes

Intended De-registration Date:

14 May 2018

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour:

Red

Manufacturing Year:

2015

Engine No.:

M9R8839C003049

Chassis No.:

VF1ABL15AUC283211

Maximum Power Output:

127.0 kW (170 bhp)

Open Market Value:

\$19,998.00

Original Registration Date:

30 Nov 2017

First Registration Date:

30 Nov 2017

Transfer Count:

0

Actual ARF Paid:

\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Nov 2025

PARF Rebate Amount:

\$14,998.00

Intended COE Rebate Details

COE Expiry Date:

29 Nov 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$33,596.00

COE Rebate Amount:

\$26,876.00

Total Rebate Amount:**\$41,874.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 May 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD647T
Vehicle to be Exported:	No
Intended De-registration Date:	01 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003049
Chassis No.:	VF1ABL15AUC283211
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$31,472.00
Total Rebate Amount:	\$46,470.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Jun 2018

OK

Trans-cab Auto Services Pte Ltd

AAD1805-128

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 647T

VF1ABL15AUC283211

RENAULT

LATITUDE

11.5.2018

AXA

		PART	LIST	
1	1	BUMPER COVER FRT <i>RE</i>	\$	1,259.42
2	1	BUMPER SPOILER FRT <i>X NN</i>	\$	181.75
3	1	BUMPER ABSORBER FRT <i>X CRA</i>	\$	394.68
4	1	BUMPER RETAINER FRT LH <i>MC</i>	\$	151.41
5	1	BUMPER SUPPORT FRT <i>X NN</i>	\$	123.88
6	1	BUMPER RETAINER FRT RH <i>MC</i>	\$	150.77
7	1	BUMPER SUPPORT FRT <i>X</i>	\$	123.88
8	1	BUMPER UNDERTRAY FRT <i>X</i>	\$	472.83
9	1	BUMPER GRILLE LOWER FRT <i>X</i>	\$	266.80
10	1	BUMPER FOG LAMP GRILLE LH <i>X</i>	\$	207.21
11	1	BUMPER FOG LAMP GRILLE RH <i>mis</i>	\$	207.21
12	1	BUMPER BEAM FRT <i>X NN</i>	\$	914.08
13	1	TOW COVER FRT <i>X</i>	\$	28.61
14	1	RADIATOR GRILLE <i>X CRA</i>	\$	1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT' <i>MC</i>	\$	225.36
16	1	RADIATOR GRILLE FRAME <i>X CRA</i>	\$	1,353.75
17	1	FRAME FULL SUPPORT PANEL <i>X CRA</i>	\$	615.90
18	1	FRAME FULL SUPPORT BRACKET <i>X</i>	\$	89.79
19	1	FRONT BRACE PANEL <i>X</i>	\$	177.22
20	1	HORN <i>X</i>	\$	314.17
21	1	HORN BRACKET <i>X</i>	\$	40.45
22	1	HEADLAMP LH <i>X</i>	\$	1,184.43
23	1	HEADLAMP RH <i>X CRA</i>	\$	1,184.43
24	1	HEADLAMP PANEL FRT LH <i>X</i>	\$	152.15
25	1	HEADLAMP PANEL FRT RH <i>X</i>	\$	152.15
26	1	BONNET <i>X</i>	\$	1,941.63
27	1	BONNET INSULATOR <i>X</i>	\$	405.73
28	1	BONNET STRUT LH <i>X</i>	\$	88.61

14116.08

Trans-cab Auto Services Pte Ltd

AAD1805-128

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

29	1	BONNET STRUT RH	X	\$	88.61
30	1	BONNET HINGE LH	X	\$	348.31
31	1	BONNET HINGE RH	X	\$	348.31
32	1	BONNET LOCK	X	\$	305.48
33	1	BONNET CABLE	X	\$	119.19
34	1	BONNET CABLE COVER	X	\$	161.03
35	1	BONNET SEAL OUTER	X	\$	92.36
36	1	BONNET SEAL INNER	X	\$	157.28
37	1	FENDER PANEL FRT LH	X	\$	783.83
38	1	FENDER PANEL FRT RH	X	\$	783.83
39	1	WHEELARCH FRT LH	X	\$	278.84
40	1	WHEELARCH FRT RH	X	\$	278.84
41	1	FENDER BRACKET LOWER LH	X	\$	15.79
42	1	FENDER BRACKET LOWER RH	X	\$	15.79
43	1	FENDER INSULATOR LH	X	\$	130.84
44	1	FENDER INSULATOR RH	X	\$	130.84
45	1	BUMPER COVER REAR	- ee	\$	1,108.46
46	1	BUMPER LOWER REAR	- ee	\$	768.84
47	1	BUMPER BRACKET CTR REAR	X	\$	113.47
48	1	BUMEP R BRACKET SIDE RH REAR	X	\$	135.97
49	1	BUMEP R RETAINER RH REAR	- mc	\$	44.99
50	1	BUMPER REFLECTOR RH	X	\$	43.61
51	1	BUMEP R BRACKET SIDE LH REAR	X	\$	135.97
52	1	BUMEP R RETAINER LH REAR	- mc	\$	44.99
53	1	BUMPER REFLECTOR LH	X	\$	43.61
54	1	BUMPER BEAM REAR	X	\$	777.52
55	1	BUMPER BEAM BRACKET LH REAR	X	\$	225.95
56	1	BUMPER BEAM BRACKET RH REAR	X	\$	225.95
57	1	BOOT REAR	X	\$	2,872.68
58	1	BOOT FINISHER	X	\$	470.06
59	1	BOOT WHEATERSTRIP	X	\$	323.05
60	1	BOOT REFLECTOR LAMP LH	X	\$	493.35
61	1	BOOT REFLECTOR LAMP RH	X	\$	493.35
62	1	BOOT BADGE 'RENAULT'	X	\$	225.36
63	1	BOOT BADGE	X	\$	225.36
64	1	BOOT STRUT LH	X	\$	276.08
65	1	BOOT STRUT RH	X	\$	276.08
66	1	BOOT HINGE LH	X	\$	367.84

13731.71

Trans-cab Auto Services Pte Ltd

AAD1805-128

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

67	1	BOOT HINGE RH	X	\$	367.84
68	1	BOOT INNER TRIM	X	\$	586.45
69	1	BOOT SWITCH	X	\$	168.13
70	1	BOOT LOCK	X	\$	202.67
71	1	BOOT LOCK CATCH	X	\$	74.40
72	2	LICENCE PLATE LAMP	X	\$	50.52
73	2	BOOT RUBBER PLUG	X	\$	221.81
74	1	FENDER PANEL INNER TRIM REAR LH	X	\$	671.45
75	1	FENDER PANEL REAR LH	X	\$	3,299.13
76	1	WHEELARCH REAR LH	X	\$	543.47
77	1	FENDER PANEL INNER TRIM REAR RH	X	\$	671.45
78	1	FENDER PANEL REAR RH	X	\$	3,299.13
79	1	WHEELARCH REAR RH	X	\$	543.47
80	1	FENDER PANEL REAR LH	X	\$	3,299.13
81	1	WHEELARCH REAR LH	X	\$	543.47
82	1	TAILLAMP RH	X	\$	552.55
83	1	TAILLAMP PANEL RH	X	\$	986.70
84	1	TAILLAMP LH	X	\$	552.55
85	1	TAILLAMP PANEL LH	X	\$	986.70
86	1	OUTER PANEL REAR (End Panel)	X	\$	1,471.77
87	1	OUTER PANEL REAR (End Panel)TRIM	X	\$	404.56
88	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X	\$	2,189.88
89	1	SPARE WHEEL PANEL TRIM	X	\$	612.21
90	1	EXHAUST REAR	X	\$	7,489.05
91	1	EXHAUST CAP REAR	X	\$	230.49

TOTAL	\$	57,866.80
10%	\$	5,786.68
	\$	52,080.12

Special Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	X	\$	52.00
2	1SET	BUMPER CLIP FRT	/	\$	66.00
3	1	BUMPER BRACKET CLIP FRT LH	X	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	X	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	X	\$	12.00

Trans-cab Auto Services Pte Ltd**AAD1805-128**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

6	1	BUMPER SUPPORT CLIP FRT RH	X	\$	10.50
7	1	TOW COVER FRT	X	\$	14.50
8	1SET	RADAIOR GRILLE SCREW	X	\$	16.00
9	1SET	BUMPER GRILLE LOWER CLIP	X	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	X	\$	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	X	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	X	\$	30.00
13	1	Windscreen moulding	X	\$	100.00
14	1SET	Front licence plate with holder	X	\$	80.00
15	1SET	PARKING AID	X	\$	700.00
16	1SET	REAR BUMPER CLIP	X	\$	66.00
17	1SET	BUMPER BRACKET CTR CLIP	X	\$	33.00
18	1SET	BUMEP R BRACKET SIDE CLIP RH RR	X	\$	10.00
19	1SET	BUMEP R RETAINER RH CLIP RR	X	\$	20.00
20	1SET	BUMEP R BRACKET SIDE CLIP LH RR	X	\$	10.00
21	1SET	BUMEP R RETAINER CLIP LH RR	X	\$	20.00
22	1SET	BUMPER LOWER REAR RIVET	X	\$	22.00
23	1SET	BUMPER LOWER REAR CLIP	X	\$	66.00
24	1	EXHAUST MOUNTING REAR	X	\$	17.82
25	1SET	BOOT FINISHER CLIP	X	\$	24.20
26	1	BOOT STICKER "Trans-cab"	X	\$	30.00
27	1	BOOT STICKER "6555-3333"	X	\$	30.00
28	1	BOOT INNER TRIM CLIP	X	\$	45.00
29	1SET	FENDER WHEELARCH REAR RH CLIP	X	\$	35.00
30	1SET	FENDER WHEELARCH REAR LH CLIP	X	\$	35.00
31	1	FENDER INNER TRIM CLIP LH	X	\$	28.00
32	1	FENDER INNER TRIM CLIP LH	X	\$	28.00
33	1	TAILLAMP CLIP RH	X	\$	5.00
34	1	TAILLAMP CLIP LH	X	\$	5.00
35	2	REAR WINDSCREEN SELANT	X	\$	80.00
36	1	WINDSCREEN MOULDING	X	\$	100.00
37	1	REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
38	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X	\$	385.00
39	1	SPARE TYRE	X	\$	330.00
				\$	2,787.52

Trans-cab Auto Services Pte Ltd

AAD1805-128

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

TOTAL PARTS \$ 54,867.64

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$ 800	5,400.00
Towing Fees.	\$ 120 / 120	120.00
To apply paint protection system (PPS) maintain and enhancement	\$ 1 X	380.00
Putty and spray painting of the affected portion.	\$ 400	6,000.00
To rust-proofing of the affected areas.	\$ X	170.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ NN X	380.00
To check steering geometry and computer wheel alignment	\$ X	220.00
To transfer of tire, rim and on wheel balancing.	\$ X	170.00
To Check Electrical Lighting Concerned.	\$ 30	170.00
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$ X	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ NN X	380.00
To lift-up engine with gear box and refit.	\$ X	440.00

Trans-cab Auto Services Pte Ltd**AAD1805-128**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	X	440.00
To remove and refit air bag system and reset.	\$	MN	X 480.00
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	X	380.00
To vacuum, replace, refix and recharge air condenser	\$	60	380.00
To replace, refix and top up coolant for radiator	\$	40	170.00
To vacuum, replace, refix and recharge Air Intercooler	\$	MN	X 170.00
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	X	170.00
To Rust-Proofing Of The Affected Areas.	\$	X	170.00
To reinstall rear bumper parking sensor.	\$	40	170.00
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	X	170.00
To repair and realign rear exhaust pipe.	\$	X	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	MN	X 170.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	X	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	X	170.00

Trans-cab Auto Services Pte Ltd

AAD1805-128

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 647T

To supply and re-do rear luggage floor panel insulation padding.

\$ X 380.00

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ X 380.00

To transfer of rear windscreen fittings and conduct water seepage test.

\$ X 170.00

To check steering geometry and computer wheel alignment

\$ X 220.00

TOTAL \$ 18,740.00**Over All Total \$ 73,607.64****(PART-BY-PART) Repair Days****20 DAYS**

75425.95

6Days .

part by part .

before paint photos .

Guo Qi ang - 8288 0282

21/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AXA INSURANCE PTE LTD 8 SHENTON WAY,#27-01 AXA TOWER 068811 SINGAPORE ATTENTION:	INVOICE NO. : INV1806-117 DATE : 30. June 2018 REFERENCE NO : AAD1805-128 TERMS : DUE DATE : 30. June 2018 PAGE : 1
---	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHD0647T;DOA 11.05.18(PART-BY-PART-18)	1	12,485.32	12,485.32

Total SGD Excl. GST : 11,668.52

7% GST : 816.80

Total SGD Incl. GST : 12,485.32

****** TWELVE THOUSAND FOUR HUNDRED EIGHTY FIVE AND THIRTY TWO SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009176/Grbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4416H	Veh. Inspected	SHD 647T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003849MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283211	Colour	RED	
Odometer	36677	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GOODYEAR	6 mm	
L/H Front Tyre	215/60 R16	GOODYEAR	6 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	6 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/05/2018	Inspection Date	21/05/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 647T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	DEFORMED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	NOT NECESSARY	181.75	-
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT LH	NECESSARY	151.41	151.41
1	BUMPER SUPPORT FRT	NOT NECESSARY	123.88	-
1	BUMPER RETAINER FRT RH	NECESSARY	150.77	150.77
1	BUMPER SUPPORT FRT	NOT NECESSARY	123.88	-
1	BUMPER UNDERTRAY FRT	NOT NECESSARY	472.83	-
1	BUMPER GRILLE LOWER FRT	NOT NECESSARY	266.80	-
1	BUMPER FOG LAMP GRILLE LH	NOT NECESSARY	207.21	-
1	BUMPER FOG LAMP GRILLE RH	MISSING	207.21	207.21
1	BUMPER BEAM FRT	NOT NECESSARY	914.08	-
1	TOW COVER FRT	NOT NECESSARY	28.61	-
1	RADIATOR GRILLE	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	NOT NECESSARY	89.79	-
1	FRONT BRACE PANEL	NOT NECESSARY	177.22	-
1	HORN	NOT NECESSARY	314.17	-
1	HORN BRACKET	NOT NECESSARY	40.45	-
1	HEADLAMP LH	NOT NECESSARY	1,184.43	-
1	HEADLAMP RH	CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	NOT NECESSARY	152.15	-
1	HEADLAMP PANEL FRT RH	NOT NECESSARY	152.15	-
1	BONNET	NOT NECESSARY	1,941.63	-
1	BONNET INSULATOR	NOT NECESSARY	405.73	-
1	BONNET STRUT LH	NOT NECESSARY	88.61	-
1	BONNET STRUT RH	NOT NECESSARY	88.61	-
1	BONNET HINGE LH	NOT NECESSARY	348.31	-
1	BONNET HINGE RH	NOT NECESSARY	348.31	-

Report Ref No. CS/FCI18009176/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LOCK	NOT NECESSARY	305.48	-
1	BONNET CABLE	NOT NECESSARY	119.19	-
1	BONNET CABLE COVER	NOT NECESSARY	161.03	-
1	BONNET SEAL OUTER	NOT NECESSARY	92.36	-
1	BONNET SEAL INNER	NOT NECESSARY	157.28	-
1	FENDER PANEL FRT LH	NOT NECESSARY	783.83	-
1	FENDER PANEL FRT RH	NOT NECESSARY	783.83	-
1	WHEELARCH FRT LH	NOT NECESSARY	278.84	-
1	WHEELARCH FRT RH	NOT NECESSARY	278.84	-
1	FENDER BRACKET LOWER LH	NOT NECESSARY	15.79	-
1	FENDER BRACKET LOWER RH	NOT NECESSARY	15.79	-
1	FENDER INSULATOR LH	NOT NECESSARY	130.84	-
1	FENDER INSULATOR RH	NOT NECESSARY	130.84	-
1	BUMPER COVER REAR	DEFORMED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DEFORMED	768.84	768.84
1	BUMPER BRACKET CTR REAR	NOT NECESSARY	113.47	-
1	BUMPER BRACKET SIDE RH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER RH REAR	NECESSARY	44.99	44.99
1	BUMPER REFLECTOR RH	NOT NECESSARY	43.61	-
1	BUMPER BRACKET SIDE LH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER LH REAR	NECESSARY	44.99	44.99
1	BUMPER REFLECTOR LH	NOT NECESSARY	43.61	-
1	BUMPER BEAM REAR	NOT NECESSARY	777.52	-
1	BUMPER BEAM BRACKET LH REAR	NOT NECESSARY	225.95	-
1	BUMPER BEAM BRACKET RH REAR	NOT NECESSARY	225.95	-
1	BOOT REAR	NOT NECESSARY	2,872.68	-
1	BOOT FINISHER	NOT NECESSARY	470.06	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	323.05	-
1	BOOT REFLECTOR LAMP LH	NOT NECESSARY	493.35	-
1	BOOT REFLECTOR LAMP RH	NOT NECESSARY	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	NOT NECESSARY	276.08	-

Report Ref No. CS/FCI18009176/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT RH	NOT NECESSARY	276.08	-
1	BOOT HINGE LH	NOT NECESSARY	367.84	-
1	BOOT HINGE RH	NOT NECESSARY	367.84	-
1	BOOT INNER TRIM	NOT NECESSARY	586.45	-
1	BOOT SWITCH	NOT NECESSARY	168.13	-
1	BOOT LOCK	NOT NECESSARY	202.67	-
1	BOOT LOCK CATCH	NOT NECESSARY	74.40	-
2	LICENCE PLATE LAMP	NOT NECESSARY	50.52	-
2	BOOT RUBBER PLUG	NOT NECESSARY	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	NOT NECESSARY	671.45	-
1	FENDER PANEL REAR LH	NOT NECESSARY	3,299.13	-
1	WHEELARCH REAR LH	NOT NECESSARY	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	NOT NECESSARY	671.45	-
1	FENDER PANEL REAR RH	NOT NECESSARY	3,299.13	-
1	WHEELARCH REAR RH	NOT NECESSARY	543.47	-
1	TAILLAMP RH	NOT NECESSARY	552.55	-
1	TAILLAMP PANEL RH	NOT NECESSARY	986.70	-
1	TAILLAMP LH	NOT NECESSARY	552.55	-
1	TAILLAMP PANEL LH	NOT NECESSARY	986.70	-
1	OUTER PANEL REAR (END PANEL)	NOT NECESSARY	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	NOT NECESSARY	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	NOT NECESSARY	2,189.88	-
1	SPARE WHEEL PANEL TRIM	NOT NECESSARY	612.21	-
1	EXHAUST REAR	NOT NECESSARY	7,489.05	-
1	EXHAUST CAP REAR	NOT NECESSARY	230.49	-
1	A/C CONDENSER (ADDITIONAL)	PUNCTURE	2,020.37	2,020.37
1	FENDER PANEL REAR LH	NOT NECESSARY	3,299.13	-
1	WHEELARCH REAR LH	NOT NECESSARY	543.47	-
	LESS 10% DISCOUNT		-5,988.71	-1,123.84
			53,898.43	10,114.52
	SPECIAL NETT ITEMS			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00

Report Ref No. CS/FCI18009176/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	NOT NECESSARY	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	NOT NECESSARY	80.00	-
1	SET PARKING AID (SN)	NOT NECESSARY	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/FCI18009176/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	NOT NECESSARY	385.00	-
1	SPARE TYRE (SN)	NOT NECESSARY	330.00	-
			2,787.52	184.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		5,400.00	800.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.		380.00	60.00
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	40.00

Report Ref No. CS/FCI18009176/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	40.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			18,740.00	1,370.00
	GRAND TOTAL		75,425.95	11,668.52
	RECOMMENDED COST OF REPAIRS			11,668.52

Report Ref No. CS/FCI18009176/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.