

INS. CASE OWNER:

Sheepin

CC 6 / III 1800

9179, Apr 23 0/1

LKK:
IDAC:

Surveyor:

Adrian

DOI:

16/5/18

Date / Time:

16/5/18

Registered in Merimen:

21/5/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SH 8025

Name of Insured : LPL

Insured Tel No. : HP:

Excess Sec II : \$5 D.O.A. : 16/5/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : HEW TIMMY AKE

Driver Tel No. : (V/L: YES / NO)

51252807

Claim No. : MIT165047

Policy No. : M165047

Make / Model : TOYOTA

Place of Accident : RIVERVALE DR INOS SEAFARM

EAST AVE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

INSRS:
WSP:
Tel :
Liability :
RMKS:

MIT

INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time

23/5/18

MIT

24/5/18

11/6/2018

21/6

RECEIVED 27 JUN 2018

RECEIVED 24 AUG 2018

After repair photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS: 5800.00

(5

days)

Reduction: 43

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. :

27

If NO or B 28, Ass. Lia :

Repair Cost:

SS: 5,800.00

Loss of Rental (LOR):

SS:

(

days)

Loss of Use (LOU):

SS:

360.00

(\$ 60

x 6

days)

Loss of Income (LOI):

SS:

(\$

x

days)

LOR only ☐ LOU only ☒

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS:

7.45

Medical:

SS:

Disbursement:

SS:

(e.g. Tow/Independent)

Legal Cost

SS:

Total:

SS:

6,167.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS:

6,167.45

Name 1:

Hew Hack Teck Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS:

Name 2:

Payee 3: (Strike if N.A.)

SS:

Name 3:

-CH 18/7/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III18009179/Ab3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 21-05-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8022S	Veh. Inspected	SLQ 5280T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/05/2018	Inspection Date	16/05/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

PEH HO KONG

17/05/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TS III

Xiao Tony

VF73DBHZTGJ886361

Accident date: 16/05/2018

Estimated repair cost for vehicle no: SLQ5280T CITROEN C4 PICASSO 1.6 A '17

CHASSIS: VF73DBHZTGJ886361

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>cracked</i>		\$2,050.00 ✓
2	1	Rear Boot Lid Emblem Logo		\$85.00 ✓
3	1	Rear Boot Lid Citroen Logo		\$95.00 ✓
4	1	Rear Boot Lid C4 Logo		\$60.00 ✓
5	1	Rear Boot Lid Picasso Logo		\$95.00 ✓
6	1	Rear Boot Lid C&C Logo		\$60.00 ✓
7	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 ✗
8	1	Rear Boot Lid Lower Cover <i>Delid</i>		\$680.00 ✓
9	1	Rear Boot Lid Windscreen Seal <i>in</i>		\$105.00 ✓
10	1	Rear Tail Lamp <i>xtol new</i>		\$580.00 ✗
11	1	Rear Bumper <i>Distorted</i>		\$1,050.00 ✓
12	1	Rear Bumper Lower <i>Delid</i>		\$490.00 ✓
13	8	Rear Bumper Clip <i>A</i>	\$8.00	\$64.00 30
14	1	Rear L/H Bumper Side Retainer <i>in</i>		\$165.00 ✓
15	1	Rear L/H Bumper Side Reflector <i>cracked</i>		\$285.00 ✓
16	1	Rear L/H Bumper Side Reflector Bracket <i>new</i>		\$155.00 ✗
17	1	Rear Bumper Reinforcement <i>Bent</i>		\$480.00 ✓
18	2	Rear Bumper Reverse Sensor <i>1 piece damaged</i>	\$190.00	\$380.00 100
19	1	Rear L/H Fender <i>Repair</i>		\$1,800.00 ✗
20	1	Rear End Panel <i>Repair</i>		\$850.00 ✗
21	1	Rear End Panel Top Garnish <i>new</i>		\$550.00 ✗

5520

5328

Subtotal :- \$10,129.00

Labour charges

To remove & refit reverse sensor	\$100.00 50
To remove & refit camera	\$180.00 50
To remove & refit cushion	\$180.00 60
To remove & refit rear windscreen	\$120.00 100
Gum	\$50.00 ✓
To reset computer	\$180.00 ✗
To check wiring	\$100.00 30
Panel beating	\$1,000.00 800
Spray painting	\$1,000.00 800

Subtotal :- \$2,910.00

Total:- \$13,039.00

total: 7268

2/8/ S.E.K

05 Days

S.E.K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poh Kin (LKKAuto)

From: Admin nht <admin@nhtmotor.com>
Sent: Thursday, 12 July 2018 3:19 PM
To: Poh Kin (LKKAuto)
Cc: Hsiao Tong (LKKAuto)
Subject: Re: confirmed settlement + DV; Our Ref: CC6/III18009179/Apb3; Your Ref NPI1806-0126 / SLQ 5280T
Attachments: SLQ5280T DV.pdf; SLQ5280T DV.pdf

Without Prejudice

Hi Poh Kin

Enclosed sign discharge voucher for your reference.

Tomorrow will hand over the original copy to Adrian bring back for you,thanks.

Please highlight to India, payment cheque issue to "New Hock Teck Motor Pte Ltd" for this claim.

*****Please take note our all new claim case effective Aug 2017 will be under New Hock Teck Motor Pte Ltd**

Before Aug 2017 all claim case is under New Hock Teck Motor Workshop.

Please help us to inform your finance department to issue the cheque accordingly,thanks.



On Thu, Jul 12, 2018 at 2:34 PM, Poh Kin (LKKAuto) <pohkin@lkkauto.com> wrote:

Dear Sukyi,

Resend DV.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Poh Kin (LKKAuto)

Sent: Tuesday, 10 July 2018 12:20 PM

To: 'Admin nht' <admin@nhtmotor.com>

Cc: 'Chloe' <chloe@nhtmotor.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: confirmed settlement + DV; Our Ref: CC6/III18009179/Apb3; Your Ref NPI1806-0126 / SLQ 5280T

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/III18009179/Apb3

Your Ref: NPI1806-0126 / SLQ 5280T

Dear Sukyi,

ROAD TRAFFIC ACCIDENT INVOLVING SH 8022S AND SLQ 5280T ON 16.05.2018

We refer to the above matter and your letter of demand dated 25th June 2018.

We hereby confirmed settlement as below:

1. Cost of Repair	S\$ 5,800.00
2. Loss of Use (\$60.00 x 6days)	S\$ 360.00
3. LTA search fee	S\$ 7.45
	<u>S\$ 6,167.45</u>

Please duly sign the **DV** enclosed and return for payment processing.

We need original copy DV.

In the meantime, kindly furnish us a copy of after repair photo for our file record.

Your prompt reply will be very much appreciate.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Print Received message

This mail is associated with :

***SLQ5280T (MCT18050407)**

[SH8022S]

TP

PEH HO KONG

May 16 2018 7:00AM

[-]

New Hock Teck Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/07/2018 11:30 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6167.45) - SLQ5280T - Claim Handler: Sherini Pillai

Approved:6167.45.

Claim Audit

AUDIT TRAIL				By
o.	On	Audit	Remarks	
1	21 May 2018 17:52	Clim Veh Model Changed	(204938) CITROEN C4 1.2 1.2 PURETECH EAT6 (A).	[A] Lau Shu Pei
2	21 May 2018 17:52	Clim Created	Reg No: SLQ5280T. Acct Date: 2018/05/16. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: New Hock Teck Motor Pte Ltd (HQ)	[A] Lau Shu Pei
3	21 May 2018 17:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	21 May 2018 17:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[A] Lau Shu Pei
5	21 May 2018 17:52	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	21 May 2018 17:53	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	21 May 2018 17:53	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
8	24 May 2018 17:42	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Bola 27, OID rear ended TP.	[A] Chong Poh Kin
9	25 May 2018 09:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[I] Sherini Pillai
10	25 May 2018 09:02	Adj Mandate Set	Approved:0.00.	[I] Sherini Pillai
11	11 Jun 2018 14:28	Video Downloaded	Downloaded Video - Accident	[A] Chong Poh Kin
12	03 Jul 2018 16:05	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	03 Jul 2018 16:05	Clim Dtl Modified	Insured Name: -> -.	[A] JOANNE LEE KHANG MIN
14	03 Jul 2018 16:05	Clim Dtl Modified	Claimant's Name: -> -. Claimant's ID: -> -.	[A] JOANNE LEE KHANG MIN
15	03 Jul 2018 16:05	Clim Dtl Modified	JPJ Reg. Date: -> 2017/07/14.	[A] JOANNE LEE KHANG MIN
16	03 Jul 2018 16:05	Clim Details Notified		[A] JOANNE LEE KHANG MIN
17	04 Jul 2018 17:26	Adj Mandate Request	Cur.Req:6167.45:PODS Liability: 100%, Bola 27. Quantum: (a) COR: \$ 5,800.00 + (b) L OU: \$360.00 + (c) LTA: \$7.45 =Total: \$6,167.45. vehicle model: CITREON C4 PICASSO 1.6 BLUEHD EAT6 [88.0 kW (118 bhp)] For your approval	[A] Chong Poh Kin

Date From



Date To



Audit Type

None

Go

ACTIVITY

5 record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1829532	11/06/2018 14:27	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLQ5280T	Sherini Pillai	xx.xx
1849533	03/07/2018	Motor	LKK Auto	LKK Auto	SLQ5280T	SH8022S	10.70

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 11 June 2018 2:38 PM
To: 'admin@nhtmotor.com'
Cc: Hsiao Tong (LKKAUTO); Vic (LKKAUTO); Shu Pei (LKKAUTO); 'chloe@nhtmotor.com'
Subject: Your Ref: SLQ 5280T; Our Ref:CC6/III18009179/Apb3
Importance: High

WITHOUT PREJUDICE

Your Ref: SLQ 5280T
Our Ref: CC6/III18009179/Apb3

Dear Sukyi,

ACCIDENT INVOLVING VEHICLES SH 8022S AND SLQ 5280T ON 16/05/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Print Received Message

This mail is associated with :

***SLQ5280T (MCT18050407)**
[SH8022S]

TP
PEH HO KONG
May 16 2018 7:00AM

New Hock Teck Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 25/05/2018 09:02 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLQ5280T - Claim Handler: Sherini Pillai

Approved:0.00.

Print Received Message

This mail is associated with :

***SLQ5280T (MCT18050407)**
[SH8022S]

TP

PEH HO KONG

May 16 2018 7:00AM

[-]

New Hock Teck Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/07/2018 11:30 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6167.45) - SLQ5280T - Claim Handler: Sherini Pillai

Approved:6167.45.

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	21 May 2018 17:52	Cim Veh Model Changed	(204938) CITROEN C4 1.2 1.2 PURETECH EAT6 (A).	[A] Lau Shu Pei
2	21 May 2018 17:52	Cim Created	Reg No: SLQ5280T, Acct Date: 2018/05/16. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: New Hock Teck Motor Pte Ltd (HQ)	[A] Lau Shu Pei
3	21 May 2018 17:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	21 May 2018 17:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[A] Lau Shu Pei
5	21 May 2018 17:52	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	21 May 2018 17:53	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	21 May 2018 17:53	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
8	24 May 2018 17:42	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% Remarks: Bola 27, OID rear ended TP.	[A] Chong Poh Kin
9	25 May 2018 09:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[I] Sherini Pillai
10	25 May 2018 09:02	Adj Mandate Set	Approved:0.00.	[I] Sherini Pillai
11	11 Jun 2018 14:28	Video Downloaded	Downloaded Video - Accident	[A] Chong Poh Kin
12	03 Jul 2018 16:05	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	03 Jul 2018 16:05	Cim Dti Modified	Insured Name: -> -.	[A] JOANNE LEE KHANG MIN
14	03 Jul 2018 16:05	Cim Dti Modified	Claimant's Name: -> -. Claimant's ID: -> -.	[A] JOANNE LEE KHANG MIN
15	03 Jul 2018 16:05	Cim Dti Modified	JPJ Reg. Date: -> 2017/07/14.	[A] JOANNE LEE KHANG MIN
16	03 Jul 2018 16:05	Cim Details Notified		[A] JOANNE LEE KHANG MIN
17	04 Jul 2018 17:26	Adj Mandate Request	Cur.Reg:6167.45:PODS Liability: 100%, Bola 27. Quantum: (a) COR: \$ 5,800.00 + (b)L OU: \$360.00 + (c) LTA: \$7.45 =Total: \$6,167.45. vehicle model: CITREON C4 PICASSO 1.6 BLUEHDI EAT6 [88.0 kW (118 bhp)] For your approval	[A] Chong Poh Kin

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1829532	11/06/2018 14:27	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SLQ5280T	Sherini Pillai	xx.xx
1849533	03/07/2018	Motor	LKK Auto	LKK Auto	SLQ5280T	SH80225	10.70

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1806-0126 / SLQ5280T
Yr Ref : SH8022S
Date : 25th June 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

WITHOUT PREJUDICE

Dear Sirs,

RE: ACCIDENT INVOLVING SLQ5280T & SH8022S RIVERVALE DR ON 16.05.2018, 07:50HR

We are instructed by **PEH HO KONG** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SLQ5280T** was damaged by vehicle **SH8022S** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 5,800.00
2) Loss of Use for 06 days (5 + 1 Weekend)	\$ 360.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 6,167.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$6,167.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,

NEW HOCK TECK MOTOR PTE LTD



LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd

Kaki Bukit Avenue 6

Blk 1 #01-43

Singapore 417883

Dear Sir,

Accident on

16/05/18, 0750

Involving Vehicles

SLQ5280T, SH80224

Along

Rivendale Dr

I/We, the registered owner/driver of vehicle registration no: _____
have involved in the above accident.

SLQ5280T

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, _____, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature

(Company's stamp if applicable)

Name: _____

NRIC No.: _____

Date: _____

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SLQ52807 and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 16 day of 05 20 18.

Signature : [Signature]
Name : REN HO KONG
ID No. : 587256181
Address : _____

Witness Signature : [Signature]
Witness Name : Chew Yee Yee
Witness ID : _____
Witness Address : 1 Kaki Bukit Avenue 6 #01-43
Singapore 417883

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: TP / MCT18050407
 Claimant Ref: SLQ 5280T

We/I, New Hock Teck Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 5,800.00 (repair cost), S\$ 360.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no: SLQ 5280T that was damaged pursuant to the accident which occurred on 16/05/2018 (date) at Rivervale Drive (location) involving vehicle no. SH 8022S (insured vehicle). This is pursuant to the inspection conducted on 16/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PEH HO KONG ("the third party claimant") of vehicle no. SLQ 5280T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLQ 5280T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 6,167.45 to New Hock Teck Motor Pte Ltd.

Dated this 16 day of 08 20 18.

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

新 福 德 車 廠
NEW HOCK TECK MOTOR PTE LTD
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit Singapore 417883
 Tel: 6747 9241 Fax: 6741 7276
 Email: admin@nhtmotor.com
 UEN: 201718370K

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



LKK AUTO CONSULTANTS PTE LTD
 51 Ubi Ave 1, #01-23
 Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256 3561



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

India International Insurance Pte Ltd

64 Cecil Street #04/ #05

IOB Building

Singapore 049711

Client: PEH HO KONG

Invoice No : NPL1806-0126

Date : 25-Jun-18

Date of Accident : 16-May-18

Vehicle No. : SLQ5280T

Model Type : Citroen C4

Descriptions		Amount
Lump Sum Repair Cost		5,800.00
Total		5,800.00

SIN DOLLARS: FIVE THOUSAND AND EIGHT HUNDRED ONLY



[> Back to OneMotoring](#)

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 May 2018 / 12:06:43

Receipt Date/Time : 16 May 2018 / 12:06:43

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180516-000992

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SH8022S As at 16 May 2018/07:50:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SH8022S Enquiry Fee 20180516120558436899	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20180516120604970	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[Print Receipt](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018 Edit Reg		16 May 2018 00:00 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	PEH HO KONG , ID: S87256181								
Vehicle Reg. No.:	SLQ5280T	Date of Loss:	16/05/2018 07:00 - :59 [10 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050407	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH8022S	Policy No. (Claimant):	1700026229						
		Excess:							
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 31/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (09/07/2018): Alert - Adj Mandate Approved (S\$6167.45) - SLQ5280T - Claim Handler: Sherini Pillai... III_SG (25/05/2018): Alert - Adj Mandate Approved (S\$0.00) - SLQ5280T - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ5280T (MCT18050407)
[SH8022S]
TP
PEH HO KONG
May 16 2018 7:00AM
[COMFORT TRANSPORTATION PTE LTD]
New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	11/06/18 14:27	Video - Accident					1	Load MP4		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
2	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
3	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
4	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
5	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
6	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
7	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
8	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
9	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
10	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
11	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
12	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
13	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
14	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
15	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
16	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
17	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
18	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
19	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
20	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
21	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
22	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
23	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
24	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
25	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
26	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
27	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
28	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
29	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
30	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
31	20/06/18 18:06	General View					1	Load JPG	<input checked="" type="checkbox"/>	
32	20/06/18 18:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
33	20/06/18 18:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
34	20/06/18 18:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	20/06/18 18:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	17/07/18 16:11	LKK SURVEY PHOTO- AFTER REPAIR	Load JPG	<input checked="" type="checkbox"/>
62	17/07/18 16:11	LKK SURVEY PHOTO- AFTER REPAIR	Load JPG	<input checked="" type="checkbox"/>
63	17/07/18 16:11	LKK SURVEY PHOTO- AFTER REPAIR	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 17:53	TP GIA REPORT	Load PDF	
2	03/07/18 16:12	WORKSHOP INVOICE	Load PDF	
3	03/07/18 16:12	LTA SEARCH	Load PDF	
4	03/07/18 16:12	LOD	Load PDF	
5	16/07/18 17:02	TP Estimate-Marked	Load PDF	
6	29/08/18 08:51	DISCHARGE VOUCHER	Load PDF	
7	29/08/18 08:51	AUTHORISATION TO ACT FORM	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 08:43	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18009179/APB3Q2

Date: 29/08/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SLQ5280T

Insured Vehicle No : SH8022S

Date of Loss: 16/05/2018

Nature of Claim: TP

Claim No: MCT18050407

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ5280T

Make & Model: CITROEN C4, 1.2 1.2 PURETECH EAT6 (A)

Engine No: 10JBHD3069685

Reg. Date: 14/07/2017 (Man. Year: 2016)

Chassis No: VF73DBHZTGJ886361

Colour: White

Odometer: 13541 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,129.00	5,328.00	4,801.00	47.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	1,940.00	970.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,039.00	7,268.00	5,771.00	44.26
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	13,039.00	5,800.00	7,239.00	55.52
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,167.45		

INSPECTION

Date of Assignment: 16/05/2018

Date Inspected: 16/05/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jul 2018)	
Parts:	N/A	CITROEN C4 1.2 1.2 PURETECH EAT6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ5280T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Cracked	2,050.00 F	*2,050.00 FL
2	1		*REAR BOOT LID EMBLEM LOGO	Necessary	85.00 F	*85.00 FL
3	1		*REAR BOOT LID CITROEN LOGO	Necessary	95.00 F	*95.00 FL
4	1		*REAR BOOT LID C4 LOGO	Necessary	60.00 F	*60.00 FL
5	1		*REAR BOOT LID PICASSO LOGO	Necessary	95.00 F	*95.00 FL
6	1		*REAR BOOT LID C&C LOGO	Necessary	60.00 F	*60.00 FL
7	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
8	1		*REAR BOOT LID LOWER COVER	Deformed	680.00 F	*680.00 FL
9	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
10	1		*REAR TAIL LAMP	Not Necessary	580.00 F	*- FL
11	1		*REAR BUMPER	Distorted	1,050.00 F	*1,050.00 FL
12	1		*REAR BUMPER LOWER	Deformed	490.00 F	*490.00 FL
13	8		*REAR BUMPER CLIP	Necessary	64.00 F	*30.00 FL
14	1		*REAR L/H BUMPER SIDE RETAINER	Necessary	165.00 F	*165.00 FL
15	1		*REAR L/H BUMPER SIDE REFLECTOR	Cracked	285.00 F	*285.00 FL
16	1		*REAR L/H BUMPER SIDE REFLECTOR BRACKET	Not Necessary	155.00 F	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	480.00 F	*480.00 FL
18	2		*REAR BUMPER REVERSE SENSOR	Damaged (1 PCS ONLY)	380.00 F	*190.00 FL
19	1		*REAR L/H FENDER	Repair	1,800.00 F	*- FL
20	1		*REAR END PANEL	Repair	850.00 F	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	550.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) **10,129.00** **5,920.00**

- List Item Discount on L Items 0.00/10.00% (\$\$) **0.00** **592.00**

Total Parts (\$\$) **10,129.00** **5,328.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT CAMERA	New	180.00	50.00
3	TO REMOVE & REFIT CUSHION	New	180.00	60.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	100.00
5	GUM	New	50.00	50.00
6	TO RESET COMPUTER	New	180.00	0.00
7	TO CHECK WIRING	New	100.00	30.00
8	PANEL BEATING	New	1,000.00	800.00
9	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,910.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >