

ASS. REC. BY:

REF: CS/EOT8009188 / RH627 | Special Instruction:

SUPERVISOR:

RUSUL

ASSIGNMENT (Office)

MENJEMEN

From (Person): Joel Goh

of

RSL

Date/Time: 18032018 4:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S6V 1991J

Insured:

at Workshop m/s

Autu N Cars

Tel:

6555 2909

of

Blk 1 Kaki Bukit Ave 6 #01-04

Policy No:

DMPPHQ18-000542

Claim No:

DM18H1001234-JH

Sum Insured:

Excess:

\$1500.00

Make of Veh:

(Client's Record)

D.O.A. 12052018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21052018 11:03am

Person Contacted:

Datta Jayden

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

S6V 1991J - CC4 11EQ18009129 / 6eb3

DOA: 120518

22/5- Revert via menmen

24/5 @ 15:24 authorise repair by Joel goh.

24/5 @ 3:35pm in form Jayden authorise repair @ \$1500+ excess

lump sum \$8800/- (Red. 12160.70 : 58%)

Surveyor: *R. Rane*

REF:

20772

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SHV19913*

at Workshop m/s *Auto N cars*

of *1, Kanki Bunt MG 6 #01-04*

Insured: *EQ1*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: *1500*

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S | O/S |
| <input type="checkbox"/> | <input type="checkbox"/> |

Bal. or Market Value: *44K*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SHV19913* Yr Regn: *2011 / PGB*

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *MAZDA RX-8 1.3M* c.c *1308*

Colour: *Yellow* A/C: Insured / Std / NI / NA

Sp. Reading: *212524* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *SE 3P 301467*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *235/45ZR17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *12/05/18* D.O.I. *24/05/18*

Survey held at *Auto N cars*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 MAR 2019

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *10*

Resurvey No. of Trip: *1+1*

Survey Fee: *300*

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : *OD*

Lump Sum / I.B.I: (\$ *8800*)

300

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-----------------------------|--------------------------------------|--------------------------------|---------|---------------|------------|-------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 16 May 2018 Sendback Est | 16 May 2018 15:42 S\$20,960.70 | 18 May 2018 16:08 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|----------------------------------|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | | | | | | | |
| Insured: | ANDIK MUHAMMAD ASY' ARI BIN IBRAHIM, ID: S8332077Z | | | | | | | | |
| Vehicle Reg. No.: | SGV1991J | Date of Loss: | 12/05/2018 14:00 - :59 [87 Months and 1 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | OD / DM18HO01234-JG | Policy/Cover Note No.: | DMPPHQ18-000942 (Comprehensive) | | | | | | |
| | | Excess: | S\$1,500.00 | | | | | | |
| Repairer: | Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909 | | | | | | | | |
| Handling Insurer: | EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2018] | | | | | | | | |
| Driver/Custodian: | MOHAMMAD IKBAR BIN RAHUD (30 / Male), NRIC: S8719901J, Tel: +6590731887 | | | | | | | | |
| Adj Asg. Remarks: | EXCESS: \$1,500.00 NO WAIVER. SURVEY AND REVERT | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

21/05/2018 @ 11:03am

Darta veh in

Racul

Claim Audit

AUDIT TRAIL

| No. | On | Audit | Remarks | By |
|-----|----------------------|----------------------------------|---|------------------------------|
| 1 | 16 May 2018 14:54 | Cim Veh Model Changed | (205498) MAZDA RX-8 1.3 (M). | [R] Jaden Choo Jing Tong |
| 2 | 16 May 2018 14:54 | Cim Created | Reg No: SGV1991J. Policy No: DMPPHQ18-000942. Acct Date: 2018/05/12. Claim Type: OD. Insurer: EQ Insurance Company Ltd (HQ). Workshop: Auto N Cars Services Pte Ltd (HQ). Created from SAS:MANC18062573 | [R] Jaden Choo Jing Tong |
| 3 | 16 May 2018 15:42 | Cim Submitted | 20960.70. | [R] Jaden Choo Jing Tong |
| 4 | 18 May 2018 16:08 | Cim Registration Modified | Excess: -> 1500.00. | [I] Joel Goh |
| 5 | 18 May 2018 16:08 | Adj Co Assigned | LKK Auto Consultants Pte Ltd (HQ):EXCESS: \$1,500.00 NO WAIVER. SURVEY AND R EVERT | [I] Joel Goh |
| 6 | 18 May 2018 16:08 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2018/05/30 | [I] Joel Goh |
| 7 | 18 May 2018 16:08 | Adj Mandate Set | Approved:0.00. | [I] Joel Goh |
| 8 | 21 May 2018 10:27 | Assignment 1st Accessed | | [A] CELINE FONG |
| 9 | 21 May 2018 17:55 | Adj Adjuster Assigned | [None] -> MOHD RASUL | [A] CATHERINE CHONG KAI LING |
| 10 | 22 May 2018 10:02 | Adj Rpt Initiated | | [A] DENISE TAY KWEE CHENG |
| 11 | 22 May 2018 10:12 | Adj Im. Advice Submitted | Next Rpt:Final Rpt.Due Date:2018/05/30 | [A] DENISE TAY KWEE CHENG |
| 12 | 22 May 2018 11:04 | Adj Mandate Request | Cur.Reg:15370.95:DAMAGE CONSISTENT REPAIR COST ECONOMICAL | [A] DENISE TAY KWEE CHENG |
| 13 | 24 May 2018 15:24 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2018/05/30. Mandate Remarks: Please proceed to authorize OD up to \$15,370.95 before excess of \$1,500.00 | [I] Joel Goh |
| 14 | 24 May 2018 15:24 | Adj Mandate Set | Approved:15370.95:Please proceed to authorize OD up to \$15,370.95 before excess of \$1,500.00Reinsp:Adj decides. | [I] Joel Goh |

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

| Bill Ref No | Bill Date | Acc Type | Acc Name | Co Name (Branch) | Ref 1 | Ref 2 | Amount |
|-------------|---------------------|----------|-----------------------------------|-----------------------------------|----------|-------|--------|
| 1806291 | 16/05/2018 14:54 | Motor | Auto N Cars Services Pte Ltd (HQ) | Auto N Cars Services Pte Ltd (HQ) | SGV1991J | | xx.xx |
| 1811116 | 22/05/2018 10:02 | Motor | LKK Auto Consultants Pte Ltd | LKK Auto Consultants Pte Ltd (HQ) | SGV1991J | | 10.70 |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 22 May 2018

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|-------------------|
| Vehicle No | : SGV1991J | Accident Date | : 12/05/2018 |
| Make | : MAZDA RX-8 | Policy No. | : DMPPHQ18-000942 |
| Assignment Date | : 18/05/2018 | Excess | : S\$1,500.00 |
| Date of Inspection | : 21/05/2018 | Est. Duration of Repair | : 10.00 |
| Inspection At | : AUTO N CARS SERVICES PTE LTD (HQ) BLK 1 KAKI BUKIT AVE 6 #01-04, AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 20,960.70 |
| Revised Amount | :S\$ | 8,387.00 |
| Check Items (Estimated) | :S\$ | 6,983.95 |
| Total | :S\$ | 15,370.95 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 44,000.00 |
| COE / PARF Rebate | :S\$ | 27,010.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 16,990.00 |

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|---|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 2077Z |
| Vehicle Details | |
| Vehicle No.: | SGV1991J |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 22 May 2018 |
| Vehicle Make: | MAZDA |
| Vehicle Model: | RX-8 1.3 M |
| Primary Colour: | Red |
| Manufacturing Year: | 2008 |
| Engine No.: | 13B543922 |
| Chassis No.: | SE3P301467 |
| Maximum Power Output: | 158.0 kW (211 bhp) |
| Open Market Value: | \$28,184.00 |
| Original Registration Date: | 11 Feb 2011 |
| First Registration Date: | 11 Feb 2011 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$28,184.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 10 Feb 2021 |
| PARF Rebate Amount: | \$16,910.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 10 Feb 2021 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$37,124.00 |
| COE Rebate Amount: | \$10,100.00 |
| Total Rebate Amount: | \$27,010.00 |
| Message | |
| Transfer of ownership or de-registration is not allowed for this vehicle. | |

The information contained herein is correct as at 22 May 2018

OK

Vehicle Registration Number of Driver's Own
Vehicle (if applicable)

Insurance Company of Driver's Own Vehicle (if
applicable)

General Information of the Accident

| | |
|--------------------|--|
| Type Of Accident | Collision- Head to Rear (TP Hit Insured) |
| Weather Conditions | Clear |
| Road Surface | Dry |

Other Information

| | |
|---|-----|
| Was any body injured in the Accident? | No |
| Was any other material or property damaged? | Yes |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | No |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | No |
| If Yes, against whom? | |

Circumstances of Accident

On 22.12.2011 at about 1445hrs, I was travelling straight at the extreme left lane along Choa Chu Kang Road towards Bukit Batok Road when vehicles in front of me stop due to traffic so I followed suit. Moment later, I felt an impact from the rear. Vehicle B (SGP8227I) collided onto my taxi's rear portion. Vehicle A: 1 passenger Vehicle B: 1 passenger /rc

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|--------------|
| Vehicle Registration Number | SGP8227T |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Name of Driver | SOH KEE CHAI |
| NRIC/Passport Number | S1350888G |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Details of Witness

| | |
|---------------|------------|
| Name | LIM SHARON |
| Phone Number | |
| Email Address | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------------|
| Date Of Report | 14/05/2018 15:29 |
| Date Of Accident | 12/05/2018 14:00 |
| Exact Location Of Accident | JALAN HUSSIEN/LOR MARZUKI |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-------------------------------------|
| Vehicle Registration Number | SGV1991J |
| Insured/Policyholder | |
| Name Of Registered Owner | ANDIK MUHAMMAD ASY' ARI BIN IBRAHIM |
| NRIC No | S8332077Z |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-86831991 |
| Alternative Phone No | OFFICE-86831991 |

Vehicle Particulars

| | |
|--------------|--------------|
| Manufacturer | MAZDA |
| Model | RX-8-1.3 (M) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

| | |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

Insurance Company

| | |
|---------------------------|--------------------------|
| Name of Insurance Company | EQ INSURANCE COMPANY LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPPHQ18-000942 |
| Cover Note Number | |

Driver

| | |
|----------------------|--------------------------|
| Name of Driver | MOHAMMAD IKBAR BIN RAHUD |
| NRIC No | S8719901J |
| Date Of Birth | 14/06/1987 |
| Occupation | INDOOR |
| Date Of Driving Pass | 02/03/2009 |
| Driving Experience | 9 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90731887 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---|
| Address | BLK 671B EDGEFIELD PLAINS #14-523 S(822671) |
| Postcode | |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | FRIEND |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| Insurance Company of Driver's Own Vehicle | - |

General Information of the Accident

| | |
|--------------------|----------------------------|
| Type Of Accident | COLLISION - MAJOR/MINOR RD |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | PUNGGOL N.P.C |
| Police Station Address | ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: - FAX NO: |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------|
| Vehicle Registration Number | SJK4396E |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE HIRE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



B 8 JK 4396 E



Refer to TP Report T/20120513/2045.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180513/2045

1 of 4

Police Station Of Origin
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No: T/20180513/2045

REPORT OF A TRAFFIC ACCIDENT

| | | |
|---|-----------------|-------------------------|
| Date/Time Report Made 13/05/2018 13:11 | Vide Report No. | Station Diary No. 41 |
|---|-----------------|-------------------------|

Informant's Particulars

| | | | |
|--|---|------------------------------|------------------------------|
| Name of Informant: MOHAMMAD IKBAR BIN RAHUD | Address APT BLK 671B EDGEFIELD PLAINS #14-523 SINGAPORE 822671 | | |
| ID Type / ID No NRIC NO / S8719901J | Contact No Home/Office: Mobile 90731887 | | |
| Nationality SINGAPORE CITIZEN | Email | | |
| Sex: Male | Age: 30 | Date of Birth: 14/06/1987 | Type of Informant: Driver |
| Race Indian | Language | | Institution / School Name: |
| Occupation: SAFETY OFFICER | Driving Licence Information: Class 2B,2A,2,3,4 Date of Expiry: | | |

General Information of the Accident

| | | | | |
|--|------------------------------------|--------------------|---|---------------------------------|
| Type of Accident: | Non-Injury Others | Drink Drive: No | Date/Time of Accident 12/05/2018 14:00 | Type of Location: T-Junction |
| Location: Along Road 1 Traveling Toward Road 2 JALAN HUSSEIN LORONG MARZUKI Along Jalan Hussein turning into Lorong Marzuki Lamp Post Number: 6 | | | | |
| Weather: Clear | Road Surface: Dry | | Road Speed Limit: | |
| Traffic Flow | Traffic Control: Not Controlled | | Traffic Volume: No Traffic | |
| Type of Collision: Between Moving Vehicles - Head On | | | Anyone conveyed by ambulance: No | |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|------|-------|-------|-----------|-----------------|
| SGV1991J | Car | | | | | 0 |
| SJK4396E | Car | | | | | 2 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180513/2045

Police Station Of Origin
Punggol N P C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 4

Report No T/20180513/2045

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|--------------------------|------------------|---|
| Driver | | | |
| Name | MOHAMMAD IKBAR BIN RAHUD | | ID No. S8719901J |
| Related Vehicle | SGV1991J (Car) | | Contact No. 90731887 |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date Class: 2B,2A,2,3,4 Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Driver | | | |
| Name | RAMESH SIVALINGAM | | ID No. S8327164G |
| Related Vehicle | SJK4396E (Car) | | Contact No. 91834450 |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On 12/05/2018 at around 1400hours, I was travelling along Jalan Hussein and turning into Lorong Marzuki at the intersection near to lamp post number 6. While I was approaching the stop line, I stopped at the stop line. There was one vehicle, SJP4609R parked stationary along Lorong Marzuki near to the intersection blocking my vision to check on the oncoming traffic from the opposite direction. As such, I inched out at a very slow speed to make a check.

Out of sudden, one vehicle, SJK4396E, approached from the opposite direction came out from nowhere collided onto my right front engine part. Due to the impact, my vehicle jerk forward. I was in shock for a few seconds. After which, I alighted from my vehicle to make a check. I wish to state that due to the damage on my driver's side door, I have difficulty to open the door. I need to forcefully push it for it to open.

There is no in-built car camera in my vehicle, I made a check on the other party camera and discovered that there is also no in-built car camera. At that point of time, there is no one injured. I wished to inform that there are tyre marks on the road and I believe that it was caused due to hard braking by the driver of SJK4396E. Due to the great impact on my vehicle, I suspect that the driver was speeding, it could have travelled more than 50km/h.

After the accident, I felt pain at my neck area. As such, I will proceed to seek for medical attention after the road traffic accident report has lodged.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

| | |
|--------------------------------|---------------------------|
| Vehicle No. : | SGV1991J |
| Vehicle Type : | P10 - Passenger Motor Car |
| Vehicle Attachment 1 : | No Attachment |
| Vehicle Scheme : | Normal |
| Vehicle Make : | MAZDA |
| Vehicle Model : | RX-8 1.3 M |
| Chassis No. : | SE3P301467 |
| Propellant : | Petrol |
| Engine No. : | 13B543922 |
| Engine Capacity : | 1308 cc |
| Maximum Power Output : | 158.0 kW (211 bhp) |
| Maximum Laden Weight : | 1560 kg |
| Unladen Weight : | 1340 kg |
| Year Of Manufacture : | 2008 |
| Original Registration Date : | 11 Feb 2011 ✓ |
| Lifespan Expiry Date : | - |
| COE Category : | A - Car (1600cc & below) |
| Quota Premium : | \$37,124.00 |
| COE Expiry Date : | 10 Feb 2021 |
| Road Tax Expiry Date : | 10 Aug 2018 |
| PARF Eligibility Expiry Date : | 10 Feb 2021 |
| Inspection Due Date : | 10 Feb 2020 |
| Intended Transfer Date : | 21 May 2018 |
| CO2 Emission : | - |
| CO Emission : | - |
| HC Emission : | - |
| NOx Emission : | - |
| PM Emission : | - |

The current road tax expiry is 10 Aug 2018. You may renew the road tax from 11 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 10 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 11 Aug 2018 to 10 Feb 2019)

| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
|---|----------------------------|---------------------|---------------------------|
| Transfer Fee : | 25.00 | - | 25.00 |
| Sub Total : | | | 25.00 |
| Nett Road Tax Amount (After Offsetting Over Payment) : | 286.00 | - | 286.00 |
| Total Amount Payable : | | | 311.00 |

Amount Payable (From 11 Aug 2018 to 10 Aug 2019)

| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
|---|----------------------------|---------------------|---------------------------|
| Transfer Fee : | 25.00 | - | 25.00 |
| Sub Total : | | | 25.00 |
| Nett Road Tax Amount (After Offsetting Over Payment) : | 572.00 | - | 572.00 |
| Total Amount Payable : | | | 597.00 |

Message

Transfer of ownership is not allowed for this vehicle.
You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------------|
| Date Of Report | 14/05/2018 15:29 |
| Date Of Accident | 12/05/2018 14:00 |
| Exact Location Of Accident | JALAN HUSSIEH/LOR MARZUKI |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-------------------------------------|
| Vehicle Registration Number | SGV1991J |
| Insured/Policyholder | |
| Name Of Registered Owner | ANDIK MUHAMMAD ASY' ARI BIN IBRAHIM |
| NRIC No | S8332077Z |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-86831991 |
| Alternative Phone No | OFFICE-86831991 |

Vehicle Particulars

| | |
|--------------|--------------|
| Manufacturer | MAZDA |
| Model | RX-8-1.3 (M) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

| | |
|---------------------------|--------------------------|
| Name of Insurance Company | EQ INSURANCE COMPANY LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMPPHQ18-000942 |
| Cover Note Number | |

Driver

| | |
|----------------------|--------------------------|
| Name of Driver | MOHAMMAD IKBAR BIN RAHUD |
| NRIC No | S8719901J |
| Date Of Birth | 14/06/1987 |
| Occupation | INDOOR |
| Date Of Driving Pass | 02/03/2009 |
| Driving Experience | 9 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90731887 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

Accident Photo



Auto N Cars Services Pte Ltd

Co. Reg: 200922097K GST Reg No: 200922097K

Auto Bay @ Kaki Bukit Bldg 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2900 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date: 15/05/2018

Total Pages: 1

TO:

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Our Customer: ANDIK MUHAMMAD

Vehicle No: SGV1991J

Model: Mazda RX-8-1.3 (M)

Manufacture Year: 2008

Date of Accident: 12/5/2018

Total Estimate Repair Days: 14

Attn: Motor Claims Department

Fax: 62243903

Re: Repair Estimate For Own Damage Claim Against Policy: DMPPHQ18-000942

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|-----|---------------------------------|-----|------------|--------------|-----------------------|
| A. | Spare Parts | | | | |
| 1 | Front no plate | 1 | \$50.00 | \$50.00 | 352 S/AI TWA |
| 2 | Front no plate base | 1 | \$90.00 | \$90.00 | 6060 |
| 3 | Front bumper | 1 | \$870.00 | \$870.00 | TWA |
| 4 | Front bumper tow cover RH | 1 | \$68.00 | \$68.00 | MS |
| 5 | Front bumper retainer | 2 | \$45.00 | \$90.00 | X NH |
| 6 | Front bumper logo | 1 | \$70.00 | \$70.00 | new |
| 7 | Front bumper sponge | 1 | \$118.00 | \$118.00 | CRA |
| 8 | Front bumper reinforcement | 1 | \$280.00 | \$280.00 | PH |
| 9 | Front bumper lower extension | 1 | \$210.00 | \$210.00 | CRA |
| 10 | Front bumper clip | 12 | \$1.50 | \$18.00 | new |
| 11 | Front bumper lower cover | 1 | \$155.00 | \$155.00 | DE |
| 12 | Front bumper RH side garnish | 1 | \$68.00 | X \$68.00 | new ? X SUC |
| 13 | Front bumper ctr grille | 1 | \$180.00 | \$180.00 | cut |
| 14 | RHF fog lamp outer garnish | 1 | \$85.00 | \$85.00 | MS |
| 15 | RH fog lamp inner garnish | 1 | \$98.00 | \$98.00 | MS |
| 16 | RH headlamp | 1 | \$998.00 | \$998.00 | BR |
| 17 | RH headlamp lower bracket | 1 | \$72.00 | \$72.00 | PH |
| 18 | RH headlamp ballast | 1 | \$720.00 | X \$720.00 | F ? X SUC |
| 19 | RH headlamp panel | 1 | \$155.00 | \$155.00 | PH |
| 20 | RHF fender | 1 | \$580.00 | \$580.00 | new |
| 21 | RHF fender support bracket | 1 | \$65.00 | \$65.00 | new |
| 22 | RHF fender splash shield top | 1 | \$138.00 | \$138.00 | DE |
| 23 | RHF fender splash shield clip | 16 | \$1.50 | \$24.00 | new |
| 24 | RHF fender splash shield bottom | 1 | \$75.00 | \$75.00 | ? DE |
| 25 | RHF door | 1 | \$1,210.00 | \$1,210.00 | Repair |
| 26 | RHF oil cooler assy | 1 | \$520.00 | \$520.00 | PH |
| 27 | RHF oil cooler bracket | 2 | \$38.00 | \$76.00 | PH |
| 28 | RHF sport rim | 1 | \$1,100.00 | X \$1,100.00 | Repair |
| 29 | RHF tyre | 1 | \$380.00 | \$380.00 | X SUC |
| 30 | Front bonnet | 1 | \$690.00 | \$690.00 | Repair ? Repair |
| 31 | LHF fog lamp outer cover | 1 | \$75.00 | \$75.00 | X SUC |
| 32 | RH side skirt | 1 | \$315.00 | \$315.00 | X Inconstant |
| 33 | RHF lower arm | 1 | \$480.00 | \$480.00 | ? PH |
| 34 | RHF control arm | 1 | \$420.00 | \$420.00 | ? PH |
| 35 | RHF shock absorber | 1 | \$320.00 | \$320.00 | ? PH |
| 36 | RHF shock absorber mounting | 1 | \$150.00 | \$150.00 | ? new |
| 37 | RHF shock absorber stopper | 1 | \$65.00 | \$65.00 | ? new |
| 38 | RHF shock absorber dust cover | 1 | \$45.00 | \$45.00 | ? X SUC |
| 39 | RHF stabilizer link | 1 | \$95.00 | \$95.00 | ? X SUC |
| 40 | RHF knuckle | 1 | \$420.00 | \$420.00 | ? PH |
| 41 | RHF knuckle bearing | 1 | \$195.00 | \$195.00 | ? new |
| 42 | Steering rack | 1 | \$1,850.00 | \$1,850.00 | new ? X SUC |
| 43 | Coolant | 1 | \$25.00 | \$25.00 | new |

Accident Photo



| | | | | | |
|---|---|---|--------------------------|--------------------|----------|
| 44 | Steering rack end | 1 | \$180.00 | \$180.00 | Reo |
| 45 | Front support panel | 1 | \$480.00 | \$480.00 | ? Repair |
| 46 | Power steering oil | 1 | \$50.00 | \$50.00 | na |
| | | | Total | \$14,418.00 | |
| | | | Cost Plus 15% | \$2,162.70 | |
| | | | Sub Total 1 | \$16,580.70 | |
| | | | Total for Parts | \$16,580.70 | |
| C. | Labour | | | | |
| 1 | To knock & straighten the necessary portion, remove & renew damaged parts, adjust & realign the same. | | \$1,380.00 | 800 + 200 4000 | |
| 2 | To putty & spray RHF door, frt bumper, frt support panel, RHF fender, frt bumper reinforcement, frt bonnet & LHF fender | | \$1,580.00 | 900 | |
| 3 | To jack & straighten both frt chassis | | \$350.00 | 150 | |
| 4 | To remove & transfer RHF fitting, fixture and conduct water seepage & wind noise test | | \$200.00 | 80 | |
| 5 | To do 4 wheel alignment | | \$120.00 | 60 | |
| 6 | To remove & refit radiator assy, air-con condensor assy, vacuum & change up gas to assist workload | | \$120.00 | 80 | |
| 7 | To drop steering rack & pinion assy and removal of the same and final checking & testing | | \$400.00 | 200 | |
| 8 | To check all wiring and all lighting | | \$60.00 | 30 | |
| 9 | To drop RHF under carriage parts, remove & renewal of the necessary parts, to perform final check & testing | | \$250.00 | 150 | |
| | | | Total Labour | \$4,380.00 | |
| | | | Total Repair Cost | \$20,960.70 | |
| * The above quoted are exclusive of GST. | | | | | |

Yours faithfully,

Jaden

f Auto N Cars Services Pte Ltd

| | |
|--------------|---------------------------|
| Name | RASUL (LKK) |
| Contact | 90010068 |
| Survey Date | 21/05/18 @ 1520 |
| Recommender | Authorize / Not Authorize |
| Before Paint | Yes / No after paint |
| Signature | 10 days 4S |

| | |
|------|--------------------------------|
| DATE | Remark From MR CHOO |
| | Please arrange for survey asap |

EXCESS: 1500
 REVERT
 Resurvey after repair

Accident Photo





Co. Reg: 200922097K GST Reg.No: 200922097K

Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date: 15/05/2018

Total Pages : 1

TO:

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Our Customer : ANDIK MUHAMMAD

Vehicle No : SGV1991J

Model : Mazda RX-8-1.3 (M)

Manufacture Year : 2008

Date of Accident : 12/5/2018

Total Estimate Repair Days : 14

Attn : Motor Claims Department

Fax : 62243903

Re: Repair Estimate For Own Damage Claim Against Policy : DMPPHQ18-000942

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|-----------|---------------------------------|-----|------------|------------|-----------------------|
| A. | Spare Parts | | | | |
| 1 | Front no plate | 1 | \$50.00 | \$50.00 | 35? S/AI Tuck |
| 2 | Front no plate base | 1 | \$90.00 | \$90.00 | 606? Tuck |
| 3 | Front bumper | 1 | \$870.00 | \$870.00 | Tuck |
| 4 | Front bumper tow cover RH | 1 | \$68.00 | \$68.00 | ms |
| 5 | Front bumper retainer | 2 | \$45.00 | \$90.00 | X nn |
| 6 | Front bumper logo | 1 | \$70.00 | \$70.00 | nn |
| 7 | Front bumper sponge | 1 | \$118.00 | \$118.00 | CRA |
| 8 | Front bumper reinforcement | 1 | \$280.00 | \$280.00 | BT |
| 9 | Front bumper lower extension | 1 | \$210.00 | \$210.00 | CRA |
| 10 | Front bumper clip | 12 | \$1.50 | \$18.00 | nn |
| 11 | Front bumper lower cover | 1 | \$155.00 | \$155.00 | DE |
| 12 | Front bumper RH side garnish | 1 | \$68.00 | \$68.00 | nn ? SVL |
| 13 | Front bumper ctr grille | 1 | \$180.00 | \$180.00 | Cut |
| 14 | RHF fog lamp outer garnish | 1 | \$85.00 | \$85.00 | ms |
| 15 | RH fog lamp inner garnish | 1 | \$98.00 | \$98.00 | ms |
| 16 | RH headlamp | 1 | \$998.00 | \$998.00 | BRO |
| 17 | RH headlamp lower bracket | 1 | \$72.00 | \$72.00 | BT |
| 18 | RH headlamp ballast | 1 | \$720.00 | \$720.00 | F ? X SVL |
| 19 | RH headlamp panel | 1 | \$155.00 | \$155.00 | BT |
| 20 | RHF fender | 1 | \$580.00 | \$580.00 | nn |
| 21 | RHF fender support bracket | 1 | \$65.00 | \$65.00 | nn |
| 22 | RHF fender splash shield top | 1 | \$138.00 | \$138.00 | DE |
| 23 | RHF fender splash shield clip | 16 | \$1.50 | \$24.00 | nn |
| 24 | RHF fender splash shield bottom | 1 | \$75.00 | \$75.00 | ? v nq |
| 25 | RHF door | 1 | \$1,210.00 | \$1,210.00 | Repair |
| 26 | RHF oil cooler assy | 1 | \$520.00 | \$520.00 | BT |
| 27 | RHF oil cooler bracket | 2 | \$38.00 | \$76.00 | BT |
| 28 | RHF sport rim | 1 | \$1,100.00 | \$1,100.00 | Repair |
| 29 | RHF tyre | 1 | \$380.00 | \$380.00 | X |
| 30 | Front bonnet | 1 | \$690.00 | \$690.00 | Repair ? repair |
| 31 | LHF fog lamp outer cover | 1 | \$75.00 | \$75.00 | X |
| 32 | RH side skirt | 1 | \$315.00 | \$315.00 | X inconsistent nn |
| 33 | RHF lower arm | 1 | \$480.00 | \$480.00 | ? BT |
| 34 | RHF control arm | 1 | \$420.00 | \$420.00 | ? BT |
| 35 | RHF shock absorber | 1 | \$320.00 | \$320.00 | ? BT |
| 36 | RHF shock absorber mounting | 1 | \$150.00 | \$150.00 | ? nn |
| 37 | RHF shock absorber stopper | 1 | \$65.00 | \$65.00 | ? nn |
| 38 | RHF shock absorber dust cover | 1 | \$45.00 | \$45.00 | ? X SVL |
| 39 | RHF stabilizer link | 1 | \$95.00 | \$95.00 | ? X RVC |
| 40 | RHF knuckle | 1 | \$420.00 | \$420.00 | ? v BT |
| 41 | RHF knuckle bearing | 1 | \$195.00 | \$195.00 | ? v nn |
| 42 | Steering rack | 1 | \$1,850.00 | \$1,850.00 | Repair ? X SVL |
| 43 | Coolant | 1 | \$25.00 | \$25.00 | nn |

| | | | | | |
|---|---|---|--------------------------|--------------------|------------------|
| 44 | Steering rack end | 1 | \$180.00 | \$180.00 | 180 ✓ |
| 45 | Front support panel | 1 | \$480.00 | \$480.00 | ? x repair |
| 46 | Power steering oil | 1 | \$50.00 | \$50.00 | ✓ |
| | | | Total | \$14,418.00 | |
| | | | Cost Plus 15% | \$2,162.70 | |
| | | | Sub Total 1 | \$16,580.70 | |
| | | | | | |
| | | | Total for Parts | \$16,580.70 | |
| C. Labour | | | | | |
| 1 | To knock & straighten the necessary portion, remove & renew damaged parts, adjust & realign the same. | | \$1,300.00 | | 800 |
| 2 | To putty & spray RHF door, frt bumper, frt support panel, RHF fender, frt bumper reinforcement, frt bonnet & LHF fender | | \$1,580.00 | | 900 |
| 3 | To jack & straighten both frt chassis | | \$350.00 | | 150 |
| 4 | To remove & transfer RHF fitting, fixture and conduct water seepage & wind noise test | | \$200.00 | | 80 |
| 5 | To do 4 wheel alignment | | \$120.00 | | 60 |
| 6 | To remove & refit radiator assy, air-con condensor assy, vacuum & change up gas to assist workload | | \$120.00 | | 80 |
| 7 | To drop steering rack & pinion assy and removal of the same and final checking & testing | | \$400.00 | | 200 |
| 8 | To check all wiring and all lighting | | \$60.00 | | 30 |
| 9 | To drop RHF under carriage parts, remove & renewal of the necessary parts, to perform final check & testing | | \$250.00 | | 150 |
| | | | Total Labour | \$4,380.00 | |
| | | | | | |
| | | | Total Repair Cost | \$20,960.70 | |
| * The above quoted are exclusive of GST. | | | | | |

Yours faithfully,

Jaden

f Auto N Cars Services Pte Ltd

| | |
|--------------|-----------------------------|
| Name | RASHUL (LKK) |
| Contact | 90010068 |
| Survey Date | 21/05/18 @ 1520 |
| Recommender | Authorize / Not Authorize |
| Before Paint | Yes / No <i>after paint</i> |
| Signature | <i>Full 10 days 4S</i> |

| | |
|------|--------------------------------|
| DATE | Remark From MR CHOO |
| | Please arrange for survey asap |

EXCESS: 1500

REVERT

Resurvey after repair

P = \$ 8,390

+ 15%

\$ 9,625.50

Stump + 95

\$ 9,720.50

= \$ 9,720.50

L = + 2,450

\$ 12,170.50

- 20%

\$ 9,736.40

Auto N Care Services Pte Ltd

100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

DATE: 11/05/2018

Total Pages: 5

TO:

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block, M2013 Complex
Singapore 069110

Our Customer: ANSHE MICHAMONG
Vehicle No: S6191911
Model: KIA/KA RK 8 1.1 (M)
Manufacture Year: 2008
Date of Accident: 12/5/2018
Total Estimate Repair Day: 14

Attn: Motor Claims Department
Tel: 62543603

Re: Repair Estimate For Own Damage Claim Against Policy: OMFFHJ18 000942

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks from Surveyor |
|-----|---------------------------------|-----|------------|------------|-----------------------|
| A. | Spare Parts | | | | |
| 1 | Front no plate | 1 | \$55.00 | \$55.00 | TSI SIN 700 |
| 2 | Front no plate base | 1 | \$80.00 | \$80.00 | TSI SIN 700 |
| 3 | Front bumper | 1 | \$870.00 | \$870.00 | TSI SIN 700 |
| 4 | Front bumper tow cover RH | 1 | \$68.00 | \$68.00 | TSI SIN 700 |
| 5 | Front bumper retainer | 1 | \$45.00 | \$45.00 | TSI SIN 700 |
| 6 | Front bumper logo | 1 | \$70.00 | \$70.00 | TSI SIN 700 |
| 7 | Front bumper sponge | 1 | \$118.00 | \$118.00 | TSI SIN 700 |
| 8 | Front bumper reinforcement | 1 | \$280.00 | \$280.00 | TSI SIN 700 |
| 9 | Front bumper lower extension | 1 | \$210.00 | \$210.00 | TSI SIN 700 |
| 10 | Front bumper clip | 12 | \$1.50 | \$18.00 | TSI SIN 700 |
| 11 | Front bumper lower cover | 1 | \$155.00 | \$155.00 | TSI SIN 700 |
| 12 | Front bumper RH side garnish | 1 | \$68.00 | \$68.00 | TSI SIN 700 |
| 13 | Front bumper str grille | 1 | \$180.00 | \$180.00 | TSI SIN 700 |
| 14 | RHF fog lamp outer garnish | 1 | \$85.00 | \$85.00 | TSI SIN 700 |
| 15 | RH fog lamp inner garnish | 1 | \$98.00 | \$98.00 | TSI SIN 700 |
| 16 | RH headlamp | 1 | \$998.00 | \$998.00 | TSI SIN 700 |
| 17 | RH headlamp lower bracket | 1 | \$72.00 | \$72.00 | TSI SIN 700 |
| 18 | RH headlamp ballast | 1 | \$720.00 | \$720.00 | TSI SIN 700 |
| 19 | RH headlamp panel | 1 | \$155.00 | \$155.00 | TSI SIN 700 |
| 20 | RHF fender | 1 | \$580.00 | \$580.00 | TSI SIN 700 |
| 21 | RHF fender support bracket | 1 | \$65.00 | \$65.00 | TSI SIN 700 |
| 22 | RHF fender splash shield top | 1 | \$138.00 | \$138.00 | TSI SIN 700 |
| 23 | RHF fender splash shield clip | 16 | \$1.50 | \$24.00 | TSI SIN 700 |
| 24 | RHF fender splash shield bottom | 1 | \$75.00 | \$75.00 | TSI SIN 700 |
| 25 | RHF door | 1 | \$1,210.00 | \$1,210.00 | TSI SIN 700 |
| 26 | RHF oil cooler Assy | 1 | \$520.00 | \$520.00 | TSI SIN 700 |
| 27 | RHF oil cooler bracket | 2 | \$18.00 | \$36.00 | TSI SIN 700 |
| 28 | RHF sport rim | 1 | \$1,100.00 | \$1,100.00 | TSI SIN 700 |
| 29 | RHF tyre | 1 | \$380.00 | \$380.00 | TSI SIN 700 |
| 30 | Front bonnet | 1 | \$690.00 | \$690.00 | TSI SIN 700 |
| 31 | LHF fog lamp outer cover | 1 | \$75.00 | \$75.00 | TSI SIN 700 |
| 32 | RH side skirt | 1 | \$115.00 | \$115.00 | TSI SIN 700 |
| 33 | RHF lower arm | 1 | \$480.00 | \$480.00 | TSI SIN 700 |
| 34 | RHF control arm | 1 | \$420.00 | \$420.00 | TSI SIN 700 |
| 35 | RHF shock absorber | 1 | \$370.00 | \$370.00 | TSI SIN 700 |
| 36 | RHF shock absorber mounting | 1 | \$150.00 | \$150.00 | TSI SIN 700 |
| 37 | RHF shock absorber stopper | 1 | \$85.00 | \$85.00 | TSI SIN 700 |
| 38 | RHF shock absorber dust cover | 1 | \$45.00 | \$45.00 | TSI SIN 700 |
| 39 | RHF stabilizer link | 1 | \$95.00 | \$95.00 | TSI SIN 700 |
| 40 | RHF knuckle | 1 | \$420.00 | \$420.00 | TSI SIN 700 |
| 41 | RHF knuckle bearing | 1 | \$195.00 | \$195.00 | TSI SIN 700 |
| 42 | Steering rack | 1 | \$1,850.00 | \$1,850.00 | TSI SIN 700 |
| 43 | Coolant | 1 | \$25.00 | \$25.00 | TSI SIN 700 |

02.05.18 P 2 =
02.05.18 P 2 =

02.05.18 P 2 =
02.05.18 P 2 =

02.05.18 P 2 =
02.05.18 P 2 =

02.05.18 P 2 =
02.05.18 P 2 =

02.05.18 P 2 =
02.05.18 P 2 =

02.05.18 P 2 =
02.05.18 P 2 =

| | | | | | |
|----|---|---|-------------------|-------------|--------|
| 44 | Steering rack end | 1 | \$180.00 | \$180.00 | Beo |
| 45 | Front support panel | 1 | \$480.00 | \$480.00 | Repair |
| 46 | Power steering oil | 1 | \$50.00 | \$50.00 | |
| | | | Total | \$14,418.00 | |
| | | | Cost Plus 15% | \$2,162.70 | |
| | | | Sub Total 1 | \$16,580.70 | |
| | | | Total for Parts | \$16,580.70 | |
| C | Labour | | \$1,300.00 | 800 | |
| 1 | To knock & straighten the necessary portion, remove & renew damaged parts, adjust & realign the same. | | \$1,580.00 | 900 | |
| 2 | To putty & spray RHF door, ftr bumper, ftr support panel, RHF fender, ftr bumper reinforcement, ftr bonnet & LHF fender | | \$150.00 | 150 | |
| 3 | To jack & straighten both ftr chassis | | \$200.00 | 80 | |
| 4 | To remove & transfer RHF fitting, fixture and conduct water seepage & wind noise test | | \$120.00 | 60 | |
| 5 | To do 4 wheel alignment | | \$120.00 | 80 | |
| 6 | To remove & refit radiator assy, air-con condensor assy, vacuum & charge up gas to assist workload | | \$400.00 | 200 | |
| 7 | To drop steering rack & pinion assy and removal of the same and final checking & testing | | \$500.00 | 30 | |
| 8 | To check all wiring and all lighting | | \$250.00 | 150 | |
| 9 | To drop RHF under carriage parts, remove & renewal of the necessary parts, to perform final check & testing | | \$4,380.00 | | |
| | | | Total Labour | \$4,380.00 | |
| | | | Total Repair Cost | \$20,960.70 | |

* The above quoted are exclusive of GST.

Yours faithfully,

mden

J Auto N Cars Services Pte Ltd

P=

4

| | |
|--------------|---------------------------|
| Name | Basul (LKK) |
| Contact | 40010068 |
| Survey Date | 21/05/18 @ 15:20 |
| Recommender | Authorize / Not Authorize |
| Before Paint | yes/no after paint |
| Signature | 10 days 45 |

| | |
|------|--------------------------------|
| DATE | Remark From MR CHOO |
| | Please arrange for survey asap |

EXCESS: 1500
REVERT
Resurvey after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|--|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 16 May 2018 Sendback Est | 16 May 2018 15:42 \$20,960.70 | 18 May 2018 16:08 Edit Adj Rpt | \$8,800.00 Edit Estimates | \$8,800.00 View Rpt | | Pending for Survey Report Cancel Case |





























| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|--|------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | | | | | | | |
| Insured: ANDIK MUHAMMAD ASY' ARI BIN IBRAHIM , ID: S8332077Z | | | | | | | | | |
| Vehicle Reg. No.: SGV1991J | | Date of Loss: 12/05/2018 14:00 - :59 [87 Months and 1 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: OD / DM18HO01234-JG | | Policy/Cover Note No.: DMPPHQ18-000942 (Comprehensive) | | | | | | | |
| | | Excess: \$1,500.00 | | | | | | | |
| Repairer: Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909 | | | | | | | | | |
| Handling Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/05/2018] | | | | | | | | | |
| Driver/Custodian: MOHAMMAD IKBAR BIN RAHUD (30 / Male) , NRIC: S8719901J, Tel: +6590731887 Email: NOEMAIL | | | | | | | | | |
| Adj Asg. Remarks: EXCESS: \$1,500.00 NO WAIVER. SURVEY AND REVERT | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| • EQI_HQ (24/05/2018): Alert - Adj Mandate Approved (\$15370.95) - SGV1991J - Claim Handler: Joel Goh | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents










SGV1991J (DM18H001234-JG)
 OD
 May 12 2018 2:00PM
 [ANDIK MUHAMMAD ASY' ARI BIN IBRAHIM]
 Auto N Cars Services Pte Ltd









| | | | | | |
|---------------------------|-----------------|-----------------------------------|--------------------|---|-------------------------------------|
| Upload Documents | | Upload Photos | Compose New Letter | View <input type="button" value="View in Browser"/> | |
| Assessment Reports | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 16/05/18 15:42 | Repairer Estimates | | Load HTM | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 22/05/18 10:12 | Adjuster Immediate Advice | | Load HTM | |
| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 21/03/19 14:19 | General View | | Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| | | |  | <input checked="" type="checkbox"/> |
| 35 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 21/03/19 14:19 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 84 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 21/03/19 14:21 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 21/03/19 14:36 | Photo After Repair |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 21/03/19 14:36 | Photo After Repair |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 21/03/19 14:36 | Photo After Repair |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 21/03/19 14:36 | Photo After Repair |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 21/03/19 14:36 | Photo After Repair |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 22/05/18 11:10 | ESTIMATE |  Load PDF | |

Linked Accident Report Documents

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 14/05/18 16:18 | Accident Statement |  Load HTM | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Auto N Cars Services Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 14/05/18 16:18 | Accident Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------|--|-------------------------------------|
| No | Finalized On | | Thumbnail | Print |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | | Thumbnail | Print |
| 1 | 14/05/18 16:17 | Sketch Plan |  Load TIF | |
| 2 | 14/05/18 16:17 | Sketch Plan #2 |  Load TIF | |
| 3 | 14/05/18 16:18 | DL |  Load TIF | |
| 4 | 14/05/18 16:18 | INS CERT |  Load TIF | |
| 5 | 14/05/18 16:18 | POLICE REPORT |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 14/05/18 16:18 | POLICE REPORT |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 14/05/18 16:18 | POLICE REPORT |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 14/05/18 16:18 | POLICE REPORT |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ18009188/R1TBE2

Date: 25/03/2019

REFERENCE

Insured/Claimant: ANDIK MUHAMMAD ASY' ARI BIN IBRAHIM

Policy No: DMPPHQ18-000942

Date of Loss: 12/05/2018

Nature of Claim: OD

Claim No: DM18HO01234-JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV1991J**
 Make & Model: MAZDA RX-8, 1.3 (M) Engine No: 13B543922
 Reg. Date: 11/02/2011 (Man. Year: 2008) Chassis No: SE3P301467
 Colour: Yellow Odometer: 212524 km
 Engine Capacity: 1308 cc
 Market Value/New Car Price: S\$44,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45Z R17 Rear Tyre Size: 235/45Z R17
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|------------------|------------------|--------------|
| Parts | 16,580.70 | 8,380.75 | 8,199.95 | 49.45 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,380.00 | 2,650.00 | 1,730.00 | 39.50 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 20,960.70 | 11,030.75 | 9,929.95 | 47.37 |
| Approved Total (Overridden) (S\$) | | 8,800.00 | | |
| - Excess (S\$) | 0.00 | 1,500.00 | -1,500.00 | |
| (S\$) | 20,960.70 | 7,300.00 | 13,660.70 | 65.17 |
| + GST 7.00/7.00% (S\$) | 1,467.25 | 511.00 | 956.25 | 65.17 |
| Nett Amount (S\$) | 22,427.95 | 7,811.00 | 14,616.95 | 65.17 |

INSPECTION

Date of Assignment: 18/05/2018 Present Location:
 Date Inspected: 21/05/2018 Inspected At:

Auto N Cars Services Pte Ltd (HQ)
 Auto N Cars Services Pte Ltd (HQ)
 Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @
 Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 25 Mar 2019) |
| Parts: | M1-COUPE | MAZDA RX-8 1.3 (M) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGV1991J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|--------------------|------------|-----------|
| 1 | 1 | | *Front no plate | Torn | 50.00 F | *35.00 FS |
| 2 | 1 | | *Front no plate base | Torn | 90.00 F | *60.00 FS |
| 3 | 1 | | *Front bumper (WCP) | Torn | 870.00 F | *870.00 F |
| 4 | 1 | | *Front bumper tow cover RH (WCP) | Missing | 68.00 F | *68.00 F |
| 5 | 1 | | *Front bumper retainer (2PCS) (WCP) | Necessary-1PC ONLY | 90.00 F | *45.00 F |
| 6 | 1 | | *Front bumper logo (WCP) | Necessary | 70.00 F | *70.00 F |
| 7 | 1 | | *Front bumper sponge (WCP) | Cracked | 118.00 F | *118.00 F |
| 8 | 1 | | *Front bumper reinforcement (WCP) | Bent | 280.00 F | *280.00 F |
| 9 | 1 | | *Front bumper lower extension (WCP) | Cracked | 210.00 F | *210.00 F |
| 10 | 12 | | *Front bumper clip (WCP) | Necessary | 18.00 F | *18.00 F |
| 11 | 1 | | *Front bumper lower cover (WCP) | Deformed | 155.00 F | *155.00 F |
| 12 | 1 | | *Front bumper RH side garnish (WCP) | Serviceable | 68.00 F | *- F |
| 13 | 1 | | *Front bumper ctr grille (WCP) | Cut | 180.00 F | *180.00 F |
| 14 | 1 | | *RHF fog lamp outer garnish (WCP) | Missing | 85.00 F | *85.00 F |
| 15 | 1 | | *RH fog lamp inner garnish (WCP) | Missing | 98.00 F | *98.00 F |
| 16 | 1 | | *RH headlamp (WCP) | Broken | 998.00 F | *998.00 F |
| 17 | 1 | | *RH headlamp lower bracket (WCP) | Bent | 72.00 F | *72.00 F |
| 18 | 1 | | *RH headlamp ballast (WCP) | Serviceable | 720.00 F | *- F |
| 19 | 1 | | *RH headlamp panel (WCP) | Bent | 155.00 F | *155.00 F |
| 20 | 1 | | *RHF fender (WCP) | Buckled | 580.00 F | *580.00 F |
| 21 | 1 | | *RHF fender support bracket (WCP) | Necessary | 65.00 F | *65.00 F |
| 22 | 1 | | *RHF fender splash shield top (WCP) | Deformed | 138.00 F | *138.00 F |
| 23 | 16 | | *RHF fender splash shield clip (WCP) | Necessary | 24.00 F | *24.00 F |
| 24 | 1 | | *RHF fender splash shield bottom (WCP) | Deformed | 75.00 F | *75.00 F |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|------------|-----------|
| 25 | 1 | | *RHF door (WCP) | Repair | 1,210.00 F | *- F |
| 26 | 1 | | *RHF oil cooler assy (WCP) | Bent | 520.00 F | *520.00 F |
| 27 | 2 | | *RHF oil cooler bracket (WCP) | Bent | 76.00 F | *76.00 F |
| 28 | 1 | | *RHF sport rim (WCP) | Repair | 1,100.00 F | *- F |
| 29 | 1 | | *RHF tyre (WCP) | Serviceable | 380.00 F | *- F |
| 30 | 1 | | *Front bonnet (WCP) | Repair | 690.00 F | *- F |
| 31 | 1 | | *LHF fog lamp outer cover (WCP) | Serviceable | 75.00 F | *- F |
| 32 | 1 | | *RH side skirt (WCP) | Not Necessary | 315.00 F | *- F |
| 33 | 1 | | *RHF lower arm (WCP) | Bent | 480.00 F | *480.00 F |
| 34 | 1 | | *RHF control arm (WCP) | Bent | 420.00 F | *420.00 F |
| 35 | 1 | | *RHF shock absorber (WCP) | Bent | 320.00 F | *320.00 F |
| 36 | 1 | | *RHF shock absorber mounting (WCP) | Necessary | 150.00 F | *150.00 F |
| 37 | 1 | | *RHF shock absorber stopper (WCP) | Necessary | 65.00 F | *65.00 F |
| 38 | 1 | | *RHF shock absorber dust cover (WCP) | Serviceable | 45.00 F | *- F |
| 39 | 1 | | *RHF stabilizer link (WCP) | Serviceable | 95.00 F | *- F |
| 40 | 1 | | *RHF knuckle (WCP) | Bent | 420.00 F | *420.00 F |
| 41 | 1 | | *RHF knuckle bearing (WCP) | Necessary | 195.00 F | *195.00 F |
| 42 | 1 | | *Steering rack (WCP) | Serviceable | 1,850.00 F | *- F |
| 43 | 1 | | *Coolant (WCP) | Necessary | 25.00 F | *25.00 F |
| 44 | 1 | | *Steering rack end (WCP) | Broken | 180.00 F | *180.00 F |
| 45 | 1 | | *Front support panel (WCP) | Repair | 480.00 F | *- F |
| 46 | 1 | | *Power steering oil (WCP) | Necessary | 50.00 F | *50.00 F |

F=Franchise part. S=SpcNett.

| | | |
|--|-----------|----------|
| Sub Total (S\$) | 14,418.00 | 7,300.00 |
| + Margin on L,N Items 15.00/15.00% (S\$) | 2,162.70 | 1,080.75 |
| Total Parts (S\$) | 16,580.70 | 8,380.75 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | To knock & straighten the necessary portion,remove & renew damaged parts,adjust & realign the same. | New | 1,300.00 | 1,000.00 |
| 2 | To putty & spray RHF door,frt bumper,frt support panel,RHF fender,frt bumper reinforcement,frt bonnet & LHF fender | New | 1,580.00 | 900.00 |
| 3 | To jack & straighten both frt chassis | New | 350.00 | 150.00 |
| 4 | To remove & transfer RHF fitting,fixture and conduct water seepage & wind noise test | New | 200.00 | 80.00 |
| 5 | To do 4 wheel alignment | New | 120.00 | 60.00 |
| 6 | To remove & refit radiator assy,air-con codensor assy,vacuum & change up gas to assist workload | New | 120.00 | 80.00 |
| 7 | To drop steering rack & pinion assy and removal of the same and final checking & testing | New | 400.00 | 200.00 |
| 8 | To check all wiring and all lighting | New | 60.00 | 30.00 |
| 9 | To drop RHF under carriage parts,remove & renewal of the necessary parts, to perform final check & testing | New | 250.00 | 150.00 |
| Gross Labour Cost (S\$) | | | 4,380.00 | 2,650.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >