

INS. CASE OWNER:

CC 4 / III1800

LKK-

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: S\$

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost: S\$

Total: S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$


Name 1:

Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Name 3:



RECEIVED 17 JUL 2018

COPY SENT 12/7/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$ 250.00

NOT finalize
LIS - \$1900+ (Red: \$4116.60 / 68 %).

N/S	O/S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18009189/Uua3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-05-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1072K	Veh. Inspected	SKE 9981C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/05/2018	Inspection Date	24/05/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9148I

Vehicle Details

Vehicle No.:	SKE9981C
Vehicle to be Exported:	No
Intended De-registration Date:	24 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC250 4MATIC
Primary Colour:	Black
Secondary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	27492030654939
Chassis No.:	WDC2539462F084382
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$42,582.00
Original Registration Date:	14 Sep 2016
First Registration Date:	14 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$51,615.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2026
PARF Rebate Amount:	\$38,711.00

Intended COE Rebate Details

COE Expiry Date:	13 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$46,507.00
Total Rebate Amount:	\$85,218.00

The information contained herein is correct as at 24 May 2018

OK



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

TP INSURER: India International Insurance Pte Ltd (HQ)
KOH CHUAN HING

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

Not Allowed
2/5/18
24/5/18
Take up to 6 After repair

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0518-5064
Policy No:		Date of Loss:	12/05/2018
Vehicle Reg. No.:	SKE9981C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	KOOH GIN SHING		

Make/Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Vehicle Reg. Date:	14/09/2016
Vehicle Colour:	BLACK		
Engine No:	27492030654939	Chassis No:	WDC2539462F084382
Odometer:	14455 KM		

Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		

LK& Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill-concealment(s) is allowed
- Supplementary claims must be resurveyed and

STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Description of Accident/Loss: I GO OVERSEA IN THE NEXT DAY AFTER ACCIDENT HAPPEN. ATTACH ARE THE PASSPORT RECORD TO PROOF THAT I WAS NO IN SINGAPORE DURING THE PERIOD FOR 24 HOURS ACCIDENT REPORT LODGING PERIOD.

Remarks: VEHICLE IS NOT IN WORKSHOP

Present Location: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	5,376.60
Miscellaneous Items	10.00
Labour	380.00
Paintwork Labour	250.00
Towing	0.00
Gross Total (\$\$)	6,016.60
+ GST 7.00% (\$\$)	421.16
Nett Amount (\$\$)	6,437.76

This claim is handled by: NG PEI WEN

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 May 2018)**Parts:** M1-SUV MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SKE9981C/19/05/2018 12:33**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER <i>Deep cut</i>	0.00	0.00	*1,743.00 F <i>✓</i>
2	10	NA	*FRONT BUMPER CLIPS <i>neu</i>	0.00	0.00	*70.00 F <i>✓</i>
3	1	NA	*FRONT BUMPER FOAM <i>11</i>	0.00	0.00	*140.00 F <i>X</i>
4	1	NA	*FRONT RIM (AMG; 19INCH) - RH - NO STOCK <i>2</i>	0.00	0.00	*2,550.00 F <i>X</i>
5	1	NA	*FRONT FENDER ARCH GARNISH - RH <i>grozed</i>	0.00	0.00	*231.00 F <i>✓</i>
6	4	NA	*FRONT BUMPER SENSOR <i>11</i>	0.00	0.00	*1,240.00 F <i>X</i>
Sub Total (\$\$)						5,974.00
- Add. Disc. on L,N Items 10.00% (\$\$)						597.40
Total Parts (\$\$)						5,376.60

F=Franchise part.

Progressive Automotive Pte Ltd/SKE9981C/19/05/2018 12:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	250.00
<u>Labour Items</u>			
2	TO 4 WHEEL ALIGNMENT	New	60.00
3	TO REMOVE; REALIGN; REPAIR; CUT/WELD; KNOCK OUT DENTS & REPLACE ACCIDENT PARTS	New	200.00
4	TO REMOVE; REPLACE FRONT BUMPER SENSOR	New	120.00
Gross Labour Cost (S\$)			630.00

Progressive Automotive Pte Ltd/SKE9981C/19/05/2018 12:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Wednesday, 30 May 2018 6:23 PM
To: Soo Leong Keat; Mei Kwan (LKKAuto); Admin A
Cc: Vivian Lau (LKKAuto); bhlm@progauto.com.sg; 'Peiwen PROGAUTO'; ray@progauto.com.sg; 'Wayne PROGAUTO'
Subject: RE: TP CLAIMS_PROGRESSIVE_SKE 9981 C & SHA 1072 K_DOA:12/05/2018

Without Prejudice,

Hi Soo,

Which BOLA you are referring to.

Please noted that our insured vehicle is not U-turn, so that BOLA 11 is no apply.

Also there is no lane marking, so that BOLA 15 is also not apply.

And also take noted that our insured vehicle is not turning from side road, our insured vehicle is from main road turning into the Takashimaya gateway. BOLA 2 is not apply for this case.

Please noted that your client side got STOP LINE and GIVE WAY SIGN.





Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Soo Leong Keat [mailto:lksoo@progauto.com.sg]

Sent: Wednesday, 30 May 2018 6:07 PM

To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; bhlum@progauto.com.sg; 'Peiwen PROGAUTO' <peiwen@progauto.com.sg>; ray@progauto.com.sg; 'Wayne PROGAUTO' <wayne@progauto.com.sg>

Subject: RE: TP CLAIMS_PROGRESSIVE_SKE 9981 C & SHA 1072 K_DOA:12/05/2018

Dear Thin Thin

I would like to seek for your good office review.

Before my customer get into the Takashimaya gateway, your insured in-front still have 2-3 vehicles to turn into Takashimaya gateway.

Photo showing the timing and all the vehicles in-front was travelling in their own lane even inside the gateway.

After checking for the oncoming vehicle to clear in my customer path. He manage to move out in safe.

But out of sudden, your insured drive into my customer lane and hit onto my customer car right front portion. Causing the tyre rim got scratches.



Due to BOLA (2 , 11 and 15) , your insured should exercise greater caution.









2.		Vehicle X – Turning Out from Side Road Vehicle Y – Moving Straight Ahead Reason: Vehicle making a turn at an intersection should exercise greater degree of care towards on-coming traffic	100%	0%
11.	(a) 	Vehicle X – U-turning Vehicle Y – Moving Straight Ahead *All U-turns (legal / illegal), or turns not prohibited by road markings.	100%	0%
11.	(b) 	Reason: All vehicles making turn or u-turn across main road must exercise greater caution.		
STRAIGHT ROAD (With / Without lane markings)				
15.		Vehicle X - Changing lane Vehicle Y – Moving in own Lane Reason: Vehicles should keep in the proper lane and change lane only when it is safe. Note: i) If point of impact of the front vehicle is found on the rear bumper scenario 27 applies ii) If point of impact is found on the fender , scenario 15 applies	100%	0%

Regards,
Soo

From: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>

Sent: Wednesday, 30 May 2018 6:01 PM

To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Soo Leong Keat <lksoo@progauto.com.sg>; Admin A <admin-a@lkkauto.com>

Cc: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: RE: TP CLAIMS_PROGRESSIVE_SKE 9981 C & SHA 1072 K_DOA:12/05/2018

"Without Prejudice"

Hi Soo,

We refer to the below matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

From your client's video, it can be seen that your client vehicle fail to stop at the stop line and collided with our insured vehicle.

Attached herewith our insured's video footage from our insured for your perusal.

Under such a circumstances, we are denying liability and unable to look into your client's claim.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Monday, 21 May 2018 3:36 PM

To: Soo Leong Keat <lksoo@progauto.com.sg>; Admin A <admin-a@lkkauto.com>

Cc: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: RE: TP CLAIMS_PROGRESSIVE_SKE 9981 C & SHA 1072 K_DOA:12/05/2018

Hi,

As requested.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Soo Leong Keat [<mailto:lksoo@progauto.com.sg>]

Sent: Monday, 21 May, 2018 3:31 PM

To: Admin A <admin-a@lkkauto.com>

Subject: TP CLAIMS_PROGRESSIVE_SKE 9981 C & SHA 1072 K_DOA:12/05/2018

Dear Sir/Madam

Kindly send me sketch plan and statement for your insured.

Thank you.

Regards,

L.K. Soo

(Claims Advisor)

Email: lksoo@progauto.com.sg

Tel: 6741 5336

Progressive Automotive

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 May 2018 Sendback Est	19 May 2018 12:33 S\$6,016.60	21 May 2018 08:44 Edit Adj Rpt	S\$1,900.00 Edit Estimates	S\$1,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	KOOH GIN SHING , ID: S73091481		
Vehicle Reg. No.:	SKE9981C	Date of Loss:	12/05/2018 19:00 - :59 [19 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18050297	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA1072K	Policy No. (Claimant):	18-MT001837-R00
		Excess:	
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/05/2018]		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- III_SG (30/05/2018): Alert - Adj Mandate Approved (S\$0.00) - SKE9981C - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKE9981C (MCT18050297)
[SHA1072K]
TP
KOOH GIN SHING
May 12 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Progressive Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Video						1 per page ☐	
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print		
1	18/05/18 11:50	Video - Accident [Linked Accident Report Documents]	1	Load AVI			
2	18/05/18 11:51	Video - Accident [Linked Accident Report Documents]	1	Load AVI			
3	18/05/18 11:51	Video - Accident [Linked Accident Report Documents]	1	Load AVI			
4	18/05/18 11:51	Video - Accident [Linked Accident Report Documents]	1	Load AVI			
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	22/05/18 16:25	Video - IV	1	Load WMV			
Assessment Reports						1 per page ☐	
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print		
1	18/05/18 11:54	Accident Statement	1	Load HTM			
2	18/05/18 16:10	Addendum Sheet	1	Load JPG	☒		
3	18/05/18 16:12	Accident Statement Addm. #1	1	Load HTM			
4	19/05/18 12:33	Repairer Estimates	1	Load HTM			
Photos/Images						3 per page ☐	
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print		
1	19/05/18 12:33	1	1	Load JPG	☒		
2	19/05/18 12:33	2	1	Load JPG	☒		
3	19/05/18 12:33	3	1	Load JPG	☒		
4	19/05/18 12:33	4	1	Load JPG	☒		
5	19/05/18 12:33	5	1	Load JPG	☒		
6	19/05/18 12:33	6	1	Load JPG	☒		
7	19/05/18 12:33	7	1	Load JPG	☒		
8	19/05/18 12:33	8	1	Load JPG	☒		
9	19/05/18 12:33	9	1	Load JPG	☒		
10	19/05/18 12:33	10	1	Load JPG	☒		
11	19/05/18 12:33	11	1	Load JPG	☒		
12	19/05/18 12:33	12	1	Load JPG	☒		
13	19/05/18 12:33	13	1	Load JPG	☒		
14	19/05/18 12:33	14	1	Load JPG	☒		
15	19/05/18 12:33	15	1	Load JPG	☒		
16	19/05/18 12:33	16	1	Load JPG	☒		
17	19/05/18 12:33	17	1	Load JPG	☒		
18	19/05/18 12:33	18	1	Load JPG	☒		
19	19/05/18 12:33	19	1	Load JPG	☒		
20	19/05/18 12:33	20	1	Load JPG	☒		
21	19/05/18 12:33	21	1	Load JPG	☒		
22	19/05/18 12:33	22		Load JPG			

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
				☒
23	19/05/18 12:33	23	 Load JPG	☒
24	19/05/18 12:33	24	 Load JPG	☒
25	19/05/18 12:33	25	 Load JPG	☒
26	19/05/18 12:33	26	 Load JPG	☒
27	19/05/18 12:33	27	 Load JPG	☒
28	19/05/18 12:33	28	 Load JPG	☒
29	19/05/18 12:33	29	 Load JPG	☒
30	19/05/18 12:33	30	 Load JPG	☒
31	19/05/18 12:33	31	 Load JPG	☒
32	19/05/18 12:33	32	 Load JPG	☒
33	19/05/18 12:33	33	 Load JPG	☒
34	19/05/18 12:33	34	 Load JPG	☒
35	19/05/18 12:33	35	 Load JPG	☒
36	19/05/18 12:33	36	 Load JPG	☒
37	19/05/18 12:33	37	 Load JPG	☒
38	19/05/18 12:33	38	 Load JPG	☒
39	19/05/18 12:33	39	 Load JPG	☒
40	19/05/18 12:33	40	 Load JPG	☒
41	19/05/18 12:33	41	 Load JPG	☒
42	19/05/18 12:33	42	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 13:16	Chassis Number	 Load JPG	☒
2	17/07/18 13:17	General View	 Load JPG	☒
3	17/07/18 13:17	General View	 Load JPG	☒
4	17/07/18 13:17	General View	 Load JPG	☒
5	17/07/18 13:17	General View	 Load JPG	☒
6	17/07/18 13:17	General View	 Load JPG	☒
7	17/07/18 13:17	General View	 Load JPG	☒
8	17/07/18 13:17	General View	 Load JPG	☒
9	17/07/18 13:17	General View	 Load JPG	☒
10	17/07/18 13:17	General View	 Load JPG	☒
11	17/07/18 13:17	General View	 Load JPG	☒
12	17/07/18 13:17	General View	 Load JPG	☒
13	17/07/18 13:17	General View	 Load JPG	☒
14	17/07/18 13:17	General View	 Load JPG	☒
15	17/07/18 13:17	General View	 Load JPG	☒
16	17/07/18 13:17	General View	 Load JPG	☒
17	17/07/18 13:17	General View	 Load JPG	☒
18	17/07/18 13:17	General View	 Load JPG	☒
19	17/07/18 13:17	General View	 Load JPG	☒
20	17/07/18 13:17	General View	 Load JPG	☒
21	17/07/18 13:17	General View	 Load JPG	☒
22	17/07/18 13:17	General View	 Load JPG	☒
23	17/07/18 13:17	General View	 Load JPG	☒
24	17/07/18 13:17	General View	 Load JPG	☒
25	17/07/18 13:17	General View	 Load JPG	☒
26	17/07/18 13:17	General View	 Load JPG	☒
27	17/07/18 13:17	General View	 Load JPG	☒
28	17/07/18 13:17	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
29	17/07/18 13:17	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	19/05/18 12:32	E-filed GIA report	 Load PDF	
2	19/05/18 12:32	Certificate of Insurance	 Load TIF	
3	19/05/18 12:32	Driver's NRIC & LICENSE	 Load TIF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 08:41	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 10:08	TP ESTIMATE - MARKED	 Load PDF	
2	17/07/18 13:16	Reject email to TP	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009189/UUA3Q2

Date: 18/07/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No : SKE9981C **Insured Vehicle No :** SHA1072K
 Date of Loss: 12/05/2018 Nature of Claim: TP Claim No: MCT18050297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE9981C**
 Make & Model: MERCEDES-BENZ GLC 250, 2.0 4MATIC (A) Engine No: 27492030654939
 Reg. Date: 14/09/2016 (Man. Year: 2016) Chassis No: WDC2539462F084382
 Colour: Black Odometer: 14632 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
 Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
 Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,376.60	1,839.60	3,537.00	65.79
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	380.00	290.00	90.00	23.68
Paintwork Labour	250.00	250.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,016.60	2,389.60	3,627.00	60.28
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	6,016.60	1,900.00	4,116.60	68.42
+ GST 7.00/7.00% (S\$)	421.16	133.00	288.16	68.42
Nett Amount (S\$)	6,437.76	2,033.00	4,404.76	68.42
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/05/2018 Present Location: Progressive Automotive Pte Ltd (HQ)
 Date Inspected: 24/05/2018 Inspected At: Progressive Automotive Pte Ltd (HQ)
 Blk 3022A Ubi Road 1, #01-45/46
 Singapore 408716
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2018)
Parts:	M1-SUV	MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE9981C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER	Deep Cut	1,743.00 F	*1,743.00 F
2	10	NA	*FRONT BUMPER CLIPS	Necessary	70.00 F	*70.00 F
3	1	NA	*FRONT BUMPER FOAM	Not Necessary	140.00 F	*- F
4	1	NA	*FRONT RIM (AMG; 19INCH) - RH - NO STOCK	Repair	2,550.00 F	*- F
5	1	NA	*FRONT FENDER ARCH GARNISH - RH	Grazed	231.00 F	*231.00 F
6	4	NA	*FRONT BUMPER SENSOR	Not Necessary	1,240.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	5,974.00	2,044.00
- Add. Disc. on L,N Items 10.00/10.00% (\$\$)	597.40	204.40
Total Parts (\$\$)	5,376.60	1,839.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	250.00	250.00
Labour Items				
2	TO 4 WHEEL ALIGNMENT	New	60.00	60.00
3	TO REMOVE; REALIGN; REPAIR; CUT/WELD; KNOCK OUT DENTS & REPLACE ACCIDENT PARTS	New	200.00	180.00
4	TO REMOVE; REPLACE FRONT BUMPER SENSOR	New	120.00	50.00
Gross Labour Cost (\$\$)			630.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >