



M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368

*Not Adherent
n/bk
21/5/18
1/58
3 day.
Take photo Attorney*

ESTIMATE

DATE : 18/05/2018
ACC DATE : 17/05/2018
REF NO. : VFIX-TP20180475
POLICY NO. :

Attention: Motor Claim Department

RE : VEHICLE NO.SLE6292R KIA CERATO FORTE

DESCRIPTION	AMOUNT S\$
1 1 TAIL LAMP RH	11 380.00 X
2 1 REAR BUMPER	12.5 560.00 —
3 1 REAR BUMPER REINFORCEMENT	367.00 ?
4 1 REAR BUMPER SPONGE	152.00 ?
5 2 REAR BUMPER BRACKET R+L	45.00 11 90.00 X
6 2 REAR BUMPER SIDE RETAINER R+L	24.00 0.534 48.00 PC
7 1 REAR BUMPER LOWER	26/mph 305.00 —
8 1 REAR BUMPER REFLECTOR RH	one 150.00 —
	\$ 2,052.00
	LESS 10%
	\$ 205.20
	\$ 1,846.80

SPECIAL NETT ITEMS:	AMOUNT S\$
1 8 REAR BUMPER CLIP	4.00 32.00 SN ✓
2 1 REVERSE SENSOR	250.00 SN 20i
	\$ 282.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten rear end panel repair/reshape dented panels in accordance with factory specifications,replace new parts refit align into position refit all necessary components/attachments	1,000.00 300
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	800.00 400
3 To install reverse sensor and check funtion	100.00 50
4 Rear number plate	11 40.00 X
	\$ 1,940.00

GRAND TOTAL : \$ 4,068.80

SINGAPORE DOLLARS : FOUR THOUSAND SIXTY EIGHT & CENTS EIGHTY ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: