



FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower SINGAPORE 069542

Attention : Motor Claim Department

Contact : 63387288/68804625 Fax No. : 68804838

Estimate : ES707064

Date : 17/05/2018
Vehicle Num. : SKT 3051Y
Make/Model : VOLVO XC60
Chassis/Eng# :
Accident Date : 17/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	LIST ITEMS :		
2.	2PCS	REAR BUMPER		1,821.00
3.	1PC	REAR BUMPER SIDE RETAINER	115.00	230.00
4.	1PC	REAR BUMPER REINFORCEMENT		662.00
5.	1PC	REAR BUMPER - BOTTOM		1,352.00
6.	1PC	REAR BUMPER LOWER GARNISH		644.00
7.	1PC	REAR BUMPER TOP PLATE		355.00
8.	2PCS	REVERSE SENSOR	351.00	702.00
9.	1PC	TAILGATE VOLVO EMBLEM		159.00
10.	1PC	TAILGATE XC60 EMBLEM		95.00
11.	1PC	TAILGATE T5 EMBLEM		95.00
12.	1PC	TAILGATE LOCK		485.00
		TAILGATE WEATHERSTRIP		415.00
List TotalS\$:				7,015.00
5.00% Discount S\$:				350.75
				6,664.25

LABOUR :

TO CHECK LIGHT SYSTEM AND WIRING

TO REMOVE/REFIT INNER TRIMS AND GARNISHES

ANTI-RUST AND BODY SEALANT

20 50.00

60 120.00

11 120.00

Not Authorised

2/1/15

3/1/15

21/5/15

Take photo after repair

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower SINGAPORE 069542

Attention : Motor Claim Department

Contact : 63387288/68804625 Fax No. : 68804838

Estimate : ES707064

Date : 17/05/2018
Vehicle Num. : SKT 3051Y
Make/Model : VOLVO XC60
Chassis/Eng# :
Accident Date : 17/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		INSTALL REVERSE SENSOR IN NEW BUMPER	50	80.00
		LABOUR/PANEL BEATING	420	600.00
		SPRAY PAINTING	600	800.00
		Labour Total S\$:		1,770.00

E. & O.E.

Total S\$:

8,434.25

=====

for FALCON AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg