

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHICLE NO: SGY 6U

not Allowed
hkn
4/5 7200/
21/5/18
take photo of the repair
4 day.

QTY	PARTICULAR		AMOUNT
1 PCS	HEADLAMP HID O/S 3655.10	scn/cne	\$3,850.00 ✓
1 PCS	FRONT BUMPER 1465.30	Dis	\$1,855.10 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	11	\$665.30 X
1 PCS	FRONT BUMPER SENSOR O/S	11	\$215.00 α
1 PCS	FRONT BUMPER FOG LAMP O/S	CN	\$389.30 ✓
1 PCS	FRONT BUMPER FOG LAMP COVER O/S	CN	\$265.40 ✓
1 PCS	FRONT BUMPER SIDE HOLDER O/S	Scn/cne	\$121.10 ✓
1 SET	FRONT BUMPER CLIPS	11	\$50.00 ✓
1 PCS	FRONT FENDER O/S 1022.30	11/11	\$1,322.30 ✓
1 PCS	FRONT FENDER INNER SHIELD O/S	11	\$285.40 ✓
1 SET	FRONT FENDER INNER SHIELD CLIPS O/S	11	\$50.00 ✓
1 PCS	FRONT DOOR O/S	11	\$1,866.30 X
1 PCS	FRONT SHOCK ABSORBER O/S 495.10	11/11	\$622.20 ✓
1 PCS	FRONT KNUCKLE ARM O/S 645.10	11	\$845.10 ✓
1 PCS	FRONT KNUCKLE ARM BEARING O/S 325.50	11	\$365.50 ✓
1 PCS	FRONT LOWER ARM O/S	11	\$599.20 α
1 PCS	FRONT DRIVE SHAFT O/S	11	\$1,820.10 α
1 PCS	FRONT SPORT RIM O/S 257	11/11	\$1,800.00 1100.5.11
			\$16,987.30
LABOUR CHARGES:			
	TO CHECK WIRING		\$50.00 20
	TO DISMENTLE & REFIX FRONT BUMPER SENSOR		\$80.00 50
	TO CONDUCT WHEEL ALIGMENT		\$100.00 60
	TO SPRAY RUST PROOFING		\$100.00 30
	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE		\$180.00 120
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$800.00 480
	TO PUTTY & SPRAY PAINTING		\$1,080.00 680
	TOTAL		\$19,377.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-8719.6
6577.2
9017.2