



INS. CASE OWNER

CC6 /AIG1800 9200, 4637

LKK IDAC

Surveyor: marcus

DOI: 27/5/18

Date / Time: 21/5/18

Pre-ass / CCU / FTE

Registered in Merimen: 21/5/18



Insured Vehicle No. : 666 84327

Claim No. : 11345562356

Name of Insured : THE MAN KING SHIPS Laundry management services

Policy No. : 3108535014

Insured Tel No. : _____ HP: _____ Make / Model : NISSAN NV200

Excess Sec II :\$5

D.O.A : 18/5/18

Place of Accident : DEPA LAKE THUNDER-HOANGKING PUE 3

Is driver the owner? (YES / NO)

Nature of Accident : _____

If NO: Driver Name / Age : _____

Driver Tel No. : _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : ☒ Final ? Yes / No

CLW 9086E

INSRS: WSP: Tom

Tel: Vim

Liability: _____

RMKS: _____



INSRS: WSP: _____

Tel: _____

Liability: _____

RMKS: _____



INSRS: WSP: _____

Tel: _____

Liability: _____

RMKS: _____



INSRS: WSP: _____

Tel: _____

Liability: _____

RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>27/5/18</u>	Non-Reporting ltr (1st): <u>22.5.18</u>	
<u>27/5/18</u>	Non-Reporting ltr (2nd):	
<u>27/5/18</u>	Non-Reporting ltr (Final):	
<u>27/5/18</u>	Notification ltr (if non-pickup):	
<u>27/5/18</u>	Call OI: <u>EMAIL 27-06-18</u>	
<u>27/5/18</u>	After call ltr to OI:	
<u>27/5/18</u>	Documentation Check List: Handler Typist	
<u>27/5/18</u>	Notification ltr (if non-pickup)	☒
<u>27/5/18</u>	After call ltr to OI:	☒
<u>27/5/18</u>	Authorisation To Act:	☒
<u>27/5/18</u>	Release Voucher:	☒
<u>27/5/18</u>	Final Repair Bill:	☒
<u>27/5/18</u>	Car Rental Invoice:	☒
<u>27/5/18</u>	Towing Invoice	☐
<u>27/5/18</u>	LTA / GIA :	☒
<u>27/5/18</u>	Medical Bill:	☐
<u>27/5/18</u>	PIR:	☐
<u>27/5/18</u>	Mandate/Reject Instruction:	☒
<u>27/5/18</u>	LOD	☐
<u>27/5/18</u>	Payment Breakdown Form:	☐
<u>27/5/18</u>	Post-Repair Photos:	☐
<u>27/5/18</u>	Others: <u>PD = PD = WORK</u>	☒

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____

Repair Cost: PP \$5 12,555.44 (12 days) Reduction: 56 % Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 11/12/18 Confirm with: Johnson Email ☒ Call ☐

Final Liability: 100 (Agreed / Assessed) BOLA S/N No. : 28 If NO or B 28, Ass. Lia : 100%

Repair Cost: with \$513,464.38 3 VEH CL DND LAST

Loss of Rental (LOR): with \$5 2,689.00 (21 days) x 100

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: \$51.44

Medical: \$5 -

Disbursement: \$5 400.41 (CLPES CONING) (e.g. Tow/Independent)

Legal Cost: \$5 -

Total: \$5 16,161.38 Global Sum \$5: _____

FINAL PAYMENT Date/Time: 11/12/18 Confirm with: Johnson Email ☒ Call ☐

Payee 1: \$5 16,161.38 Name 1: THE MAN KING SHIPS LTD

Payee 2: (Strike if N.A.) \$5 Name 2: _____

Payee 3: (Strike if N.A.) \$5 Name 3: _____

(08/11/13) ref

ASS. REC. BY: Marcus

REF:

A161
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLW 9086Cat Workshop m/s Tan Lim

of _____

Insured: ABH 84328

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 78k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLW 9086C Yr Regn: 3, 18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda Jazz CVT c.c. 1318Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 4332 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK3850JX 213065Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 18/5/18 D.O.I. 21/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>LTA 43069 new car 83k nett 34931</u>
	<u>FF: + 0.583-44</u>
	<u>(REQ: + 0.583-88 36%)</u>
	<u>1258344</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18009200/Ueb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-05-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 8432Z	Veh. Inspected	SLW 9086E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/05/2018	Inspection Date	21/05/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

P/P # 12204-40

Not Authorized

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Telephone Before Repair
21/5/18
12h.
 陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore S39216

Tel : 68685151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Fax: 62564315

Miss Lim Chwee Yee

Date : 21 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid <i>only 20</i>	\$ 1718.30
02	1 pc	tailgate lid lock <i>7-1/2m</i>	\$ 173.20
03	1 pc	tailgate lid lock stricker <i>1.1</i>	\$ 24.70
04	1 pc	tailgate lid weatherstrip <i>7m</i>	\$ 92.30
05	1 pc	tailgate lid inner trimboard <i>1.1</i>	\$ 52.70
06	2 ps	tailgate lid rubber stoppers @ \$8.50 <i>1.1</i>	\$ 17.00
07	1 pc	tailgate lid inner closing handle garnish <i>1.1</i>	\$ 15.00
08	2 ps	tailgate lid hinge top @ \$30.20 <i>1.1</i>	\$ 60.40
09	2 ps	tailgate lid reflector garnish @ \$45.00 <i>1.1</i>	\$ 90.00
10	1 pc	tailgate lid outer garnish <i>5.00</i>	\$ 103.40
11	1 pc	tailgate lid outer garnish "H" badge <i>new</i>	\$ 15.50
12	1 pc	tailgate lid Jazz badge <i>new</i>	\$ 10.50
13	1 pc	tailgate lid opening lever/handle outer <i>1.1</i>	\$ 59.20
14	2 ps	tailgate lid damper stays @ \$104.70 <i>1.1</i>	\$ 209.40
15	2 ps	tailgate lid drainage grommet @ \$55.00 <i>1.1</i>	\$ 110.00
16	1 pc	rear windscreen glass <i>shattered</i>	\$ 1430.00
17	1 pc	rear wiper motor <i>1.1</i>	\$ 96.20
18	1 pc	rear wiper arm <i>1.1</i>	\$ 41.70
19	1 pc	rear wiper blade <i>1.1</i>	\$ 48.20
20	1 pc	rear wiper arm cover <i>1.1</i>	\$ 8.80
21	2 ps	rear licence plate lamps @ \$32.80 <i>1.1</i>	\$ 65.60
22	1 pc	rear end panel inner <i>NS</i>	\$ 225.00
23	1 pc	rear end panel outer <i>3.50</i>	\$ 314.00
24	1 pc	rear end panel inner trim <i>7m</i>	\$ 60.80
25	2 ps	rear lamps @ \$217.40 <i>one</i>	\$ 434.80
26	1 pc	left rear lamp panel <i>BT</i>	\$ 75.30
27	4 ps	left rear lamp <i>equal</i> clip holders @ \$3.50 <i>1.1</i>	\$ 14.00
28	1 pc	rear luggage floor panel <i>1</i>	\$ 92.00
29	1 pc	rear luggage floor tools compartment foam <i>2e/7m</i>	\$ 130.80
30	1 pc	rear bumper <i>DIJ</i>	\$ 527.00
31	2 ps	rear bumper side retainers @ \$11.50 <i>NS. Benta</i>	\$ 23.00
32	2 ps	rear bumper side holder @ \$45.00 <i>1.1</i>	\$ 90.00
33	2 ps	rear bumper screw spacer @ \$25.00 <i>1.1</i>	\$ 50.00
34	2 ps	rear bumper fog lamp garnish @ \$20.00 <i>NS</i>	\$ 40.00
35	1 pc	rear bumper centre garnish <i>NS</i>	\$ 85.00
36	8 ps	rear bumper clips @ \$3.50 <i>new</i>	\$ 28.00
37	2 ps	rear bumper splashield cover @ \$250.00 <i>1.1</i>	\$ 500.00
38	1 pc	left rear fender <i>1</i>	\$ 550.30
39	1 pc	left rear fender inner liner <i>1.1</i>	\$ 65.70

4222.40



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel: 68585151 (24 Hours) Fax: 68580877
GST Reg. No.: S2-3002054-2

AIGAsia Insured's Veh No: GBG8432Z
Date of Accident: 18 May 2018

Miss Lim Chwee Yee

Date: 21 May 2018

Estimate To Repair SLW8088E - Honda Jazz 1.3 CVT (A)
Chassis No: JHMGK3850JX213065

bif #4222.40

S/No	Quantity	Description	Amount
LIST ITEMS			
40	8 ps	left rear fender inner liner clips @ \$3.50 11	\$ 28.00 X
41	2 ps	rear fender air vent @ \$26.00 11	\$ 52.00 X
42	1 pc	speaker shelf board 11	\$ 165.60 165.60
43	2 ps	rear fender inner top garnish @ \$95.80 11	\$ 191.60 X
44	1 pc	bonnet 546	\$ 527.00 527
45	2 ps	bonnet hinges @ \$24.90 11	\$ 49.80 X
46	1 pc	bonnet lock 11	\$ 41.70 X
47	1 pc	bonnet lock cable 11	\$ 15.80 X
48	1 pc	bonnet insulator 11	\$ 86.00 X
49	6 ps	bonnet insulator clips @ \$3.50 11	\$ 21.00 X
50	1 pc	right bonnet underseal weatherstrip 11	\$ 14.10 X
51	1 pc	left bonnet underseal weatherstrip 11	\$ 14.10 X
52	1 pc	left bonnet underseal weatherstrip inner 11	\$ 18.50 X
53	1 pc	right bonnet underseal weatherstrip inner 11	\$ 18.50 X
54	2 ps	bonnet rubber stoppers @ \$10.50 11	\$ 21.00 X
55	1 pc	front support panel 546	\$ 474.30 X
56	2 ps	headlamps @ \$470.30 11	\$ 940.60 X
57	2 ps	headlamp lower brackets @ \$23.80 11	\$ 47.20 X
58	1 pc	front bumper 11	\$ 594.70 594.70
59	1 pc	front bumper reinforcement 11	\$ 295.00 X
60	2 ps	front bumper air guide @ \$23.60 11	\$ 47.20 X
61	4 ps	front bumper air guide clips @ \$3.50 11	\$ 14.00 X
62	1 pc	front bumper lower centre air grille 11	\$ 405.00 X
63	2 ps	front bumper lower centre air grille side garnish @ \$25.00 11	\$ 50.00 X
64	2 ps	front bumper spot lamp garnish @ \$85.00 11	\$ 170.00 X
65	10 ps	front bumper clips @ \$3.90 11	\$ 39.00 X
66	1 pc	front bumper tow cover 11	\$ 13.50 X
67	2 ps	front bumper side retainers @ \$15.40 11	\$ 30.80 X
68	2 ps	front fenders @ \$435.00 11	\$ 870.00 X
69	2 ps	front fender inner liner @ \$90.20 11	\$ 180.40 X
70	8 ps	front fender inner liner clips @ \$3.50 11	\$ 28.00 X
71	1 pc	windscreen washer tank 11	\$ 56.40 X
72	1 pc	windscreen washer tank motor front 11	\$ 59.60 X
73	1 pc	windscreen washer tank motor rear 11	\$ 59.60 X
74	2 ps	windscreen washer tank motor pipe @ \$25.50 11	\$ 51.00 X
75	1 pc	wiper grille 11	\$ 1232.20 X
76	1 pc	radiator assy 11	\$ 1107.40 X
77	1 pc	radiator expansion tank 11	\$ 21.50 X
78	1 pc	radiator expansion tank bracket 11	\$ 35.00 X



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10, Singapore 538216
Tel: 68585151 (24 hours) Fax: 68580877
GST Regn. No.: M2-9522654-2

AIGAsia Insured's Veh No: GBG8432Z
Date of Accident: 18 May 2018

Miss Lim Chwee Yee

Date: 21 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)
Chassis No: JHMGK3850JX213065

618 7613.40

B/No	Quantity	Description	Amount
LIST ITEMS			
79	1 pc	radiator grille <i>CAR</i>	\$ 317.70
80	1 pc	radiator grille outer chrome garnish <i>CAR</i>	\$ 233.90
81	1 pc	radiator grille emblem badge <i>MIS</i>	\$ 14.60
82	3 ps	radiator grille emblem badge clips @ \$3.90 <i>1-1</i>	\$ 11.70
83	1 pc	radiator grille emblem badge base/holder <i>MIS</i>	\$ 32.60
84	1 pc	radiator grille chrome moulding <i>CAR</i>	\$ 165.00
85	6 ps	radiator grille clips @ \$3.90 <i>1-1</i>	\$ 23.40
86	2 ps	radiator top mount bush @ \$15.50 <i>1-1</i>	\$ 31.00
87	1 pc	radiator fan shroud <i>1-1</i>	\$ 89.30
88	1 pc	radiator fan blade <i>1-1</i>	\$ 78.00
89	1 pc	radiator fan motor <i>1-1</i>	\$ 219.00
90	1 pc	radiator top hose <i>1-1</i>	\$ 16.80
91	1 pc	radiator bottom hose <i>1-1</i>	\$ 16.40
92	2 ps	radiator bottom mount bush @ \$11.10 <i>1-1</i>	\$ 22.20
93	1 pc	radiator expansion tank hose <i>1-1</i>	\$ 21.50
94	1 pc	inlet manifold assy <i>1-1</i>	\$ 370.00
95	1 pc	inlet manifold rubber hose <i>1-1</i>	\$ 18.50
96	1 pc	inlet manifold rubber hose clip holder <i>1-1</i>	\$ 8.50
97	1 pc	air cleaner tank - intake duct <i>TW1</i>	\$ 35.50
98	2 ps	air cleaner tank - intake duct clips @ \$3.50 <i>MIS</i>	\$ 7.00
99	1 pc	air cleaner tank - intake hose <i>1-1</i>	\$ 34.50
100	1 pc	aircon condenser <i>PuA/Sat</i>	\$ 204.00
101	1 pc	aircon fan blade <i>1-1</i>	\$ 43.80
102	1 pc	aircon fan motor <i>1-1</i>	\$ 310.00
103	1 pc	aircon fan shroud <i>1-1</i>	\$ 78.00
104	1 pc	aircon pipe condenser to compressor <i>1-1</i>	\$ 141.90
105	1 pc	aircon hose compressor to evaporator <i>1-1</i>	\$ 109.70
106	1 pc	battery cover <i>DE</i>	\$ 17.70
107	1 pc	battery tray <i>TW1</i>	\$ 15.70
108	1 pc	battery support panel <i>1-1</i>	\$ 72.20
109	12 ps	roof-gutter moulding clips @ \$4.50 <i>1-1</i>	\$ 54.00
Less 20 %			\$ 10840.10
			\$ 8672.08
SPECIAL NETT ITEMS			
110	1 set	sundries and clips <i>1-1</i>	\$ 900.00
111	1 pc	rear windscreen glass sealant <i>MIS</i>	\$ 180.00
112	1 pc	rear windscreen glass sponge seal <i>MIS</i>	\$ 300.00
113	1 pc	rear windscreen glass solat film <i>MIS</i>	\$ 500.00

9191.50
1838.30
7353.20

8436.7
40
30
200



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 538216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Reg. No. : M2-8852054-2

AIGAsia Insured's Veh No : GBG8432Z
Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 21 May 2018

Estimate To Repair SLW9086F - Honda Jazz 1.3 CVT (A)
Chassis No : JHMGK3850JC213065

S/Ns	Quantity	Description	Amount
		SPECIAL NETT ITEMS	
114	1 pc	rear licence plate <i>But</i>	\$ 50.00 <i>40</i>
115	1 pc	backoff camera with night vision <i>AA</i>	\$ 550.00 <i>X</i>
116	1 pc	rear luggage floor panel insulator <i>AA</i>	\$ 250.00 <i>X</i>
117	1 set	rear bumper parking sensor <i>Shush</i>	\$ 500.00 <i>280</i>
118	1 pc	front licence plate <i>But</i>	\$ 80.00 <i>40</i>
119	1 tin	radiator coolant <i>rec</i>	\$ 80.00 <i>30</i>
120	1 pc	battery <i>AA</i>	\$ 200.00 <i>X</i>
			\$ 2590.00 <i>660</i>
		LABOUR & MISC. CHARGES	
01		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 850.00 <i>280</i>
02		To rust-proofing of the affected areas.	\$ 250.00 <i>120</i>
03		To apply panel protection system and shines	\$ 450.00 <i>X</i>
04		To remove and refit rear windscreen glass and vacuum shattered broken glass	\$ 250.00 <i>120</i>
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 180.00 <i>60</i>
06		To reinstall of rear bumper parking sensor.	\$ 200.00 <i>120</i>
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 250.00 <i>20</i>
08		To remove backoff camera and settings.	\$ 120.00 <i>50</i>
09		To dismantling air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 300.00 <i>100</i>
10		To check electrical lighting concerned.	\$ 80.00 <i>30</i>
11		Labour to remove and renew inlet manifold assy and front chassis.	\$ 250.00 <i>X</i>
12		To conduct diagnostic check and recall error codes and settings.	\$ 500.00 <i>X</i>
13		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 300.00 <i>1600</i>
14		Putty and spray painting of the affected portion.	\$ 250.00 <i>1700</i>
			\$ 8800.00
		Total	\$ 22802.08 <i>490</i>



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : GBG8432Z
Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 20 June 2018

Supplementary To Repair SLW9086E - Honda Jazz 1.3 CVT (A)
Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	battery positive terminal cover	\$ 19.50
02	1 pc	air cleaner tank housing bottom	\$ 126.90
03	1 pc	radiator grille bracket	\$ 19.50
04	1 pc	left rear luggage floor side extension panel	\$ 90.40
05	1 pc	front licence plate garnish	\$ 78.00
06	2 ps	rear bumper side garnish @ \$28.00	\$ 56.00
07	1 set	rear windshield glass weatherstrip	\$ 60.00
08	1 pc	radiator glass cover	\$ 25.00
		grille	\$ 475.30
		Less 20 %	\$ 95.06
			\$ 380.24
		Total	\$ 380.24
		part	7353.20
		part Sp part	660.00
		part supplement	380.24
		labour	4190.00
			<u>12,583.44</u>

NEA
CPA
CPA
BT
NEA
BT
NEA
NEA



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid <i>sedson</i>	\$ 0.00
02	1 pc	tailgate lid lock <i>7m, 1/2m</i>	\$ 0.00
03	1 pc	tailgate lid lock stricker <i>1/2 X</i>	\$ 0.00
04	1 pc	tailgate lid weatherstrip <i>7m, 1/2m</i>	\$ 0.00
05	1 pc	tailgate lid inner trimboard <i>?</i>	\$ 0.00
06	2 ps	tailgate lid rubber stoppers @ \$.00 <i>?</i>	\$ 0.00
07	1 pc	tailgate lid inner closing handle garnish <i>?</i>	\$ 0.00
08	2 ps	tailgate lid hinge top @ \$.00 <i>1/2 X</i>	\$ 0.00
09	2 ps	tailgate lid reflector garnish @ \$.00	\$ 0.00
10	1 pc	tailgate lid outer garnish <i>sedson</i>	\$ 0.00
11	1 pc	tailgate lid outer garnish "H" badge <i>sedson</i>	\$ 0.00
12	1 pc	tailgate lid Jazz badge <i>sedson</i>	\$ 0.00
13	1 pc	tailgate lid opening lever/handle outer	\$ 0.00
14	2 ps	tailgate lid damper stays @ \$.00 <i>1/2 X</i>	\$ 0.00
15	2 ps	tailgate lid drainage grommet @ \$.00 <i>1/2 X</i>	\$ 0.00
16	1 pc	rear windscreen glass <i>sedson</i>	\$ 0.00
17	1 pc	rear wiper motor <i>1/2 X</i>	\$ 0.00
18	1 pc	rear wiper arm <i>1/2 X</i>	\$ 0.00
19	1 pc	rear wiper blade <i>1/2 X</i>	\$ 0.00
20	1 pc	rear wiper arm cover <i>1/2 X</i>	\$ 0.00
21	2 ps	rear licence plate lamps @ \$.00 <i>1/2 X</i>	\$ 0.00
22	1 pc	rear end panel inner <i>sedson</i>	\$ 0.00
23	1 pc	rear end panel outer <i>sedson</i>	\$ 0.00
24	1 pc	rear end panel inner trim <i>7m, 1/2m</i>	\$ 0.00
25	2 ps	rear lamps @ \$.00 <i>sedson</i>	\$ 0.00
26	1 pc	left rear lamp panel <i>?</i>	\$ 0.00
27	4 ps	left rear lamp panel clip holders @ \$.00 <i>1/2 X</i>	\$ 0.00
28	1 pc	rear luggage floor panel <i>?</i>	\$ 0.00
29	1 pc	rear luggage floor tools compartment foam <i>2e/7e</i>	\$ 0.00
30	1 pc	rear bumper <i>dis</i>	\$ 0.00
31	2 ps	rear bumper side retainers @ \$.00 <i>2e/7e 1/2 pc</i>	\$ 0.00
32	2 ps	rear bumper side holder @ \$.00	\$ 0.00
33	2 ps	rear bumper screw spacer @ \$.00 <i>?</i>	\$ 0.00
34	2 ps	rear bumper fog lamp garnish @ \$.00 <i>sedson</i>	\$ 0.00
35	1 pc	rear bumper centre garnish <i>?</i>	\$ 0.00
36	8 ps	rear bumper clips @ \$.00 <i>sedson</i>	\$ 0.00
37	2 ps	rear bumper splashshield cover @ \$.00 <i>?</i>	\$ 0.00
38	1 pc	left rear fender <i>sedson</i>	\$ 0.00
39	1 pc	left rear fender inner liner <i>1/2 X</i>	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	8 ps	left rear fender inner liner clips @ \$.00 11X	\$ 0.00
41	2 ps	rear fender air vent @ \$.00 11X	\$ 0.00
42	1 pc	speaker shelf board ?	\$ 0.00
43	2 ps	rear fender inner top garnish @ \$.00 ?	\$ 0.00
44	1 pc	bonnet	\$ 0.00
45	2 ps	bonnet hinges @ \$.00 2m ✓	\$ 0.00
46	1 pc	bonnet lock 7m ✓	\$ 0.00
47	1 pc	bonnet lock cable 11X	\$ 0.00
48	1 pc	bonnet insulator Dis ✓	\$ 0.00
49	6 ps	bonnet insulator clips @ \$.00 2m ✓	\$ 0.00
50	1 pc	right bonnet underseal weatherstrip 2m ✓	\$ 0.00
51	1 pc	left bonnet underseal weatherstrip 2m ✓	\$ 0.00
52	1 pc	left bonnet underseal weatherstrip inner 11X	\$ 0.00
53	1 pc	right bonnet underseal weatherstrip inner 11X	\$ 0.00
54	2 ps	bonnet rubber stoppers @ \$.00 11X	\$ 0.00
55	1 pc	front support panel 34c ✓	\$ 0.00
56	2 ps	headlamps @ \$.00 2m/3m ✓	\$ 0.00
57	2 ps	headlamp lower brackets @ \$.00 ?	\$ 0.00
58	1 pc	front bumper Dis ✓	\$ 0.00
59	1 pc	front bumper reinforcement 2m ✓	\$ 0.00
60	2 ps	front bumper air guide @ \$.00 ?	\$ 0.00
61	4 ps	front bumper air guide clips @ \$.00 ?	\$ 0.00
62	1 pc	front bumper lower centre air grille ?	\$ 0.00
63	2 ps	front bumper lower centre air grille side garnish @ \$.00 ?	\$ 0.00
64	2 ps	front bumper spot lamp garnish @ \$.00 11X	\$ 0.00
65	10 ps	front bumper clips @ \$.00 2m ✓	\$ 0.00
66	1 pc	front bumper tow cover 7.1 ✓	\$ 0.00
67	2 ps	front bumper side retainers @ \$.00 34c ✓	\$ 0.00
68	2 ps	front fenders @ \$.00 2x	\$ 0.00
69	2 ps	front fender inner liner @ \$.00 11X	\$ 0.00
70	8 ps	front fender inner liner clips @ \$.00 11X	\$ 0.00
71	1 pc	windscreen washer tank ?	\$ 0.00
72	1 pc	windscreen washer tank motor front ?	\$ 0.00
73	1 pc	windscreen washer tank motor rear 11X	\$ 0.00
74	2 ps	windscreen washer tank motor pipe @ \$.00 11X	\$ 0.00
75	1 pc	wiper grille 11X	\$ 0.00
76	1 pc	radiator assy ?	\$ 0.00
77	1 pc	radiator expansion tank ?	\$ 0.00
78	1 pc	radiator expansion tank bracket ?	\$ 0.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
79	1 pc	radiator grille <i>me ✓</i>	\$ 0.00
80	1 pc	radiator grille outer chrome garnish <i>CM ✓</i>	\$ 0.00
81	1 pc	radiator grille emblem badge <i>MIS ✓</i>	\$ 0.00
82	3 ps	radiator grille emblem badge clips @ \$.00 <i>11X</i>	\$ 0.00
83	1 pc	radiator grille emblem badge base/holder <i>?</i>	\$ 0.00
84	1 pc	radiator grille chrome moulding <i>CM ✓</i>	\$ 0.00
85	6 ps	radiator grille clips @ \$.00 <i>11X</i>	\$ 0.00
86	2 ps	radiator top mount bush @ \$.00 <i>11X</i>	\$ 0.00
87	1 pc	radiator fan shroud <i>?</i>	\$ 0.00
88	1 pc	radiator fan blade <i>?</i>	\$ 0.00
89	1 pc	radiator fan motor <i>?</i>	\$ 0.00
90	1 pc	radiator top hose <i>?</i>	\$ 0.00
91	1 pc	radiator bottom hose <i>?</i>	\$ 0.00
92	2 ps	radiator bottom mount bush @ \$.00 <i>?</i>	\$ 0.00
93	1 pc	radiator expansion tank hose	\$ 0.00
94	1 pc	inlet manifold assy <i>3vc X</i>	\$ 0.00
95	1 pc	inlet manifold rubber hose <i>11 X</i>	\$ 0.00
96	1 pc	inlet manifold rubber hose clip holder <i>11 X</i>	\$ 0.00
97	1 pc	air cleaner tank - intake duct <i>7mi ✓</i>	\$ 0.00
98	2 ps	air cleaner tank - intake duct clips @ \$.00 <i>me ✓</i>	\$ 0.00
99	1 pc	air cleaner tank - intake hose <i>?</i>	\$ 0.00
100	1 pc	aircon condenser <i>pan / Bal ✓</i>	\$ 0.00
101	1 pc	aircon fan blade <i>?</i>	\$ 0.00
102	1 pc	aircon fan motor <i>?</i>	\$ 0.00
103	1 pc	aircon fan shroud <i>?</i>	\$ 0.00
104	1 pc	aircon pipe condenser to compressor <i>11 X</i>	\$ 0.00
105	1 pc	aircon hose compressor to evaporator <i>11 X</i>	\$ 0.00
106	1 pc	battery cover <i>me ✓</i>	\$ 0.00
107	1 pc	battery tray	\$ 0.00
108	1 pc	battery support panel <i>11 X</i>	\$ 0.00
109	12 ps	roof-gutter moulding clips @ \$.00 <i>11 X</i>	\$ 0.00
		Less 20 %	\$ 0.00
		<u>SPECIAL NETT ITEMS</u>	
110	1 set	sundries and clips <i>11 X</i>	\$ 100.00 <i>x</i>
111	1 pc	rear windscreen glass sealant <i>me</i>	\$ 180.00 <i>40</i>
112	1 pc	rear windscreen glass sponge seal <i>me</i>	\$ 100.00 <i>30</i>
113	1 pc	rear windscreen glass solat film <i>me</i>	\$ 500.00 <i>200</i>



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 18 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
114	1 pc	rear licence plate <i>Ref</i>	\$ 50.00
115	1 pc	backoff camera with night vision	\$ 550.00
116	1 pc	rear luggage floor panel insulator	\$ 250.00
117	1 set	rear bumper parking sensor <i>shred 200</i>	\$ 500.00
118	1 pc	front licence plate <i>Ref</i>	\$ 80.00
119	1 tin	radiator coolant <i>new</i>	\$ 80.00
120	1 pc	battery	\$ 200.00
			\$ 2,590.00
LABOUR & MISC. CHARGES			
01		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 850.00
02		To rust-proofing of the affected areas.	\$ 350.00
03		To apply panel protection system and shines	\$ 450.00
04		To remove and refit rear windscreen glass and vaccum shattered broken glass	\$ 250.00
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 180.00
06		To reinstall of rear bumper parking sensor.	\$ 200.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 250.00
08		To remove backoff camera and settings.	\$ 120.00
09		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 300.00
10		To check electrical lighting concerned.	\$ 80.00
11		Labour to remove and renew inlet manifold assy and front chassis.	\$ 250.00
12		To conduct diagnostic check and recall error codes and settings.	\$ 500.00
13		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,800.00
14		Putty and spray painting of the affected portion.	\$ 2,500.00
			\$ 10,080.00
Total			\$ 12,670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (illicit) modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

40
7
7
200
40
30
?
280
120
?
120
60
50
20
50
100
30
x
x
1800
1700

P/R # 12583.44

Not Authorized

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

Take up before repair
12/5/18
12h.



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 21 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid <i>solly do</i>	\$ 716.30
02	1 pc	tailgate lid lock <i>7w./jam</i>	\$ 173.20
03	1 pc	tailgate lid lock stricker <i>11</i>	\$ 24.70
04	1 pc	tailgate lid weatherstrip <i>7w/</i>	\$ 92.30
05	1 pc	tailgate lid inner trimboard <i>11</i>	\$ 52.10
06	2 ps	tailgate lid rubber stoppers @ \$8.50 <i>11</i>	\$ 17.00
07	1 pc	tailgate lid inner closing handle garnish <i>11</i>	\$ 15.00
08	2 ps	tailgate lid hinge top @ \$30.20 <i>11</i>	\$ 60.40
09	2 ps	tailgate lid reflector garnish @ \$45.00 <i>11</i>	\$ 90.00
10	1 pc	tailgate lid outer garnish <i>5w</i>	\$ 103.40
11	1 pc	tailgate lid outer garnish "H" badge <i>rec</i>	\$ 15.50
12	1 pc	tailgate lid Jazz badge <i>rec</i>	\$ 10.50
13	1 pc	tailgate lid opening lever/handle outer <i>11</i>	\$ 59.20
14	2 ps	tailgate lid damper stays @ \$104.70 <i>11</i>	\$ 209.40
15	2 ps	tailgate lid drainage grommet @ \$55.00 <i>11</i>	\$ 110.00
16	1 pc	rear windscreen glass <i>shattered</i>	\$ 1,430.00
17	1 pc	rear wiper motor <i>11</i>	\$ 98.20
18	1 pc	rear wiper arm <i>11</i>	\$ 41.70
19	1 pc	rear wiper blade <i>11</i>	\$ 40.20
20	1 pc	rear wiper arm cover <i>11</i>	\$ 8.80
21	2 ps	rear licence plate lamps @ \$32.80 <i>11</i>	\$ 65.60
22	1 pc	rear end panel inner <i>NS</i>	\$ 225.00
23	1 pc	rear end panel outer <i>Body</i>	\$ 314.00
24	1 pc	rear end panel inner trim <i>7w/</i>	\$ 60.80
25	2 ps	rear lamps @ \$217.40 <i>car</i>	\$ 434.80
26	1 pc	left rear lamp panel <i>Body</i>	\$ 75.30
27	4 ps	left rear lamp panel clip holders @ \$3.50 <i>rec</i>	\$ 14.00
28	1 pc	rear luggage floor panel <i>R</i>	\$ 697.00
29	1 pc	rear luggage floor tools compartment foam <i>de/foam</i>	\$ 130.80
30	1 pc	rear bumper <i>DI</i>	\$ 527.00
31	2 ps	rear bumper side retainers @ \$11.50 <i>NS Bent</i>	\$ 23.00
32	2 ps	rear bumper side holder @ \$45.00 <i>11</i>	\$ 90.00
33	2 ps	rear bumper screw spacer @ \$25.00 <i>11</i>	\$ 50.00
34	2 ps	rear bumper fog lamp garnish @ \$20.00 <i>NS</i>	\$ 40.00
35	1 pc	rear bumper centre garnish (block) <i>gravel</i>	\$ 85.00
36	8 ps	rear bumper clips @ \$3.50 <i>rec</i>	\$ 28.00
37	2 ps	rear bumper splashshield cover @ \$250.00 <i>11</i>	\$ 500.00
38	1 pc	left rear fender <i>R</i>	\$ 559.30
39	1 pc	left rear fender inner liner <i>11</i>	\$ 65.70

4222-40

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 21 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
40	8 ps	left rear fender inner liner clips @ \$3.50 11	\$ 28.00 X
41	2 ps	rear fender air vent @ \$26.00 11	\$ 52.00 X
42	1 pc	speaker shelf board 11	\$ 165.60 X
43	2 ps	rear fender inner top garnish @ \$95.80 11	\$ 191.60 X
44	1 pc	bonnet 346	\$ 527.00 ✓
45	2 ps	bonnet hinges @ \$24.90 11	\$ 49.80 ✓
46	1 pc	bonnet lock 11	\$ 41.70 ✓
47	1 pc	bonnet lock cable 11	\$ 15.80 X
48	1 pc	bonnet insulator 11	\$ 86.00 ✓
49	6 ps	bonnet insulator clips @ \$3.50 11	\$ 21.00 ✓
50	1 pc	right bonnet underseal weatherstrip 11	\$ 14.10 ✓
51	1 pc	left bonnet underseal weatherstrip 11	\$ 14.10 ✓
52	1 pc	left bonnet underseal weatherstrip inner 11	\$ 18.50 X
53	1 pc	right bonnet underseal weatherstrip inner 11	\$ 18.50 X
54	2 ps	bonnet rubber stoppers @ \$10.50 11	\$ 21.00 X
55	1 pc	front support panel 346	\$ 474.30 ✓
56	2 ps	headlamps @ \$470.30 11	\$ 940.60 ✓
57	2 ps	headlamp lower brackets @ \$23.60 11	\$ 47.20 ✓
58	1 pc	front bumper 11	\$ 594.70 ✓
59	1 pc	front bumper reinforcement 11	\$ 295.00 ✓
60	2 ps	front bumper air guide @ \$23.60 11	\$ 47.20 ✓
61	4 ps	front bumper air guide clips @ \$3.50 11	\$ 14.00 X
62	1 pc	front bumper lower centre air grille 11	\$ 105.00 ✓
63	2 ps	front bumper lower centre air grille side garnish @ \$25.00 11	\$ 50.00 ✓
64	2 ps	front bumper spot lamp garnish @ \$85.00 11	\$ 170.00 X
65	10 ps	front bumper clips @ \$3.90 11	\$ 39.00 ✓
66	1 pc	front bumper tow cover 11	\$ 13.50 ✓
67	2 ps	front bumper side retainers @ \$15.40 11	\$ 30.80 ✓
68	2 ps	front fenders @ \$435.00 11	\$ 870.00 X
69	2 ps	front fender inner liner @ \$90.20 11	\$ 180.40 X
70	8 ps	front fender inner liner clips @ \$3.50 11	\$ 28.00 X
71	1 pc	windscreen washer tank 11	\$ 56.10 X
72	1 pc	windscreen washer tank motor front 11	\$ 59.60 X
73	1 pc	windscreen washer tank motor rear 11	\$ 59.60 X
74	2 ps	windscreen washer tank motor pipe @ \$25.50 11	\$ 51.00 X
75	1 pc	wiper grille 11	\$ 1,732.20 X
76	1 pc	radiator assy 11	\$ 1,187.40 X
77	1 pc	radiator expansion tank 11	\$ 27.50 X
78	1 pc	radiator expansion tank bracket 11	\$ 35.00 X

7613.4

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 21 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount	
		<u>LIST ITEMS</u>		
79	1 pc	radiator grille <i>CNE</i>	\$ 317.70	✓
80	1 pc	radiator grille outer chrome garnish <i>CNE</i>	\$ 233.90	✓
81	1 pc	radiator grille emblem badge <i>MIS</i>	\$ 14.60	✓
82	3 ps	radiator grille emblem badge clips @ \$3.90 <i>11</i>	\$ 11.70	X
83	1 pc	radiator grille emblem badge base/holder <i>Dye</i>	\$ 32.50	✓
84	1 pc	radiator grille chrome moulding <i>CNE</i>	\$ 165.00	✓
85	6 ps	radiator grille clips @ \$3.90 <i>11</i>	\$ 23.40	X
86	2 ps	radiator top mount bush @ \$15.50 <i>11</i>	\$ 31.00	X
87	1 pc	radiator fan shroud <i>11</i>	\$ 89.30	X
88	1 pc	radiator fan blade <i>11</i>	\$ 78.00	X
89	1 pc	radiator fan motor <i>11</i>	\$ 219.00	X
90	1 pc	radiator top hose <i>11</i>	\$ 16.80	X
91	1 pc	radiator bottom hose <i>11</i>	\$ 16.40	X
92	2 ps	radiator bottom mount bush @ \$11.10 <i>11</i>	\$ 22.20	X
93	1 pc	radiator expansion tank hose <i>11</i>	\$ 21.50	X
94	1 pc	inlet manifold assy <i>11</i>	\$ 370.00	X
95	1 pc	inlet manifold rubber hose <i>11</i>	\$ 18.50	X
96	1 pc	inlet manifold rubber hose clip holder <i>11</i>	\$ 8.50	X
97	1 pc	air cleaner tank - intake duct <i>TW</i>	\$ 35.50	✓
98	2 ps	air cleaner tank - intake duct clips @ \$3.50 <i>M</i>	\$ 7.00	✓
99	1 pc	air cleaner tank - intake hose <i>Dange</i>	\$ 34.50	✓
100	1 pc	aircon condenser <i>PUN/SOL</i>	\$ 704.00	✓
101	1 pc	aircon fan blade <i>11</i>	\$ 43.90	X
102	1 pc	aircon fan motor <i>11</i>	\$ 310.00	X
103	1 pc	aircon fan shroud <i>11</i>	\$ 78.00	X
104	1 pc	aircon pipe condenser to compressor <i>11</i>	\$ 141.90	X
105	1 pc	aircon hose compressor to evaporator <i>11</i>	\$ 109.70	X
106	1 pc	battery cover <i>De</i>	\$ 17.70	✓
107	1 pc	battery tray <i>TW</i>	\$ 15.70	✓
108	1 pc	battery support panel <i>11</i>	\$ 72.20	X
109	12 ps	roof-gutter moulding clips @ \$4.50 <i>11</i>	\$ 54.00	X
			\$ 19,040.10	
		Less 20 %	\$ 3,808.02	
			\$ 15,232.08	
		<u>SPECIAL NETT ITEMS</u>		
110	1 set	sundries and clips <i>11</i>	\$ 100.00	X
111	1 pc	rear windscreen glass sealant <i>M</i>	\$ 180.00	40
112	1 pc	rear windscreen glass sponge seal <i>M</i>	\$ 100.00	30
113	1 pc	rear windscreen glass solat film <i>M</i>	\$ 500.00	200

9191.5

AIGAsia Insured's Veh No : GBG8432Z

Date of Accident : 18 May 2018

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Chwee Yee

Date : 21 May 2018

Estimate To Repair SLW9086E - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
114	1 pc	rear licence plate <i>But</i>	\$ 50.00
115	1 pc	backoff camera with night vision <i>11</i>	\$ 550.00
116	1 pc	rear luggage floor panel insulator <i>11</i>	\$ 250.00
117	1 set	rear bumper parking sensor <i>shush</i>	\$ 500.00
118	1 pc	front licence plate <i>But</i>	\$ 80.00
119	1 tin	radiator coolant <i>neu</i>	\$ 80.00
120	1 pc	battery <i>11</i>	\$ 200.00
			\$ 2,590.00
LABOUR & MISC. CHARGES			
01		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 850.00
02		To rust-proofing of the affected areas.	\$ 350.00
03		To apply panel protection system and shines	\$ 11 450.00
04		To remove and refit rear windscreen glass and vaccum shattered broken glass	\$ 250.00
05		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 180.00
06		To reinstall of rear bumper parking sensor.	\$ 200.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 250.00
08		To remove backoff camera and settings.	\$ 120.00
09		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 300.00
10		To check electrical lighting concerned.	\$ 80.00
11		Labour to remove and renew inlet manifold assy and front chassis.	\$ 11 250.00
12		To conduct diagnostic check and recall error codes and settings.	\$ 11 500.00
13		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,800.00
14		Putty and spray painting of the affected portion.	\$ 2,500.00
			\$ 10,080.00
Total			\$ 27,902.08

40 ✓
200
2002 ✓
40
32
660
280
120
20
120
60
120
20
120
100
30
1600
1700
490



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBG8432Z
Date of Accident : 18 May 2018

Miss Lim Chwee Yee

Date : 20 June 2018

Supplementary To Repair SLW9086E - Honda Jazz 1.3 CVT (A)
Chassis No : JHMGK3850JX213065

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	battery positive terminal cover <i>Dis</i>	\$ 19.50
02	1 pc	air cleaner tank housing bottom <i>Twl</i>	\$ 126.90
03	1 pc	radiator grille bracket <i>one</i>	\$ 19.50
04	1 pc	left rear luggage floor side extension panel <i>20</i>	\$ 90.40
05	1 pc	front licence plate garnish <i>Dis</i>	\$ 78.00
06	2 ps	rear bumper side garnish @ \$28.00 (black) <i>gross</i>	\$ 56.00
07	1 set	rear windshield glass weatherstrip <i>Acrylic</i>	\$ 60.00
08	1 pc	radiator glass cover <i>one</i>	\$ 25.00
		<i>Grille</i>	\$ 475.30
		Less 20 %	\$ 95.06
		Total	\$ 380.24
		<i>part</i>	<i>7353.20</i>
		<i>part Sp New</i>	<i>660.00</i>
		<i>part supplementary</i>	<i>380.24</i>
		<i>labour</i>	<i>4190.00</i>
			<i>12,583.44</i>
			<i>26/6/18</i>
			<i>26/06/18</i>
			<i>26/6/18</i>
			<i>26/06/18</i>

P- 966680
202
7733.44
660
4190
12583.44

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	21 May 2018 18:32	Cim Veh Model Changed	(202021) ADIVA AD200A 200cc (M).	[A] Lau Shu Pei
2	21 May 2018 18:32	Cim Created	Reg No: SLW9086E, Acct Date: 2018/05/18, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Tan Lim Motor Pte Ltd (Defu)	[A] Lau Shu Pei
3	21 May 2018 18:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	21 May 2018 18:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[A] Lau Shu Pei
5	21 May 2018 18:32	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	21 May 2018 18:32	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
7	21 May 2018 18:32	Label Added	(19):Fastlane.	[A] Lau Shu Pei
8	21 May 2018 18:32	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
9	22 May 2018 16:38	Cim Veh Model Changed	(202021) -> (204445) HONDA JAZZ 1.3 CVT (A).	[A] Lau Shu Pei
10	08 Jun 2018 14:30	Cim Registration Modified	Acct Time:00:00:00->13:00:00.	[I] AIG OneClaim Integration User
11	11 Sep 2018 15:50	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
12	11 Sep 2018 15:50	Cim Dtl Modified	JPJ Reg. Date: -> 2018/03/08.	[A] JOANNE LEE KHANG MIN
13	11 Sep 2018 15:50	Cim Details Notified		[A] JOANNE LEE KHANG MIN
14	15 Sep 2018 15:19	Adj Mandate Request	Cur.Req:15183.77:15,183.77	[A] Asher Sng Rong Yi
15	26 Oct 2018 08:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/31	[I] MdNoor, Norsiah
16	26 Oct 2018 08:34	Adj Mandate Set	Approved:15183.77.	[I] MdNoor, Norsiah
17	30 Oct 2018 12:38	Adj Mandate Request	Cur.Req:15584.38:15,584.38	[A] Asher Sng Rong Yi
18	31 Oct 2018 10:52	Adj Mandate Set	Approved:15584.38.	[I] MdNoor, Norsiah
19	09 Nov 2018 17:17	Adj Mandate Request	Cur.Req:16761.38:TP SUBMIT PO/DO TO REQUEST FOR EXTRA DOWNTIME, PLS REFER TO THE WORKCHART.	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[07/06/2018 14:01] Asher Sng Rong Yi:
FILE REVIEW: 100% 8:28 3 VEH CC OID LAST
[22/05/2018 19:06] Lau Shu Pei :
SENT NON REPORTING LETTER TO OI

Merimen Billing for this case - Transaction History

Post Ref No.	Ref Date	Acc Type	Acc Name	On Remit To	Ref 1	Ref 2	Amount
1913558	11/09/2018 15:50	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLW9086E	GBG8432Z	10.70

Print Received Message

This mail is associated with :

***SLW9086E (1154556123SG)
[GBG8432Z]**

TP

LIM CHWEE YEE

May 18 2018 1:00PM

[JUE MAN HING SHIP'S LAUNDRY MANAGEMENT SERVICES]

Tan Lim Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 29/11/2018 17:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16761.38) - SLW9086E - Claim Handler: MdNoor, Norsiah

Approved:16761.38.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP024052018
Your Ref GBG8432Z

Date 05/07/18

WITHOUT PREJUDICE

Claims Department - Executive in charge
AIG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SLW9086E / GBG8432Z / GBA7506H on 18/05/18

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / copies of photographs
☒ Original Tax-invoice number TP0718/004 ☒ Original rental invoice number 17181062
☐ SAS / AS & IS / police report ☐ police result
☐ Certificate Of Insurance ☒ Vehicle search result
☒ Authorization to act ☒ receipt for coating

*Survey under insurance instruction / Independent surveyor / No survey.

LKK

a)	Cost of repair (inclusive GST)	\$ <u>13,464.28</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
d)	Loss of hire / use / rental / earnings / rental fees	\$ <u>3,124.40</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	<u>Premium glass coating & interior cleaning</u>	\$ <u>469.09</u>
	Total	\$ <u>17,065.26</u> =====

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlmotor.com.sg / sam@tlmotor.com.sg / johnson.chua@tlmotor.com.sg

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

370 Ubi Road 3, 408551 SINGAPORE

Ubi Service Centre

Phone No. : +65 6841 3838 Fax No. : +65 6741 5092

LIM CHWEE YEE

533 HOUGANG AVENUE 6

#12-335

SINGAPORE, 530533

SINGAPORE

Customer No. : ****93858

Service Tax InvoiceGST Reg No. M20069223
Company Ref. No. 560FC13805

Invoice No. : SINV-UB18003827
 Invoice Date : 02/04/18
 Order No. : SVO18018740
 Reference :
 Job Card No. : 7006
 Date/Time Received : 02/04/18 / 9:53:30 AM
 Licence No. : SLV19088E
 Model : JAZZ 1.3LXR CVT 18YM
 Car Chassis No. : JHMGB3850JX213065
 Car Engine No. : L13B11030393
 Mileage : 1528
 Service Advisor : YONG KAI XUAN SHAWN
 Served By : NADIA
 Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount Includ		GST
						Amount	Amount	
KAHSHINE-P-G-S468	PREMIUM GLASS COATING	1	Labor	468.00	20	374.40	25.21	400.61
Sum External Services						374.40	25.21	400.61
Total SGD						374.40	25.21	400.61
Total Payable (SGD)								400.61
Payment - In	Type	Document Number	Currency	Remaining Amount	Payment Discount	Amount		
Date								
02/04/18	Invoice	SINV-UB18003827		400.61	0.00	400.61		
Amount to Pay						400.61		
VISAUBI-WS						-400.61		
Amount given						400.61		
Change Money								

Printed by NADIA on 18 Aug 2018 at 11:44:10 AM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your
feedback by scanning
the QR Code using
mobile device



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

370 Ubi Road 3, SINGAPORE 408651

Ubi Service Centre

Phone No. : +65 6841 3838 Fax No. : +65 6741 5092

GST Reg No. M200050223
Company Ref. No. S60FC1380G

LIM CHWEE YEE
533 HOUGANG AVENUE 6
#12-335
SINGAPORE, 530533
SINGAPORE

Customer No. : ****9385B

Invoice No. : SINV-UB18010699
Invoice Date : 03/09/18
Order No. : SVO18051536
Reference :
Job Card No. : 186772
Date/Time Received : 03/09/18 / 11:50:02 AM
Licence No. : SLW9086E
Model : JAZZ 1.3LXR CVT 18YM
Car Chassis No. : JHMGK3850JX213065
Car Engine No. : L13B11030393
Mileage : 9225
Service Advisor : SIEW KOK LEONG 0335
Served By : CONNIEPOA
Page : 1

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount incld		
						Amount	Amount	GST
KAHSHINE-P-GI-S548	PREMIUM GLASS COATING & INTERIOR CLEANING PROMOTION LESS 20%	1	Labor	548.00	20	438.40	30.69	469.09
Sum External Services						438.40	30.69	469.09
Total SGD						438.40	30.69	469.09
Total Payable (SGD)								469.09

03 SEP 2018

Printed by CONNIEPOA on 03 Sep 2018 at 3:30:14 PM

This is a computer generated invoice. No signature is required.

Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted.

GST Amount is calculated from individual line(s)

Please give us your
feedback by scanning
the QR Code using
mobile device.





日天汽車配件有限公司
JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710 TEL: 6745 3833 FAX: 6745 4442, 6745 0616 (Account)
WAREHOUSE: 48A SUNGEI KADUT AVE SINGAPORE 729672 TEL: 6365 1255 FAX: 6365 2580
Email: jaeauto@pacific.net.sg GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

DATE:21/5/2018

PERSON IN CHARGE

Tan Lim Motor Pte Ltd

51 Defu Lane 10 Singapore 539216

REFER : Purchase of spare parts for SLW9086E

Please be informed that spare parts below require to special order from japan . Estimated arrival time is about 3 to 4 week.

- 1] Front support panel 2]Radiator grille 3]radiator grille chrome 4]Front bumper reinforcement
- 5]Battery cover terminal 6]Air intake tube 7]Battery cover 8]Air cleaner case cover
- 9]Licence garnish 10]Front bumper

YOURS REGARDS

JAE AUTO PTE LTD

HONDA DEPARTMENT

CHEN



各種各樣的汽車擋風玻璃與配件

WINDSCREEN GLASS & ACCESSORIES FOR ALL TYPES OF CARS

日美汽車私人有限公司 **JAE AUTO PTE LTD**

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TAN LIM MOTOR PTE LTD
 51 DEFU LANE 10

SINGAPORE 539216
 TEL : 68585151 FAX : 68580877
 ATTN : HUA : 93424525

P/c 91009

TP 201805024



Wiper blade: NWD (Nippon Wiper blade, Silper 1 Made in Korea L.
 Forch 1 Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201806-04823
 DATE : 11/06/2018
 CUSTOMER ID : TAN004
 VEH REG. NO. : SLW9086E
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 1
 CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. H60400-T5B-J007Z. GK3 2018	SUPPORT PANTEL	PA SUPPLIER	1		
2. H71121-T5A-J50 GK3 2018	GRILLE ASSY	PA SUPPLIER	1		
3. H71122-T5A-J50 GK3 2018	GRILLE CHROME	PA SUPPLIER	1		
4. H71130-T5A-J50ZZ. GK3 2018	REINFORCEMENT	PA SUPPLIER	1		

SUB-TOTAL :
 ADD GST 7.00 %

E & O E

TOTAL AMOUNT SGD :

[P] 08/06/2018 5:44:08PM

[E] 08/06/2018 2:08:11PM

Goods Sold are not refundable for Cash.
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
 Sales Executive : CHEN



Goods Received in Good Order

This is computer generated document.
 No signature is required.

Signature / Co Stamp / Date

ORIGINAL

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TAN LIM MOTOR PTE LTD
51 DEFU LANE 10

SINGAPORE 539216
TEL: 68585151 FAX: 68580877
ATTN: HUA: 93424525

P/O 91009

TP 201805024

Auto/Overdue-0.832
Dept Direct: 6417 9191 / 6725 9191



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9795

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blades: NWB (Nippon Wiper blades, Seiper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201806-05072
DATE : 11/06/2018
CUSTOMER ID : TAN004
VEH REG. NO. : SLW9086E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. H32418-T5A-003 RU1	TERMINAL, BATTERY COVER	U1 HI.2-R12-D	1		
2. H17251-5R0-000 GG7 GK8	TUBE, AIR INTAKE	U1 HI.2-F6-D	1		
3. H31531-T5A-003 GK3 PI	COVER BATTERY	U1 I.2-F8-A	1		
4. H17201-5R0-008 GK3 PI GG7	CASE SET AIR CLEANER	U1 HI.2-A1	1		
5. H71145-TAR-T50	LICENSE GARNISH	U1 SUPPLIER	1		

SUB-TOTAL :
ADD GST 7.00 %

E & O E

TOTAL AMOUNT SGD :

[P] 08/06/2018 5:44:27PM

[E] 08/06/2018 5:00:00PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Dept Direct: 6417 9751 / 6745 9609



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9752



Dept Direct: 6417 9754

Dept Direct: 6417 9755

Dept Direct: 6417 9756

Dept Direct: 6417 9757

Wiper blade: NPB (Nippon Wiper blades, Shovel / Made in Korea)

Forch / Made in Germany

Spark plug: Nippon Denso, NGK (Made in Japan)

TAN LIM MOTOR PTE LTD

51 DEFU LANE 10

SINGAPORE 539216

TEL : 68585151 FAX : 68580877

ATTN : HUA : 93424525

P/c 9/1/10

TR 201805024

① TAX INVOICE : AR201806-05193
DATE : 11/06/2018
CUSTOMER ID : TAN004
VEH REG. NO. : SLW9086E
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H04711-T5A-J502Z GK3-2018	FR BUMPER	PA SUPPLIER	1		

[Handwritten signature]

SUB-TOTAL :
ADD GST 7.00 %

E. & O.E

TOTAL AMOUNT SGD :

[P] 09/06/2018 9:42:11AM

[E] 09/06/2018 9:39:22AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHEN



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 7 June 2018 6:00 PM
To: 'sales@astoriadrycleaning.com.sg'
Subject: ACCIDENT INVOLVING GBG 8432Z/ SLW 9086E / OTHERS ON 18/05/2018

Our Ref: CC6/AIG18009200/Ueb3

07 JUNE 2018

JUE MAN HING SHIP'S LAUNDRY MANAGEMENT SERVICES

Dear Sir/Madam,

ACCIDENT INVOLVING GBG 8432Z/ SLW 9086E / OTHERS ON 18/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Lim Chwee Yee ("the third party claimant")
of Block 533 Hwang Avenue 6 #12-335 (S) 530533 (address),
owner of SLW9086E (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLW9086E that was
damaged pursuant to the accident which occurred on 18/05/2018 (date) along
Slip Road of Peta Lure 10 towards Hwang Avenue 3 (location)
involving vehicle no/s G1B G 8432 Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 18 day of May (month) 20 18 (year)



Signed by "the third party claimant"




Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$13,464.28 (Repair Cost), S\$2,889.00 (Loss of Use/Rental), S\$408.10 (Disbursement) for vehicle no. SLW 9086E that was damaged pursuant to the accident which occurred on 18/05/2018 (date) along SLIP ROAD OF DEFU LANE 10 TOWARDS HOUGANG AVE 3 (location) involving vehicle no/s GBG 8432Z.

This is pursuant to the inspection conducted on 21/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM CHWEE YEE ("the third party claimant") of vehicle no. SLW 9086E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLW 9086E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11th (day) of December (month) 2018 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0718/004

(Please quote our reference number TP024052018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Lim Chwee Yee

Date: 03/07/2018

Vehicle No: SLW9086E
Model: HONDA JAZZ

Description	Amount
To part by part repair as recommended by surveyor.	\$12,583.44
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$12,590.44
Add 7% GST	\$881.33
Total	\$13,471.77



Tan Lim Motor Pte Ltd

Bill To: LIM CHWEE YEE (C/O TAN LIM MOTOR PTE LTD)
BLK 533 HOUGANG AVENUE 6
#12-335
SINGAPORE 530533

Tax Invoice : 17181062
Date : 16 JUN 2018

Vehicle No	Description	Agreement No.	Total Amount
EU688X	Toyota Axio 1.5 Rental Charges From 21-05-2018 to 16-06-2018 3.0 weeks @ \$660.00 per week	ST6989	SGD 1,980.00
	5.0 days @ \$110.00 per day	ST6989	SGD 550.00
SKK9535B	Chevrolet Cruze 1.6L AUTO ABS D/AB 2 WD 4DR Rental Charges From 18-05-2018 to 20-05-2018 3.0 days @ \$130.00 per day	ST6987	SGD 390.00

PAID
30 JUN 2018
BY: VOB187501

TPU24052018-SLW9086E
Sub-Total 2,920.00
Add: GST (7.00%) 204.40
Amount Payable (SGD) 3,124.40

SINGAPORE DOLLAR: THREE THOUSAND ONE HUNDRED TWENTY-FOUR AND CENTS FORTY ONLY.

Cheque should be crossed "A/C Payee Only" and made payable to GLOBAL ADVANCE LEASING
Please write your invoice number on the reverse side of the cheque.
Payment should be made within 7 days from invoice.
Interest at 24% per annum on overdue account.
For bill enquiry, please call 6100 0425 / 9018 0988



GLOBAL ADVANCE LEASING

Siz Reg: 852935825E
GST Reg No: 200409785W
C/o 51 Defu Lane 10 S(539216)
Tel: 61000GAL

Agreement: 6987

Vehicle No SKK 9535B		Make & Model Chev. Cruze		Date 18.05.2018	
Hirer Name Lim CHIEE YEE		Class 2 / 2A / 2B / 3 / 4 / 5		Check Out / Check In 18.05.2018	
Address 533 Honggang Avenue 6 #10-335 (350533)				Date Out 18.05.2018	
Contact Person		Tel 90920286		Time Out 1440 hrs KM Out 51237	
1st Driver Name YEON WEI LING (YANG HUIYU)		Class 2 / 2A / 2B / 3 / 4 / 5		Date In 20.05.2018	
Address AS ABNE				Time In 2030 hrs KM In 51440	
(H/P) 81022189 (O)		(H)		PETROL E 1/4 1/2 3/4 F	
Passport/NRIC No S0019385B		Nationality Singapore		Mode of Payment	
Driving Licence No		Driving Exp 03 yrs		Cash / Cheque / Company Billing / Credit Card / Others	
Country of Issue Singapore		Expiry Date Unlimited		Cheque / Card Details:	
Additional Driver Name		Class 2 / 2A / 2B / 3 / 4 / 5		Expiry Date:	
Address				Rental Charges	
(H/P) (O) (H)				03 Days @ \$130.00 /day \$390.00	
Passport/NRIC No		Nationality		Week/s @ \$ /week \$	
Driving Licence No		Driving Exp yrs		Month/s @ \$ /month \$	
Country of Issue		Expiry Date		SUBTOTAL \$	
Non Waivable Excess				COW @ \$ \$	
The Hirer acknowledges a \$1,500.00 collision damage excess per accident applies.				PAI @ \$ \$	
X				Petrol Top Up \$	
Collision Damage Waiver (COW)				Delivery / Collection fee \$	
The Hirer may limit his liability for any damage arising from collision to \$ by purchasing COW and paying the specified sum.				Misc \$27.30	
X				Misc \$	
Personal Accident Insurance (PAI)				Less	
PAI may be purchased at a premium specified herein. The Hirer acknowledges that the insurance is written by an independent insurance company and acknowledges that he has received, read and understood the policy conditions relating to the same.				Pre-Payment / Deposit (\$)	
X				Misc (\$)	
Special Instructions				Total Due \$417.30	
				Charges Subject to Final Audit	
				Refundable Deposit	
				Deposit \$	
				Date of Refund	
				Refund Acknowledgement X	
				For Official Use	
				Invoice No: 17181062 Date	
				Receipt No Date	

Important Notes

- Rental Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the owner.
- Only persons authorised by Global Advance Leasing may drive the vehicle.
- All parking and traffic violations are the responsibility of the Hirer. An Administrative charge will be levied on any traffic violations redirected.
- The Hirer shall be liable for excess charges for any late return at the rate shown per hour or per day.
- In the event of accident, the Hirer shall report to the rental office immediately.

I/We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have been made on the applicable credit card charge slip.

X
(Hirer's signature)

X
(Additional Driver's signature)

X
(Global Advance Leasing)



GLOBAL ADVANCE LEASING

Biz Reg: B52935825E
GST Reg No: 206409785W
C/o 51 Delfu Lane 10 S2539216
Tel: 61000GAL

Agreement: 6989

Vehicle No	EU 688 X	Make & Model	T/AxiO	Date	21.05.2018
Hirer	Class 2 / 2A / 2B / 3 / 4 / 5			Check Out / Check In	
Name	Lim Chwee Yee			Date Out 21.05.2018	
Address	533 Hongkong Avenue 6 #12-335 (530533)			Time Out 1032 Hrs KM Out 15173	
Contact Person	Tel 90920286			PETROL E 1/4 1/2 3/4 F	
1st Driver	Class 2 / 2A / 2B / 3 / 4 / 5			Date In 16.06.2018	
Name	Yeo Wei Jang (Yang Hailan)			Time In 1510 Hrs KM In 16480	
Address	AS ABOVE			PETROL E 1/4 1/2 3/4 F	
(H/P) 81022189 (O)	(H)			Mode of Payment	
Passport/NRIC No S8932608G	Nationality Singapore			Cash / Cheque / Company Billing / Credit Card / Others	
Driving Licence No	Driving Exp 08 yrs			Cheque / Card Details:	
Country of Issue Singapore	Expiry Date Unlimited			Expiry Date:	
Additional Driver	Class 2 / 2A / 2B / 3 / 4 / 5			Rental Charges	
Name YEO SENG CHEONG				05 Day/s @ \$ 110.00 /day \$ 550.00	
Address B1K 533 Hongkong Ave 6, #12-335 SE 530533				03 Week/s @ \$ 660.00 /week \$ 1980.00	
(H/P) (O) (H)				Month/s @ \$ /month \$	
Passport/NRIC No S184 5834 I	Nationality Singapore			SUBTOTAL \$	
Driving Licence No S18458342	Driving Exp yrs			CDW @ \$ \$	
Country of Issue Spain	Expiry Date Unlimited			PAI @ \$ \$	
Non Waiverable Excess	(Spec Use) + \$1500 (Mig Use)			Petrol Top Up \$	
The Hirer acknowledges a \$1500 collision damage excess per accident applies	Additional Excess for above \$5			Delivery / Collection fee \$	
X Section I \$1500 + Additional Section II \$2500 + Attachment				Misc \$ 177.10	
Collision Damage Waiver (CDW)	The Hirer may limit his liability for any damage arising from collision to \$ by purchasing CDW and paying the specified sum.			Misc \$	
X				Less \$	
Personal Accident Insurance (PAI)	PAI may be purchased at a premium specified herein. The Hirer acknowledges that the insurance is written by an independent insurance company and acknowledges that he has received, read and understood the policy conditions relating to the same.			Pre-Payment / Deposit (\$ \$)	
X				Misc (\$ \$)	
Special Instructions				Total Due \$ 2707.10	
				Charges Subject to Final Audit	
				Refundable Deposit	
				Deposit \$	
				Date of Refund	
				Refund Acknowledgement X	
				For Official Use	
				Invoice No: 17181062 Date	
				Receipt No Date	

Important Notes

- Rental Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the owner.
- Only persons authorised by Global Advance Leasing may drive the vehicle.
- All parking and traffic violations are the responsibility of the Hirer. An Administrative charge will be levied on any traffic violations rectified.
- The Hirer shall be liable for excess charges for any late return at the rate shown per hour or per day.
- In the event of accident, the Hirer shall report to the rental office immediately.

I/We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have been made on the applicable credit card charge slip.

X (Hirer's signature)

X (Additional Driver's signature)

X (Global Advance Leasing)

Enquire Vehicle & Owner Information (Vehicle No. GBG8432Z As At 18 May 2018 / 13:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SLW9086E

Current Owner Details

Owner ID Type: Business
Owner ID: 46893300W
Owner Name: JUE MAN HING SHIP'S LAUNDRY MANAGEMENT SERVICES
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 1
Registered Street Name: CLAYMORE DRIVE
Registered Unit No.: # 02 - 12
Registered Building Name: ORCHARD TOWER REAR BLOCK APT
Registered Postal Code: 229594

Current Vehicle Details

Vehicle No.: GBG8432Z
Make Description/Model: NISSAN / NV350 PANEL VAN 2.5 5MT 5DR
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018 Edit Reg		21 May 2018 00:00 Edit Adj Rpt	\$12,583.44 Edit Estimates	\$12,583.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	JUE MAN HING SHIP'S LAUNDRY MANAGEMENT SERVICES , Co. Reg. No.: B46893300W								
Main Claimant:	LIM CHWEE YEE , ID: S00193858								
Vehicle Reg. No.:	SLW9086E	Date of Loss:	18/05/2018 13:00 - :59 [2 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1154556123SG	Policy/Cover Note No.:	1700078818 (Comprehensive) Coverage: 16/11/2017 - 15/11/2018						
Vehicle Reg. No. (Insured):	GBG8432Z	Policy No. (Claimant):	5100535041						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (29/11/2018): Alert - Adj Mandate Approved (\$16761.38) - SLW9086E - Claim Handler: MdNoor, No... - AIG_SG_EXPRESS (28/11/2018): Alert - Adj Mandate Approved (\$15584.38) - SLW9086E - Claim Handler: MdNoor, No... - AIG_SG_EXPRESS (31/10/2018): Alert - Adj Mandate Approved (\$15584.38) - SLW9086E - Claim Handler: MdNoor, No... - AIG_SG_EXPRESS (26/10/2018): Alert - Adj Mandate Approved (\$15183.77) - SLW9086E - Claim Handler: MdNoor, No... - AIG_SG (22/05/2018): No OI GIA Report - AIG_SG (22/05/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW9086E (1154556123SG)

[GBG8432Z]

TP

LIM CHWEE YEE

May 18 2018 1:00PM

[JUE MAN HING SHIP'S LAUNDRY MANAGEMENT SERVICES]

Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
Photos/Images															3 per page		☒			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	21/05/18 19:14		Chassis Number												1	Load JPG	☒			
2	21/05/18 19:14		Odometer Reading												1	Load JPG	☒			
3	21/05/18 19:18		General View												1	Load JPG	☒			
4	21/05/18 19:18		General View												1	Load JPG	☒			
5	21/05/18 19:18		General View												1	Load JPG	☒			
6	21/05/18 19:18		General View												1	Load JPG	☒			
7	21/05/18 19:18		General View												1	Load JPG	☒			
8	21/05/18 19:18		General View												1	Load JPG	☒			
9	21/05/18 19:18		General View												1	Load JPG	☒			
10	21/05/18 19:18		General View												1	Load JPG	☒			
11	21/05/18 19:18		General View												1	Load JPG	☒			
12	21/05/18 19:18		General View												1	Load JPG	☒			
13	21/05/18 19:18		General View												1	Load JPG	☒			
14	21/05/18 19:18		General View												1	Load JPG	☒			
15	21/05/18 19:18		General View												1	Load JPG	☒			
16	21/05/18 19:18		General View												1	Load JPG	☒			
17	21/05/18 19:18		General View												1	Load JPG	☒			
18	21/05/18 19:18		General View												1	Load JPG	☒			
19	21/05/18 19:18		General View												1	Load JPG	☒			
20	21/05/18 19:18		General View												1	Load JPG	☒			
21	21/05/18 19:18		General View												1	Load JPG	☒			
22	21/05/18 19:18		General View												1	Load JPG	☒			
23	21/05/18 19:18		General View												1	Load JPG	☒			
24	21/05/18 19:18		General View												1	Load JPG	☒			
25	21/05/18 19:18		General View												1	Load JPG	☒			
26	21/05/18 19:18		General View												1	Load JPG	☒			
27	21/05/18 19:18		General View												1	Load JPG	☒			
28	21/05/18 19:18		General View												1	Load JPG	☒			
29	21/05/18 19:18		General View												1	Load JPG	☒			
30	21/05/18 19:18		General View												1	Load JPG	☒			
31	21/05/18 19:18		General View												1	Load JPG	☒			
32	21/05/18 19:18		General View												1	Load JPG	☒			
33	21/05/18 19:18		General View												1	Load JPG	☒			
34	21/05/18 19:18		General View												1	Load JPG	☒			

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	21/05/18 19:18	General View	 Load JPG	☒
36	21/05/18 19:18	General View	 Load JPG	☒
37	21/05/18 19:18	General View	 Load JPG	☒
38	21/05/18 19:18	General View	 Load JPG	☒
39	21/05/18 19:18	General View	 Load JPG	☒
40	21/05/18 19:18	General View	 Load JPG	☒
41	21/05/18 19:18	General View	 Load JPG	☒
42	21/05/18 19:18	General View	 Load JPG	☒
43	21/05/18 19:18	General View	 Load JPG	☒
44	21/05/18 19:18	General View	 Load JPG	☒
45	21/05/18 19:18	General View	 Load JPG	☒
46	21/05/18 19:18	General View	 Load JPG	☒
47	21/05/18 19:18	General View	 Load JPG	☒
48	21/05/18 19:18	General View	 Load JPG	☒
49	21/05/18 19:18	General View	 Load JPG	☒
50	21/05/18 19:18	General View	 Load JPG	☒
51	21/05/18 19:18	General View	 Load JPG	☒
52	21/05/18 19:18	General View	 Load JPG	☒
53	21/05/18 19:18	General View	 Load JPG	☒
54	21/05/18 19:18	General View	 Load JPG	☒
55	21/05/18 19:18	General View	 Load JPG	☒
56	21/05/18 19:18	General View	 Load JPG	☒
57	21/05/18 19:18	General View	 Load JPG	☒
58	21/05/18 19:18	General View	 Load JPG	☒
59	21/05/18 19:18	General View	 Load JPG	☒
60	21/05/18 19:18	General View	 Load JPG	☒
61	21/05/18 19:18	General View	 Load JPG	☒
62	21/05/18 19:18	General View	 Load JPG	☒
63	21/05/18 19:18	General View	 Load JPG	☒
64	21/05/18 19:18	General View	 Load JPG	☒
65	21/05/18 19:18	General View	 Load JPG	☒
66	21/05/18 19:18	General View	 Load JPG	☒
67	21/05/18 19:18	General View	 Load JPG	☒
68	21/05/18 19:18	General View	 Load JPG	☒
69	21/05/18 19:18	General View	 Load JPG	☒
70	21/05/18 19:18	General View	 Load JPG	☒
71	21/05/18 19:18	General View	 Load JPG	☒
72	21/05/18 19:18	General View	 Load JPG	☒
73	21/05/18 19:18	General View	 Load JPG	☒
74	21/05/18 19:18	General View	 Load JPG	☒
75	21/05/18 19:18	General View	 Load JPG	☒
76	21/05/18 19:18	General View	 Load JPG	☒
77	21/05/18 19:18	General View	 Load JPG	☒
78	21/05/18 19:18	General View	 Load JPG	☒
79	21/05/18 19:18	General View	 Load JPG	☒
80	21/05/18 19:18	General View	 Load JPG	☒
81	21/05/18 19:18	General View	 Load JPG	☒
82	21/05/18 19:18	General View	 Load JPG	☒
83	21/05/18 19:18	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	21/05/18 19:18	General View	 Load JPG	☒
85	21/05/18 19:18	General View	 Load JPG	☒
86	21/05/18 19:18	General View	 Load JPG	☒
87	21/05/18 19:18	General View	 Load JPG	☒
88	21/05/18 19:18	General View	 Load JPG	☒
89	21/05/18 19:18	General View	 Load JPG	☒
90	21/05/18 19:18	General View	 Load JPG	☒
91	21/05/18 19:18	General View	 Load JPG	☒
92	21/05/18 19:18	General View	 Load JPG	☒
93	21/05/18 19:18	General View	 Load JPG	☒
94	21/05/18 19:18	General View	 Load JPG	☒
95	21/05/18 19:18	General View	 Load JPG	☒
96	21/05/18 19:18	General View	 Load JPG	☒
97	21/05/18 19:18	General View	 Load JPG	☒
98	21/05/18 19:18	General View	 Load JPG	☒
99	21/05/18 19:18	General View	 Load JPG	☒
100	21/05/18 19:18	General View	 Load JPG	☒
101	21/05/18 19:18	General View	 Load JPG	☒
102	21/05/18 19:18	General View	 Load JPG	☒
103	21/05/18 19:18	General View	 Load JPG	☒
104	21/05/18 19:18	General View	 Load JPG	☒
105	21/05/18 19:18	General View	 Load JPG	☒
106	21/05/18 19:18	General View	 Load JPG	☒
107	21/05/18 19:18	General View	 Load JPG	☒
108	21/05/18 19:18	General View	 Load JPG	☒
109	21/05/18 19:18	General View	 Load JPG	☒
110	21/05/18 19:18	General View	 Load JPG	☒
111	21/05/18 19:18	General View	 Load JPG	☒
112	21/05/18 19:18	General View	 Load JPG	☒
113	21/05/18 19:18	General View	 Load JPG	☒
114	21/05/18 19:19	General View	 Load JPG	☒
115	21/05/18 19:19	General View	 Load JPG	☒
116	21/05/18 19:19	General View	 Load JPG	☒
117	21/05/18 19:19	General View	 Load JPG	☒
118	21/05/18 19:19	General View	 Load JPG	☒
119	21/05/18 19:19	General View	 Load JPG	☒
120	21/05/18 19:19	General View	 Load JPG	☒
121	21/05/18 19:19	General View	 Load JPG	☒
122	21/05/18 19:19	General View	 Load JPG	☒
123	21/05/18 19:19	General View	 Load JPG	☒
124	21/05/18 19:19	General View	 Load JPG	☒
125	21/05/18 19:19	General View	 Load JPG	☒
126	21/05/18 19:19	General View	 Load JPG	☒
127	21/05/18 19:19	General View	 Load JPG	☒
128	21/05/18 19:19	General View	 Load JPG	☒
129	21/05/18 19:19	General View	 Load JPG	☒
130	21/05/18 19:19	General View	 Load JPG	☒
131	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
132	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
133	21/05/18 19:19	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
135	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
136	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
137	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
138	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
139	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
140	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
141	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
142	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
143	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
144	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
145	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
146	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
147	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
148	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
149	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
150	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
151	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
152	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
153	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
154	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
155	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
156	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
157	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
158	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
159	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
160	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
161	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
162	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
163	21/05/18 19:19	Reinspection Photo	 Load JPG	☒
164	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
165	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
166	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
167	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
168	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
169	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
170	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
171	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
172	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
173	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
174	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
175	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
176	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
177	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
178	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
179	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
180	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
181	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
182	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
183	14/06/18 08:55	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
185	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
186	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
187	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
188	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
189	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
190	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
191	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
192	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
193	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
194	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
195	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
196	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
197	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
198	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
199	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
200	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
201	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
202	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
203	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
204	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
205	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
206	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
207	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
208	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
209	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
210	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
211	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
212	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
213	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
214	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
215	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
216	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
217	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
218	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
219	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
220	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
221	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
222	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
223	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
224	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
225	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
226	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
227	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
228	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
229	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
230	14/06/18 08:55	Reinspection Photo	Load JPG	☒
231	14/06/18 08:55	Reinspection Photo	Load JPG	☒
232	14/06/18 08:55	Reinspection Photo	Load JPG	☒
233	14/06/18 08:55	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
234	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
235	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
236	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
237	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
238	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
239	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
240	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
241	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
242	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
243	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
244	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
245	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
246	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
247	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
248	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
249	14/06/18 08:55	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 17:53	TP GIA REPORT	 Load PDF	
2	22/05/18 17:53	TP ESTIMATE- MARKED	 Load PDF	
3	23/05/18 11:28	Non reporting letter	 Load PDF	
4	07/06/18 17:59	LETTER TO OI	 Load PDF	
5	11/09/18 16:19	RENTAL RECEIPT	 Load PDF	
6	11/09/18 16:19	LTA SEARCH	 Load PDF	
7	30/10/18 12:38	COATING INVOICE	 Load PDF	
8	09/11/18 17:13	Work Chart	 Load PDF	
9	09/11/18 17:13	PURCHASE ORDER	 Load PDF	
10	09/11/18 17:13	DELIVERY ORDER	 Load PDF	
11	17/12/18 08:39	WORKSHOP INVOICE	 Load PDF	
12	17/12/18 08:39	AUTHORISATION TO ACT FORM	 Load PDF	
13	17/12/18 08:39	Release Voucher	 Load PDF	
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/06/18 09:27	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG8432Z (Insd veh)	Model:	HONDA JAZZ 1.3 CVT (A)
	SLW9086E (TP veh)		
Date of Accident:	18/05/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		30,262.08
Final Repair Cost	:	\$		13,464.28
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		2,889.00 27 days
LTA / GIA Search Fee	:	\$		7.49
Others:	:	\$		400.61
	:	\$		
Final Settlement Sum	:	\$		16,761.38

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 100 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 16,761.38
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

17 Dec
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18009200/UEB3Q2

Date: 17/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700078818
Claimant Vehicle No : SLW9086E **Insured Vehicle No :** GBG8432Z
 Date of Loss: 18/05/2018 Nature of Claim: TP Claim No: 1154556123SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW9086E**
 Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B11030393
 Reg. Date: 08/03/2018 (Man. Year: 2018) Chassis No: JHMGK3850JX213065
 Colour: Maroon Odometer: 4332 km
 Engine Capacity: 1318 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,202.32	8,393.44	9,808.88	53.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,080.00	4,190.00	5,890.00	58.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	28,282.32	12,583.44	15,698.88	55.51
+ GST 7.00/7.00% (\$\$)	1,979.76	880.84	1,098.92	55.51
Nett Amount (\$\$)	30,262.08	13,464.28	16,797.80	55.51
+ Car Rental (27.0 x S\$100.00/day + 7.00% GST) (\$\$)		2,889.00		
+ Doc/Search Fee (\$\$)		7.49		
+ Other Costs (\$\$)		400.61		
Nett Liability (\$\$)		16,761.38		

INSPECTION

Date of Assignment: 21/05/2018
 Date Inspected: 21/05/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216
 Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	716.30 FL	*716.30 FL
2	1		*TAILGATE LID LOCK	Twisted / Jammed	173.20 FL	*173.20 FL
3	1		*TAILGATE LID LOCK STRICKER	Not Necessary	24.70 FL	*- FL
4	1		*TAILGATE LID WEATHERSTRIP	Twisted	92.30 FL	*92.30 FL
5	1		*TAILGATE LID INNER TRIMBOARD	Not Necessary	52.10 FL	*- FL
6	2		*TAILGATE LID RUBER STOPPERS	Not Necessary	17.00 FL	*- FL
7	1		*TAILGATE LID INNER CLOSING HANDLE GARNISH	Not Necessary	15.00 FL	*- FL
8	2		*TAILGATE LID HINGE TOP	Not Necessary	60.40 FL	*- FL
9	2		*TAILGATE LID REFLECTOR GARNISH	Not Necessary	90.00 FL	*- FL
10	1		*TAILGATE LID OUTER GARNISH	Broken	103.40 FL	*103.40 FL
11	1		*TAILGATE LID OUTER GARNISH H BADGE	Necessary	15.50 FL	*15.50 FL
12	1		*TAILGATE LID JAZZ BADGE	Necessary	10.50 FL	*10.50 FL
13	1		*TAILGATE LID OPENING LEVER /HANDLE OUTER	Not Necessary	59.20 FL	*- FL
14	2		*TAILGATE LID DAMPER STAYS	Not Necessary	209.40 FL	*- FL
15	2		*TAILGATE LID DRAINAGE GROMMET	Not Necessary	110.00 FL	*- FL
16	1		*REAR WINDSCREEN GLASS	Shattered	1,430.00 FL	*1,430.00 FL
17	1		*REAR WIPER MOTOR	Not Necessary	98.20 FL	*- FL
18	1		*REAR WIPER ARM	Not Necessary	41.70 FL	*- FL
19	1		*REAR WIPER BLADE	Not Necessary	40.20 FL	*- FL
20	1		*REAR WIPER ARM COVER	Not Necessary	8.80 FL	*- FL
21	2		*REAR LICENCE PLATE LAMP	Not Necessary	65.60 FL	*- FL
22	1		*REAR END PANEL INNER	No such part	225.00 FL	*- FL
23	1		*REAR END PANEL OUTER	Badly Dented	314.00 FL	*314.00 FL
24	1		*REAR END PANEL INNER TRIM	Twisted	60.80 FL	*60.80 FL
25	2		*REAR LAMPS	Cracked	434.80 FL	*434.80 FL
26	1		*LEFT REAR LAMP PANEL	Badly Dented	75.30 FL	*75.30 FL
27	4		*LEFT REAR LAMP PANEL CLIP HOLDERS	Necessary	14.00 FL	*14.00 FL
28	1		*REAR LUGGAGE FLOOR PANEL	Repair	697.00 FL	*- FL
29	1		*REAR LUGGAGE FLOOR TOOLS COMPARTMENT FOAM	Deformed / Torn	130.80 FL	*130.80 FL
30	1		*REAR BUMPER	Distorted	527.00 FL	*527.00 FL
31	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	23.00 FL	*11.50 FL
32	2		*REAR BUMPER SIDE HOLDER	Not Necessary	90.00 FL	*- FL
33	2		*REAR BUMPER SCREW SPACER	Not Necessary	50.00 FL	*- FL
34	2		*REAR BUMPER FOG LAMP GARNISH	No such part	40.00 FL	*- FL
35	1		*REAR BUMPER CENTRE GARNISH (BLACK)	Grazed	85.00 FL	*85.00 FL
36	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
37	2		*REAR BUMPER SPLASHIELD COVER	Not Necessary	500.00 FL	*- FL
38	1		*LEFT REAR FENDER	Repair	559.30 FL	*- FL
39	1		*LEFT REAR FENDER INNER LINER	Not Necessary	65.70 FL	*- FL
40	8		*LEFT REAR FENDER INNER LINER CLIPS	Not Necessary	28.00 FL	*- FL
41	2		*REAR FENDER AIR VENT	Not Necessary	52.00 FL	*- FL
42	1		*SPEAKER SHELF BOARD	Not Necessary	165.60 FL	*- FL
43	2		*REAR FENDER INNER TOP GARNISH	Not Necessary	191.60 FL	*- FL
44	1		*BONNET	Buckled	527.00 FL	*527.00 FL
45	2		*BONNET HINGES	Twisted	49.80 FL	*49.80 FL
46	1		*BONNET LOCK	Twisted	41.70 FL	*41.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BONNET LOCK CABLE	Not Necessary	15.80 FL	*- FL
48	1		*BONNET INSULATOR	Distorted	86.00 FL	*86.00 FL
49	6		*BONNET INSULATOR CLIPS	Necessary	21.00 FL	*21.00 FL
50	1		*RIGHT BONNET UNDERSEAL WEATHERSTRIP	Necessary	14.10 FL	*14.10 FL
51	1		*LEFT BONNET UNDERSEAL WEATHERSTRIP	Necessary	14.10 FL	*14.10 FL
52	1		*LEFT BONNET UNDERSEAL WEATHERSTRIP INNER	Not Necessary	18.50 FL	*- FL
53	1		*RIGHT BONNET UNDERSEAL WEATHERSTRIP INNER	Not Necessary	18.50 FL	*- FL
54	2		*BONNET RUBBER STOPPERS	Not Necessary	21.00 FL	*- FL
55	1		*FRONT SUPPORT PANEL	Buckled	474.30 FL	*474.30 FL
56	2		*HEADLAMPS	Cracked / Broken	940.60 FL	*940.60 FL
57	2		*HEADLAMP LOWER BRACKETS	Cracked	47.20 FL	*47.20 FL
58	1		*FRONT BUMPER	Distorted	594.70 FL	*594.70 FL
59	1		*FRONT BUMPER REINFORCEMENT	Dented	295.00 FL	*295.00 FL
60	2		*FRONT BUMPER AIR GUIDE	Twisted	47.20 FL	*47.20 FL
61	4		*FRONT BUMPER AIR GUIDE CLIPS	Not Necessary	14.00 FL	*- FL
62	1		*FRONT BUMPER LOWER CENTRE AIR GRILLE	Deformed / Twisted	105.00 FL	*105.00 FL
63	2		*FRONT BUMPER LOWER CENTRE AIR GRILLE SIDE GARNISH	Twisted	50.00 FL	*50.00 FL
64	2		*FRONT BUMPER SPOT LAMP GARNISH	Not Necessary	170.00 FL	*- FL
65	10		*FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
66	1		*FRONT BUMPER TOW COVER	Torn	13.50 FL	*13.50 FL
67	2		*FRONT BUMPER SIDE RETAINERS	Bent	30.80 FL	*30.80 FL
68	2		*FRONT FENDERS	Repair	870.00 FL	*- FL
69	2		*FRONT FENDER INNER LINER	Not Necessary	180.40 FL	*- FL
70	8		*FRONT FENDER INNER LINER CLIPS	Not Necessary	28.00 FL	*- FL
71	1		*WINDSCREEN WASHER TANK	Not Necessary	56.10 FL	*- FL
72	1		*WINDSCREEN WASHER TANK MOTOR FRONT	Not Necessary	59.60 FL	*- FL
73	1		*WINDSCREEN WASHER TANK MOTOR REAR	Not Necessary	59.60 FL	*- FL
74	2		*WINDSCREEN WASHER TANK MOTOR PIPE	Not Necessary	51.00 FL	*- FL
75	1		*WIPER GRILLE	Not Necessary	1,732.20 FL	*- FL
76	1		*RADIATOR ASSY	Not Necessary	1,187.40 FL	*- FL
77	1		*RADIATOR EXPANSION TANK	Not Necessary	27.50 FL	*- FL
78	1		*RADIATOR EXPANSION TANK BRACKET	Not Necessary	35.00 FL	*- FL
79	1		*RADIATOR GRILLE	Cracked	317.70 FL	*317.70 FL
80	1		*RADIATOR GRILLE OUTER CHROME GARNISH	Cracked	233.90 FL	*233.90 FL
81	1		*RADIATOR GRILLE EMBLEM BADGE	Missing	14.60 FL	*14.60 FL
82	3		*RADIATOR GRILLE EMBLEM BADGE CLIPS	Not Necessary	11.70 FL	*- FL
83	1		*RADIATOR GRILLE EMBLEM BADGE BASE /HOLDER	Damaged	32.50 FL	*32.50 FL
84	1		*RADIATOR GRILLE CHROME MOULDING	Cracked	165.00 FL	*165.00 FL
85	6		*RADIATOR GRILLE CLIPS	Not Necessary	23.40 FL	*- FL
86	2		*RADIATOR TOP MOUNT BUSH	Not Necessary	31.00 FL	*- FL
87	1		*RADIATOR FAN SHROUD	Not Necessary	89.30 FL	*- FL
88	1		*RADIATOR FAN BLADE	Not Necessary	78.00 FL	*- FL
89	1		*RADIATOR FAN MOTOR	Not Necessary	219.00 FL	*- FL
90	1		*RADIATOR TOP HOSE	Not Necessary	16.80 FL	*- FL
91	1		*RADIATOR BOTTOM HOSE	Not Necessary	16.40 FL	*- FL
92	2		*RADIATOR BOTTOM MOUNT BUSH	Not Necessary	22.20 FL	*- FL
93	1		*RADIATOR EXPANSION TANK HOSE	Not Necessary	21.50 FL	*- FL
94	1		*INLET MANIFOLD ASSY	Not Necessary	370.00 FL	*- FL
95	1		*INLET MANIFOLD RUBBER HOSE	Not Necessary	18.50 FL	*- FL
96	1		*INLET MANIFOLD RUBBER HOSE CLIP HOLDER	Not Necessary	8.50 FL	*- FL
97	1		*AIR CLEANER TANK -INTAKE DUCT	Twisted	35.50 FL	*35.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	2		*AIR CLEANER TANK -INTAKE DUCT CLIPS	Necessary	7.00 FL	*7.00 FL
99	1		*AIR CLEANER TANK -INTAK HOSE	Damaged	34.50 FL	*34.50 FL
100	1		*AIRCON CONDENSER	Punctured / Bent	704.00 FL	*704.00 FL
101	1		*AIRCON FAN BLADE	Not Necessary	43.90 FL	*- FL
102	1		*AIRCON FAN MOTOR	Not Necessary	310.00 FL	*- FL
103	1		*AIRCON FAN SHROUD	Not Necessary	78.00 FL	*- FL
104	1		*AIRCON PIPE CONDENSER TO COMPRESSOR	Not Necessary	141.90 FL	*- FL
105	1		*AIRCON HOSE COMPRESSOR TO EVAPORATOR	Not Necessary	109.70 FL	*- FL
106	1		*BATTERY COVER	Deformed	17.70 FL	*17.70 FL
107	1		*BATTERY TRAY	Twisted	15.70 FL	*15.70 FL
108	1		*BATTERY SUPPORT PANEL	Not Necessary	72.20 FL	*- FL
109	12		*ROOF -GUTTER MOULDING CLIPS	Not Necessary	54.00 FL	*- FL
110	1		*SET SUNDRIES AND CLIPS	Not Necessary	100.00 FS	*- FS
111	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	180.00 FS	*40.00 FS
112	1		*REAR WINDSCREEN GLASS SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
113	1		*REAR WINDSCREEN GLASS SOLAR FILM	Necessary	500.00 FS	*200.00 FS
114	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS
115	1		*BACKOFF CAMERA WITH NIGHT VISION	Not Necessary	550.00 FS	*- FS
116	1		*REAR LUGGAGE FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
117	1		*SET REAR BUMPER PARKING SENSOR	Shorted	500.00 FS	*280.00 FS
118	1		*FRONT LICENCE PLATE	Bent	80.00 FS	*40.00 FS
119	1		*TIN RADIATOR COOLANT	Necessary	80.00 FS	*30.00 FS
120	1		*BATTERY	Not Necessary	200.00 FS	*- FS
121	1		*BATTERY POSITIVE TERMINAL COVER	Distorted	19.50 FL	*19.50 FL
122	1		*AIR CLEANER TANK HOUSING BOTTOM	Twisted	126.90 FL	*126.90 FL
123	1		*RADIATOR GRILLE BRACKET	Cracked	19.50 FL	*19.50 FL
124	1		*LEFT REAR LUGGAGE FLOOR SIDE EXTENSION PANEL	Dented	90.40 FL	*90.40 FL
125	1		*FRONT LICENCE PLATE GARNISH	Distorted	78.00 FL	*78.00 FL
126	2		*REAR BUMPER SIDE GARNISH (BLACK)	Grazed	56.00 FL	*56.00 FL
127	1		*SET REAR WINDSHIELD GLASS MOULDING	Necessary	60.00 FL	*60.00 FL
128	1		*REAR GRILLE COVER	Cracked	25.00 FL	*25.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **22,105.40** **10,326.80**
 - List Item Discount on L Items 20.00/20.00% (\$\$) **3,903.08** **1,933.36**

Total Parts (\$\$) **18,202.32** **8,393.44**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	850.00	280.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	350.00	120.00
3	TO APPLY PANEL PROTECTION SYSTEM AND SHINES	New	450.00	0.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND VACUUM SHATTERED BROKEN GLASS	New	250.00	120.00
5	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	180.00	60.00
6	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	200.00	50.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	250.00	80.00
8	TO REMOVE BACKOFF CAMERA AND SETTINGS	New	120.00	50.00
9	TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE-IN GAS	New	300.00	100.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	30.00
11	LABOUR TO REMOVE AND RENEW INLET MANIFOLD ASSY AND FRONT CHASSIS	New	250.00	0.00
12	TO CONDUCT DIAGNOSTIC CHECK AND RECALL ERROR CODES AND SETTINGS	New	500.00	0.00
13	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,800.00	1,600.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,500.00	1,700.00
Gross Labour Cost (\$\$)			10,080.00	4,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >