

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref :

\$ 43,241.00

M/S AIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GU9589R

CR420021905

List Items

- | | | | | |
|-----|-------|-------------------------|---------|---|
| 01) | 1 PC | TAILGATE | 3015.00 | — |
| 02) | 1 PC | TAILGATE GLASS MOULDING | neu | ✓ |
| 03) | 1 PC | REAR BUMPER | 22/00 | — |
| 04) | 1 SET | REAR BUMPER CLIPS | neu | — |
| 05) | 2 PCS | REAR BUMPER REFLECTOR | 11X | — |
| 06) | 1 PC | FRONT LH HEADLAMP RIM | 11X | — |
| 07) | 1 PC | LH SIDELAMP | 11X | — |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LESS 25%

SEALANT rear windscreen

Labour Charge

- | | | | | |
|-----|--------------------------------|----|--------|-----|
| 08) | TO REMOVE AND REFIX REAR GLASS | \$ | 120.00 | ✓ |
| 09) | TUFFKOTE | \$ | 80.00 | 30 |
| 10) | SPRAY PAINTING | \$ | 380.00 | 300 |
| | LABOUR CHARGE | \$ | 450.00 | 300 |
| | WIRING CHECK | \$ | 30.00 | 20 |

neu \$ 40.00 —

TOTAL

not signed
hale
2/5/18
4 day take photo after repair