## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

REPAIR ESTIMATE* VEHICLE NO: SHC 2677Z DATE 18/5/2018 10:05					IVV		
	o: SHC 2677Z	DATE	18/5/2018 10:05			4	
MAKE MODEL	: : HYUNDAI SONATA					1	
Qty	Parts Description/ Labour	Type	Unit Price		Amount	1 M	
2.7	Rear Bumper	-34-		\$	578.40		
	Rear Bumper Reinforcement ?			\$	483.30		
	Rear Bumper Clip			\$	22.00		
	Rear Bumper Sponge ,7			\$	137.40		
	Rear Bumper Under Cover X			\$	185.80		
	Rear Bumper Protector (LH/RH) & Mysl		\$ 38.0	) \$	76.00		
	SUB TOTAL			\$	1,482.90	]	
	LESS 20%			\$	296.58		
	DISCOUNTED TOTAL		- 3711-7	\$	1,186.32		
	Rear Bumper Reverse Sensor			\$	135.70	Nett	
						-	
				\$	135.70	-	
	Labour Charge			0	200		
	Panel Beating			\$	280.00	200	
	Spray Painting Charge Wiring Charge			\$	250.00	4	
	Remove/Refix Reverse Sensor			\$	5 <u>0.00</u> 120. <del>00</del>		
	Remove/Renx Reverse Sensor			D.	12000	2	
	TOTAL LABOUR			\$	700.00	1	
	TOTAL LABOUR			9	700.00	1	
	ESTIMATE TOTAL			\$	2,022.02	1	
						1	
	Kalur (ClCK)  18/5/10 1045hs  2 Rys			_			
	Kalve ic	LICK Auto	Consultants hence not	fy	1		
	1/ 10/1/8 1045hs	the Repa	Tel Ul tilo		1		
	// 10/21	<ul> <li>To resurv</li> </ul>	by beloverated during res	urvey			
	2 Rys	Parts pri	damaged part(s) during bes are subject to confirmation by survey is on a "Without Pit world (ration(s) is allowed	ejudice"	basis		
	2"	• Third pa	ty survey is one allowed				
	45	No meg     Supple	al modification(s) is allowed mentary item(s) must be resu ct to final approval from Insu	rance Co	ompany		
	111 Para della	is subje	CC 10 IIII				
	Hs Reporpla	Acknow	edged by Repairer				
	/ / / /	Signatu	re:				
		Date:					

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.