



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI18009220/Usbe2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 25-06-2018



Code : EQI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YM 5565P
Policy No.	DMCFHQ18-000059	Coverage (\$)	0.00
Claim No.	DM18HO01213/FN	Excess (\$)	3,000.00
Assign From	FRANCIS NG	Assign Date	21/05/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FM657MSRDEC (M)	c.c	7545
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	FM657MB10143	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	10.00-20	VIKRANT	6 mm
L/H Front Tyre	10.00-20	VIKRANT	6 mm
R/H Rear Tyre	10.00-20 (D)	VIKRANT	6/6 mm
L/H Rear Tyre	10.00-20 (D)	VIKRANT	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/05/2018	Inspection Date	22/05/2018
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		

5a. Remarks

A)THE MARKET VALUE IS S\$46,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------