







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18009226/T1pb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-05-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLF 3592P	Veh. Inspected	PA 5859L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	16/05/2018	Inspection Date	21/05/2018
Survey held at	SIN HUP LEE SERVICE CO BLK 1005 BUKIT MERAH LANE 2 #01-20 SINGAPORE 159761		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

Attn: Motor Claim Department  
AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

Ng Say Choo  
c/o Sin Hup Lee Service Co.  
Block 1005 Bukit Merah Lane 2 #01-20  
Singapore 159761

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

20 May 2018  
Car No. 62563561  
Tanglim 97445749  
21/5/18 @ 115 pm.  
"WP."  
Lumpsum  
Resurvey after paint  
sw @ 11kants.com  
6 days

Dear Sir/Ms,

Re: Road Traffic on 16 May 2018 along Bukit Batok West Ave 8, involving vehicle SLF3592P / PA5859L

Quotation for Repair Vehicle No: PA5859L, Toyota Hiace (Third Party Claim)

Quantity	List Item	
1	Head Lamp LH	\$ car ✓ 479.80
1	Head Lamp Clip	\$ rec ✓ 21.30
1	Front Grille	\$ car ✓ 398.50
8	Front Grille Clip	\$ rec ✓ 40.60
1	Bonnet	\$ht ✓ 553.20
1	Front Bumper	\$ car ✓ 513.20
1	Front Bumper Tow Cover	\$ mis ✓ 43.60
1	Front Bumper Reinforcement	\$ bt ✓ 474.20
2	Front Bumper Bracket (L+R)	98.70 LH-car ✓, RH-SXM 197.40
1	Front Bumper Fog Light Cover LH	\$ car ✓ 85.50
10	Front Bumper Clip	\$ wa ✓ 40.80
1	Front Bumper Side Bracket LH	\$ dis ✓ 171.20
1	Radiator	\$ bt ✓ 1,377.60

- 1 Radiator Lower Bracket
- 1 Radiator Fan Assy *= 7 photo*
- 1 Wire Harness Assembly
- 1 Wire Harness LH Door
- 1 Front Door LH
- 1 Front Pillar LH

\$ *bt* 263.70  
 \$ ? 578.20 *cr*  
 \$ *1500* { 3,169.50  
 \$ { 2,976.10  
 \$ *bt* 1,574.20  
 \$ *Rx* 796.40  
 \$ 43,755.00  
 \$ 3,438.75  
 \$ 10,316.25

$\frac{\$8214.30}{25\%}$   
 $\$6160.73$

- NETT ITEM** *Chrome*
- 1 Front Bumper *Chrome* LH
  - 1 Front Bumper Sensor

\$ *cr* 200.00  
 \$ *cr* 200.00

**Labour**

- 1 To cut-weld Front Door Pillar LH. To repair Front Panel LH, Floor Panel LH, Step Panel LH, remove and re-fix damaged parts, straighten and realign affected areas.
- 2 To spray affected areas
- 3 To remove and re-fix Rear Dashboard Side Cover, Glove Box and other attachment parts
- 4 To remove and re-fix Door Mechanism. Check & test Power Window and Centre Locking System
- 5 To remove and re-fix Wire Harness Claim Clip and other attachment parts
- 6 To remove and re-fix Radiator Electric Form & Hose Pipe
- 7 To rustproof affected areas
- 8 To check body structure and chassis alignment

\$ *700* 1,120.00

\$ *600* 900.00

*un photo* X \$ ? 200.00

\$ *60* 100.00

\$ *100* 200.00

\$ *60* 100.00

\$ *40* 80.00

*1660* \$ *100* 200.00

**Total Amount** \$ 13,616.25

Kindly arrange your surveyor to survey my vehicle.  
 We look forward to hear from you soon.  
 Thank you.

Yours Faithfully  
 Mr Wong  
 81122116

$\$8,214.30$   
 $- 25\%$   
 $\$6,160.73$   
 $+ \$400.00$   
 $+ \$1,660.00$   
 $\$8,220.73$   
 $- 20\%$   
 $\$6,576.58$

*= Us: \$6,550.00 with 6 working day*

## Poh Kin (LKKAuto)

---

**From:** sin hup lee <sinhuplee@gmail.com>  
**Sent:** Sunday, 25 November 2018 11:24 PM  
**To:** Poh Kin (LKKAuto)  
**Subject:** Re: Our Ref: CC6/AIG18009226/T1pb3(PA 5859L)  
**Attachments:** image001.jpg; PA5859L\_1.jpeg; PA5859L\_DV.pdf; PA5859L\_2.jpeg; PA5859L\_3.jpeg

**Categories:** clear

Hi Pho Kin,

As requested

Regards,  
Mr Wong

On Wed, Nov 21, 2018 at 4:29 PM Poh Kin (LKKAuto) <[pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)> wrote:

### WITHOUT PREJUDICE

Our Ref: CC6/AIG18009226/T1pb3

Your Ref: PA 5859L

Dear Mr Wong,

### **ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLF 3592P AND PA 5859L ON 16/05/2018**

We refer to the above matter and our tele conversation on even date.

We hereby confirmed settlement as below:

1. Cost of Repair	S\$ 6,550.00
2. Loss of Rental (\$130.00 x 8 days)	<u>S\$ 1,040.00</u>
	<b><u>S\$ 7,590.00</u></b>

**Poh Kin (LKKAuto)**

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Wednesday, 21 November 2018 4:29 PM  
**To:** 'sin hup lee'  
**Subject:** RE: Our Ref: CC6/AIG18009226/T1pb3(PA 5859L)  
**Attachments:** DV PA 5859L.pdf

**Importance:** High

**WITHOUT PREJUDICE**

Our Ref: CC6/AIG18009226/T1pb3  
Your Ref: PA 5859L

Dear Mr Wong,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLF 3592P AND PA 5859L ON 16/05/2018**

We refer to the above matter and our tele conversation on even date.

We hereby confirmed settlement as below:

1. Cost of Repair	S\$ 6,550.00
2. Loss of Rental (\$130.00 x 8 days)	<u>S\$ 1,040.00</u>
	<b><u>S\$ 7,590.00</u></b>

Please duly sign the DV attached and return with Rental Agreement for payment processing.

In the meantime, we appreciate if you could let us have a copy of after repair photo for our file record.

Your prompt reply will be very much appreciated.

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Monday, 24 September 2018 4:52 PM  
**To:** 'sin hup lee'  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: Our Ref: CC6/AIG18009226/T1pb3(PA 5859L)

### WITHOUT PREJUDICE

Our Ref: CC6/AIG18009226/T1pb3  
Your Ref: PA 5859L

Dear Mr Wong,

### **ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SLF 3592P AND PA 5859L ON 16/05/2018**

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair	S\$ 6,550.00
2. Loss of Rental (\$100.00 x 8 days)	<u>S\$ 800.00</u>
	<b><u>S\$ 7,350.00</u></b>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Friday, 7 September 2018 2:29 PM  
**To:** 'sinhuplee@gmail.com'  
**Cc:** Taufikh (LKKAuto); Hsiao Tong (LKKAuto)  
**Subject:** Our Ref: CC6/AIG18009226/T1pb3(PA 5859L)  
**Attachments:** TP Estimate-Marked.pdf

**Importance:** High

### Without Prejudice

Our Ref: CC6/AIG18009226/T1pb3(PA 5859L)

Dear Mr Wong,

We refer to the above matter.

For COR, our surveyor had recommended amount for this cases as below:

- **PA 5859L, DOA 16/05/2018- L/S \$6,550.00 with 6 working days.**

Please note that: All finalisation is subject to our Principal insurer's approval.

In the meantime, kindly furnish us a copy of **after repair photo** for our file record.

\*\*\* Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2018 <a href="#">Edit Reg</a>		21 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$6,550.00</b> <a href="#">Edit Estimates</a>	<b>\$6,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main
Reference
Claim Details
Documents
[Show All](#)

### CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	WONG CHAI, ID: S0209396J		
Main Claimant:	NG SAY CHOO, ID: -		
Vehicle Reg. No.:	PA5859L	Date of Loss:	16/05/2018 13:00 - :59 [148 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1711162906SG	Policy/Cover Note No.:	2100479286 (Comprehensive) Coverage: 24/08/2017 - 23/08/2018
Vehicle Reg. No. (Insured):	SLF3592P	Policy No. (Claimant):	DMB1SN1802111800
Repairer:	Sin Hup Lee Service Co (HQ) Bk 1005 Bukit Merah Lane 2, #01-209 Alexandra Village Industrial Estate, 159761 Bukit Merah - Tel: 6278-2482		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/05/2018]		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Letters/Correspondences			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/09/18 09:01	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
66	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
69	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
72	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
76	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
77	24/09/18 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
78	24/09/18 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	24/09/18 09:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	24/09/18 09:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLF3592P (Insd veh) ✓	Model:	TOYOTA HIACE 2.0 (M) ✓
	PA5859L (TP veh) ✓		
Date of Accident:	16/05/2018 ✓		

Global Sum Settlement	:	[ ] Yes	[ X ] No
Repair Estimate	:\$		13,616.25 ✓
Final Repair Cost	:\$		6,550.00 ✓
Loss of Use	:\$		_____ days at \$0.00 per day
Rental (if any)	:\$		1,040.00 ✓ 8 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum	:\$		7,590.00 ✓
<b>Is Third Party Workshop GIA Registered?</b> [ ] YES [ X ] NO (Kindly indicate below)			
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability _____ 100 _____ (%)	
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Sin Hup Lee Service Co. ✓	:\$	7,590.00 ✓
2)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

06 Dec  
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18009226/T1PB3S2

Date: 06/12/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479286  
 Claimant Vehicle No: PA5859L Insured Vehicle No: SLF3592P  
 Date of Loss: 16/05/2018 Nature of Claim: TP Claim No: 1711162906SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: PA5859L  
 Make & Model: TOYOTA HIACE, 2.0 (M) Engine No: 2KD1380381  
 Reg. Date: 13/01/2006 (Man. Year: 2005) Chassis No: KDH2220011174  
 Colour: Grey Odometer: 544202 km  
 Engine Capacity: 2500 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,716.25	6,560.72	4,155.53	38.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,660.00	1,240.00	42.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,616.25</b>	<b>8,220.72</b>	<b>5,395.53</b>	<b>39.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,616.25</b>	<b>6,550.00</b>	<b>7,066.25</b>	<b>51.90</b>
<b>+ Car Rental (8.0 x S\$130.00/day) (S\$)</b>		<b>1,040.00</b>		
<b>Nett Liability (S\$)</b>		<b>7,590.00</b>		

## INSPECTION

Date of Assignment: 21/05/2018  
 Date Inspected: 21/05/2018 Inspected At: Sin Hup Lee Service Co (HQ)  
 Village Industrial Estate  
 Singapore 159761  
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH	Cracked	479.80 FL	*479.80 FL
2	1		*HEAD LAMP CLIP	Necessary	21.30 FL	*21.30 FL
3	1		*FRONT GRILLE	Cracked	398.50 FL	*398.50 FL
4	1		*FRONT GRILLE CLIP	Necessary	40.60 FL	*40.60 FL
			8pcs			
5	1		*BONNET	Bent	553.20 FL	*553.20 FL
6	1		*FRONT BUMPER	Cracked	513.20 FL	*513.20 FL
7	1		*FRONT BUMPER TOW COVER	Missing	43.60 FL	*43.60 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	474.20 FL	*474.20 FL
9	1		*FRONT BUMPER BRACKET L+R	N/s Cracked/O/s Not Necessary	197.40 FL	*98.70 FL
10	1		*FRONT BUMPER FOG LIGHT COVER LH	Cracked	85.50 FL	*85.50 FL
11	10		*FRONT BUMPER CLIP	Necessary	40.80 FL	*40.80 FL
12	1		*FRONT BUMPER SIDE BRACKET LH	Distorted	171.20 FL	*171.20 FL
13	1		*RADIATOR	Bent	1,377.60 FL	*1,377.60 FL
14	1		*RADIATOR LOWER BRACKET	Bent	263.70 FL	*263.70 FL
15	1		*RADIATOR FAN ASSY	Cracked	578.20 FL	*578.20 FL
16	1		*WIRE HARNESS ASSEMBLY }	Torn	3,169.50 FL	*1,500.00 FL
17	1		*WIRE HARNESS LH DOOR }		2,976.10 FL	*- FL
18	1		*FRONT DOOR LH	Bent	1,574.20 FL	*1,574.20 FL
19	1		*FRONT PILLAR LH	Repair	796.40 FL	*- FL
20	1		*FRONT BUMPER CHROME LH	Cracked	200.00 FS	*200.00 FS
21	1		*FRONT BUMPER SENSOR	Cracked	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,155.00</b>	<b>8,614.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>3,438.75</b>	<b>2,053.58</b>
<b>Total Parts (S\$)</b>	<b>10,716.25</b>	<b>6,560.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT-WELD FRONT DOOR PILLAR LH. TO REPAIR FRONT PANEL LH, FLOOR PANEL LH, STEP PANEL LH, REMOVE AND RE-FIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS.	New	1,120.00	700.00
2	TO SPRAY AFFECTED AREAS.	New	900.00	600.00
3	TO REMOVE AND RE-FIX REAR DASHBOARD SIDE COVER, GLOVE BOX AND OTHER ATTACHMENT PARTS.	New	200.00	0.00
4	TO REMOVE AND RE-FIX DOOR MECHANISM. CHECK & TEST POWER WINDOW AND CENTRE LOCKING SYSTEM.	New	100.00	60.00
5	TO REMOVE AND RE-FIX WIRE HARNESS CLAIM CLIP AND OTHER ATTACHMENT PARTS.	New	200.00	100.00
6	TO REMOVE AND RE-FIX RADIATOR ELECTRICAL FORM & HOSE PIPE.	New	100.00	60.00
7	TO RUSTPROOF AFFECTED AREAS.	New	80.00	40.00
8	TO CHECK BODY STRUCTURE AND CHASSIS ALIGNMENT.	New	200.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>2,900.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >