

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0589/2018/GW  
**Date** : 21-May-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : SLE 4060 G

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms. Ng Yoke Chun Irene  
**Address** : 10 Newton Road  
#13-01  
Singapore 307947  
**Telephone** : HP +65 92959462  
**Type of Claim** : Third Party Claims  
**Policy No.** : 2100393126-03  
**Vehicle No** : **SCJ 9699 L**  
**Model Code** : Audi A3 SEDAN 1.4 TFSI  
**Model / Year** : Nov-14  
**Engine No** : CXS 072215  
**Chassis No** : WAUZZZ8V2E1025367  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 20-May-18  
**Place of Accident** : DROP OFF/ TAXI BAY AT YISHUN MRT ALONG YISHUN AVE 2

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SCJ 9699 L.

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ <del>1,800.00</del> 750 ✓
3	To respray front bumper and bonnet.	\$ <del>1,500.00</del> 1100 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u><u>3,852.00</u></u></b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SCJ 9699 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	\$ 1,739.00	X
2	RADIATOR GRILLE <i>Cracked</i>	\$ 573.00	✓
3	RADIATOR GRILLE COVER ?	\$ 86.00	?
4	BONNET <i>Repair</i>	\$ 2,755.00	X
5	EDGE PROTECTION <i>new</i>	\$ 24.00	✓
6	SIGN 'CUATION ' <i>2 new</i>	\$ 12.00	✓
7	STICKER AIR CONDITIONER	\$ 7.00	✓
8	FRONT NO. PLATE <i>new</i>	S/N \$ 25.00	✓
8	SUNDRIES ?	\$ 200.00	?
<b>TOTAL SPARE PARTS CHARGES</b>		<b>: \$ 5,421.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,852.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 9,273.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian King  
**Surveyed Date** : 25/05/18.0  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, out days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant